

Introduction to

STATISTICAL

QUALITY

CONTROL

6th Edition

Douglas C. Montgomery

Contents

PART 1

INTRODUCTION 1

1 QUALITY IMPROVEMENT IN THE MODERN BUSINESS ENVIRONMENT 3

| | |
|---|----|
| Chapter Overview and Learning Objectives | 3 |
| 1.1 The Meaning of Quality and Quality Improvement | 4 |
| 1.1.1 Dimensions of Quality | 4 |
| 1.1.2 Quality Engineering Terminology | 8 |
| 1.2 A Brief History of Quality Control and Improvement | 9 |
| 1.3 Statistical Methods for Quality Control and Improvement | 13 |
| 1.4 Management Aspects of Quality Improvement | 16 |
| 1.4.1 Quality Philosophy and Management Strategies | 17 |
| 1.4.2 The Link Between Quality and Productivity | 35 |
| 1.4.3 Quality Costs | 36 |
| 1.4.4 Legal Aspects of Quality | 41 |
| 1.4.5 Implementing Quality Improvement | 42 |

2 THE DMAIC PROCESS 45

| | |
|--|----|
| Chapter Overview and Learning Objectives | 45 |
| 2.1 Overview of DMAIC | 45 |
| 2.2 The Define Step | 49 |
| 2.3 The Measure Step | 50 |
| 2.4 The Analyze Step | 52 |
| 2.5 The Improve Step | 53 |
| 2.6 The Control Step | 54 |

| | |
|---|----|
| 2.7 Examples of DMAIC | 54 |
| 2.7.1 Litigation Documents | 54 |
| 2.7.2 Improving On-Time Delivery | 56 |
| 2.7.3 Improving Service Quality in a Bank | 59 |

PART 2 STATISTICAL METHODS USEFUL IN QUALITY CONTROL AND IMPROVEMENT 61

3 MODELING PROCESS QUALITY 63

| | |
|--|----|
| Chapter Overview and Learning Objectives | 63 |
| 3.1 Describing Variation | 64 |
| 3.1.1 The Stem-and-Leaf Plot | 64 |
| 3.1.2 The Histogram | 66 |
| 3.1.3 Numerical Summary of Data | 69 |
| 3.1.4 The Box Plot | 71 |
| 3.1.5 Probability Distributions | 72 |
| 3.2 Important Discrete Distributions | 76 |
| 3.2.1 The Hypergeometric Distribution | 76 |
| 3.2.2 The Binomial Distribution | 77 |
| 3.2.3 The Poisson Distribution | 79 |
| 3.2.4 The Pascal and Related Distributions | 80 |
| 3.3 Important Continuous Distributions | 81 |
| 3.3.1 The Normal Distribution | 81 |
| 3.3.2 The Lognormal Distribution | 86 |
| 3.3.3 The Exponential Distribution | 88 |
| 3.3.4 The Gamma Distribution | 89 |
| 3.3.5 The Weibull Distribution | 91 |
| 3.4 Probability Plots | 93 |
| 3.4.1 Normal Probability Plots | 93 |
| 3.4.2 Other Probability Plots | 95 |
| 3.5 Some Useful Approximations | 96 |
| 3.5.1 The Binomial Approximation to the Hypergeometric | 96 |

X Contents

| | | |
|-------|---|----|
| 3.5.2 | The Poisson Approximation to the Binomial | 96 |
| 3.5.3 | The Normal Approximation to the Binomial | 97 |
| 3.5.4 | Comments on Approximations | 98 |

4

INFERENCE ABOUT PROCESS QUALITY

103

| | |
|--|-----|
| Chapter Overview and Learning Objectives | 104 |
| 4.1 Statistics and Sampling Distributions | 104 |
| 4.1.1 Sampling from a Normal Distribution | 105 |
| 4.1.2 Sampling from a Bernoulli Distribution | 108 |
| 4.1.3 Sampling from a Poisson Distribution | 109 |
| 4.2 Point Estimation of Process Parameters | 110 |
| 4.3 Statistical Inference for a Single Sample | 112 |
| 4.3.1 Inference on the Mean of a Population, Variance Known | 113 |
| 4.3.2 The Use of <i>P</i> -Values for Hypothesis Testing | 116 |
| 4.3.3 Inference on the Mean of a Normal Distribution, Variance Unknown | 117 |
| 4.3.4 Inference on the Variance of a Normal Distribution | 120 |
| 4.3.5 Inference on a Population Proportion | 122 |
| 4.3.6 The Probability of Type II Error and Sample Size Decisions | 124 |
| 4.4 Statistical Inference for Two Samples | 127 |
| 4.4.1 Inference for a Difference in Means, Variances Known | 128 |
| 4.4.2 Inference for a Difference in Means of Two Normal Distributions, Variances Unknown | 130 |
| 4.4.3 Inference on the Variances of Two Normal Distributions | 137 |
| 4.4.4 Inference on Two Population Proportions | 139 |
| 4.5 What If There Are More Than Two Populations? The Analysis of Variance | 140 |
| 4.5.1 An Example | 140 |
| 4.5.2 The Analysis of Variance | 142 |
| 4.5.3 Checking Assumptions: Residual Analysis | 148 |
| 4.6 Linear Regression Models | 150 |
| 4.6.1 Estimation of the Parameters in Linear Regression Models | 151 |

| | | |
|-------|---|-----|
| 4.6.2 | Hypothesis Testing in Multiple Regression | 157 |
| 4.6.3 | Confidence Intervals in Multiple Regression | 163 |
| 4.6.4 | Prediction of New Observations | 164 |
| 4.6.5 | Regression Model Diagnostics | 165 |

PART 3

BASIC METHODS OF STATISTICAL PROCESS CONTROL AND CAPABILITY ANALYSIS

177

5

METHODS AND PHILOSOPHY OF STATISTICAL PROCESS CONTROL

179

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 179 |
| 5.1 Introduction | 180 |
| 5.2 Chance and Assignable Causes of Quality Variation | 181 |
| 5.3 Statistical Basis of the Control Chart | 182 |
| 5.3.1 Basic Principles | 182 |
| 5.3.2 Choice of Control Limits | 189 |
| 5.3.3 Sample Size and Sampling Frequency | 191 |
| 5.3.4 Rational Subgroups | 193 |
| 5.3.5 Analysis of Patterns on Control Charts | 195 |
| 5.3.6 Discussion of Sensitizing Rules for Control Charts | 197 |
| 5.3.7 Phase I and Phase II of Control Chart Application | 198 |
| 5.4 The Rest of the Magnificent Seven | 199 |
| 5.5 Implementing SPC in a Quality Improvement Program | 205 |
| 5.6 An Application of SPC | 206 |
| 5.7 Applications of Statistical Process Control and Quality Improvement Tools in Transactional and Service Businesses | 213 |

6

CONTROL CHARTS FOR VARIABLES

226

| | |
|--|-----|
| Chapter Overview and Learning Objectives | 226 |
| 6.1 Introduction | 227 |

| | | |
|-------|--|-----|
| 6.2 | Control Charts for \bar{x} and R | 228 |
| 6.2.1 | Statistical Basis of the Charts | 228 |
| 6.2.2 | Development and Use of \bar{x} and R Charts | 231 |
| 6.2.3 | Charts Based on Standard Values | 242 |
| 6.2.4 | Interpretation of \bar{x} and R Charts | 243 |
| 6.2.5 | The Effect of Nonnormality on \bar{x} and R Charts | 246 |
| 6.2.6 | The Operating-Characteristic Function | 246 |
| 6.2.7 | The Average Run Length for the \bar{x} Chart | 249 |
| 6.3 | Control Charts for \bar{x} and s | 251 |
| 6.3.1 | Construction and Operation of \bar{x} and s Charts | 251 |
| 6.3.2 | The \bar{x} and s Control Charts with Variable Sample Size | 255 |
| 6.3.3 | The s^2 Control Chart | 259 |
| 6.4 | The Shewhart Control Chart for Individual Measurements | 259 |
| 6.5 | Summary of Procedures for \bar{x} , R , and s Charts | 268 |
| 6.6 | Applications of Variables Control Charts | 268 |

7 CONTROL CHARTS FOR ATTRIBUTES

288

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 288 |
| 7.1 Introduction | 289 |
| 7.2 The Control Chart for Fraction Nonconforming | 289 |
| 7.2.1 Development and Operation of the Control Chart | 290 |
| 7.2.2 Variable Sample Size | 301 |
| 7.2.3 Applications in Transactional and Service Businesses | 304 |
| 7.2.4 The Operating-Characteristic Function and Average Run Length Calculations | 306 |
| 7.3 Control Charts for Nonconformities (Defects) | 308 |
| 7.3.1 Procedures with Constant Sample Size | 309 |
| 7.3.2 Procedures with Variable Sample Size | 319 |
| 7.3.3 Demerit Systems | 321 |

| | | |
|-------|--|-----|
| 7.3.4 | The Operating-Characteristic Function | 322 |
| 7.3.5 | Dealing with Low Defect Levels | 323 |
| 7.3.6 | Nonmanufacturing Applications | 326 |
| 7.4 | Choice Between Attributes and Variables Control Charts | 326 |
| 7.5 | Guidelines for Implementing Control Charts | 330 |

8

PROCESS AND MEASUREMENT SYSTEM CAPABILITY ANALYSIS 344

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 345 |
| 8.1 Introduction | 345 |
| 8.2 Process Capability Analysis Using a Histogram or a Probability Plot | 347 |
| 8.2.1 Using the Histogram | 347 |
| 8.2.2 Probability Plotting | 349 |
| 8.3 Process Capability Ratios | 351 |
| 8.3.1 Use and Interpretation of C_p | 351 |
| 8.3.2 Process Capability Ratio for an Off-Center Process | 354 |
| 8.3.3 Normality and the Process Capability Ratio | 356 |
| 8.3.4 More about Process Centering | 357 |
| 8.3.5 Confidence Intervals and Tests on Process Capability Ratios | 359 |
| 8.4 Process Capability Analysis Using a Control Chart | 364 |
| 8.5 Process Capability Analysis Using Designed Experiments | 366 |
| 8.6 Process Capability Analysis with Attribute Data | 367 |
| 8.7 Gauge and Measurement System Capability Studies | 368 |
| 8.7.1 Basic Concepts of Gauge Capability | 368 |
| 8.7.2 The Analysis of Variance Method | 373 |
| 8.7.3 Confidence Intervals in Gauge R & R Studies | 376 |
| 8.7.4 False Defectives and Passed Defectives | 377 |
| 8.7.5 Attribute Gauge Capability | 381 |
| 8.8 Setting Specification Limits on Discrete Components | 383 |
| 8.8.1 Linear Combinations | 384 |
| 8.8.2 Nonlinear Combinations | 387 |

| | | |
|-------|--|-----|
| 8.9 | Estimating the Natural Tolerance Limits of a Process | 388 |
| 8.9.1 | Tolerance Limits Based on the Normal Distribution | 389 |
| 8.9.2 | Nonparametric Tolerance Limits | 390 |

| | | |
|-------|---|-----|
| 9.2.2 | Design of an EWMA Control Chart | 422 |
| 9.2.3 | Robustness of the EWMA to Non-normality | 424 |
| 9.2.4 | Rational Subgroups | 425 |
| 9.2.5 | Extensions of the EWMA | 425 |
| 9.3 | The Moving Average Control Chart | 428 |

PART 4

OTHER STATISTICAL PROCESS-MONITORING AND CONTROL TECHNIQUES 397

9 CUMULATIVE SUM AND EXPONENTIALLY WEIGHTED MOVING AVERAGE CONTROL CHARTS 399

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 400 |
| 9.1 The Cumulative Sum Control Chart | 400 |
| 9.1.1 Basic Principles: The Cusum Control Chart for Monitoring the Process Mean | 400 |
| 9.1.2 The Tabular or Algorithmic Cusum for Monitoring the Process Mean | 403 |
| 9.1.3 Recommendations for Cusum Design | 408 |
| 9.1.4 The Standardized Cusum | 410 |
| 9.1.5 Improving Cusum Responsiveness for Large Shifts | 410 |
| 9.1.6 The Fast Initial Response or Headstart Feature | 410 |
| 9.1.7 One-Sided Cusums | 413 |
| 9.1.8 A Cusums for Monitoring Process Variability | 413 |
| 9.1.9 Rational Subgroups | 414 |
| 9.1.10 Cusums for Other Sample Statistics | 414 |
| 9.1.11 The V-Mask Procedure | 415 |
| 9.1.12 The Self-Starting Cusum | 417 |
| 9.2 The Exponentially Weighted Moving Average Control Chart | 419 |
| 9.2.1 The Exponentially Weighted Moving Average Control Chart for Monitoring the Process Mean | 419 |

10 OTHER UNIVARIATE STATISTICAL PROCESS MONITORING AND CONTROL TECHNIQUES 433

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 434 |
| 10.1 Statistical Process Control for Short Production Runs | 435 |
| 10.1.1 \bar{x} and R Charts for Short Production Runs | 435 |
| 10.1.2 Attributes Control Charts for Short Production Runs | 437 |
| 10.1.3 Other Methods | 437 |
| 10.2 Modified and Acceptance Control Charts | 439 |
| 10.2.1 Modified Control Limits for the \bar{x} Chart | 439 |
| 10.2.2 Acceptance Control Charts | 442 |
| 10.3 Control Charts for Multiple-Stream Processes | 443 |
| 10.3.1 Multiple-Stream Processes | 443 |
| 10.3.2 Group Control Charts | 443 |
| 10.3.3 Other Approaches | 445 |
| 10.4 SPC With Autocorrelated Process Data | 446 |
| 10.4.1 Sources and Effects of Autocorrelation in Process Data | 446 |
| 10.4.2 Model-Based Approaches | 450 |
| 10.4.3 A Model-Free Approach | 458 |
| 10.5 Adaptive Sampling Procedures | 462 |
| 10.6 Economic Design of Control Charts | 463 |
| 10.6.1 Designing a Control Chart | 463 |
| 10.6.2 Process Characteristics | 464 |
| 10.6.3 Cost Parameters | 464 |
| 10.6.4 Early Work and Semieconomic Designs | 466 |
| 10.6.5 An Economic Model of the \bar{x} Control Chart | 467 |
| 10.6.6 Other Work | 472 |
| 10.7 Cuscore Charts | 473 |
| 10.8 The Changepoint Model for Process Monitoring | 475 |
| 10.9 Profile Monitoring | 476 |

| | |
|---|-----|
| 10.10 Control Charts in Health Care Monitoring and Public Health Surveillance | 481 |
| 10.11 Overview of Other Procedures | 482 |
| 10.11.1 Tool Wear | 482 |
| 10.11.2 Control Charts Based on Other Sample Statistics | 482 |
| 10.11.3 Fill Control Problems | 484 |
| 10.11.4 Precontrol | 484 |
| 10.11.5 Tolerance Interval Control Charts | 485 |
| 10.11.6 Monitoring Processes with Censored Data | 486 |
| 10.11.7 Nonparametric Control Charts | 487 |

11
MULTIVARIATE PROCESS MONITORING AND CONTROL **494**

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 494 |
| 11.1 The Multivariate Quality-Control Problem | 495 |
| 11.2 Description of Multivariate Data | 497 |
| 11.2.1 The Multivariate Normal Distribution | 497 |
| 11.2.2 The Sample Mean Vector and Covariance Matrix | 498 |
| 11.3 The Hotelling T^2 Control Chart | 499 |
| 11.3.1 Subgrouped Data | 499 |
| 11.3.2 Individual Observations | 506 |
| 11.4 The Multivariate EWMA Control Chart | 509 |
| 11.5 Regression Adjustment | 513 |
| 11.6 Control Charts for Monitoring Variability | 516 |
| 11.7 Latent Structure Methods | 518 |
| 11.7.1 Principal Components | 518 |
| 11.7.2 Partial Least Squares | 523 |

12
ENGINEERING PROCESS CONTROL AND SPC **527**

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 527 |
| 12.1 Process Monitoring and Process Regulation | 528 |
| 12.2 Process Control by Feedback Adjustment | 529 |
| 12.2.1 A Simple Adjustment Scheme: Integral Control | 529 |
| 12.2.2 The Adjustment Chart | 534 |
| 12.2.3 Variations of the Adjustment Chart | 536 |

| | |
|--|-----|
| 12.2.4 Other Types of Feedback Controllers | 539 |
| 12.3 Combining SPC and EPC | 540 |

PART 5
PROCESS DESIGN AND IMPROVEMENT WITH DESIGNED EXPERIMENTS **547**

13
FACTORIAL AND FRACTIONAL FACTORIAL EXPERIMENTS FOR PROCESS DESIGN AND IMPROVEMENT **549**

| | |
|--|-----|
| Chapter Overview and Learning Objectives | 550 |
| 13.1 What is Experimental Design? | 550 |
| 13.2 Examples of Designed Experiments In Process and Product Improvement | 552 |
| 13.3 Guidelines for Designing Experiments | 554 |
| 13.4 Factorial Experiments | 556 |
| 13.4.1 An Example | 558 |
| 13.4.2 Statistical Analysis | 558 |
| 13.4.3 Residual Analysis | 563 |
| 13.5 The 2^k Factorial Design | 564 |
| 13.5.1 The 2^2 Design | 564 |
| 13.5.2 The 2^k Design for $k \geq 3$ Factors | 569 |
| 13.5.3 A Single Replicate of the 2^k Design | 579 |
| 13.5.4 Addition of Center Points to the 2^k Design | 582 |
| 13.5.5 Blocking and Confounding in the 2^k Design | 585 |
| 13.6 Fractional Replication of the 2^k Design | 587 |
| 13.6.1 The One-Half Fraction of the 2^k Design | 587 |
| 13.6.2 Smaller Fractions: The 2^{k-p} Fractional Factorial Design | 592 |

14
PROCESS OPTIMIZATION WITH DESIGNED EXPERIMENTS **602**

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 602 |
| 14.1 Response Surface Methods and Designs | 603 |
| 14.1.1 The Method of Steepest Ascent | 605 |

| | | |
|--------|---|-----|
| 14.1.2 | Analysis of a Second-Order Response Surface | 607 |
| 14.2 | Process Robustness Studies | 611 |
| 14.2.1 | Background | 611 |
| 14.2.2 | The Response Surface Approach to Process Robustness Studies | 613 |
| 14.3 | Evolutionary Operation | 619 |

PART 6
ACCEPTANCE SAMPLING **629**

15
LOT-BY-LOT ACCEPTANCE SAMPLING FOR ATTRIBUTES **631**

| | |
|---|-----|
| Chapter Overview and Learning Objectives | 631 |
| 15.1 The Acceptance-Sampling Problem | 632 |
| 15.1.1 Advantages and Disadvantages of Sampling | 633 |
| 15.1.2 Types of Sampling Plans | 634 |
| 15.1.3 Lot Formation | 635 |
| 15.1.4 Random Sampling | 635 |
| 15.1.5 Guidelines for Using Acceptance Sampling | 636 |
| 15.2 Single-Sampling Plans for Attributes | 637 |
| 15.2.1 Definition of a Single-Sampling Plan | 637 |
| 15.2.2 The OC Curve | 637 |
| 15.2.3 Designing a Single-Sampling Plan with a Specified OC Curve | 642 |
| 15.2.4 Rectifying Inspection | 643 |
| 15.3 Double, Multiple, and Sequential Sampling | 646 |
| 15.3.1 Double-Sampling Plans | 647 |
| 15.3.2 Multiple-Sampling Plans | 651 |
| 15.3.3 Sequential-Sampling Plans | 652 |
| 15.4 Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859) | 655 |
| 15.4.1 Description of the Standard | 655 |
| 15.4.2 Procedure | 657 |
| 15.4.3 Discussion | 661 |
| 15.5 The Dodge–Romig Sampling Plans | 663 |
| 15.5.1 AOQL Plans | 664 |
| 15.5.2 LTPD Plans | 667 |
| 15.5.3 Estimation of Process Average | 667 |

16
OTHER ACCEPTANCE-SAMPLING TECHNIQUES **670**

| | |
|--|-----|
| Chapter Overview and Learning Objectives | 670 |
| 16.1 Acceptance Sampling by Variables | 671 |
| 16.1.1 Advantages and Disadvantages of Variables Sampling | 671 |
| 16.1.2 Types of Sampling Plans Available | 672 |
| 16.1.3 Caution in the Use of Variables Sampling | 673 |
| 16.2 Designing a Variables Sampling Plan with a Specified OC Curve | 673 |
| 16.3 MIL STD 414 (ANSI/ASQC Z1.9) | 676 |
| 16.3.1 General Description of the Standard | 676 |
| 16.3.2 Use of the Tables | 677 |
| 16.3.3 Discussion of MIL STD 414 and ANSI/ASQC Z1.9 | 679 |
| 16.4 Other Variables Sampling Procedures | 680 |
| 16.4.1 Sampling by Variables to Give Assurance Regarding the Lot or Process Mean | 680 |
| 16.4.2 Sequential Sampling by Variables | 681 |
| 16.5 Chain Sampling | 681 |
| 16.6 Continuous Sampling | 683 |
| 16.6.1 CSP-1 | 683 |
| 16.6.2 Other Continuous-Sampling Plans | 686 |
| 16.7 Skip-Lot Sampling Plans | 686 |

APPENDIX **691**

| | |
|--|-----|
| I. Summary of Common Probability Distributions Often Used in Statistical Quality Control | 692 |
| II. Cumulative Standard Normal Distribution | 693 |
| III. Percentage Points of the χ^2 Distribution | 695 |
| IV. Percentage Points of the t Distribution | 696 |
| V. Percentage Points of the F Distribution | 697 |
| VI. Factors for Constructing Variables Control Charts | 702 |
| VII. Factors for Two-Sided Normal Tolerance Limits | 703 |
| VIII. Factors for One-Sided Normal Tolerance Limits | 704 |

BIBLIOGRAPHY **705**

ANSWERS TO SELECTED EXERCISES **721**

INDEX **729**