

**Second Edition**

# **Metal Fabrication Technology for Agriculture**



**Larry Jeffus**

# Contents

<b>Preface</b> .....	x	Fire Protection .....	34
<b>Features of the Text</b> .....	xii	Equipment Maintenance .....	36
<b>Acknowledgments</b> .....	xiv	Work Area .....	37
<b>About the Author</b> .....	xv	Hand Tools .....	37
<b>Index of Experiments and Practices</b> .....	xvii	Hand Tool Safety .....	38
		Hammer Safety .....	38
		Power Tools .....	39
		Metal Cutting Machines .....	41
		Safe Use of Circular Saws .....	42
		Material Handling .....	44
<b>Chapter 1 Introduction to Agriculture Welding and Fabrication</b>		<b>Chapter 3 Oxyfuel Welding and Cutting Equipment, Setup, and Operation</b>	
Introduction .....	1	Introduction .....	49
Welding Defined .....	2	Pressure Regulators .....	50
Uses of Welding .....	3	Design and Service of Welding and Cutting Torches .....	55
Welding Processes .....	4	Welding and Heating Tips .....	56
Occupational Opportunities in Welding .....	8	Reverse Flow and Flashback Valves .....	58
Training for Welding Occupations .....	9	Hoses and Fittings .....	60
Student Organizations .....	10	Backfires and Flashbacks .....	61
Experiments and Practices .....	10	Uses of the Oxyacetylene Flame .....	62
Metric Units .....	11	Characteristics of the Fuel-gas Flame .....	62
		Fuel Gases .....	63
		Acetylene (C <sub>2</sub> H <sub>2</sub> ) .....	63
		Liquefied Fuel Gases .....	66
		Propane and Natural Gas .....	68
		Leak Detection .....	68
		Types of Flames .....	73
		Filler Metals .....	74
		Mild Steel .....	76
<b>Chapter 2 Safety in Welding and Fabrication</b>		<b>Chapter 4 Oxyacetylene Welding</b>	
Introduction .....	15	Introduction .....	79
Burns .....	16	Mild Steel Welds .....	80
Eye and Ear Protection .....	18		
Respiratory Protection .....	21		
Ventilation .....	24		
Material Specification Data Sheets (MSDS) .....	24		
Waste Material Disposal .....	24		
Ladder Safety .....	25		
Electrical Safety .....	26		
Electrical Safety Systems .....	26		
Voltage Warnings .....	28		
Extension Cords .....	28		
Safety Rules for Portable Electric Tools .....	30		
General Work Clothing .....	30		
Special Protective Clothing .....	31		
Handling and Storing Cylinders .....	32		

Outside Corner Joint .....	88	Selecting the Correct Tip and Setting	
Butt Joint .....	88	the Pressure .....	153
Lap Joint .....	90	The Chemistry of a Cut .....	154
Tee Joint .....	92	The Physics of a Cut .....	155
Out-of-position Welding .....	93	Plate Cutting .....	158
Vertical Welds .....	93	Cutting Table .....	158
Butt Joint .....	95	Torch Guides .....	158
Lap Joint .....	96	Distortion .....	160
Tee Joint .....	96	Cutting Applications .....	162
Horizontal Welds .....	97	Pipe Cutting .....	164
Horizontal Stringer Bead .....	97		
Butt Joint .....	98	<b>Chapter 7 Plasma Arc Cutting</b>	
Lap Joint .....	98	Introduction .....	169
Tee Joint .....	98	Plasma .....	170
Overhead Welds .....	98	Plasma Torch .....	171
Stringer Bead .....	99	Cables and Hoses .....	173
Mild Steel Pipe and Tubing .....	100	Power Requirements .....	173
Horizontal Rolled Position 1G .....	100	Heat Input .....	174
Horizontal Fixed Position 5G .....	103	Distortion .....	175
Vertical Fixed Position 2G .....	104	Applications .....	175
45° Fixed Position 6G .....	105	Starting Methods .....	177
Thin-wall Tubing .....	106	Kerf .....	178
		Gases .....	179
<b>Chapter 5 Soldering and Brazing</b>		Machine Cutting .....	180
Introduction .....	109	Safety .....	181
Advantages of Soldering and Brazing .....	110	Manual Cutting .....	182
Fluxes .....	112	Straight Cuts .....	182
Filler Metals .....	115	Beveling of a Plate .....	184
Joint Design .....	120	Cutting Holes .....	185
Building Up Surfaces and Filling Holes .....	127	Gouging .....	186
Silver Brazing .....	130	Cutting Round Stock .....	187
Soldering .....	132		
		<b>Chapter 8 Shielded Metal Arc Equipment, Setup, and Operation</b>	
<b>Chapter 6 Oxyacetylene Cutting</b>		Introduction .....	191
Introduction .....	139	Welding Current .....	192
Metals Cut by the Oxyfuel Process .....	140	Types of Welding Power .....	194
Eye Protection for Flame Cutting .....	140	Open Circuit Voltage .....	195
Cutting Torches .....	141	Operating Voltage .....	195
Cutting Tips .....	142	Arc Blow .....	195
Oxyfuel Cutting, Setup, and Operation .....	145	Types of Power Sources .....	196
Hand Cutting .....	148	Generators and Alternators .....	200
Layout .....	152		

Rectifiers .....	201
Duty Cycle .....	202
Welding Cables .....	203
Electrode Holders .....	204
Work Clamps .....	205
Setup .....	205

## **Chapter 9 Shielded Metal Arc Welding of Plate**

Introduction .....	209
Effect of Too High or Too Low Current Settings .....	212
Electrode Size and Heat .....	213
Arc Length .....	214
Electrode Angle .....	215
Electrode Manipulation .....	218
Positioning of the Welder and the Plate .....	219
Practice Welds .....	220
Stringer Beads .....	221
Square Butt Joint .....	223
Edge Weld .....	227
Outside Corner Joint .....	232
Lap Joint .....	236
Tee Joint .....	239

## **Chapter 10 Shielded Metal Arc Welding of Pipe**

Introduction .....	245
Pipe and Tubing .....	247
Preparation and Assembly .....	248
Practice Welds .....	250
1G Horizontal Rolled Position .....	254
2G Vertical Fixed Position .....	258
5G Horizontal Fixed Position .....	260
Pipe Tee Joints .....	261
Laying Out a Saddle Pipe Tee Joint .....	263

## **Chapter 11 Gas Metal Arc Welding Equipment, Setup, and Operation**

Introduction .....	269
Metal Transfer .....	270
Filler Metal Specifications .....	274

Wire Melting and Deposition Rates .....	274
Welding Power Supplies .....	275
Molten Weld Pool Control .....	277
Equipment .....	281
Spot Welding .....	285

## **Chapter 12 Gas Metal Arc Welding**

Introduction .....	291
Setup .....	292
Gas Density and Flow Rates .....	298
Amperage and Arc Voltage Characteristics .....	298
Electrode Extension .....	300
Welding Gun Angle .....	302
Effect of Shielding Gas on Welding .....	303
Practices .....	304
Metal Preparation .....	304
Flat Position, 1G and 1F Positions .....	305
Vertical Up 3G and 3F Positions .....	308
Vertical Down 3G and 3F Positions .....	311
Horizontal 2G and 2F Positions .....	312
Overhead 4G and 4F Positions .....	313
Pulsed Arc Metal Transfer, 1G Position .....	316
Axial Spray .....	319

## **Chapter 13 Flux Cored Arc Welding Equipment, Setup, and Operation**

Introduction .....	323
Principles of Operation .....	325
Equipment .....	326
Advantages .....	326
Limitations .....	328
Electrodes .....	328
Flux .....	329
Shielding Gas .....	333
Welding Techniques .....	334
Troubleshooting FCA Welding .....	339

## **Chapter 14 Flux Cored Arc Welding**

Introduction .....	343
Practices .....	344
Flat-position Welds .....	348

Square-groove Welds .....	349
V-Groove and Bevel-groove Welds .....	349
Fillet Welds .....	353
Vertical Welds .....	356
Horizontal Welds .....	358
Overhead-position Welds .....	361
Thin-gauge Sheet Metal Welding .....	364

## **Chapter 15 Filler Metal Selection**

Introduction .....	369
Manufacturers' Electrode Information .....	370
Understanding the Electrode Data .....	370
Data Resulting from Mechanical Tests .....	370
Data Resulting from Chemical Analysis .....	370
SMAW Operating Information .....	371
Core Wire .....	371
Functions of the Flux Covering .....	372
Filler Metal Selection .....	373
AWS Filler Metal Classifications .....	374
Carbon Steel .....	376
Stainless Steel Electrodes .....	381
Aluminum and Aluminum Alloys .....	384

## **Chapter 16 Weldability of Metals**

Introduction .....	389
Steel Classification and Identification .....	390
Carbon and Alloy Steels .....	392
Stainless Steels .....	393
Cast Iron .....	395
Preweld and Postweld Heating of Cast Iron .....	396
Practice Welding Cast Iron .....	397
Welding without Preheating or Postheating .....	398
Aluminum Weldability .....	400
Repair Welding .....	401
Hardfacing .....	403

## **Chapter 17 Welding Joint Design, Welding Symbols, and Fabrication**

Introduction .....	409
Weld Joint Design .....	410
Mechanical Drawings .....	414

Welding Symbols .....	423
Indicating Types of Welds .....	423
Weld Location .....	423
Location Significance of Arrow .....	425
Fillet Welds .....	425
Groove Welds .....	426
Backing .....	427
Fabrication .....	427
Layout .....	432
Material Shapes .....	440
Assembly .....	441
Assembly Tools .....	442
Fitting .....	444
Tack Welding .....	444
Welding .....	445
Finishing .....	446

## **Chapter 18 Plastic and Other Nonmetallic Fabrication Techniques**

Introduction .....	459
Types of Plastics .....	460
Acrylonitrile/Butadiene/Styrene (ABS) .....	461
Polyethylene (PE) .....	461
Polyvinyl Chloride (PVC) and Chlorinated Polyvinyl Chloride (CPVC) .....	461
Polypropylene (PP) .....	461
Polybutylene (PB) .....	462
Plastic Identification .....	462
The Welding of Plastic .....	464
Heat Welding .....	465
High-speed Welding .....	466
Filler Material .....	466
Hot-gas Plastic Welding .....	467
Setup, Shutdown, and Servicing .....	467
Airless Plastic Welding .....	469
Welding Temperatures .....	469
Plastic Welding .....	470
Hot-gas and Airless Welding Techniques .....	470
Double V-Groove Welds .....	474
Tack Welding .....	475
Pipe Welding .....	476
Solvent Welding .....	480

**Appendices .....485**

- I. Student Welding Report .....486
- II. Conversion of Decimal Inches to Millimeters  
and of Fractional Inches to Decimal Inches  
and Millimeters.....487
- III. Conversion Factors: U.S. Customary  
(Standard) Units and Metric Units (S.I.) .....488
- IV. Abbreviations and Symbols .....490

- V. Metric Conversion Approximations .....491
- VI. Pressure Conversion.....491
- VII. Welding Associations and Organizations .....492
- VIII. Careers.....493

**Bilingual Glossary.....495**

**Index.....534**