


The Quality Technician's Handbook

Fifth Edition

Gary K. Griffith



1	Introduction to Quality	1
	The Quality Organization	2
	Quality Systems	2
	Quality and Communication	7
	Motivation (Human Factors) and Quality	7
	Review Questions	9
2	Total Quality Management	12
	Quality Functions	13
	Responsibility for Quality	14
	TQM Tools	25
	A Systematic Approach to TQM	33
	Management Involvement and Commitment	34
	Metrics	35
	Problem Solving	36
	Summary	36
	Review Questions	37
3	Quality Costs	41
	Categories of Quality Costs	41
	Quality Cost Relationships	42
	Pareto's Law and Quality Costs	43
	Graphs, Charts, and Quality Costs	45
	Hidden Quality Costs	47
	Prevention: The Return on Quality Investment	47
	Quality Cost Reporting	48
	Quality Cost System Results	50
	Review Questions	51
4	Quality Audits	53
	Why Audit?	53
	Key Steps of the Auditing Process	54
	Audit Findings and Observations	54

Types of Quality Audits	54
Quality System Audits	55
Audit Approaches and Purposes	55
Auditors and Audit Teams	56
Planning the Audit	58
Conducting the Audit	59
Audit Reporting	61
Corrective Action	62
Closing the Audit	62
Review Questions	63
5 Inspection Systems and Planning	66
Inspection Systems	66
Inspection Points	67
Inspection Personnel	69
Inspection Planning	69
Review Questions	82
6 Reading Engineering Drawings	85
Lines on an Engineering Drawing	85
Orthographic Projection Views	89
Auxiliary Views	91
Change Block, Notes, and Tabular Dimensions	95
The Title Block	97
Rules to Follow When Using Engineering Drawings	99
Tolerances	100
Allowances and Fits	101
Threads (Nomenclature)	103
Specifying Screw Threads	105
Chamfers	106
Additional Visualization Practice	107
Review Questions	111
7 Geometric Dimensioning and Tolerancing	114
Comparison of the Standards	116
Other Drawing Symbols	116
The Dimension Origin Symbol	116
Maximum Material Condition—Least Material Condition	121
The Virtual Condition	123
General Rules for ASME Y14.5M–1994 Tolerancing	125
Inspecting Size Tolerances per ASME Y14.5 Rule 1	126
Datums	127
Datum Targets	130

Contents

How to Contact Feature Datums	133
Coordinate Method of Positioning Features	136
Position Tolerancing	137
When Features Are Out of Position Tolerance	142
Understanding Bonus Tolerancing	147
Additional Tolerance from Size Datums	148
Chain, Baseline, and Direct Dimensioning	149
Composite Position Tolerances	150
Position Tolerance Stated at LMC	151
Zero Position Tolerance at MMC	152
Bidirectional Position Tolerances	154
Position: Fixed and Floating Fastener Cases	156
Projected Tolerance Zones	158
Functional Gages	160
The Chain Line	163
Changes in the Geometric Tolerancing Standard	165
Review Questions	165
8 Graphical Inspection Analysis	171
Geometric Tolerancing Principles	171
Graphical Inspection Analysis Procedure	180
Work Problems	190
Graphical Inspection Analysis Advantages	194
Computer Inspection Analysis	198
Review Questions	199
9 Common Measuring Tools and Measurements	201
Dimensional Measurement	201
Measuring Tools	201
Measurements and Accuracy	203
Types of Measurement Errors	205
The Steel Rule	205
Spring Calipers	207
Gage Blocks	208
Mechanical Indicators	211
Cosine Error in Indicators	216
TIR, FIR, and FIM	218
Dial Indicating Gages	219
Micrometers	230
Vernier Instruments	242
Telescoping Gages	245
Small Hole Gages	249
Attribute Gages	249
Radius Gages	256

Tapered (Adjustable) Parallels	257
Centerline Attachments	260
Mechanical Comparators	263
Measuring and Gaging Internal Threads	267
Measuring and Gaging External Threads	268
Measuring Threads: The Three-Wire Method	270
Basic Calibration Techniques	273
Review Questions	274

10 Surface Plate Inspection Methods 279

Surface Plates	279
Fixed Parallels	284
Care of Surface Plates	285
Surface Gages	286
Possible Sources of Errors in Measurement	288
Making Linear Measurements Using the Transfer Method or the Direct-Reading Method	289
Centerline Measurement of Features	292
Parallelism Measurement	294
Flatness Measurement	298
Concentricity Measurement	300
Runout Tolerances	303
Perpendicularity Measurement	307
Coaxiality Measurement (Using Position Tolerance)	309
Angularity Measurement: Angularity versus Simple Angles	311
Symmetry	315
Straightness (of an Axis)	317
Straightness Measurement: Straightness of Surface Elements	319
Using Profile Tolerances for Coplanarity	321
1-2-3 Blocks	322
Review Questions	324

11 Special Measuring Equipment and Techniques 328

Electronic Measuring Equipment	328
Special Measuring Devices	332
Flatness Measurement (Using Optical Flats)	336
Measuring Surface Finish	341
Pneumatic Comparators (Air Gages)	349
Circularity (Roundness) Measurement	352
Cylindricity	355
Free State Variation	357
Optical Comparators (Profile Tolerances)	359
Profile Tolerances per ASME Y14.5M-1994	363
Coordinate Measuring Machines	367
Torque Measurement	372

Hardness Testing	374
Review Questions	380

12 Lot-by-Lot Acceptance Sampling Plans 384

Basic Probability	384
Sample Statistics versus Population Parameters	388
Probability Distributions for Attributes	389
Relationships between Sampling and 100 Percent Inspection	393
Lot-by-Lot Acceptance Sampling versus Process Control Sampling	395
Random Sampling	396
Using ANSI/ASQC Z1.4 for Sampling Inspection	399
Introduction to Dodge–Romig Sampling Tables	405
ANSI/ASQC Z1.9 Variables Sampling Tables	406
Operating Characteristic (OC) Curves	418
Review Questions	419

13 Statistical Process Control 423

Objectives of SPC	423
Tools for Process Control	424
The Importance of Distribution	425
Measures of Central Tendency	429
Measures of Dispersion (Variation)	433
Computing the Average, Range, and Standard Deviation with Negative Numbers in the Data	436
Definition of a Process in Control	439
Control Limits versus Specification Limits	440
Table for the Initial Selection of Subgroup Sizes and Intervals	440
Various Plotting Errors to Avoid	442
How Measurement Errors Affect Charts	442
Importance of Rational Subgroups	443
How Calculation Errors Affect Charts	444
Guidelines for Starting an Average and Range Control Chart	444
Average and Sigma Charts	449
Median Control Charts	452
Control Charts for Individuals and Moving Ranges	454
Attribute Control Charts	458
Interpreting Control Charts: Pattern Analysis	474
Process Capability	479
Gage Repeatability and Reproducibility Studies	494
Miscellaneous Topics	503
Review Questions	504

14 Shop Mathematics 508

Adding and Subtracting Fractions	508
Multiplying and Dividing Fractions	513

Working with Decimals	514
Adding and Subtracting Angles	517
Working with Equations	519
The Circle	521
Perimeters	527
Areas	529
Volumes	532
Solving the Right Triangle for Sides Only: The Pythagorean Theorem	535
Solving the Right Triangle	538
Memorizing the Trigonometry Formulas for the Right Triangle	546
Solving Oblique Triangles	546
Tapers	550
Units of Measurement	556
Metric or English: A Comparison	556
Ratios	559
Temperature Conversion	559
The Real Number Line	560
The Cartesian Coordinate System	561
Scientific Notation	563
Review Questions	564
Glossary A: Quality Terms and Definitions	567
Glossary B: Various Manufacturing Processes	575
Glossary C: Terms Used in Reliability	579
Glossary D: Overview of Nondestructive Evaluation Methods	583
Bibliography	585
Appendix Tables	587
Subject Index	593
Formulas Index	603