STATISTICAL PROCESS ANALYSIS



Layth C. Alwan

McGRAW-HILL INTERNATIONAL EDITIONS
Management & Organization Series

CONTENTS

Chapter 1

Data Analysis and Process Management 1

1.1 Quality Management: A Brief Overview 2
1.2 Quality Pioneers 4
Walter A. Shewhart 4
W. Edwards Deming 6
Joseph M. Juran 8
Armand V. Feigenbaum 10
Kaoru Ishikawa 11
Genichi Taguchi 12
George E. P. Box 14
1.3 Focus on Processes 14
1.4 Reliance on Data 16
1.5 Role of Statistics 19
1.6 Basic Process Improvement Toolbox 23
Flowchart 24
Check Sheet 24
Pareto Diagram 25
Cause-and-Effect Diagram 27
Scatter Plot 30
Histogram 32
Control Chart 34

Chapter 2

A Review of Some Basic Statistical Concepts 41

2.1 Populations, Processes, and Samples 42
Finite Populations 42
Conceptual Populations 43
2.2 Types of Process Data 45
2.3 Characterizing Process Data: Visual Displays 46
Time-Series Display 46
Histogram 55
2.4 Time versus Distribution Behavior 61
2.5 Summarizing Process Data: Numerical Measures 64
Measures of Central Tendency 65
Measures of Variability 69
2.6 Random Variables and Probability Distributions 72
Properties of Random Variables 77
2.7 Some Useful Discrete Distributions 80
Bernoulli Distribution 80
Binomial Distribution 81
Poisson Distribution 84
2.8 Normal Distribution 86
2.9 Sample Statistics as Random Variables 91
Sampling Distribution of the Sample Mean $\bar{X}$: σ Known 92
Sampling Distribution of the Sample Mean $\bar{X}$: σ Unknown 95
Sampling Distribution of the Sample Variance S^2 97
2.10 Estimation of Parameters 98
Criteria for Choosing an Estimator 98
Point Estimation 100
Interval Estimation 100

Chapter 3

Modeling Process Data 117

3.1 Diagnostic Checks for Randomness 118
Runs Test 119
Autocorrelation Function 126
3.2 Diagnostic Checks for Normality 133
Standardized Data 133
Normal Probability Plot 135
3.3 Dealing with Nonnormal Data 139
Normalizing Transformations 141
3.4 Conceptual Framework for Processes 147
Random Process Model 147
General Process Model 148
3.5 Model Fitting Based on Least-Squares Estimation 150
3.6 Modeling a Simple Linear Trend Process 152
Detailed Breakdown of Regression Output 160
Diagnostic Checking of Fitted Model 166
Prediction of Future Outcomes 169

3.7 Modeling a Nonlinear Trend Process 171
3.8 Modeling a Meandering Process 180
3.9 Modeling a Combination of Process Effects 192
3.10 Summary of Process Modeling Steps 202

Chapter 4
Introduction to the Control Chart Concept 215

4.1 Approaches to Process Control 216
4.2 Common- and Special-Cause Variation: Basic Breakdown 217
Managerial Implications 218
4.3 State of Statistical Control: Historical Perspective 220
4.4 Statistical Nature of Special-Cause Variation 223
4.5 Hazards of Overcontrol 225
Funnel Experiment—Time-Series Perspective 227
4.6 Basic Statistical Framework for Control Charts 230
Hypothesis-Testing Connection 232
Three-Sigma Control Limits 234
4.7 Average Run Length Concept 239
4.8 Control Limits versus Specification Limits: Distinct Concepts 240
4.9 Supplementary Rules for Detecting Special-Cause Variation 242
4.10 Classification of Standard Control Charts 247
4.11 Five Basic Assumptions Underlying Use of Standard Control Charts 250
4.12 Limitations of Standard Control Charts 251
Challenges to Assumption 1 252
Challenges to Assumptions 2 and 3 259
Challenges to Assumptions 4 and 5 262
4.13 Control Charts and PDCA 263
4.14 Summary 267

Chapter 5
Monitoring Individual Variable Measurements 277

5.1 Standard Control Limits for Individual Measurements: X Chart 278
5.2 Example of Appropriate X Chart Application 280
5.3 Monitoring a Simple Linear Trend Process 287
Trend Control Chart 291
Fitted-Values Chart and Special-Cause Chart 292
5.4 Monitoring a Nonrandom and Nonnormal Process 298
Regression Model Revision for Prospective Control 301
5.5 Monitoring a Process Influenced by Lagged Effects Only 307
5.6 Monitoring a Process Influenced by Trend and Lagged Effects 315
5.7 Monitoring Variability for Individual Measurements 319
Standard Moving-Range Chart 319
Half-Normal Based Chart 322
Data Analysis Approach to Monitoring Moving Ranges 324

Chapter 6
Monitoring Subgroup Variable Measurements 339

6.1 Designing Subgroup Control Charts: Preliminary Considerations 340
Rational Subgrouping 341
Subgroup Size 342
Sampling Frequency 344
6.2 Subgroup Control Charts Based on the Range 345
$\bar{x}$ and R Charts 345
Revision of Retrospective Control Limits and Control Chart Maintenance 351
Practical Issues Concerning the Range Statistic 352
Obtaining an Estimate for σ 353
Probability Limits for the $\bar{x}$ Chart 354
Probability Limits for the R Chart 355
6.3 Performance Measures of $\bar{x}$ and R Charts 357
Operating-Characteristic Curve 357
Average Run Length for the $\bar{x}$ Chart 360
6.4 Subgroup Control Charts Based on the Sample Standard Deviation 362

$\bar{x}$ and s Charts with Constant Subgroup Size 362
$\bar{x}$ and s Charts with Variable Subgroup Size 366
S^2 chart 370
6.5 Assumptions Underlying Development of Subgroup Charts 371
6.6 Practical Challenges to Standard Subgroup Charts 373
Dangers of Studying Subgroup Statistics Only 373
Consequences of Within-Subgroup Correlation 378
Gapping Strategy 384
R Chart in the Presence of Within-Subgroup Correlation 390
Appendix to Chapter 6 393

Chapter 7
Monitoring Attribute Data 413
7.1 Monitoring Binomial-Based Statistics 415
Control Chart for Proportion Nonconforming: p Chart 416
Control Chart for Number of Nonconforming: np Chart 421
Subgroup Selection 422
Variable Control Limits 425
Control Chart for Standardized Proportion Data 427
Control Limits Based on Average Subgroup Size 430
Beyond Special-Cause Searching 432
7.2 Violations of p Chart Assumptions 434
Testing the Binomial Assumption 440
7.3 Monitoring Poisson-Based Statistics 445
Control Chart for Number of Nonconformities: c Chart 446
Control Chart for Nonconformities When Unit Interval Varies: u Chart 451
Control Chart for Weighted Nonconformities: D Chart 455
7.4 Violations of the c Chart Assumptions 457
Testing the Poisson Assumption 460
7.5 Systematic Variation in Attribute Processes 463
Seasonal Behavior 464
Seasonal and Trend Behavior 470
Autoregressive Behavior 475

Chapter 8
Memory Control Charts 493
8.1 The Cumulative-Sum Control Chart 494
Basic Idea of a CUSUM-Type Statistic 496
V-Mask CUSUM Procedure for Monitoring the Process Mean 501
Tabular CUSUM Procedure for Monitoring the Process Mean 508
FIR CUSUM 517
Combined Shewhart-CUSUM Scheme 521
Monitoring Variability of Individual Observations Using CUSUM 523
Violation of Standard CUSUM Assumptions 526
8.2 The Moving-Average Control Chart for Monitoring the Process Mean 535
8.3 The Exponentially Weighted Moving-Average Control Chart 540
EWMA Chart for Monitoring the Process Mean 540
Monitoring Process Variability with EWMA 547
Violations of Standard EWMA Assumptions 552

Chapter 9
Process Capability 567
9.1 Process Capability Studies 568
9.2 The Need for Process Stability 573
9.3 Reporting Nonconformance Rates in Parts per Million Units 575
9.4 Process Capability Indices 577
Potential Capability Index C_p 577
Estimating Process Standard Deviation 579
One-Sided Capability Indices C_{pl} and C_{pu} 585
Performance Capability Index C_{pk} 591
Target-Focused Capability Index C_{pm} 594
9.5 Nonnormality and Process Capability Indices 596
9.6 Capability Indices and Sampling Variation 605
9.7 Measurement Error 608
Estimating Accuracy 609
Estimating Precision Components: Repeatability and Reproducibility 611

9.8 Measurement Error Variability and Process Capability 619

Chapter 10

Related Special Topics 629

10.1 SPC Methods for Short-Run Production 630
Short-Run Variable Charts: Constant Variation across Batches 632
Testing the Equality of Variances 634
Standardized Short-Run Charts 639

10.2 Multivariate Quality Control 641
Chi-Square Multivariate Control Chart: Parameters Known 646
Hotelling T^2 Control Chart: Parameters Unknown 651
Special-Cause Searching and Multivariate Signals 664
Multivariate Monitoring of Process Variability 665
Assumptions for Standard Multivariate Charts 669

10.3 All-Purpose Model Strategy 672

10.4 Relationship between Processes: A Broader Modeling Perspective 675

10.5 Reducing Process Variability by Adjustment 679

10.6 Further Opportunities 691

Appendix to Chapter 10 694

Appendix 722

Basic Overview of Minitab 742

Index 746