
TRENDS IN OPTICAL
NON-DESTRUCTIVE
TESTING AND
INSPECTION EDITORS
PRAMOD RASTOGI
DANIELE INAUDI

Suranaree University of Technology



31051000647814

ELSEVIER

Contents

1. The impact of new measurement systems on structural engineering	1
<i>I.F.C. Smith</i>	
1. Introduction	
2. Traditional structural engineering	
2.1. Engineering by simulation	
2.2. Challenges of simulation	
2.3. Measurement of the behaviour of structures in service	
3. Examples of new measurement systems	
4. Performance based structural engineering	
4.1. A definition	
4.2. Convergence of low-cost technologies and new objectives	
4.3. Examples of research aimed at supporting PBSE	
4.3.1. Coordinating theoretical modelling and in-service measurement	
4.3.2. Intelligent structures	
5. Conclusions	
References	
2. Methods of interferogram analysis	15
<i>D. Malacara-Hernandez</i>	
1. How interferograms are produced	
1.1. Twyman-Green interferograms	
1.2. Lateral shearing interferograms	
2. Early methods for the analysis of interferograms	
2.1. Discrete manual sampling	
2.2. Fringe skeletonizing	
2.3. Global and local interpolation	
3. Demodulation of interferograms with a spatial carrier	
3.1. Demodulation with a linear carrier	
3.2. Demodulation with a circular carrier	
4. Phase shifting interferometry	
5. Phase detection algorithms	
5.1. Three 120°-step algorithm	
5.2. Wyant's three-step algorithm	
5.3. Four-step algorithm	
5.4. Schwider-Hariharan five-step algorithm	
5.5. Schmit and Creath algorithm	
6. Conclusions	
References	
3. Challenges in phase unwrapping	37
<i>J.M. Huntley</i>	
1. Introduction	
2. Recent developments in phase unwrapping	
2.1. Spatial unwrapping	
2.2. Temporal unwrapping	
3. Temporal phase unwrapping: shape measurement	
4. Temporal phase unwrapping: high speed speckle interferometry	
5. Conclusions	
References	
4. Active phase measuring metrology	45
<i>W. Osten, M. Kujawinska</i>	
1. Introduction	
2. Direct and inverse problems	
3. The formation and evaluation of fringe patterns	
3.1. Intensity distributions and components for their manipulation	
3.2. Reconstruction of interference phases in optical metrology	
3.2.1. Passive phase reconstruction by using a-priori knowledge	
3.2.2. Quasi active phase reconstruction by phase modulation	
3.2.3. Active phase reconstruction by multi-wavelength techniques	
3.2.4. Direct phase reconstruction by digital holography	

4. Some examples for active phase measuring optical metrology
 - 4.1. Material fault recognition in HNDDT using recognition by synthesis
 - 4.2. Active surface metrology by systematic combination of different measurement techniques
 - 4.3. Active projected-fringe-technique for shape control with automatic pattern adaption
5. Conclusions
- References

5. Customized phase shift algorithms

71

Y. Surrel

1. Introduction
2. Requirements on the algorithm
 - 2.1. Introduction
 - 2.2. Supplementary assumptions and error sources
 - 2.2.1. Assumption on the fringe profile
 - 2.2.2. Assumption on the phase steps
 - 2.2.3. Assumption on the bias
 - 2.2.4. Vibrations
3. Determination of the characteristic diagram
 - 3.1. Rejection of harmonics
 - 3.2. Miscalibration
 - 3.3. Bias variation
4. Determination of the algorithm
 - 4.1. Method
 - 4.2. Aliased algorithms
5. Noise
6. Examples of algorithms
 - 6.1. N-bucket or DFT algorithm
 - 6.2. (N+ 1)-bucket algorithm
 - 6.3. WDFT algorithm
 - 6.4. Other algorithms

References

6. Desensitized interferometry using two object beams

85

X. Colonna de Lega

1. Principles of dual object beam interferometry
 2. Requirements for smooth parts measurement
 3. Requirements for rough parts measurement
 4. Imaging requirements
 5. Coherence requirements
 6. Quantitative measurements/part alignment requirements
 7. Conclusions and perspectives
- References

7. Object deformation measurement by holographic interferometry: analysis on curved surfaces and aspects of generalization

97

W. Schumann

1. Introduction
 2. First derivative of the optical path difference. Strain and rotation
 3. Deformation of geodesic curves. Integrability
 4. Transverse ray aberration. Fringe and visibility vectors
 5. Second derivative of the optical path difference. Fringe curvature
 6. Conclusion
- Appendix
References

8. Digital holographic interferometry

113

T. Kreis

1. Introduction
2. CCD recording of holograms
3. Reconstruction of digitally recorded holograms
 - 3.1. Numerical reconstruction by the Fresnel transform
 - 3.2. Reconstruction by the convolution approach
 - 3.3. Suppression of the dc-term
4. Applications

4.1. Deformation measurement by digital holographic interferometry	
4.2. Contour measurement by digital holographic interferometry	
4.3. Holographic particle characterization	
5. Conclusions	
References	
9. Difference holographic interferometry	129
<i>F. Gyimesi, Z. Fuzessy and B. Raczkevi</i>	
1. Introduction	
2. DHI idea	
3. DHI theory	
3.1. Corresponding points model 3.2	
3.2. Wave optical theory	
3.2.1. Holographic interferometry	
3.2.2. Difference holographic interferometry	
4. DHI methods	
5. DHI applications	
6. Future prospective	
References	
10. Holographic interferometric microscopy	141
<i>G. Wernicke</i>	
1. Introduction	
2. Basic considerations	
3. Experimental arrangement	
3.1. Quasi-heterodyne technique	
3.2. Spatial heterodyne technique	
3.3. Electro-optic holography	
4. Experimental results	
5. Conclusion	
References	
11. Speckle displacement and decorrelation -- theory and applications	151
<i>I. Yamaguchi</i>	
1. Introduction	
2. Correlation properties of speckle for linear system	
3. Speckle displacement and decorrelation in the diffraction field	
4. Speckle displacement and decorrelation in the image field	
5. Detection of speckle displacement	
5.1. Speckle photography	
5.2. Electronic speckle correlation	
6. Applications of speckle displacement	
6.1. Speckle encoders	
6.2. Speckle strain gauge	
6.3. Whole field strain measurement using 2-D speckle correlation	
7. Conclusions	
References	
12. Concept of speckle photography for in-plane strain determination	171
<i>P.K. Rastogi</i>	
1. Speckle pattern as a surface finger print	
2. Speckle photography as an in-plane measurement tool: point-wise approach	
3. Principle of speckle shearing photography	
4. Results	
5. Conclusions	
References	
13. Digital speckle photography	179
<i>M. Sjödaahl</i>	
1. Introduction	
2. White light speckle	
2.1. 3-D deformations and shape	
2.2. Small measurement volumes	
2.3. Internal deformations	
3. Laser speckle	
3.1. Use of speckle decorrelation	

- 3.2. Measurement of strain fields using defocused speckle patterns
 - 3.3. Combined digital speckle photography and interferometry
 - 4. Summary
 - References
- 14. Roughness measurement using speckle photography** 197
- C.J. Tay, S.L. Toh and H.M. Shang*
- 1. Introduction
 - 2. Roughness measurement
 - 2.1. The double-exposure method
 - 2.2. The single-exposure method
 - 3. Applications
 - 3.1. Surface roughness measurement
 - 3.2. Plastic strain measurement
 - 3.3. Damage detection
 - 4. Concluding remarks
 - References
- 15. ESPI - Principles and prospects** 207
- E. Hack*
- 1. Need for imaging methods
 - 2. Interference and speckle effect
 - 2.1. Two beam interference
 - 2.2. Interferometry at rough surfaces: the speckle effect
 - 3. Speckle pattern correlation interferometry
 - 3.1. Intensity correlation
 - 3.2. Phase retrieval methods
 - 3.3. Fringe phase map analysis
 - 3.4. Limitations
 - 4. Measurable quantities and interferometer types
 - 4.1. Initial considerations
 - 4.2. Sensitivity vector analysis
 - 4.3. Measurement of static deformations
 - 4.4. Dual illumination beam setups
 - 4.5. Measurement of dynamic deformations
 - 4.6. Measurement of deformation gradients
 - 4.7. Measurement of object contour and slope
 - 5. Outlook and prospects
 - References
- 16. Pulsed ESPI** 223
- A.J. Moore, J.D.C. Jones and J.D.R. Valera*
- 1. Introduction
 - 2. Harmonic vibration measurement (dual-pulse and stroboscopic ESPI)
 - 2.1. Addition
 - 2.2. Subtracted-addition
 - 2.3. Subtraction
 - 2.4. Examples
 - 3. Repeatable transient deformation measurements (dual-pulse ESPI)
 - 4. Nonrepeatable transient deformation measurements (high-speed cameras)
 - 5. Future directions
 - References
- 17. Electronic speckle pattern interferometry (ESPI) and related techniques: current and future applications in the automotive industry** 241
- F. Chen, T.E. Allen and C.T. Griffen*
- 1. Introduction
 - 2. Vibration measurement
 - 2.1. Time average and stroboscopic methods
 - 2.2. Complex vibration measurement: vibration amplitude and phase
 - 3. Deformation/strain measurement
 - 4. Nondestructive testing
 - 5. Transient event measurement
 - 6. Trends and future work
 - References

18. Nondestructive testing of composite materials with electronic speckle pattern interferometry and shearography 257
S. Waldner and G. Kress
1. Introduction
 2. Typical defects in composite materials
 - 2.1. Composite materials
 - 2.2. Damage types
 3. How to test composite materials
 - 3.1. Measurement environment and object preparation
 - 3.2. Object loading
 - 3.3. Flexible arrangements
 - 3.4. Compact measurement devices
 - 3.5. Specific testing facilities
 4. How to evaluate ESPI and shearography measurements
 - 4.1. Qualitative defect detection
 - 4.2. Quantitative evaluation of defect size and location
 - 4.3. Quantitative evaluation of deformation
 5. Conclusions
 - References
19. Artwork inspection using electronic speckle pattern interferometry 273
D. Paoletti and G. Schirripa Spagnolo
1. Introduction
 2. General remarks on artworks decay
 3. ESPI experimental arrangement for in situ operation
 4. Digital processing of ESPI images
 - 4.1. Contrast enhancement
 - 4.2. Filtering
 - 4.3. Image composition
 - 4.5. Quantitative information
 5. Application in artwork diagnostics
 6. Problem perspective and further development
 - References
20. Digital shearography and applications 287
Y.Y. Hung
1. Introduction
 2. Principles of digital shearography
 - 2.1. Description of the technique
 - 2.2. Principles of fringe formation
 - 2.3. Fringe interpretation
 - 2.4. Automated fringe phase determination
 3. Applications
 - 3.1. General surface deformation measurement
 - 3.2. Out-of-plane deformation measurement
 - 3.3. In-plane deformation measurement
 - 3.4. Comparison of deformation of two different objects
 - 3.5. Residual stress measurement
 - 3.6. Study of steady-state vibration
 - 3.6.1. Time-integrated shearography
 - 3.6.2. Stroboscopic shearography
 - 3.7. Time-dependent deformation measurement
 - 3.8. Nondestructive testing
 - 3.8.1. How does shearography detect flaws?
 - 3.8.2. Shearography vs. ultrasound
 - 3.8.3. Methods of stressing
 - 3.8.4. Flaw recognition
 - 3.9. Three-dimensional shape measurement
 - 3.9.1. Double wavelength method
 - 3.9.2. Double refractive index method
 - 3.9.3. Two source method
 - 3.10. Detection of gas leakage
 4. Limitations and remedies
 5. Conclusion
 - References

21. On the way to experimental modal analysis by means of digital shearography

309

W. Steinchen, G. Kupfer, P. Mäckel, F. Vössing

1. Introduction
2. Real time vibration analysis by time average digital shearography
 - 2.1. Real time subtraction using fixed reference frame measuring method
 - 2.2. Real time subtraction using permanently refreshed reference frame measuring method
3. Quantitative evaluation of digital shearogram of a vibrating object
 - 3.1. Stroboscopic illumination in conjunction with the phase shifting technique
 - 3.2. Determination of the vibration mode and the dynamic strain field of the shearogram
 - 3.3. Numerical evaluation of the stroboscopic illuminated shearograms
4. Conclusions
- References

22. Spectral and temporal phase evaluation for interferometry and speckle applications

323

N.J. Tiziani

1. Introduction
2. Wavelength-scanning interferometry
 - 2.1. Theory
 - 2.2. Experimental arrangement
 - 2.3. Wavelength variation with an external cavity
 - 2.4. Signal analysis
 - 2.5. Resolution
 - 2.6. Experimental results
3. Temporal speckle pattern interferometry for out-of-plane deformation
 - 3.1. Theory and setup
 - 3.2. Experimental procedure and results
4. Speckle shearing interferometer for the measurement of large deformations
 - 4.1. Theory and setup
 - 4.2. Experimental procedure and results
5. Shape measurement by temporal phase evaluation.
 - 5.1. Theory and setup
 - 5.2. Experimental results
6. Heterodyne temporal speckle pattern interferometry
 - 6.1. Theory
 - 6.2. Experiment and results
7. Conclusion and outlook
- References

23. Moiré in science and engineering

345

C.A. Sciammarella

1. Introduction
2. Gratings as carriers of displacement information: In-plane displacements
 - 2.1. Introduction
3. The moiré method
 - 3.1. In-plane measurements using incoherent illumination
 - 3.2. Coherent observation of moiré patterns: Moiré interferometry
 - 3.3. Carrier fringes
 - 3.4. Out of plane measurements
 - 3.4.1. Incoherent illumination
 - 3.4.2. Coherent illumination
4. Three-dimensional problems
5. Optical processing of displacement information
 - 5.1. Fringe separation, multiplication and interpolation
 - 5.2. Pattern differentiation
6. Techniques to observe intrinsic moiré patterns
 - 6.1. Grating printing
 - 6.2. Incoherent illumination
 - 6.3. Coherent illumination
 - 6.4. Analysis of moiré patterns
7. Measurements of displacements perpendicular to a plane
 - 7.1. Shadow moiré
 - 7.2. Projection moiré
8. Measurement of slopes. Reflection moiré
9. Dynamic studies with moiré

10. Large deformations
11. Computer processing of moiré patterns
- 11.1. Introduction
 - 11.2. Signal acquisition
 - 11.3. Signal processing
 - 11.3.1. Phase stepping
 - 11.3.2. Fourier methods
 - 11.4. Basic properties of the displacement signal
12. Computer assisted moiré
13. Future trends
- References
- 24. Moiré interferometry** 375
- D. Post, B. Han and P.G. Ifju*
1. Introduction/basic concepts
 2. Applications
 - 2.1. Biomechanics/human teeth
 - 2.2. Electronic packaging/microscopic moiré interferometry
 - 2.3. Residual stresses induced in composites manufacture
 3. Trends/predictions
 - 3.1. Replication of deformed gratings
 - 3.2. Data reduction from single images
 - 3.3. Instrumentation
 - 3.4. Micromechanics
 - 3.5. Propagation into college/university curricula
 - 3.6. Diverse applications
- References
- 25. Digital moiré for deformation analysis** 391
- A. Asundi*
1. Digital moiré principles
 2. In-plane moiré
 3. Shadow moiré
 4. Projection moiré
 5. Conclusion
- References
- 26. Deformation measurement in civil engineering using high-resolution moiré** 401
- C. Fomo*
1. Classical optics and James Burch
 2. High resolution moiré photography (HRMP)
 - 2.1. Basic principles
 - 2.2. Slotted mask
 - 2.3. Surface treatment
 - 2.4. Recording and reconstructing fringe patterns
 - 2.5. Analysis of fringe maps
 3. Examples of civil engineering applications of the technique
 - 3.1. Victorian bridges
 - 3.2. Degradation of houses through vehicle-induced vibration
 - 3.3. Hong Kong and Shanghai Bank
 - 3.4. High pressure wind tunnel
 - 3.5. Real-time moiré photography — early experiments
 - 3.6. Real-time moiré photography with CCD cameras
 4. Camera specification
 5. System test
 6. Conclusion
- References
- 27. Real-time phase distribution analysis in moiré** 415
- Y. Morimoto and M. Fujigaki*
1. Introduction
 2. Geometric moiré method and scanning moiré method (GMM & SMM)
 3. Phase-shifting scanning moiré method (PSSMM)
 4. Phase-difference scanning moiré method (PDSMM) (equal displacement contour lines)
 5. Phase-shifting method (PSM)
 6. Phase-shifting method using correlation with rectangular function (PSM/CR)

7. Integrated phase-shifting method (IPSM)	
8. Conclusions and future perspectives	
References	
28. Fiber optics in smart structures – an introductory overview	433
<i>B. Culshaw</i>	
1. Introduction	
2. Fibre optic sensors in structural assessment	
3. Mechanical measurements with optical fibres	
3.1. Optical fibre bragg gratings	
3.2. Integrated strain sensor systems	
3.3. Distributed sensing systems	
3.4. Structural strain measurement – some overall comments	
4. Distributed chemical measurements, corrosion and erosion	
5. Some concluding observations	
References	
29. Distributed deformation sensors	447
<i>L. Thevenaz</i>	
1. Introduction	
2. Stimulated Brillouin scattering	
3. Applications	
4. Future trends	
References	
30. Application of fiber optic sensors to structural monitoring	459
<i>D. Inaudi</i>	
1. Monitoring as a structure management tool	
2. Strain vs. long-gage sensors	
3. Long-fiber optic sensor types	
3.1. SOFO displacement sensors	
3.2. Microbend displacement sensors	
3.3. Bragg grating strain sensors	
3.4. Fabry-Perot strain sensors	
3.5. Raman and Brillouin distributed sensors	
3.6. Hydrogel distributed humidity sensors	
4. Application example: the Versoix bridge	
4.1. Fiber optic instrumentation	
4.2. Measurements on single sensors	
4.3. Global displacement measurements	
5. Outlook	
6. Conclusions	
References	
31. Reliability of fiber optic sensors	473
<i>U. Sennhauser and Ph.M. Nellen</i>	
1. Introduction	
2. Reliability of fiber optic sensor components	
2.1. Fibers	
2.2. Fiber coatings	
2.3. Fiber-structure bonding	
2.4. Fiber Bragg gratings	
3. Reliability of fiber optic sensing systems	
4. Application examples	
5. Recommendations	
6. Future trends	
References	
32. Fiber optic gyros	487
<i>K. Hotate</i>	
1. Introduction	
2. Configurations and noise factors of interferometer fiber optic gyro	
2.1. Minimum configuration	
2.2. Noise factors and countermeasures	
2.3. Closed-loop operation	
3. Applications of interferometer fiber optic gyro	

4. Other configurations
 - 4.1. Resonator fiber optic gyro
 - 4.2. Brillouin fiber optic gyro
 - 4.3. Monolithically integrated optical waveguide gyro

5. Conclusions

References

33. Detection and characterization of flaws by laser-ultrasonics

503

J.-P. Monchalin

1. Introduction
2. Principles of generation
3. Principles of detection
4. Detection of flaws in polymer-matrix composite materials
 - 4.1. Description of the system developed
 - 4.2. Results obtained on composite parts
 - 4.3. Aircraft inspection on a maintenance site
5. Detection of small defects in objects by laser-ultrasonics and SAFT processing
 - 5.1. Principle of SAFT
 - 5.2. Description of a demonstration setup and of the results obtained on a test specimen
6. Other approaches
 - 6.1. Detection of flaws inside objects with an array of sources
 - 6.2. Detection of surface defects
7. Measurement of thickness
8. Conclusion and perspectives

References

34. Photorefractive interferometry for the optical detection of the ultrasonic motion of a scattering surface

519

P. Delaye, A. Blouin, J.-P. Monchalin, G. Roosen

1. Introduction
2. Specifications of a useful optical ultrasonic sensor
3. Photorefractive beam combiner
 - 3.1. Theoretical description
 - 3.2. Performance of the beam combiner with photorefractive semiconductors
 - 3.3. Operation of the sensor with other kinds of photorefractive materials
4. Other detection systems using the photorefractive effect
 - 4.1. The double phase conjugate heterodyne detection
 - 4.2. The adaptive photodetector
5. Conclusion and perspectives

References

35. Recent advances in digital photoelasticity

533

T.Y. Chen

1. Introduction
2. Basic principles of photoelasticity
3. Digital image processing
4. Digital analysis of photoelastic fringe patterns
 - 4.1. Extraction of fringe point
 - 4.2. Intensity calibration methods
 - 4.3. Use of different wavelengths
 - 4.4. Phase stepping method
 - 4.5. Use of different loads
 - 4.6. Determination of principal stress direction
 - 4.7. Comparison of various methods and applications
 - 4.8. System and error assessment
5. Conclusions and future perspectives

References

36. Fourier transform profilometry

545

M. Takeda

1. Introduction
2. Classical Fourier transform profilometry
3. Spatial frequency-multiplex Fourier transform profilometry
4. Fourier transform speckle profilometry
5. Conclusions

References

37. Approaches in flow visualization

559

W. Merzkirch

1. Principles of flow visualization techniques
2. Flow visualization by tracer material
3. Visualization by refractive index changes
4. Surface flow visualization
 - 4.1. Mechanical interaction
 - 4.2. Chemical interaction
 - 4.3. Thermal interaction

References

38. Computer vision applied to shape and deformation measurement

571

M.A. Sutton, S.R. McNeill, J.D. Helm, H.W. Schreier

1. Introduction
2. Two-dimensional digital image correlation method
 - 2.1. Basic concepts
 - 2.2. Measurement of surface shape at high magnification using DIC-2D and a scanning electron microscope
 - 2.2.1. Parallel projection method
 - 2.2.2. Micro-scale measurement of surface height using DIC-2D
 - 2.2.3. Baseline tests
 - 2.2.4. Fracture surface measurements
 - 2.2.5. Discussion of results
 - 2.3. Mixed mode I/II crack growth studies
 - 2.3.1. Specimen configuration and test procedure
 - 2.3.2. Experimental results
 - 2.3.3. Simulation studies
 - 2.3.4. Discussion of results
3. Three-dimensional digital image correlation method
 - 3.1. Basic concepts
 - 3.2. Global-local measurement systems
 - 3.2.1. Experimental setup
 - 3.2.2. Specimen preparation
 - 3.2.3. Composite panel test
 - 3.2.4. Discussion of results

References

39. Applications of infrared thermography in nondestructive evaluation

591

X. Maldague

1. Introduction
2. Active and passive thermography for NDE
3. Advantages and difficulties of IR thermography
4. Theory
 - 4.1. Radiometry, emissivity and temperature measurement
 - 4.2. Heat transfer considerations
5. Passive thermography
6. Active thermography
 - 6.1. Pulsed thermography
 - 6.2. Step heating (long pulse)
 - 6.3. Lock-in thermography
 - 6.4. Vibrothermography
7. Which scheme to choose from?
8. Trends
 - 8.1. Hardware
 - 8.2. Software
 - 8.3. Applications
9. Conclusion

References

Index of authors

611

Keyword index

613