


 WILEY-VCH

Phase Transformations in Materials

Edited by Gernot Kostorz



Contents

1	Thermodynamics and Phase Diagrams of Materials	1
	<i>A. D. Pelton</i>	
2	Solidification	81
	<i>H. Müller-Krumbhaar, W. Kurz, E. Brener</i>	
3	Diffusion in Crystalline Solids	171
	<i>G. E. Murch</i>	
4	Statistical Theories of Phase Transitions	239
	<i>K. Binder</i>	
5	Homogeneous Second Phase Precipitation	309
	<i>R. Wagner, R. Kampmann, P. W. Voorhees</i>	
6	Spinodal Decomposition	409
	<i>K. Binder, P. Fratzl</i>	
7	Transformations Involving Interfacial Diffusion	481
	<i>G. R. Purdy, Y. J. M. Bréchet</i>	
8	Atomic Ordering	519
	<i>G. Inden</i>	
9	Diffusionless Transformations	583
	<i>L. Delaey</i>	
10	High Pressure Phase Transformations	655
	<i>M. Kunz</i>	
Index	697

1 Thermodynamics and Phase Diagrams of Materials

Arthur D. Pelton

Centre de Recherche en Calcul Thermochimique, École Polytechnique,
Montréal, Québec, Canada

List of Symbols and Abbreviations	3
1.1 Introduction	5
1.1.1 Notation	5
1.2 Gibbs Energy and Equilibrium	5
1.2.1 Gibbs Energy	5
1.2.2 Chemical Equilibrium	6
1.3 Predominance Diagrams	7
1.3.1 Calculation of Predominance Diagrams	7
1.3.2 Ellingham Diagrams as Predominance Diagrams	8
1.3.3 Discussion of Predominance Diagrams	9
1.4 Thermodynamics of Solutions	9
1.4.1 Gibbs Energy of Mixing	9
1.4.2 Chemical Potential	10
1.4.3 Tangent Construction	11
1.4.4 Gibbs-Duhem Equation	11
1.4.5 Relative Partial Properties	11
1.4.6 Activity	12
1.4.7 Ideal Raoultian Solutions	12
1.4.8 Excess Properties	13
1.4.9 Activity Coefficient	14
1.4.10 Multicomponent Solutions	14
1.5 Binary Phase Diagrams	14
1.5.1 Systems with Complete Solid and Liquid Miscibility	14
1.5.2 Thermodynamic Origin of Phase Diagrams	16
1.5.3 Pressure-Composition Phase Diagrams	19
1.5.4 Minima and Maxima in Two-Phase Regions	20
1.5.5 Miscibility Gaps	21
1.5.6 Simple Eutectic Systems	22
1.5.7 Regular Solution Theory	23
1.5.8 Thermodynamic Origin of Simple Phase Diagrams Illustrated by Regular Solution Theory	24
1.5.9 Immiscibility – Monotectics	26
1.5.10 Intermediate Phases	26
1.5.11 Limited Mutual Solubility – Ideal Henrian Solutions	29
1.5.12 Geometry of Binary Phase Diagrams	31

1.6	Application of Thermodynamics to Phase Diagram Analysis	34
1.6.1	Thermodynamic/Phase Diagram Optimization	34
1.6.2	Polynomial Representation of Excess Properties	34
1.6.3	Least-Squares Optimization	35
1.6.4	Calculation of Metastable Phase Boundaries	39
1.7	Ternary and Multicomponent Phase Diagrams	39
1.7.1	The Ternary Composition Triangle	39
1.7.2	Ternary Space Model	39
1.7.3	Polythermal Projections of Liquidus Surfaces	41
1.7.4	Ternary Isothermal Sections	43
1.7.4.1	Topology of Ternary Isothermal Sections	45
1.7.5	Ternary Isopleths (Constant Composition Sections)	46
1.7.5.1	Quasi-Binary Phase Diagrams	47
1.7.6	Multicomponent Phase Diagrams	47
1.7.7	Nomenclature for Invariant Reactions	49
1.7.8	Reciprocal Ternary Phase Diagrams	49
1.8	Phase Diagrams with Potentials as Axes	51
1.9	General Phase Diagram Geometry	56
1.9.1	General Geometrical Rules for All True Phase Diagram Sections	56
1.9.1.1	Zero Phase Fraction Lines	58
1.9.2	Choice of Axes and Constants of True Phase Diagrams	58
1.9.2.1	Tie-lines	60
1.9.2.2	Corresponding Phase Diagrams	60
1.9.2.3	Theoretical Considerations	60
1.9.2.4	Other Sets of Conjugate Pairs	61
1.10	Solution Models	62
1.10.1	Sublattice Models	62
1.10.1.1	All Sublattices Except One Occupied by Only One Species	62
1.10.1.2	Ionic Solutions	62
1.10.1.3	Interstitial Solutions	64
1.10.1.4	Ceramic Solutions	64
1.10.1.5	The Compound Energy Formalism	65
1.10.1.6	Non-Stoichiometric Compounds	65
1.10.2	Polymer Solutions	66
1.10.3	Calculation of Limiting Slopes of Phase Boundaries	66
1.10.4	Short-Range Ordering	68
1.10.5	Long-Range Ordering	71
1.11	Calculation of Ternary Phase Diagrams From Binary Data	72
1.12	Minimization of Gibbs Energy	74
1.12.1	Phase Diagram Calculation	76
1.13	Bibliography	76
1.13.1	Phase Diagram Compilations	76
1.13.2	Thermodynamic Compilations	77
1.13.3	General Reading	78
1.14	References	78

2 Solidification

Heiner Müller-Krumbhaar

Institut für Festkörperforschung, Forschungszentrum Jülich, Germany

Wilfried Kurz

Département des Matériaux, EPFL, Lausanne, Switzerland

Efim Brener

Institut für Festkörperforschung, Forschungszentrum Jülich, Germany

List of Symbols and Abbreviations	82
2.1 Introduction	85
2.2 Basic Concepts in First-Order Phase Transitions	86
2.2.1 Nucleation	87
2.2.2 Interface Propagation	89
2.2.3 Growth of Simple Crystal Forms	91
2.2.4 Mullins–Sekerka Instability	93
2.3 Basic Experimental Techniques	95
2.3.1 Free Growth	96
2.3.2 Directional Growth	98
2.4 Free Dendritic Growth	100
2.4.1 The Needle Crystal Solution	101
2.4.2 Side-Branching Dendrites	108
2.4.3 Experimental Results on Free Dendritic Growth	115
2.5 Directional Solidification	120
2.5.1 Thermodynamics of Two-Component Systems	121
2.5.2 Scaled Model Equations	124
2.5.3 Cellular Growth	126
2.5.4 Directional Dendritic Growth	131
2.5.5 The Selection Problem of Primary Cell Spacing	135
2.5.6 Experimental Results on Directional Dendritic Growth	139
2.5.7 Extensions	149
2.6 Eutectic Growth	152
2.6.1 Basic Concepts	152
2.6.2 Experimental Results on Eutectic Growth	158
2.6.3 Other Topics	163
2.7 Summary and Outlook	164
2.8 References	165

3 Diffusion Kinetics in Solids

Graeme E. Murch

Department of Mechanical Engineering, University of Newcastle, N.S.W. 2308, Australia

List of Symbols and Abbreviations	173
3.1 Introduction	175
3.2 Macroscopic Diffusion	175
3.2.1 Fick's Law	175
3.2.2 Types of Diffusion Coefficients	178
3.2.2.1 Tracer or Self-Diffusion	178
3.2.2.2 Impurity and Solute Diffusion	178
3.2.2.3 Chemical or Interdiffusion	178
3.2.2.4 Intrinsic or Partial Diffusion Coefficients	179
3.2.2.5 Surface Diffusion Coefficients	180
3.2.3 Phenomenological Equations of Irreversible Thermodynamics	181
3.2.3.1 Tracer Diffusion	182
3.2.3.2 Chemical Diffusion	184
3.2.3.3 Einsteinian Expressions for the Phenomenological Coefficients	185
3.2.3.4 Relating Phenomenological Coefficients to Tracer Diffusion Coefficients	185
3.2.4 Short-Circuit Diffusion	186
3.3 Microscopic Diffusion	189
3.3.1 Random Walk Theory	189
3.3.1.1 Mechanisms of Diffusion	189
3.3.1.2 The Einstein Equation	192
3.3.1.3 Tracer Correlation Factor	193
3.3.1.4 Impurity Correlation Factor	196
3.3.1.5 Correlation Factors for Concentrated Alloy Systems	199
3.3.1.6 Correlation Factors for Highly Defective Systems	201
3.3.1.7 The Physical or Conductivity Correlation Factor	204
3.3.1.8 Correlation Functions (Collective Correlation Factors)	206
3.3.2 The Nernst–Einstein Equation and the Haven Ratio	211
3.3.3 The Isotope Effect in Diffusion	213
3.3.4 The Jump Frequency	216
3.3.4.1 The Exchange Frequency	217
3.3.4.2 Vacancy Concentration	218
3.4 Diffusion in Materials	219
3.4.1 Diffusion in Metals	220
3.4.1.1 Self-Diffusion	220
3.4.1.2 Impurity Diffusion	220
3.4.2 Diffusion in Dilute Alloys	221

3.4.2.1	Substitutional Alloys	221
3.4.2.2	Interstitial Alloys	224
3.4.3	Diffusion in Concentrated Binary Substitutional Alloys	226
3.4.4	Diffusion in Ionic Crystals	227
3.4.4.1	Defects in Ionic Crystals	227
3.4.4.2	Diffusion Theory in Ionic Crystals	228
3.5	Experimental Methods for Measuring Diffusion Coefficients	231
3.5.1	Tracer Diffusion Methods	231
3.5.2	Chemical Diffusion Methods	232
3.5.3	Diffusion Coefficients by Indirect Methods	233
3.5.3.1	Relaxation Methods	233
3.5.3.2	Nuclear Methods	234
3.5.4	Surface Diffusion Methods	234
3.6	Acknowledgements	235
3.7	References	235

4 Statistical Theories of Phase Transitions

Kurt Binder

Institut für Physik, Johannes Gutenberg-Universität Mainz,
Mainz, Federal Republic of Germany

List of Symbols and Abbreviations	240
4.1 Introduction	245
4.2 Phenomenological Concepts	246
4.2.1 Order Parameters and the Landau Symmetry Classification	246
4.2.2 Second-Order Transitions and Concepts about Critical Phenomena (Critical Exponents, Scaling Laws, etc.)	260
4.2.3 Second-Order Versus First-Order Transitions; Tricritical and Other Multicritical Phenomena	269
4.2.4 Dynamics of Fluctuations at Phase Transitions	277
4.2.5 Effects of Surfaces and of Quenched Disorder on Phase Transitions: a Brief Overview	279
4.3 Computational Methods Dealing with the Statistical Mechanics of Phase Transitions and Phase Diagrams	283
4.3.1 Models for Order–Disorder Phenomena in Alloys	283
4.3.2 Molecular Field Theory and its Generalization (Cluster Variation Method, etc.)	288
4.3.3 Computer Simulation Techniques	293
4.4 Concepts About Metastability	298
4.5 Discussion	303
4.6 References	304

5 Homogeneous Second-Phase Precipitation

Richard Wagner

Forschungszentrum Jülich GmbH, Jülich, Germany

Reinhard Kampmann

Institut für Werkstofforschung, GKSS-Forschungszentrum GmbH, Geesthacht, Germany

Peter W. Voorhees

Department of Materials Science and Engineering, Northwestern University, Evanston, Ill., USA

List of Symbols and Abbreviations	311
5.1 Introduction	314
5.2 General Considerations	315
5.2.1 General Course of an Isothermal Precipitation Reaction	315
5.2.2 Thermodynamic Considerations – Metastability and Instability	317
5.2.3 Decomposition Mechanisms: Nucleation and Growth versus Spinodal Decomposition	319
5.2.4 Thermodynamic Driving Forces for Phase Separation	322
5.3 Experimental Techniques for Studying Decomposition Kinetics	326
5.3.1 Microanalytical Tools	326
5.3.1.1 Direct Imaging Techniques	326
5.3.1.2 Scattering Techniques	328
5.3.2 Experimental Problems	330
5.3.2.1 Influence of Quenching Rate on Kinetics	330
5.3.2.2 Distinction of the Mode of Decomposition	332
5.4 Precipitate Morphologies	334
5.4.1 Experimental Results	334
5.4.2 Factors Controlling the Shapes and Morphologies of Precipitates	336
5.5 Early Stage Decomposition Kinetics	339
5.5.1 Cluster-Kinetics Approach	340
5.5.1.1 Classical Nucleation – Sharp Interface Model	340
5.5.1.2 Time-Dependent Nucleation Rate	343
5.5.1.3 Experimental Assessment of Classical Nucleation Theory	345
5.5.1.4 Non-Classical Nucleation – Diffuse Interface Model	347
5.5.1.5 Distinction Between Classical and Non-Classical Nucleation	349
5.5.2 Diffusion-Controlled Growth of Nuclei from the Supersaturated Matrix	350

5.5.3	The Cluster-Dynamics Approach to Generalized Nucleation Theory	352
5.5.4	Spinodal Theories	356
5.5.5	The Philosophy of Defining of 'Spinodal Alloy' – Morphologies of 'Spinodal Alloys'	363
5.5.6	Monte Carlo Studies	367
5.6	Coarsening of Precipitates	370
5.6.1	General Remarks	370
5.6.2	The LSW Theory of Coarsening	370
5.6.3	Extensions of the Coarsening Theory to Finite Precipitate Volume Fractions	373
5.6.4	Other Approaches Towards Coarsening	377
5.6.5	Influence of Coherency Strains on the Mechanism and Kinetics of Coarsening – Particle Splitting	377
5.7	Numerical Approaches Treating Nucleation, Growth and Coarsening as Concomitant Processes	381
5.7.1	General Remarks on the Interpretation of Experimental Kinetic Data of Early Decomposition Stages	381
5.7.2	The Langer and Schwartz Theory (LS Model) and its Modification by Kampmann and Wagner (MLS Model)	383
5.7.3	The Numerical Modell (N Model) of Kampmann and Wagner (KW)	385
5.7.4	Decomposition of a Homogeneous Solid Solution	385
5.7.4.1	General Course of Decomposition	385
5.7.4.2	Comparison Between the MLS Model and the N Model	387
5.7.4.3	The Appearance and Experimental Identification of the Growth and Coarsening Stages	387
5.7.4.4	Extraction of the Interfacial Energy and the Diffusion Constant from Experimental Data	389
5.7.5	Decomposition Kinetics in Alloys Pre-Decomposed During Quenching	391
5.7.6	Influence of the Loss of Particle Coherency on the Precipitation Kinetics	392
5.7.7	Combined Cluster-Dynamic and Deterministic Description of Decomposition Kinetics	394
5.8	Self-Similarity, Dynamical Scaling and Power-Law Approximations	395
5.8.1	Dynamical Scaling	395
5.8.2	Power-Law Approximations	398
5.9	Non-Isothermal Precipitation Reactions	401
5.10	Acknowledgements	402
5.11	References	402

6 Spinodal Decomposition

Kurt Binder

Institut für Physik, Johannes Gutenberg-Universität Mainz,
Mainz, Federal Republic of Germany

Peter Fratzl

Erich-Schmid-Institut der Österreichischen Akademie der Wissenschaften
und Montan-Universität Leoben, Leoben, Austria

List of Symbols and Abbreviations	411
6.1 Introduction	414
6.2 General Concepts	416
6.2.1 Phenomenological Thermodynamics of Binary Mixtures and the Basic Ideas of Phase Separation Kinetics	416
6.2.2 The Cahn–Hilliard–Cook Nonlinear Diffusion Equation	420
6.2.3 Linearized Theory of Spinodal Decomposition	421
6.2.4 Spinodal Decomposition of Polymer Mixtures	426
6.2.5 Significance of the Spinodal Curve	428
6.2.6 Towards a Nonlinear Theory of Spinodal Decomposition in Solids and Fluids	437
6.2.7 Effects of Finite Quench Rate	441
6.2.8 Interconnected Precipitated Structure Versus Isolated Droplets, and the Percolation Transition	442
6.2.9 Coarsening and Late Stage Scaling	445
6.2.10 Effects of Coherent Elastic Mismatch	447
6.3 Survey of Experimental Results	450
6.3.1 Metallic Alloys	451
6.3.2 Glasses, Ceramics, and Other Solid Materials	454
6.3.3 Fluid Mixtures	455
6.3.4 Polymer Mixtures	457
6.4 Extensions	460
6.4.1 Systems Near a Tricritical Point	460
6.4.2 Spontaneous Growth of Ordered Domains out of Initially Disordered Configurations	462
6.4.3 Phase Separation in Reduced Geometry and near Surfaces	467
6.4.4 Effects of Quenched Impurities; Vacancies; Electrical Resistivity of Metallic Alloys Undergoing Phase Changes	468
6.4.5 Further Related Phenomena	470

6.5	Discussion	471
6.6	Acknowledgements	473
6.7	References	474

7 Transformations Involving Interfacial Diffusion

Gary R. Purdy

Department of Materials Science and Engineering, McMaster University, Hamilton, Ontario, Canada

Yves J. M. Bréchet

Laboratoire de Thermodynamique et Physico-Chimie Métallurgiques, E.N.S.E.E.G., Institut National Polytechnique de Grenoble, France

List of Symbols and Abbreviations	482
7.1 Introduction	484
7.2 Equilibrium Properties of Solid–Solid Interfaces	484
7.2.1 Structures of Grain Boundaries	484
7.2.2 Structures of Interphase Boundaries	486
7.2.3 Segregation to an Interface	489
7.3 Interfacial Diffusion	490
7.4 Forces for Interface Migration	492
7.4.1 Capillary Forces	492
7.4.2 Chemical Forces	493
7.4.3 Mechanical Forces	493
7.4.3.1 Elastic Strain Energy	493
7.4.3.2 Plastic Response	494
7.4.4 Frictional Forces	496
7.4.4.1 Solute Drag	496
7.4.4.2 Particle Pinning	498
7.5 Examples	498
7.5.1 The Massive Transformation	498
7.5.2 Chemically-Induced Grain Boundary Migration	503
7.5.3 Discontinuous Precipitation	504
7.5.3.1 Initiation of Discontinuous Precipitation	505
7.5.3.2 Theories of Steady Cooperative Growth	507
7.5.3.3 Experimental Observations	510
7.5.4 Interface Migration in Multilayers	514
7.6 Conclusions	516
7.7 References	516

8 Atomic Ordering

Gerhard Inden

Max-Planck-Institut für Eisenforschung GmbH, Düsseldorf, Federal Republic of Germany

List of Symbols and Abbreviations	521
8.1 Introduction	523
8.2 Definition of Atomic Configurations	523
8.2.1 Configurational Variables	523
8.2.2 Point Variables	525
8.2.3 Point Correlation Functions and Point Probabilities	526
8.2.4 Pair Variables, Correlation Functions, and Probabilities	527
8.2.5 Generalized Cluster Variables, Correlation Functions, and Probabilities	529
8.2.6 Short-Range-Order (sro) Configurations – Long-Range-Order (lro) Configurations	529
8.3 The Existence Domain and Configuration Polyhedron	531
8.3.1 F.C.C. Structure, First Neighbor Interactions	532
8.3.2 F.C.C. Structure, First and Second Neighbor Interactions	535
8.3.3 B.C.C. Structure, First and Second Neighbor Interactions	537
8.4 Ground States	538
8.4.1 Pair Interactions	538
8.4.1.1 Ground State Energies	540
8.4.1.2 F.C.C. Structure, First Neighbor Interactions	540
8.4.1.3 F.C.C. Structure, First and Second Neighbor Interactions	543
8.4.1.4 B.C.C. Structure, First and Second Neighbor Interactions	544
8.4.1.5 Energy Minimum at Constant Composition	544
8.4.1.6 Canonical Energy of lro States	546
8.4.1.7 Relevant Literature	547
8.4.2 Effective Cluster Interactions (ECIs)	548
8.5 Phase Equilibria at Finite Temperatures	551
8.5.1 Cluster Variation Method	551
8.5.2 Calculation of Phase Diagrams with the CVM	554
8.5.3 Phase Diagram Calculation with the Monte Carlo Method	554
8.5.4 Examples of Prototype Diagrams	555
8.5.4.1 F.C.C. Structure, First Neighbor Interactions	555
8.5.4.2 F.C.C. Structure, First and Second Neighbor Interactions	557
8.5.4.3 B.C.C. Structure, First and Second Neighbor Interactions	558
8.5.4.4 Hexagonal Lattice, Anisotropic Nearest-Neighbor Interactions	558
8.5.5 The Cluster Site Approximation (CSA)	560
8.6 Application to Real Systems	561
8.6.1 The Au–Ni System	563

8.6.2	The Thermodynamic Factor of Ordered Phases	563
8.6.2.1	The B.C.C. Fe–Al System	565
8.6.2.2	The F.C.C. Ni–Al System	567
8.6.3	Ternary Systems	569
8.6.3.1	B.C.C. Fe–Ti–Al	569
8.6.3.2	B.C.C. Ferromagnetic Fe–Co–Al	570
8.6.4	H.C.P. Cd–Mg	573
8.6.5	Concluding Remarks	574
8.7	Appendix	575
8.8	Acknowledgements	578
8.9	References	578

9 Diffusionless Transformations

Luc Delaey

Departement Metaalkunde en Toegepaste Materiaalkunde,
Katholieke Universiteit Leuven, Heverlee-Leuven, Belgium

List of Symbols and Abbreviations	585
9.1 Introduction	587
9.2 Classification and Definitions	590
9.3 General Aspects of the Transformation	593
9.3.1 Structural Relations	593
9.3.2 Pre-transformation State	597
9.3.3 Transformation Mechanisms	599
9.3.4 Microstructures	600
9.3.5 Shape Changes	600
9.3.6 Transformation Thermodynamics and Kinetics	604
9.4 Shuffle Transformations	607
9.4.1 Ferroic Transformations	609
9.4.2 Omega Transformations	610
9.5 Dilatation-Dominant Transformations	610
9.6 Quasi-Martensitic Transformations	611
9.7 Shear Transformations	613
9.8 Martensitic Transformations	615
9.8.1 Crystallography of the Martensitic Transformation	615
9.8.1.1 Shape Deformation and Habit Plane	615
9.8.1.2 Orientation Relationship	616
9.8.1.3 Morphology, Microstructure and Substructure	618
9.8.1.4 Crystallographic Phenomenological Theory	620
9.8.1.5 Structure of the <i>Habit Plane</i>	623
9.8.2 Thermodynamics and Kinetics of the Martensitic Transformation	624
9.8.2.1 Critical Driving Force and Transformation Temperatures	624
9.8.2.2 Nucleation	630
9.8.2.3 Growth and Kinetics	632
9.8.2.4 Transformation Hysteresis	634
9.9 Materials	634
9.9.1 Metallic Materials	634
9.9.1.1 Ferrous Alloys	635
9.9.1.2 Non-Ferrous Alloys	637
9.9.2 Non-Metals	639
9.10 Special Properties and Applications	641
9.10.1 Hardening of Steel	641

9.10.2	The Shape-Memory Effect	641
9.10.3	High Damping Capacity	647
9.10.4	TRIP Effect	647
9.11	Recent Progress in the Understanding of Martensitic Transformations	649
9.12	Acknowledgements	651
9.13	References	652

10 High Pressure Phase Transformations

Martin Kunz

ETH Zürich, Labor für Kristallographie, Zürich, Switzerland

List of Symbols and Abbreviations	657
10.1 Introduction	659
10.2 Pressure-Driven Phase Transitions	660
10.2.1 Framework flexion	661
10.2.2 Increase in coordination number	663
10.2.3 Pressure-induced ordering	664
10.3 Generating High Pressure	666
10.3.1 Dynamic pressure generation	667
10.3.2 Static pressure devices	668
10.3.2.1 Large-volume presses	668
10.3.2.2 Diamond anvil cells	671
10.4 Probing Phase Transformations in Materials at High Pressure	673
10.4.1 Volumetric techniques	674
10.4.2 Spectroscopic techniques	674
10.4.2.1 Microscopy	674
10.4.2.2 Raman and infrared spectroscopy	674
10.4.2.3 Mössbauer spectroscopy	675
10.4.2.3 X-Ray absorption spectroscopy	676
10.4.2.5 NMR	676
10.4.3 Ultrasonic sound velocity	677
10.4.4 Diffraction techniques	678
10.4.4.1 X-ray diffraction	678
10.4.4.2 Neutron diffraction	679
10.5 Examples	679
10.5.1 Zinblende-type semiconductors	679
10.5.1.1 Si and Ge	680
10.5.1.2 GaAs	681
10.5.1.3 InSb	682
10.5.2 Materials in the B-C-N system	683
10.5.2.1 C	684
10.5.2.2 B-N	685
10.5.2.3 C-N	686
10.5.2.4 B-C	686
10.5.2.5 B-C-N	686
10.5.3 H ₂ O	687
10.5.3.1 Ice Ih, XI and Ic	688

10.5.3.2	Ice II	689
10.5.3.3	Ice III and Ice IX	689
10.5.3.4	Ice V, Ice IV and Ice XII	690
10.5.3.5	Ice VI, Ice VII, Ice VIII, Ice X	690
10.5.3.6	Amorphous ice at high pressure	691
10.6	Acknowledgment	692
10.7	References	692