



**CONTAMINATION AND
ESD CONTROL IN
HIGH-TECHNOLOGY
MANUFACTURING**



ROGER W. WELKER, R. NAGARAJAN, AND CARL E. NEWBERG

CONTENTS

PREFACE	xv
1 FUNDAMENTALS OF CONTAMINATION CONTROL	1
1.1 Introduction	1
1.1.1 Contamination Sources	1
1.1.2 Contamination Adhesion Forces	3
1.1.3 Contamination Control Methods	9
1.2 Glossary of Contamination Control Terms	10
1.3 Specifying Contamination in Air and on Surfaces	13
1.4 Sources of Contamination	16
1.5 Contamination Control Requirements	18
1.5.1 Airborne Particle Requirements	18
1.5.2 Chemical Vapor Contamination Control Limits	33
1.5.3 Ionic Contamination Control Limits	35
1.5.4 Magnetic Contamination Control Limits	37
1.5.5 Surface Contamination Rates and Air Ionization	37
1.5.6 Contact Transfer and In Situ Contamination	38
1.5.7 Airflow Requirements	39
1.5.8 Pressure Requirements and Enclosure Exhausts	39
1.5.9 Maintenance Requirements	40
1.5.10 Other Requirements	43
1.5.11 Summary of Requirements	43
1.6 Pertinent Standards	43
References and Notes	46
Additional Reading	46
2 FUNDAMENTALS OF ESD CONTROL	48
2.1 Introduction and Historical Perspective	48
2.2 Glossary of Electrostatic Charge Control Terms	52

2.3	Sources of Electrostatic Charge	56
2.3.1	Static Electricity	57
2.3.2	Effects of Electrostatic Charge and Discharge	65
2.3.3	Failure Modes in High-Technology ESD-Sensitivity Devices	67
2.4	Requirements of ESD Control	68
2.4.1	Determining ESD Damage Sensitivity	69
2.4.2	Electrically Explosive Device ESD Modeling	74
2.5	Building the ESD-Safe Workplace	75
2.5.1	Surface Resistivity of Materials	75
2.5.2	Grounding	77
2.5.3	Identification of and Access to an ESD-Safe Work Area	78
2.5.4	ESD-Protective Floor Coverings	78
2.5.5	Work Surfaces and Table Mats	81
2.5.6	Wrist Strap Ground Points	83
2.5.7	Air Ionization Systems	83
2.5.8	Relative Humidity	88
2.5.9	Chairs and Stools	90
2.5.10	Trash Cans	90
2.5.11	Cathode-Ray Tube Displays	91
2.5.12	Field Potential Limits	93
2.5.13	Tools and Fixtures	94
2.5.14	Conveyors	94
2.6	ESD Controls for People	95
2.6.1	Wrist Strap and Coiled Cord	95
2.6.2	Training and Certification Program	95
2.6.3	Cleanroom Gowns and ESD Lab Coats	97
2.6.4	Footwear	98
2.6.5	Gloves, Liners, and Finger Cots	100
2.7	Consumables and Accessories	100
2.7.1	Packaging	100
2.7.2	Desiccants	102
2.7.3	Tote Boxes, Bins, and Other Shipping Containers	102
2.7.4	Notebooks and Sheet Protectors	104
2.7.5	Swabs and Wipers	104
2.7.6	Paper	104
2.7.7	Tape	104
2.8	Personnel Equipment and Procedures for Its Use	105
2.8.1	Wrist Straps and Wrist Strap Monitors	105
2.8.2	Sit–Stand Protocol	106
2.9	Transportation of ESD-Sensitive Products	106
2.10	Inspections and Record Keeping	106
2.10.1	Daily Visual Inspection	106
2.10.2	Periodic Instrumental Inspection	107
2.10.3	Testing Protocols	109
2.11	ESD Control Program	112
2.12	ESD and Contamination Control	115
2.13	Useful Reference Standards	116
	References and Notes	117

3 SAMPLING AND ANALYSIS METHODS	119
3.1 Introduction	119
3.2 Classification of Analysis Methods	119
3.2.1 Functional Laboratory Tests	121
3.2.2 Nonfunctional Tests: Objective Laboratory Tests	124
3.3 Sampling of Contaminants in Air, in Liquids, and on Surfaces	133
3.3.1 Contaminants in Air	133
3.3.2 Contaminants in Liquids	134
3.3.3 Surface-Borne Contaminants	135
3.4 <i>Organic Contamination Analysis Methods</i>	136
3.4.1 Water Break Test	136
3.4.2 Contact Angle Measurement	136
3.4.3 Optically Stimulated Electron Emission Technique	137
3.4.4 Nonvolatile Residue Test	137
3.4.5 Organic Sampling Techniques	137
3.4.6 Central Atmospheric Monitoring System	138
3.4.7 Electron Spectroscopy for Chemical Analysis	139
3.4.8 Gas Chromatography/Mass Spectroscopy	139
3.4.9 Secondary Ion Mass Spectroscopy	139
3.5 Ionic and Inorganic Contamination Analysis Methods	139
3.6 Electrostatic Discharge Methods	141
3.6.1 Tribocharge Testing	141
3.6.2 Bulk and Surface Resistance Measurements	142
3.6.3 Air Ionizer Testing	144
3.6.4 Typical ESD Field Instruments	145
3.7 Numerical Simulation	146
3.8 Algebraic Predictive Modeling	147
3.9 Statistical Analysis Methods	150
3.9.1 Basic Statistical Analysis Tools	150
3.9.2 Gage Capability Analysis of Cleanliness Measurement Methods	151
Additional Reading	156
References and Notes	156
4 FACILITIES DESIGN: CONTAMINATION- AND ESD-SAFE WORK AREAS	158
4.1 Introduction	158
4.2 Basics of Cleanroom Design	159
4.2.1 What Can Be Called a Cleanroom	159
4.2.2 What It Takes to Make a Cleanroom Work	161
4.2.3 How Filters Work	162
4.3 Cleanrooms	165
4.3.1 Non-Unidirectional-Flow (Conventional or Mixed-Flow) Cleanrooms	166
4.3.2 Air Ionization for Non-Unidirectional-Flow Cleanrooms	168
4.3.3 Unidirectional Flow: 100% Filter Coverage	169
4.3.4 Air Ionization in Unidirectional-Flow Cleanrooms	174
4.3.5 Adding a Perforated Raised Floor	174

4.3.6	Balancing a Room Using a Perforated Raised Floor	175
4.3.7	Airflow Balancing After Tool Installation	176
4.3.8	Solid vs. Perforated Work Surfaces	181
4.3.9	Parts Storage Locations	181
4.3.10	Horizontal Unidirectional-Airflow Cleanrooms	182
4.4	Cleanroom Construction and Operating Costs	183
4.5	Modern Energy-Saving Approaches	184
4.5.1	Unidirectional-Flow Clean Benches	184
4.5.2	Isolators and Minienvironments	186
4.5.3	Point-of-Use Clean Air Cleanrooms	187
4.5.4	Tunnelizing an Existing Ballroom Cleanroom	188
4.5.5	Minienvironments	190
4.6	Other Design Considerations	191
4.6.1	Doors and Air Showers	191
4.6.2	Pass-Throughs	192
4.6.3	Equipment Pass-Throughs	193
4.6.4	Service Areas	193
	References and Notes	193
5	GETTING CLEAN PARTS AND GETTING PARTS CLEAN	195
5.1	Introduction	195
5.2	Historical Perspective	196
5.3	Gross and Precision Cleanliness Protocols	197
5.3.1	Approaches to Specifying Cleanliness Levels	199
5.4	Design for Manufacturability and Cleanability	202
5.4.1	Design-for-Manufacturability Guidelines	202
5.4.2	Design-for-Cleanability Guidelines	203
5.4.3	Cleanability Indexes for Indirect Cleanliness Measurements	203
5.4.4	Design-for-Cleanability Planning Considerations	206
5.4.5	Design-for-Cleanability Management Considerations	216
5.5	Process Design Guidelines	216
5.5.1	Use of Water-Soluble Cutting Fluids	217
5.5.2	Minimizing Work in Progress by Implementing Continuous-Flow Manufacturing	218
5.5.3	Rinsing After Machining	218
5.5.4	Parts Handling After Final Cleaning	218
5.5.5	Soldering and Flux Removal	219
5.5.6	Clean-Then Assemble vs. Assemble-Then Clean	219
5.6	Cleaning Processes	220
5.6.1	Particles in Liquid Baths	221
5.6.2	Boundary Layers	221
5.6.3	Ultrasonic Cleaning	221
5.6.4	Spray Cleaning	225
5.6.5	Spin-Rinse Dryer Cleaning	228
5.6.6	Vapor Degreasing	230
5.6.7	Chemical Cleaning	230

5.6.8	Solvent Cleaning	230
5.6.9	Mechanical Agitation Cleaning	231
5.6.10	Manual Cleaning	231
5.6.11	Specialty Cleaning	232
5.7	Drying Processes	234
5.7.1	Spin-Rinse Drying	234
5.7.2	Forced-Air Drying	234
5.7.3	Vacuum Drying	235
5.7.4	Adsorption Drying	235
5.7.5	Chemical Drying	235
5.8	Cost of Cleaning	236
5.9	Vendor Process Contamination Checklist	236
5.10	Case Studies: Cleaning Equipment and Cleaning Process Design	246
5.11	Details on the Clean-Then Assemble and Assemble-Then Clean Procedures	252
5.11.1	Cleaning Strategies	253
5.11.2	Case Studies: CTA and ATC	255
5.11.3	Case Study Results and Discussion	262
5.12	Particle Size Distributions	264
5.12.1	MIL-STD-1246	264
5.12.2	Analytical Methods	265
5.12.3	Extraction Methods Tested	266
5.12.4	Results	266
5.13	Tool Part Cleanliness	272
	References and Notes	273

6 TOOLING DESIGN AND CERTIFICATION 276

6.1	Introduction	276
6.1.1	Tooling Design Process	277
6.1.2	Applications and Limitations of Tooling Design	278
6.2	Contamination and ESD Control Requirements	279
6.3	Maintenance Requirements	280
6.3.1	(Basics of a) Wipe-Down Procedure	280
6.3.2	Maintenance Wipe-Down	281
6.3.3	Engineering Changes	282
6.3.4	Summary of Requirements	282
6.4	General Design Alternatives	283
6.4.1	Eliminating Contamination Generators	283
6.4.2	Relocating Contamination Generators	284
6.4.3	Enclosing and Evacuating Contamination Generators	285
6.5	Materials	293
6.5.1	Guidelines for Materials	293
6.5.2	Guidelines for Wear	297
6.5.3	Guidelines for Plastics	301
6.6	Surface Treatments	308
6.6.1	Paints	309
6.6.2	Anodizing and Related Treatments	310

6.6.3	Electroplating, Electropolishing, and Other Treatments	311
6.6.4	Cautions About Coatings	311
6.6.5	Synergistic Coatings	311
6.6.6	Relative Wear Properties of Coatings	312
6.6.7	Surface Texture and Porosity	312
6.7	Selection and Evaluation of Components	313
6.7.1	Pneumatic Devices	314
6.7.2	Linear Motion Guides	314
6.7.3	Electric Motors	314
6.7.4	Process Piping and Point-of-Use Filtration	315
6.7.5	In Situ Monitoring Equipment	316
6.7.6	Hand Tools	317
6.8	Tool and Workstation Layout	318
6.8.1	Flow Control Enclosures, Minienvironments, and the Standard Machine Interface	318
6.8.2	Putting the Cleanroom Tool Together	322
6.9	Cleanroom Certification of Automated Tooling	325
6.9.1	Statistical Requirements for Sampling	327
6.9.2	Analytical Equipment and Methods	331
	References and Notes	334
	Additional Reading	334

7 CONTINUOUS MONITORING 336

7.1	Introduction	336
7.1.1	Approaches to Monitoring	337
7.1.2	Traditional Airborne Particle Measurements	338
7.1.3	Critical and Busy Sampling	339
7.1.4	Modified Data Collection Protocol	339
7.1.5	Ongoing Use of Critical and Busy Sampling	340
7.1.6	Case Studies: Traditional vs. Critical and Busy Sampling	341
7.1.7	Trend, Cyclic, and Burst Patterns of Particle Generation	346
7.1.8	Case Studies: Other Applications of Continuous Monitoring	348
7.1.9	Summary and Conclusions	350
7.2	Continuous Contamination Monitoring	350
7.2.1	Electronically Multiplexed Monitoring	350
7.2.2	Pneumatically Multiplexed Particle Monitoring	351
7.3	Continuous Monitoring of Manufacturing	352
7.3.1	Air Quality	352
7.3.2	Process Fluid Purity	355
7.3.3	The Value of 100% Sampling	356
7.3.4	Cleanliness of Surfaces and Electrostatic Charge	358
7.4	Evaluation of In Situ Monitoring in an Aqueous Cleaning Application	359
7.4.1	Description of Experiment	360
7.4.2	Experimental Results	362
7.4.3	Management Using ISPM	370
7.4.4	Conclusions	371
7.5	Antennas for Electrostatic Charge Monitoring	372
	References and Notes	372

8	CONSUMABLE SUPPLIES AND PACKAGING MATERIALS	374
8.1	Introduction	374
8.2	Cleanroom and ESD Gloves	375
8.3	Functional vs. Nonfunctional Testing	376
8.3.1	Functional Materials Qualification Tests	376
8.3.2	Nonfunctional Testing: Objective Laboratory Measurements	377
8.3.3	ESD Considerations in Glove Selection	379
8.4	Glove Use Strategies	381
8.5	Initial Qualification vs. the Need for Ongoing Lot Certification	381
8.6	Glove Washing	383
8.6.1	Early Observations with Natural Rubber Latex Gloves	383
8.6.2	Gloves Washability	384
8.6.3	Nitrile Glove Performance	387
8.6.4	Glove Washing Conclusions	388
8.7	ESD Performance of Gloves	388
8.7.1	Materials Selection for ESD Properties	389
8.7.2	Specifying the ESD Performance of Cleanroom Gloves and Glove Liners	389
8.7.3	Testing Considerations	391
8.7.4	Factors That Affect the ESD Performance of Gloves	392
8.8	Glove Laundering	396
8.8.1	Cost-Benefit Problem	397
8.8.2	Polyurethane Glove Laboratory Properties	397
8.8.3	ESD Performance	398
8.8.4	Chemical Contamination	399
8.8.5	Wear Characteristics	399
8.8.6	Laundering Tests	401
8.8.7	Impact of Laundering and Reuse on Glove Cost	401
8.8.8	Conclusions	402
8.9	Wipers and Swabs	402
8.9.1	Selecting the Correct Wiper or Swab	403
8.10	Reusable and Disposable Packaging Materials	405
8.10.1	ESD Consideration in Packaging	405
8.10.2	Carbon-Filled Polymers	405
8.10.3	Metal Loading	406
8.10.4	Topical and Incorporated Organic Agents	406
8.10.5	Copolymer Blends	407
8.11	Facial Coverings	407
	References and Notes	408
9	CONTROLLING CONTAMINATION AND ESD FROM PEOPLE	410
9.1	Introduction	410
9.2	People as a Source of Contamination	410
9.2.1	Skin and Hair	411
9.2.2	Fingerprints	413
9.2.3	Bacteria and Fungi	414
9.2.4	Spittle Droplets	414

9.2.5	Street Clothing	415
9.2.6	Other Forms of Contamination	416
9.3	Typical Gowning Protocols	417
9.3.1	Inner Suit	418
9.3.2	Hair Cover (Bouffant)	419
9.3.3	Woven Gloves	419
9.3.4	Barrier Gloves	420
9.3.5	Facial Cover	420
9.3.6	Hood and Powered Headgear	421
9.3.7	Frock, Coverall, and Two-Piece Suit	422
9.3.8	Shoe Covers, Booties, and Special Shoes	424
9.3.9	Suggested Frequency of Change	426
9.4	Procedures for Entering a Cleanroom	426
9.4.1	Pre-Change Room Procedure	427
9.4.2	Wipe-Down	427
9.4.3	Hairnet and Face Mask	428
9.4.4	Shoe Cleaners	429
9.4.5	Handwashing	430
9.4.6	Changing into Cleanroom Garments	431
9.4.7	Powered Headgear	433
9.4.8	Footwear	433
9.4.9	Shoe Cleaners and Tacky Mats	436
9.5	Behavior in a Cleanroom	437
9.5.1	Working in a Cleanroom	438
9.5.2	HEPA Filters	439
9.5.3	Raised Floors	439
9.5.4	Glove Awareness	439
9.6	Procedures for Exiting a Cleanroom	439
9.6.1	Knee-High Booties	440
9.6.2	Frock or Jumpsuit	440
9.6.3	Head Covering	440
9.6.4	Hairnets, Gloves, and Disposable Shoe Covers	441
9.7	Relationship between Attire and Class Achieved	441
9.8	Procedures for Entering an ESD-Safe Work Area	443
9.8.1	Behavior in an ESD-Safe Work Area	444
9.8.2	ESD-Safe Work Area in a Cleanroom	445
9.9	Garments and Laundry Services	446
9.9.1	Garment Options	446
9.9.2	Measurements of Garment Cleanliness	446
9.9.3	Selection of Fabrics	448
9.9.4	Design and Construction of Garments	448
9.9.5	Selection of a Cleanroom Laundry Service	449
	References and Notes	449

10 LAYOUT OF CHANGE ROOMS 451

10.1	Principles of Efficient Change Room Design	451
10.2	Case Studies: Change Rooms	454

10.3	Entering the Cleanroom	467
10.3.1	Planning a Trip into the Cleanroom	468
10.3.2	Pregowning Actions	469
10.3.3	Dressing in Cleanroom Garments	469
10.3.4	Finishing Dressing	469
10.4	Exiting the Cleanroom	470
10.5	Other Considerations	472
	References and Notes	474
11	PROCEDURES AND DOCUMENTATION	475
11.1	Hierarchy of Documents and Audits	475
11.2	Operator Self-Check	476
11.3	Noninstrument Audits	478
11.4	Instrument Audits	479
11.5	Independent Audits	480
11.6	Managing Use of the Audit Scorecard	481
11.7	Typical Survey	483
11.8	Case Study: Broken Magnet Procedure	488
11.8.1	Definition of a Broken Magnet	489
11.8.2	Recommendations for the Broken Magnet Procedure	489
	Reference	491
INDEX		493