

# LEAN SIX SIGMA

---

Using SigmaXL and Minitab

---

ISSA BASS AND BARBARA LAWTON, PH.D.



# Contents

<b>Preface</b>	<b>xiii</b>
<b>Acknowledgments</b>	<b>xv</b>
<b>Introduction</b>	<b>1</b>
<b>An Overview of SigmaXL</b>	<b>3</b>
SigmaXL menu bar	3
SigmaXL templates	5
Solution	6
<b>Chapter 1. Define</b>	<b>9</b>
Project Planning	9
The Gantt chart	10
Program evaluation and review technique (PERT)	13
Project Charter	15
Project number	16
Project champion	16
Project definition	16
Project description	17
Value statement	17
Stakeholders	17
Project monitoring	17
Scheduling	17
Alternative plans	17
Risk analysis	17
Capturing the Voice of the Customer	17
Capturing the voice of the external customer	19
Capturing the voice of the internal customer	21
Capturing the voice of the customers of a project	21
Capturing the voice of the next step in the process	21
Critical-to-Quality Tree	22
Kano analysis	24
Suppliers-Input-Process-Output-Customers (SIPOC)	26

Cost of Quality	29
Assessing the cost of quality	29
Cost of conformance	30
Preventive cost	30
Appraisal cost	31
Cost of nonconformance	31
Internal failure	31
External failure	31
Optimal Cost of Quality	34
Cost of Quality According to Taguchi	36
Stakeholder Analysis	38
Force field analysis (FFA)	39
<b>Chapter 2. Measure</b>	<b>43</b>
Data Gathering	43
Data Types	43
Attribute data	44
Variable data	44
Locational data	44
Basic Probability	44
So what is probability?	44
Discrete versus continuous distributions	44
Expected value, variance, and standard deviation of discrete distribution	45
Discrete probability distributions	47
Approximating binomial problems by Poisson distribution	56
Continuous distribution	56
Z transformation	58
Planning for Sampling	66
Random Sampling versus Nonrandom Sampling	67
Random sampling	67
Nonrandom sampling	68
Nonsampling errors	68
Sampling error	68
Central Limit Theorem	69
Sampling distribution of the mean $\bar{X}$	70
Estimating the population mean with large sample sizes	71
Estimating the population mean with small sample sizes and $\sigma$ unknown $t$ -distribution	74
$\chi^2$ Distribution	77
Estimating sample sizes	80
Sample size when estimating the mean	81
Measurement Systems Analysis	82
Precision and Accuracy	86
Measurement errors due to precision	86
Variations due to accuracy	93
Gauge bias	94
Gauge linearity	96

Attribute Gauge Study	100
Assessing a Processes Ability to Meet Customers' Expectations—Process Capability Analysis	103
Process Capabilities with Normal Data	106
Estimating Sigma	106
Short-term sigma	106
Long-term sigma	107
Potential Capabilities	107
Short-term potential capabilities, $C_p$ and $C_r$	107
Long-term potential performance	109
Actual capabilities	109
Capability indices and parts per million	111
Process capability and Z transformation	111
Minitab output	115
Taguchi's capability indices $C_{PM}$ and $P_{PM}$	116
Process Capability Analysis with Nonnormal Data	121
Normality Assumption and Box-Cox Transformation	122
Process Capability Using Box-Cox Transformation	123
Process Capability Using Nonnormal Distribution	128
Lean Six Sigma Metrics	130
Six Sigma metrics	131
First time yield (FTY)	133
Lean metrics	134
Work in Progress (WIP)	141
<b>Chapter 3. Analyze</b>	<b>143</b>
Brainstorming	143
Nominal Group Process	143
Affinity Diagram	144
Cause-and-Effect Analysis	146
Pareto Analysis	149
Using Minitab	152
Fault Tree Analysis	152
Seven Types of Waste	154
Overproduction	156
Wait	157
Unnecessary inventory	158
Motion	158
Unnecessary transportation	158
Inappropriate processing	159
Product defects	159
Lean Approach to Waste Reduction	159
Cycle Time Reduction	161
Takt time	162
Batch versus one-piece flow	164
Data Gathering and Process Improvement	165
Value stream mapping	166
How to map your value stream	167

<b>Failure Mode and Effect Analysis</b>	<b>168</b>
Failure mode assessment	170
Action plan	171
Hypothesis testing	174
P-value method	177
<b>Nonparametric Hypothesis Testing</b>	<b>182</b>
Chi-square test	182
Contingency analysis—Chi square test of independence	185
The Mann-Whitney U test	187
Normality testing	195
Normalizing data	196
<b>Analysis of Variance</b>	<b>198</b>
Mean square	200
<b>Regression Analysis</b>	<b>204</b>
Simple linear regression (or first-order linear model)	206
Multiple regression analysis	210
<b>Chapter 4. Improve</b>	<b>213</b>
Design of Experiments	213
Factorial Experiments	215
Main effect and Interaction effect	216
$2^k$ Factorial design	217
$2^2$ Two factors and two levels	218
Degrees of freedom	222
Using Minitab	222
Interpretation	225
Using SigmaXL	225
Regression Model	234
SigmaXL output	236
Residual analysis	236
$2^k$ Two levels with more than 2 factors	237
Main effects for $2^3$ —two levels with three factors	239
Blocking	252
Confounding	254
$2^{k-1}$ Fractional factorial design	256
$2^{3-1}$ Fractional factorial design	258
$2^{4-1}$ Fractional design	260
Design resolution	260
The Theory of Constraints	268
The process throughput is tied to the bottleneck	271
TOC Metrics	273
Thinking Process	273
The Goldratt Cloud	274
The Goldratt Reality Trees	275
Current reality tree	276
Future reality tree	278
5s	280

<b>Chapter 5. Control</b>	<b>283</b>
<b>Statistical Process Control (SPC)</b>	<b>283</b>
Variation Is the Root Cause of Defects	284
Assignable (or special) causes of variation	285
Common (or chance) causes of variation	286
How to build a control chart	287
Rational subgrouping	288
Probability for misinterpreting control charts	289
Type I error $\alpha$	289
Type II error $\beta$	291
How to determine if the process is out of control—WECO rules	293
<b>Categories of Control Charts</b>	<b>295</b>
Variable control charts	295
The mean and range charts— $\bar{X}$ and $R$ charts	296
Calculating the sample statistics to be plotted	296
Calculating the center line and control limits	297
Control limits for $\bar{X}$ chart	298
Standard-error-based $\bar{X}$ chart	298
Mean-range-based $\bar{X}$ control charts	299
Control limits for $R$ chart	302
The mean and standard deviation charts $\bar{X}$ and $s$ charts	305
Individual Values Control Charts	309
Individual Moving Range Charts	310
Individual Value Chart	311
Monitoring Shifts in the Process Mean	313
CUSUM	314
Computational Approach	317
Exponentially Weighted Moving Average	319
<b>Attribute Control Charts</b>	<b>322</b>
The $p$ chart	324
The $np$ chart	327
The $c$ chart	329
The $u$ chart	330
<b>Appendix. Tables</b>	<b>333</b>
Table A.1 Binomial	334
Table A.2 Poisson	339
Table A.3 Chi Square	343
Table A.4 Z Table	344
Table A.5 t Table	345
Table A.6 F Table	346
<b>Index</b>	<b>347</b>