

# Catalysts and Surfaces

## Characterization Techniques

B. Viswanathan • S. Kannan • R.C. Deka



Alpha  
Science

# Contents

---

*Preface*

v

<b>1. Introduction</b>	<b>1.1-1.16</b>
References	1.15
<b>2. Surface Analytical Techniques: An Overview</b>	<b>2.1-2.8</b>
<b>3. Thermal Methods</b>	<b>3.1-3.20</b>
3.1 Surface Acidity Determination	3.4
3.2 Preparation of Catalysts – Application of Temperature Programmed Methods	3.8
3.3 Studies on the Phase Composition – TPR Studies	3.12
References	3.19
<b>4. Introduction to Electron Spectroscopy</b>	<b>4.1-4.14</b>
4.1 Composition Analysis	4.3
4.2 <i>Binding Energies and Oxidation States</i>	4.3
4.3 Final State Effects	4.6
4.4 Reference	4.7
4.5 Charging and Sample Damage	4.8
4.6 Angle Dependent XPS	4.9
4.7 Ultraviolet Photoelectron Spectroscopy	4.9
4.8 Auger Electron Spectroscopy	4.11
4.9 Inverse Photoemission Spectroscopy	4.12
Reference	4.13
<b>5. Ultraviolet Photoelectron Spectroscopy (UV-PES)</b>	<b>5.1-5.10</b>
5.1 Adsorption of Gases on Metallic Surfaces as Studied by UV-PES	5.3
5.2 Physical Adsorption of Dinitrogen on Metal Surfaces	5.6
5.3 UPS Studies of Adsorption of Carbon Monoxide on Metallic Surfaces	5.7
5.4 Determination of the Valence Band Structure of Metals	5.8
References	5.9



<b>6. Principle and Applications of Auger Electron Spectroscopy</b>	<b>6.1-6.12</b>
6.1 Deriving Quantitative Data from Auger Electron Spectra	6.5
6.2 Chemical State of the Elements	6.6
6.3 Depth Profiling	6.7
6.4 Adsorption-desorption Studies	6.9
6.5 Surface Reactions	6.10
6.6 Catalytic Activity	6.11
6.7 Comparison of the Techniques	6.11
References (Suggested Reading Material)	6.12
<b>7. Photo Electron Spectroscopy</b>	<b>7.1-7.60</b>
7.1 Introduction	7.1
7.2 Factors Complicating the XPS Spectra	7.9
7.3 Important Features of the X-ray Photo Electron Spectroscopy	7.18
7.4 XPS in Catalysis	7.27
7.5 Ultraviolet Photoelectron Spectra of Atoms	7.51
7.6 Perceptions	7.58
References	7.59
<b>8. X-ray Diffraction—Basics and Applications for Catalysts</b>	
<b>Characterization</b>	<b>8.1-8.30</b>
8.1 Introduction	8.1
8.2 Theory of Diffraction	8.2
References	8.26
<b>9. Determination of Pore Size Distribution in Solid Catalysts</b>	<b>9.1-9.18</b>
9.1 Incomplete Wetting Theory	9.3
9.2 The Bottle Neck Theory	9.3
9.3 The Open Pore Theory	9.4
9.4 Determination of Pore Size Distribution	9.6
9.5 Shull's Method	9.7
9.6 Barrett, Joyner and Halenda (BJH) Procedure	9.7
9.7 The Thickness of Adsorbed Layer in Pores	9.10
9.8 Determination of Micropore Volume and Micropore Size Distribution	9.15
9.9 Criteria of the Correctness of the Pore Size Analysis	9.16
References	9.17
<b>10. Electron Microscopy</b>	<b>10.1-10.18</b>
10.1 Electron Microscopic Studies on Carbon and Carbon Supported Catalytic Systems	10.6
10.2 Zeolites and Related Materials	10.12
10.3 Supported Catalysts	10.13
10.4 Influence of Origin of the Support on Catalyst Activity	10.14
10.5 Deactivation of Catalysts	10.14
10.6 Particle Size and Number	10.15
References	10.16

<b>11. Computer Modelling and Theoretical Aspects of Catalysts</b>	<b>11.1-11.14</b>
11.1 Introduction	11.1
11.2 Methods	11.2
11.3 Applications	11.8
11.4 Summary	11.13
References	11.13
<i>Index</i>	<i>I.1-I.4</i>