


THERMODYNAMICS OF MICROSTRUCTURES

T. Nishizawa



Contents

Preface	ix
About the Author	xi

Chapter 1 Introduction—An Overview of Microstructure in Materials 1

1.1 Matter and Materials	1
1.2 Matter Science: Its Short History	3
1.2.1 Democritus’s Atomic Theory	3
1.2.2 The Birth of Modern Chemistry	3
1.3 Establishment of Metallography	4
1.3.1 Discovery of Microstructure	4
1.3.2 From Observation to Science	7
1.4 Flowering of Materials Science	8
1.4.1 Progress of Steel Technology	8
1.4.2 Progress in Synthetic Polymers and Ceramics	9
1.4.3 Establishment and Development of Materials Science	10
Appendix: The Glass Fiber Reinforced Plastic “Magic Wand”	10

Chapter 2 Free Energy of Pure Substances 13

2.1 Energy Relating to Microstructure	13
2.1.1 Units of Energy	13
2.1.2 Energy of Atoms and Molecules and Macroscopic Energy	16
2.1.3 Heat Capacity and Enthalpy of Transformation	19
2.2 Entropy and Free Energy	23
2.2.1 Stability Condition in Thermal Equilibrium	24
2.2.2 Boltzmann Entropy Relation	27

2.2.3	Maxwell-Boltzmann Distribution Law (M-B Statistics)	29
2.3	Statistical Thermodynamics of Thermal Vibration of Crystal	32
2.3.1	Energy of Thermal Vibration	33
2.3.2	Entropy and Free Energy of Thermal Vibration	37
2.4	Thermodynamics of Magnetic Transition (Iron Hardens Twice!)	38
2.4.1	Magnetic Domain Structure of Ferromagnetic Materials	39
2.4.2	Magnetization and Magnetic Transition of Ferromagnetic Materials	39
2.4.3	Analysis of Magnetic Transition Using the Ising Model	41
2.4.4	Thermodynamics of A_3 Transformation of Pure Iron	43
2.5	Free Energy of Amorphous Phase	47
2.5.1	Is the Amorphous a Solid Phase or a Liquid Phase?	47
2.5.2	Is the Amorphous a Stable Phase or a Metastable Phase?	48
	Appendix: Synthesis of Diamond by Very High Pressure	52

Chapter 3 Thermodynamics of Solutions 55

3.1	Solutions, Mixtures, and Compounds	55
3.1.1	The Ways of Mixing of Atoms and Molecules	55
3.1.2	Components, Systems, and Composition Axes	56
3.1.3	Entropy of Solutions and Mixtures	57
3.2	Approximation of Free Energy by Regular Solution Model	60
3.2.1	Nearest-Neighbor Assumption and Random Distribution Assumption—Basic Assumptions for Bragg-Williams-Gorski (B-W-G) Model	61
3.2.2	B-W-G Approximation of Enthalpy in Solid Solution	61
3.2.3	B-W-G Approximation of Entropy in Solid Solution	65
3.2.4	B-W-G Approximation of Free Energy in Solid Solution	65

3.3	Approximation of Free Energy by Sublattice Model	67
3.3.1	Free Energy of III–V Compound Solutions	67
3.3.2	Free Energy of Interstitial Solutions	71
3.4	Chemical Potential	73
3.4.1	Partial Molar Quantity	73
3.4.2	Activity and Activity Coefficient of Solute Atoms	77
3.5	Nonrandom Distribution of Solute Atoms	81
3.5.1	I-S Bonding between Interstitial Atoms (I) and Substitutional Atoms (S)	82
3.5.2	Estimation of I-S Bonding Energy ($\Delta\varepsilon_{I-S}$)	83
	Appendix: Hume-Rothery's 15% Rule	85
Chapter 4 Thermodynamics of Phase Diagrams		91
4.1	Basic Rules of Heterogeneous Equilibrium	91
4.1.1	Common Tangent Law	91
4.1.2	Enhancement to Multicomponent Systems	93
4.1.3	Gibbs Phase Rule	97
4.2	Liquidus Line and Solidus Line	99
4.2.1	Phase Diagram of Completely Miscible Type	99
4.2.2	Liquidus Line and Solidus Line at Low Concentration Region	101
4.2.3	Primary Crystallization Line (Liquidus Line) of Compounds	103
4.3	Solubility Curve (Solid Solubility Curve)	104
4.3.1	Mutual Solubility Curve	105
4.3.2	Solubility Curve of Compound	106
4.3.3	Solubility Product of Compound	108
4.4	Binodal Curve	110
4.4.1	Miscibility Gap and Spinodal Curve	110
4.4.2	Miscibility Gap Island (MGI)	114
	Appendix: The Phase Diagram of Ceramics	121
Chapter 5 Thermodynamics of Interfaces		123
5.1	Energy of Surface and Interface	123
5.2	Gibbs-Thomson Effect	128
5.2.1	Experiment on Soap Bubbles	128
5.2.2	Transformation Temperature and Pressure of Fine Particles	129
5.2.3	Solubility of Fine Particles	131
5.3	Thermodynamics of Grain-Boundary Segregation	133
5.3.1	Monolayer Adsorption and Multilayer Adsorption	133

5.3.2	McLean's Grain-Boundary Segregation Equation	134
5.3.3	Analysis of Grain-Boundary Segregation by "Boundary Phase Model"	136
5.3.4	Relationship between Ultrarefinement of Grains and Grain-Boundary Segregation	140
5.4	"Roughness" and Mobility of Interface	142
5.4.1	Smooth Interface and Rough Interface	142
5.4.2	Adhesion Growth and Lateral Growth	146
5.4.3	Kinetic Description of Mobility of Interface	147
5.4.4	Analysis of Velocity of Solidification	149
5.5	Thermodynamics of Grain Growth	151
5.5.1	Grain Growth of Pure Substances	151
5.5.2	Solute Drag Effect	154
5.5.3	Grain-Boundary Pinning by Dispersed Particles	157
	Appendix: Transparent Sintered Alumina	165

Chapter 6 Thermodynamics of Diffusion 167

6.1	Brownian Motion and Diffusion	167
6.1.1	Random Walk Model	167
6.1.2	Einstein's Equation for Brownian Motion	170
6.2	Fick's Diffusion Laws	171
6.2.1	The First Law and the Second Law	171
6.2.2	Examples of Analysis of Diffusion Law	173
6.3	Review of Solid Phase Diffusion	177
6.3.1	Kirkendall Effect	177
6.3.2	Dependency of Interdiffusion Coefficient on Concentration	178
6.3.3	Uphill Diffusion	181
6.3.4	Thermodynamic Modification of Fick's Diffusion Laws	182
6.4	Mechanism of Diffusion and Diffusion Coefficient	185
6.4.1	Frequency Factor of Diffusion Coefficient and Activation Energy	185
6.4.2	Diffusion by Vacancy Mechanism and Interstitial Diffusion	186
6.4.3	Surface Diffusion and Grain-Boundary Diffusion	190
	Appendix: Diffusion Path	194

Chapter 7 Thermodynamics of Ordering 197

7.1	Ordering Phenomena	197
7.1.1	Ordering in Microscopic Structure	197
7.1.2	Short-Range Ordering	198
7.2	Analysis of CuZn Ordering by B-W-G Model	202
7.2.1	Sublattice and Order Parameter	202
7.2.2	Change in Enthalpy and Entropy According to Ordering	203
7.2.3	Equilibrium Order Parameter	204
7.3	Analysis of Cu ₃ Au Ordering by B-W-G Model	207
7.3.1	Degree of Order and Number of Atomic Pairs	208
7.3.2	Change in Free Energy According to Ordering	209
7.3.3	Discontinuous Change in Equilibrium Order Parameter	210
7.4	Phase Separation due to Ordering	212
7.4.1	Symbiosis of Ordering and Phase Separation	212
7.4.2	Analysis on Ordering by B-W-G Model Considering Second Nearest Neighbor Atoms	212
7.4.3	Miscibility Gap Island in Consideration of Ordering	216
Appendix: Effect of the Inversion Type of Phase Separation		222

Chapter 8 Thermodynamics of Nucleation 225

8.1	Basic Subjects of Nucleation	225
8.1.1	Small Droplets Experiment	225
8.1.2	Homogeneous Nucleation (Spontaneous Nucleation)	226
8.1.3	Heterogeneous Nucleation (Interface Nucleation)	232
8.2	Spontaneous Nucleation in Solution	235
8.2.1	Fluctuation in Concentration of Solution	235
8.2.2	Driving Force of Nucleation in a Solution	236
8.2.3	Radius and Generation Rate of Critical Nucleus in a Solution	238
8.3	Nucleation by Inoculation	241
8.3.1	Morphological Control of Primary Crystal by Inoculation	241
8.3.2	Refinement of Solidification Structure by Inoculation	244

8.4	<i>Nucleation in Solid</i>	246
8.4.1	<i>Formation of Precipitation Nuclei and Clusters</i>	247
8.4.2	<i>Formation of Guinier-Preston Zone</i>	249
	<i>Appendix: True Colors of Guinier-Preston Zone</i>	255
Chapter 9 Thermodynamics of Microstructure Change		259
9.1	<i>Outline of Microstructure Change</i>	259
9.1.1	<i>Types of Microstructure Change</i>	259
9.1.2	<i>Rate of Structure Change</i>	261
9.2	<i>Johnson-Mehl-Avrami-Kolmogorov (JMAK) Equation</i>	263
9.2.1	<i>Extended Volume of Product Phase</i>	263
9.2.2	<i>JMAK Equation for Precipitation</i>	265
9.2.3	<i>JMAK Equation for $\gamma \rightarrow \alpha$ Transformation of Steel</i>	267
9.3	<i>Thermodynamics of Eutectic Solidification and Eutectoid Transformation</i>	270
9.3.1	<i>Effective Driving Force on Eutectic-Eutectoid Transformation</i>	271
9.3.2	<i>Rate Equation of Eutectic Solidification (Volume Diffusion Model)</i>	273
9.3.3	<i>Rate Equation of Eutectoid Transformation (Interface Diffusion Model)</i>	276
9.3.4	<i>Rate Equation of Pearlite (Interface Diffusion and Interface Migration Model)</i>	278
	<i>Appendix: Carburized Pearlite</i>	284
Reference Information		287
	<i>Physical Constants</i>	287
	<i>Unit Symbols</i>	287
	<i>SI Prefixes</i>	287
	<i>Greek Alphabet</i>	287
	<i>Unit Conversion Table</i>	288
	<i>Note for Periodic Table of Elements</i>	289
	<i>Index</i>	291