


Mechanisms of Diffusional Phase Transformations in Metals and Alloys



Hubert I. Aaronson
Masato Enomoto
Jong K. Lee

 CRC Press
Taylor & Francis Group

Contents

Preface.....	xv
Authors.....	xvii

Chapter 1	Applied Thermodynamics	1
1.1	Free Energy–Composition Relationships for Binary Substitutional Solid Solutions.....	1
1.1.1	Basic Free Energy–Composition Relationship.....	1
1.1.2	Gibbs Free Energy of the Standard States of Pure Elements	1
1.1.3	Mixing Free Energy, ΔG^M	4
1.1.3.1	Fundamentals	4
1.1.3.2	Ideal Solution Approximation	7
1.1.3.3	Regular Solution Approximation.....	7
1.1.3.4	Subregular and Other-Type Solutions	12
1.1.3.5	Relationships for Partial Molar Free Energies, Phase Equilibria, and Critical Temperature.....	12
1.1.3.6	Comparison between Regular Solutions and Nonregular Solutions	16
1.2	Free Energy–Composition Diagram and Applications to Driving Force Calculations	17
1.2.1	Some Considerations on the Free Energy vs. Composition Curve.....	17
1.2.2	Total Free Energy Change Attending Precipitation	21
1.2.3	Free Energy Change Attending the Precipitation of a Small Amount of α	24
1.2.4	Division of the Total Free Energy Change between Capillarity and Diffusion.....	25
1.2.5	Influence of Capillarity upon Solubility.....	27
1.2.6	Division of ΔG between Diffusion and Uniform Interfacial Reaction.....	29
1.2.7	Permissible Range of Nonequilibrium Precipitate Compositions	30
1.3	Thermodynamics of Interstitial Solid Solutions through Application to the Proeutectoid Ferrite Reaction in Fe–C Alloys	31
1.3.1	Introduction	31
1.3.2	Free Energy and Positional Entropy of Ideal Interstitial Solid Solutions	32
1.3.3	Free Energy and Positional Entropy of Nonideal Interstitial Solid Solution.....	33
1.3.4	Evaluation of Constants in a Partial Molar Free Energy Equation	35
1.3.5	Application of Partial Molar Free Energy Equations.....	36
1.3.5.1	Calculation of the $\gamma/(\alpha + \gamma)$ or Ae_3 Phase Boundary.....	36
1.3.5.2	Driving Force for the Massive Transformation in Fe–C Alloys.....	37
1.3.5.3	Driving Force for the Precipitation of Proeutectoid Ferrite	37
1.3.5.4	Graphical Presentations of the Results of Sections 1.3.5.1 through 1.3.5.3.....	38

1.3.6	Interpretation of z in Terms of Carbon–Carbon Interaction Energy.....	39
1.3.7	More Sophisticated Treatments of Interstitial Statistical Thermodynamics	41
	References	46
Chapter 2	Diffusional Nucleation in Solid–Solid Transformations.....	49
2.1	Introduction through Qualitative General Statements	49
2.2	Brief Comparative Survey of Nucleation in the Four Basic Types of Phase Transformation.....	52
2.2.1	Vapor-to-Liquid Transformation	52
2.2.2	Vapor-to-Solid Transformation	52
2.2.3	Liquid-to-Solid Transformation (Solidification)	52
2.2.4	Solid-to-Solid Transformation.....	53
2.2.5	General Remarks	53
2.3	Outline of Approach for Development of Nucleation Theory	53
2.4	Proof That the Equilibrium Concentration of Critical Nuclei Is Proportional to $\exp(-\Delta G^*/kT)$	53
2.5	Fictitious Equilibrium Nucleation Rate	55
2.6	Derivation of Steady-State Nucleation Rate.....	55
2.7	Estimation of β^*	59
2.8	Time-Dependent Nucleation Rate	59
2.9	Feder et al.'s Treatment of τ	63
2.9.1	Relationships for δ and for τ_δ	64
2.9.2	Relationship for τ'	65
2.9.3	Total Value of τ	66
2.10	Time-Dependent Nucleation Rate for Homogeneous Nucleation with Isotropic γ	66
2.10.1	Introduction	66
2.10.2	Activation Energy of Nucleation ΔG^*	67
2.10.2.1	Introduction to the Critical Nucleus Shape Problem.....	67
2.10.2.2	G - x Diagram Approach	67
2.10.2.3	Introduction to the Volume Strain Energy Incorporation Problem	68
2.10.2.4	Conventional Gibbsian Approach.....	69
2.10.2.5	Wulff Volume Approach for ΔG^*	69
2.10.2.6	Nucleus Volume Approach for ΔG^*	71
2.10.3	Frequency Factor β^*	72
2.10.4	Zeldovich Factor, Incubation Time and the Re-Derivation of Frequency Factor	72
2.10.5	Nucleation Site Density, N	75
2.10.6	Time-Dependent Nucleation Rate	75
2.11	Ancillary Parameters.....	75
2.11.1	Volume Diffusivity.....	75
2.11.2	Volume Free Energy Change	76
2.11.3	Volume Strain Energy	79
2.11.3.1	Elementary Calculation of Dilatational Strain Energy for a Plate-Shaped Nucleus.....	80
2.11.3.2	Volume Strain Energy of Fully Coherent Precipitates	82

2.11.3.3	Volume Strain Energy of Incoherent Precipitates	89
2.11.3.4	Volume Shear Strain Energy	90
2.11.3.5	Unsolved Major Problems in Volume Strain Energy	91
2.11.4	Interfacial Energy	91
2.11.4.1	Scope.....	91
2.11.4.2	Energy of Coherent Interphase Boundaries.....	92
2.11.4.3	Energy of Partially Coherent Interphase Boundaries	125
2.11.4.4	Energy of Disordered Interphase Boundaries.....	126
2.12	Preliminary Consideration of the Approximation for $\phi = \Delta G_v + W$	132
2.13	Nonclassical Nucleation Theory.....	134
2.13.1	Continuum Theory	134
2.13.1.1	General Introduction	134
2.13.1.2	Calculation of the Nonclassical ΔG^*	135
2.13.1.3	General Properties of the Critical Nucleus.....	140
2.13.1.4	Nucleation in a Regular Solution	149
2.13.1.5	Applicability Region of Classical Theory	155
2.13.2	Discrete Lattice Point Theory.....	156
2.14	Modifications of Homogeneous Nucleation Kinetics by Anisotropic Interfacial Energy	159
2.14.1	Equilibrium Shape Problem	159
2.14.1.1	Rudimentary Solution of the Equilibrium Shape Problem	160
2.14.1.2	γ -Plot and Some Properties	161
2.14.1.3	Wulff Construction	163
2.14.1.4	Simple Approach to Calculation of γ -Plots.....	164
2.14.1.5	Wulff Construction of Equilibrium Shape vs. Temperature in a Regular Solution, fcc Miscibility Gap	165
2.14.2	Sphere Faceted at One Boundary Orientation.....	169
2.14.2.1	γ -Plot and Force Balance	170
2.14.2.2	Calculation of r^* and ΔG^*	171
2.14.2.3	Calculation of β^*	173
2.14.2.4	Calculation of Zeldovich Factor, Z , and Incubation Time, τ	174
2.14.3	Nonspherical Critical Nucleus Shapes with a Finite Number of Interfacial Energies and Analytically Describable Interfaces	179
2.15	Nucleation Kinetics at the Faces of Disordered Grain Boundaries	180
2.15.1	Introductory Comments on Grain Boundary Geometry and Structure.....	180
2.15.2	Equilibrium Shape Problem at Grain Boundaries.....	180
2.15.3	Shape-Dependent Nucleation Kinetics Factors for the Two Spherical Cap Nucleus with Isotropic $\gamma_{\alpha\beta}$	182
2.15.3.1	ΔG^* and R^*	182
2.15.3.2	β^* , Z , τ , and Transport by Interfacial Diffusion	183
2.15.4	Nucleation Kinetics of the Double Spherical Cap Faceted at One Boundary Orientation	184
2.15.4.1	When $\phi \leq \phi_{c_1}$ and $\gamma_{\alpha\beta}^c > \gamma_{\beta\beta}/2$	184
2.15.4.2	Two-Dimensional Nuclei.....	185
2.15.4.3	Three-Dimensional Nuclei When $\phi > \phi_{c_1}$	191

2.16	Comparative Nucleation Kinetics at Grain Faces, Edges, and Corners Relative to Homogeneous Nucleation: Trade-Offs between N and ΔG^* When $\gamma_{\alpha\beta}$ Is Isotropic.....	196
2.17	Nucleation at Dislocations.....	201
2.17.1	Incoherent Nucleation.....	202
2.17.1.1	The Cahn Treatment.....	202
2.17.1.2	The Gomez-Ramirez and Pound Treatment.....	205
2.17.2	Coherent Nucleation.....	210
2.18	Comparisons of Theory and Experiment.....	211
2.18.1	Homogeneous Nucleation.....	211
2.18.1.1	Homogeneous Nucleation of Co-Rich Precipitates in Cu-Rich Cu-Co Alloys.....	212
2.18.1.2	Homogeneous Nucleation of Ni_3Al Precipitates in Ni-Rich Ni-Al Alloys.....	226
2.18.1.3	Homogeneous Nucleation in Liquids.....	228
2.18.2	Nucleation at Grain Boundaries.....	230
2.18.2.1	Nucleation of Proeutectoid Ferrite at Austenite Grain Boundaries in Fe-C Alloys.....	230
2.18.3	Nucleation at Grain Faces vs. Grain Edges.....	238
2.18.4	Nucleation at Dislocations.....	239
2.18.5	Secondary Sideplate Selectivity.....	244
	References.....	245

Chapter 3	Diffusional Growth.....	249
3.1	Basic Differences between Diffusional Nucleation and Diffusional Growth.....	249
3.2	A General Theory of Precipitate Morphology.....	249
3.3	Disordered Interphase Boundaries.....	252
3.3.1	Introduction.....	252
3.3.2	Volume Diffusion-Controlled Growth Kinetics.....	253
3.3.2.1	Mathematics for Diffusion and Flux Equations.....	253
3.3.2.2	Comparisons with Experiment.....	303
3.3.3	Growth Faster than Volume Diffusion Control Allows.....	332
3.3.3.1	Grain Boundary Allotriomorphs.....	332
3.3.3.2	Dissolution of Grain Boundary Allotriomorphs.....	340
3.3.3.3	Plate Lengthening.....	342
3.3.4	Growth Slower than Volume Diffusion Control Allows.....	343
3.4	Partially and Fully Coherent Interphase Boundaries.....	347
3.4.1	Introduction.....	347
3.4.2	Misfit Dislocations at Partially Coherent Interphase Boundaries ...	347
3.4.2.1	Theory.....	347
3.4.2.2	Comparisons of Theory and Experiment.....	354
3.4.3	Acquisition of the Misfit Dislocation Structure of Partially Coherent Interphase Boundaries.....	368
3.4.3.1	Theory.....	368
3.4.3.2	Comparisons of Theory with Experiment.....	378
3.4.4	Growth Ledges at Partially and Fully Coherent Interphase Boundaries.....	386
3.4.4.1	Prevalence and Role in Interface Crystallography.....	386
3.4.4.2	Visibility Conditions for Ledges.....	387

3.4.4.3	Sources of Ledges.....	389
3.4.4.4	Ledge Heights.....	394
3.4.4.5	Inter-Ledge Spacings.....	395
3.4.5	Structural Ledges at Partially Coherent Interphase Boundaries.....	397
3.4.6	Migration of Partially and Fully Coherent Interphase Boundaries by Growth Ledges.....	409
3.4.6.1	Theory.....	409
3.4.6.2	Comparison of Theory and Experiment for Growth of Lileged Interphase Boundaries.....	419
3.5	Relative Growth Kinetics of Disordered and Partially Coherent Interphase Boundaries.....	425
	References.....	427

Chapter 4	Precipitation.....	433
4.1	Introduction.....	433
4.2	Metastable Equilibrium Phase Boundaries.....	433
4.2.1	Types of Metastable Equilibrium Phases.....	433
4.2.2	Calculation of Metastable Equilibrium Phase Boundaries.....	435
4.3	GP Zones.....	438
4.3.1	Definition.....	438
4.3.2	Early History and Methods of Experimental Detection.....	438
4.3.3	GP Zone Solvus Curves.....	442
4.3.4	Description of GP Zones: Morphology, Size, Number Density, and Composition.....	444
4.3.5	Kinetics of GP Zone Formation.....	448
4.3.6	Origins of GP Zone Formation.....	451
4.4	Transition Phases.....	458
4.4.1	Definition and Basic Characteristic.....	458
4.4.2	Occurrence and Thermodynamics.....	459
4.4.3	Crystallography.....	459
4.4.4	Nucleation Sequence of Transition Phases.....	462
4.4.4.1	From the Viewpoint of ΔG_v	463
4.4.4.2	From the Viewpoint of Interfacial Energy.....	463
4.4.4.3	Nucleation Sites of Successive Transition Phases.....	464
4.5	Nucleation Sites.....	465
4.5.1	Homogeneous Nucleation.....	465
4.5.2	Nucleation at Large-Angle Grain Boundaries.....	466
4.5.3	Nucleation Kinetics at Small-Angle Boundaries.....	467
4.5.4	Nucleation at Dislocations.....	469
4.5.4.1	General Remarks.....	469
4.5.4.2	Stacking Fault Nucleation and Edgewise Growth.....	469
4.5.4.3	Nucleation on Displaced and Freshly Generated Dislocations.....	470
4.5.5	Nucleation at Point Defect Clusters.....	472
4.5.6	Nucleation on Precipitates.....	475
4.5.6.1	Nucleation on Precipitates of a Different Phase.....	475
4.5.6.2	Sympathetic Nucleation.....	478
4.6	Successive Reactions Involving Different Phases.....	478
4.7	Precipitate Free Zones.....	479

4.8	Coarsening (Ostwald Ripening)	482
4.9	Overall Evolution of the Microstructure	488
4.9.1	Effects of the Ratio of Growth Rates of Disordered-to-Partially Coherent Boundaries	488
4.9.2	Effects of Diffusion Distance-to-Matrix Grain Radius Ratio	488
4.9.3	Effects of the Lever Rule and of Nucleation-to-Growth Rate Ratio	490
	References	491
Chapter 5	Massive Transformation	495
5.1	Definition and History	495
5.2	Phase Diagrams	495
5.3	Thermodynamics	497
5.3.1	Free Energy Composition Diagram.....	497
5.3.2	Experimental Evaluation of Enthalpy Change Associated with Massive Reaction	497
5.4	Overall Reaction Kinetics and the Existence Range.....	499
5.5	Nucleation of Massive Transformation	508
5.5.1	Nucleation during Continuous Cooling	508
5.5.2	Nucleation during Isothermal Transformation	514
5.5.3	Nucleation Sites and Massive Crystal Morphology.....	516
5.6	Growth Kinetics.....	523
5.6.1	Theory.....	523
5.6.1.1	Disordered Interphase Boundaries.....	523
5.6.1.2	Partially Coherent Interphase Boundaries	524
5.6.2	Comparison with Experiment.....	525
5.7	Interfacial Structure, Habit Planes, Orientation Relationships, and Growth Mechanisms.....	532
5.8	Note on the Driving Force for Trans-Interphase Boundary Diffusion during Massive Transformation in a Two-Phase Field.....	540
	References	541
Chapter 6	Cellular Reaction	543
6.1	Definition and Introduction	543
6.2	Systematics of Cellular Reactions	545
6.3	Nucleation of Cellular Reactions.....	552
6.3.1	Crystallography-Based Mechanisms	552
6.3.1.1	Tu–Turnbull Replacive Mechanism	552
6.3.1.2	Proposals of Aaronson and Aaron.....	554
6.3.2	Noncrystallographic Mechanism of Fournelle and Clark	555
6.3.3	Other Mechanisms for Inducing Grain Boundary Motion before and during Cellular Reaction, Including DIGM	556
6.4	Growth Kinetics of Cells.....	561
6.4.1	Introductory Comments.....	561
6.4.2	Turnbull Theory of Cell Growth Kinetics.....	562
6.4.3	Cahn Theory of Cell Growth Kinetics.....	564
6.4.4	Comparisons with the Experiment of the Turnbull and Cahn Theories.....	567

	6.4.5	Hillert Theory of Growth Kinetics.....	570
	6.4.6	Volume versus Boundary Diffusion Control and Interactions with Continuous Precipitation.....	572
		References	573
Chapter 7		Pearlite Reaction.....	575
	7.1	Systematics	575
	7.1.1	Definition.....	575
	7.1.2	Pearlite in the Context of Eutectoid Decomposition Products.....	575
	7.1.3	Occurrence of Pearlite	575
	7.1.3.1	In Steel.....	575
	7.1.3.2	In Other Alloy Systems	575
	7.1.4	Preliminary Discussion of Pearlite Nucleation	576
	7.1.5	Morphology of Pearlite	576
	7.2	Crystallography, Nucleation, and Growth Mechanisms.....	582
	7.2.1	Hull and Mehl Concept.....	582
	7.2.2	Hillert Concept	584
	7.2.3	Reprise.....	586
	7.3	Edgewise Growth Kinetics of Pearlite	588
	7.3.1	Comparative Thermodynamics with Cellular Reaction	588
	7.3.2	Role of Growth in Pearlite Reaction.....	589
	7.3.3	Approximate Treatments of Edgewise Growth.....	590
	7.3.3.1	Volume Diffusion–Controlled Growth.....	590
	7.3.3.2	Growth Controlled by Diffusion along Colony Boundary.....	592
	7.3.4	Improved Treatments.....	593
	7.3.4.1	Volume Diffusion–Controlled Growth.....	593
	7.3.4.2	Boundary Diffusion–Controlled Growth.....	594
	7.3.5	Experimental Measurements for Growth Kinetics Studies	595
	7.3.5.1	Interlamellar Spacing	595
	7.3.5.2	Rate of Growth	595
	7.3.6	Comparisons of Theory and Experiment and the Problem of S	596
		References	599
Chapter 8		Martensitic Transformations.....	601
	8.1	Definition.....	601
	8.2	Salient Characteristics (Described Briefly).....	601
	8.2.1	Crystallography	601
	8.2.2	Morphology	601
	8.2.3	Surface Relief Effects.....	602
	8.2.4	Time-Dependence of Martensite Formation	602
	8.2.5	Temperature Dependence of Martensite Formation.....	604
	8.2.6	Reversibility.....	606
	8.2.7	Influence of Applied Stress	606
	8.2.8	Thermal Stabilization	608
	8.3	Thermodynamics of Martensite Transformation	608
	8.3.1	T_0 Temperature.....	608
	8.3.2	Difference between T_0 and M_s	612

8.4	Overall Kinetics of Martensite Transformation.....	615
8.4.1	Qualitative Kinetics	615
8.4.2	Quantitative Kinetics	615
8.4.2.1	Anisothermal Martensite Formation	615
8.4.2.2	Isothermal Martensite Formation.....	617
8.5	Nucleation of Martensite	620
8.6	Crystallography and Growth (or Propagation) of Martensite	622
8.6.1	Physics of Phenomenological Theory of Martensite Crystallography	622
8.6.2	Comparisons with Experiment	625
	References	632
Chapter 9	Bainite Reaction and Role of Shear in Diffusional Phase Transformations.....	635
9.1	Introduction.....	635
9.2	Three Definitions of Bainite	635
9.2.1	Generalized Microstructural Definition	635
9.2.2	Kinetic Definition of Bainite	643
9.2.3	Surface Relief Definition of Bainite.....	649
9.3	Upper Bainite versus Lower Bainite, and Inverse Bainite.....	651
9.4	Sources of Carbide Precipitation	651
	References	654
	Further Readings	655
Index		657