

**INSTRUMENTATION AND MEASUREMENT SERIES**



# **Applied Metrology for Manufacturing Engineering**

**Ammar Grous**

**ISE**

 **WILEY**

# Table of Contents

<b>Chapter 1. Fundamentals of Error Analysis and their Uncertainties in Dimensional Metrology Applied to Science and Technology . . . . .</b>	<b>1</b>
1.1. Introduction to uncertainties in dimensional metrology . . . . .	1
1.2. Definition of standards . . . . .	4
1.3. Definition of errors and uncertainties in dimensional metrology . . . . .	9
1.3.1. What is the difference between error and uncertainty? . . . . .	10
1.3.2. Why make a calculation of errors' uncertainty? . . . . .	11
1.3.3. Reminder of basic errors and uncertainties . . . . .	11
1.3.4. Properties of uncertainty propagation . . . . .	13
1.3.5. Reminder of random basic variables and their functions . . . . .	14
1.3.6. Properties of random variables of common functions . . . . .	15
1.4. Errors and their impact on the calculation of uncertainties . . . . .	15
1.4.1. Accidental or fortuitous errors . . . . .	15
1.4.2. Systematic errors . . . . .	16
1.4.3. Errors due to apparatus . . . . .	18
1.4.4. Errors due to the operator . . . . .	18
1.4.5. Errors due to temperature differences . . . . .	18
1.4.6. Random errors . . . . .	21
1.5. Applications based on errors in dimensional metrology . . . . .	35
1.5.1. Absolute error $ \delta  = E_a$ . . . . .	35
1.5.2. Relative error $\delta = E_r$ . . . . .	35
1.5.3. Systematic error . . . . .	36
1.5.4. Accidental error (fortuitous error) . . . . .	36
1.5.5. Expansion effect on a bore/shaft assembly . . . . .	36
1.6. Correction of possible measurement errors . . . . .	42
1.6.1. Overall error and uncertainty . . . . .	45
1.6.2. Uncertainty due to calibration methods . . . . .	46
1.6.3. Capability of measuring instruments . . . . .	47

1.7. Estimation of uncertainties of measurement errors in metrology . . . . .	48
1.7.1. Definitions of simplified equations of uncertainty measurements . . . . .	48
1.7.2. Issue of mathematical statistics evaluation of uncertainties in dimensional metrology . . . . .	49
1.7.3. Uncertainty range, coverage factor k and range of relative uncertainty . . . . .	51
1.8. Approaches for determining type A and B uncertainties according to the GUM . . . . .	53
1.8.1. Introduction . . . . .	53
1.8.2. Properties . . . . .	54
1.8.3. Brief description of type-A uncertainty evaluation method . . . . .	57
1.8.4. Type-B uncertainty methods . . . . .	59
1.9. Principle of uncertainty calculation: types A and B . . . . .	69
1.9.1. Error on the repeated measure: calculation of compound standard uncertainty . . . . .	71
1.9.2. Applications on the laboratory calculations of uncertainties . . . . .	74
1.9.3. Simplified models for the calculations of measurement uncertainties . . . . .	75
1.9.4. Laboratory model of dimensional metrology . . . . .	79
1.9.5. Measurement uncertainty evaluation discussion . . . . .	79
1.9.6. Contribution of the GUM in dimensional metrology . . . . .	81
1.10. Summary . . . . .	82
1.11. Bibliography . . . . .	83
<b>Chapter 2. Fundamentals of Dimensional and Geometrical Tolerances According to ISO, CSA (Canada), and ANSI (USA) . . . . .</b>	<b>85</b>
2.1. Introduction to geometrical products specification . . . . .	85
2.2. Dimensional tolerances and adjustments . . . . .	89
2.2.1. Adjustments with clearance: Ø80 H8/f7 . . . . .	91
2.2.2. Adjustments with uncertain clearance: Ø80 H7/k6 . . . . .	91
2.2.3. Adjustments with clamping or interference . . . . .	91
2.2.4. Approach for the calculation of an adjustment with clearance . . . . .	93
2.2.5. Dimensioning according to ANSI and CSA . . . . .	94
2.2.6. Definition of geometrical form constraints . . . . .	96
2.3. International vocabulary of metrology . . . . .	97
2.3.1. Local nominal dimensions according to ISO/DIS 14660-1996 . . . . .	97
2.3.2. Definition of the axis extracted from a cylinder or a cone . . . . .	98
2.3.3. Definition of the local size extracted from a cylinder . . . . .	99

2.3.4. Definition of local size extracted from two parallel surfaces . . . . .	100
2.3.5. Notion of simulated element and associated element . . . . .	101
2.4. GPS standard covering ISO/TR14638-1995 . . . . .	103
2.4.1. Principle of independency according to ISO 8015-1985 (classic case) . . . . .	103
2.4.2. Envelope requirement according to ISO 8015 . . . . .	104
2.4.3. Maximum material principle according to ISO 2692-1988 (classic case) . . . . .	106
2.4.4. Form tolerances . . . . .	108
2.4.5. Flatness tolerances . . . . .	109
2.4.6. Straightness tolerance . . . . .	109
2.4.7. Roundness . . . . .	111
2.4.8. Cylindricity . . . . .	112
2.4.9. Orientation tolerances . . . . .	113
2.4.10. Parallelism (straight line/straight line) . . . . .	114
2.4.11. Parallelism plane/plane (plane/straight line) on CMM . . . . .	116
2.4.12. A workshop exercise on dimensional metrology . . . . .	118
2.4.13. Angularity . . . . .	119
2.4.14. Positioning tolerances . . . . .	119
2.4.15. Tolerance of single radial flap (radial runout) . . . . .	127
2.4.16. Tolerance of single axial flap (axial runout) . . . . .	127
2.4.17. Zone of tolerance applied to a restricted portion of the piece (as in // and in □) . . . . .	130
2.4.18. Projected tolerance zone according to ISO 10578 (classic case) . . . . .	131
2.5. Conicity according to ISO 3040-1990 . . . . .	136
2.5.1. Conicity calculation: slope, $\tan(\alpha)$ , large and small diameter . . . . .	138
2.6. Linear dimensional tolerances . . . . .	139
2.6.1. Consequence: “size” tolerancing . . . . .	141
2.6.2. Consequence: independency with regard to the form . . . . .	142
2.7. Positioning a group of elements . . . . .	143
2.8. GPS standards according to the report CR ISO/TR14638 of 1996 . . . . .	145
2.9. Rational dimensioning for a controlled metrology: indices of capability and performance indices statistical process specification . . . . .	147
2.10. Summary and discussion . . . . .	159
2.11. Bibliography . . . . .	161
<b>Chapter 3. Measurement and Controls Using Linear and Angular Standards . . . . .</b>	<b>163</b>
3.1. Key dimensional metrology standards . . . . .	163
3.1.1. Time and frequency standards . . . . .	164
3.1.2. Force and pressure standards . . . . .	165

3.1.3. Electrical standards . . . . .	165
3.1.4. Temperature standards . . . . .	166
3.1.5. Photometric standards . . . . .	166
3.1.6. Measurement, comparison, and control . . . . .	166
3.2. Meter, time, and mass . . . . .	168
3.2.1. The meter . . . . .	168
3.2.2. Time . . . . .	169
3.2.3. Mass . . . . .	170
3.3. Deformations and mechanical causes of errors . . . . .	170
3.3.1. Quantitative assessment of gauge blocks . . . . .	170
3.3.2. Assessment of cylindrical rod and ball gauges (spheres). Local crashing of cylindrical rods $K_1$ . . . . .	172
3.3.3. Recommendations for correct block staking . . . . .	173
3.3.4. Punctual contact (spherical buttons, beads, and thread flanks of a thread buffer) $K_2^\circ$ . . . . .	174
3.3.5. Total flattening of cylindrical gauges ( $k_p$ ) . . . . .	175
3.3.6. Total flattening of balls (spheres) $K_{sph}$ . . . . .	176
3.3.7. Measurement and precision with micrometer . . . . .	177
3.4. Marble, V-blocks, gauge blocks, and dial gauges . . . . .	180
3.4.1. Control of flat surfaces on marble . . . . .	180
3.4.2. Measurement by comparison of small marble surfaces . . . . .	180
3.4.3. V-shaped block . . . . .	182
3.4.4. Parallel blocks . . . . .	183
3.5. Dial gauge . . . . .	185
3.5.1. Mechanical dial gauges with inside and outside contacts . . . . .	188
3.5.2. Sizes of fixed dimensions, or Max–Min . . . . .	189
3.5.3. Bore gauges . . . . .	189
3.5.4. Bore gauges . . . . .	191
3.5.5. Plain rings . . . . .	191
3.5.6. Spindle bores . . . . .	192
3.5.7. Inside gauges (micrometer) . . . . .	193
3.5.8. Depth gauges . . . . .	195
3.5.9. Telescopic bore gauges . . . . .	196
3.6. Example of a laboratory model . . . . .	199
3.6.1. Table of experimental measurements . . . . .	199
3.7. Precision height . . . . .	200
3.7.1. Directions for use of height masters (or height gauges) . . . . .	201
3.7.2. Adjustable parallel gauge blocks and holding accessories . . . . .	201
3.7.3. Example of a laboratory model . . . . .	203
3.7.4. Table of experimental measurements . . . . .	203
3.7.5. Precision height gauge check master . . . . .	204
3.7.6. Caliper gauge control . . . . .	205
3.8. The universal protractor vernier . . . . .	205

3.8.1. Direct angle measurement . . . . .	207
3.8.2. Indirect angular measurement . . . . .	208
3.8.3. Vernier height gauge . . . . .	208
3.8.4. Gear tooth vernier caliper . . . . .	209
3.9. Vernier calipers . . . . .	211
3.9.1. Various measurements of a dimension using a caliper . . . . .	213
3.9.2. Possible errors when using a caliper . . . . .	214
3.10. Micrometer or Palmer . . . . .	216
3.10.1. Principle of micrometric screw . . . . .	217
3.10.2. Manipulations to perform a measurement with a Palmer . . . . .	217
3.10.3. Adjusting micrometers . . . . .	220
3.10.4. Control of parallelism and flatness of the micrometer's measuring surfaces using optical glass . . . . .	221
3.10.5. Measurement of screw threads by three-wire method . . . . .	226
3.10.6. Ruler and gauges for the control of screw threads . . . . .	228
3.10.7. Micrometer with fine point . . . . .	229
3.10.8. Disc micrometers to measure shoulder distances . . . . .	230
3.10.9. Outside micrometer caliper type . . . . .	231
3.11. Summary . . . . .	234
3.12. Bibliography . . . . .	235
<b>Chapter 4. Surface Control . . . . .</b>	<b>237</b>
4.1. Control and measurement of angles . . . . .	237
4.1.1. Angles defects . . . . .	239
4.2. Surfaces of revolution . . . . .	241
4.2.1. Fundamentals of the analysis of conical surfaces control . . . . .	243
4.2.2. Control by comparison to a standard . . . . .	245
4.2.3. Using the buffer and the cone-shaped ring . . . . .	246
4.2.4. Measuring angles with gauges and balls . . . . .	246
4.2.5 Principle of measurement called "sine" . . . . .	253
4.2. Metric thread (M) measurement on gauge . . . . .	258
4.3.1. Laboratory control of the conicity with balls and gauges . . . . .	259
4.4. Controls of cones on machine-tools . . . . .	261
4.4.1. Method of swivel slide . . . . .	261
4.4.2. Method of lateral displacement of the tailstock of a lathe . . . . .	263
4.5. Control of flat surfaces . . . . .	264
4.5.1. Properties of a dihedron . . . . .	265
4.5.2. Control of large flat surfaces . . . . .	266
4.6. Control of cylindrical surfaces (of revolution) . . . . .	270
4.6.1. Cylindrical surface . . . . .	270
4.6.2. Associated definitions . . . . .	270
4.6.3. Cylindricity defects . . . . .	271

4.6.4. Control of a cylinder on three contact tips on a V-block . . . . .	272
4.6.5. Practical control of the straightness of the generatrix of a cylinder . . . . .	280
4.6.6. Control of the perpendicularity of the generatrix and the drive circle . . . . .	280
4.7. Control of surfaces of revolution with spherical forms . . . . .	281
4.7.1. Description and functioning of a spherometer . . . . .	282
4.7.2. Laboratory (workshop) simulated on the appropriate use of spherometer . . . . .	284
4.7.3. Control and measurement with spherometer (second approach) . . . . .	285
4.7.4. Generating a spherical surface . . . . .	287
4.8. Control of the relative positions of surfaces . . . . .	290
4.8.1. Control of parallelism for surfaces or edges . . . . .	291
4.8.2. Control of parallelism for two dihedral edges . . . . .	291
4.8.3. Control of the angular position of surfaces, distance between the axis of a bore and the plane . . . . .	292
4.8.4. Control of distance between the sphere center and the plane . .	293
4.8.5. Control of the position of the edge of a dihedron . . . . .	294
4.9. Methods of dimensional measurement . . . . .	294
4.9.1. Direct method (calibration curve) . . . . .	294
4.9.2. Indirect method (by comparison or differential) . . . . .	294
4.9.3. Indirect method known under the term “at zero” . . . . .	295
4.9.4. Measurement of flatness defect . . . . .	296
4.9.5. Method for measuring flatness deviation . . . . .	296
4.9.6. Operating procedure for flatness deviation measurement . .	299
4.9.7. Relative position of measuring instruments and the workpiece .	302
4.9.8. Control of the perpendicularity of a line to a plane . . . . .	303
4.9.9. Relative position of measuring instruments and the workpiece .	305
4.9.10. Other controls of dimensions in relative positions . . . . .	305
4.9.11. Direct measurement of an intrinsic dimension using micrometer . . . . .	306
4.9.12. Summary on relative positions . . . . .	307
4.10. Bibliography . . . . .	308
<b>Chapter 5. Opto-Mechanical Metrology . . . . .</b>	<b>309</b>
5.1. Introduction to measurement by optical methods . . . . .	309
5.1.1. Description of profile projector (type Mitutoyo PH-350H) . . .	309
5.1.2. Presentation of the main operating functions of GEOCHECK .	312
5.1.3. Selecting the point of origin (preset operation, zero reset) . .	313
5.1.4. The main functions of optical comparator . . . . .	315
5.1.5. Metrology laboratories on profile projector . . . . .	318

5.1.6. Plates measurement standards for profile projector . . . . .	321
5.2. Principle of interferential metrology (example: prism spectroscope) . . . . .	322
5.2.1. Function of two sine-waves interference . . . . .	323
5.2.2. Statistical description . . . . .	324
5.3. Flatness measurement by optical planes . . . . .	325
5.4. Principle of interferoscope . . . . .	326
5.5. Control of parallelism (case of parallel gauge-blocks) . . . . .	330
5.5.1. Numerical example of laboratory . . . . .	336
5.6. Conclusion . . . . .	339
5.7. Bibliography . . . . .	340
<b>Chapter 6. Control of Surface States . . . . .</b>	<b>341</b>
6.1. Introduction to surface states control for solid materials . . . . .	341
6.1.1. Terminology and definition of surface states criteria . . . . .	343
6.1.2. Surface states (texture) and sampling lengths . . . . .	345
6.1.3. Waviness parameters . . . . .	346
6.2. Instruments for measuring surface state . . . . .	348
6.2.1. Selecting cutoff for roughness measurements . . . . .	348
6.3. Symbols used in engineering drawings to describe the appropriate surface state according to ANSI/ASME Y14. 36M-1996 . . . . .	349
6.3.1. Surface characteristics in a drawing using CAD–CAO software . . . . .	351
6.3.2. Expressions of the terms of surface roughness . . . . .	355
6.3.3. Description of the main surface states . . . . .	358
6.4. Presentation of Mitutoyo Surftest 211 . . . . .	362
6.4.1. Components of rugosimeter 211 . . . . .	362
6.4.2. Calibration of Mitutoyo rugosimeter 211 . . . . .	365
6.4.3. Measurement . . . . .	365
6.4.4. Practical example on the application of Surftest 211 . . . . .	365
6.4.5. Portable rugosimeter SJ-400 of Mitutoyo . . . . .	367
6.5. The main normalized parameters of surface states used in the industry, their formulas and definitions . . . . .	370
6.5.1. Waviness parameters . . . . .	372
6.6. Example on the control of the roughness of a plate grade 6061 . . . . .	383
6.6.1. Questionnaire and laboratory approach . . . . .	385
6.6.2. Table of calibrated measurement results in [micrometer] and [microinch] . . . . .	386
6.6.3. Plotting using MathCAD Software . . . . .	386
6.6.4. Plotting with the aid of MathCAD . . . . .	388
6.6.5. Graphical results of arithmetic means $R_a$ . . . . .	390
6.6.6. Discussions . . . . .	390

6.7. Calculations of the overall uncertainty in the GUM method compared to the Monte Carlo method using the software GUMic . . . . .	391
6.8. Summary . . . . .	392
6.9. Bibliography . . . . .	393
<b>Chapter 7. Computer-Aided Metrology-CAM . . . . .</b>	<b>395</b>
7.1. Coordinate-measuring machine (CMM) . . . . .	395
7.1.1. Morphology of the CMM . . . . .	395
7.1.2. The CMM and its environment . . . . .	397
7.1.3. Advantages of CMM in metrology . . . . .	398
7.2. Commonly-used geometric models in dimensional metrology . . . . .	399
7.2.1. Constructive solid geometry models . . . . .	400
7.2.2. Boundary representation models (B-REP) . . . . .	401
7.2.3. Hybrid models CSG/B-REP (solid + surfaces) . . . . .	401
7.2.4. NURBS (Non-Uniform Rational Beta-Splines) . . . . .	402
7.2.5. TTRS (Technologically and Topologically Related Surfaces) models . . . . .	406
7.2.6. Real forms, real geometric elements, real geometrical surfaces . . . . .	409
7.3. Nominal geometric elements . . . . .	411
7.3.1. Modeling the ideal geometric form of a workpiece . . . . .	411
7.3.2. Model of real geometric elements, reference surface (SR) . . . . .	412
7.3.3. Substitution surfaces models . . . . .	412
7.4. Description of styli and types of probing . . . . .	415
7.4.1. Styli with ruby ball . . . . .	415
7.4.2. Hemispherical-ended styli . . . . .	416
7.4.3. Sharp styli or styli with small radius . . . . .	416
7.4.4. Disc styli (or simply discs) . . . . .	416
7.4.5. Cylindrical stylus . . . . .	417
7.4.6. Accessories and styli extensions . . . . .	417
7.5. Software and computers supporting the CMM . . . . .	420
7.5.1. Geometric control . . . . .	420
7.5.2. Surface control . . . . .	420
7.5.3. Coordinates systems and probes calibration . . . . .	421
7.6. Starting a B504B-Mitutoyo CMM . . . . .	423
7.6.1. Number of probing points . . . . .	425
7.6.2. Key measuring functions of the Mitutoyo B504B CMM . . . . .	425
7.7. Measurements on CMM using the Cosmos software . . . . .	427
7.7.1. Case of circle-to-circle distance . . . . .	431
7.7.2. STATPAK-Win of Cosmos, Mitutoyo . . . . .	441
7.8. Examples of applications using CMM . . . . .	443
7.8.1. Compiling the technical file . . . . .	449

7.8.2. Constitution of the CMM laboratory report under Cosmos (or other) . . . . .	450
7.9. Chapter summary and future extensions of CMMs . . . . .	450
7.10. Bibliography . . . . .	452
<b>Chapter 8. Control of Assembly and Transmission Elements . . . . .</b>	<b>453</b>
8.1. Introduction to the control of components for temporary assembly and elements for power transmission: threads, gears, and splines . . . . .	453
8.1.1. Method of obtaining threads and tapping in mechanical manufacturing. . . . .	453
8.1.2. General description of thread dimensioning . . . . .	455
8.1.3. Designation of threads and tapped holes for blind holes . . . . .	457
8.2. Helical surface for screw threads . . . . .	459
8.2.1. Technological processes for tapping and its control (Go – Not Go). . . . .	459
8.2.2. Tapping (by hand) with tap wrench and set of taps . . . . .	461
8.3. The main threads in the industry . . . . .	461
8.3.1. ISO Threads . . . . .	462
8.3.2. American Standard pipe threads . . . . .	467
8.3.3. The Whitworth thread . . . . .	468
8.3.4. BRIGGS tapered threads; cone 6.25% . . . . .	469
8.3.5. American Standard thread, NC and NF series . . . . .	470
8.3.6. Pipe threads called “GAS” . . . . .	470
8.3.7. Main threads implemented in Canada. . . . .	471
8.4. Principles of threads control . . . . .	478
8.4.1. Defects of the helical surface . . . . .	479
8.4.2. Control, without measurement, of threads . . . . .	480
8.4.3. Control of a thread pitch using ruler and gauge . . . . .	486
8.4.4. Checking the straightness of tapping tools by squaring . . . . .	486
8.5. Screws resistance and quality classes . . . . .	487
8.5.1. Minimum torques for screws with diameters of 1 to 10 mm. . . . .	487
8.5.2. Example of calculations of efforts on threads (North American concept) . . . . .	488
8.6. Control of screw thread by mechanical and optical comparison . . . . .	491
8.6.1. Laboratory example on threads control . . . . .	491
8.7. Introduction to gear control . . . . .	494
8.7.1. Parallel spur gears . . . . .	495
8.7.2. Metrological control of the main types of gears . . . . .	504
8.7.3. Spur gears with helical teeth . . . . .	505
8.7.4. Helical gears with parallel axes. . . . .	506
8.7.5. Parallel spur gears with helical teeth. . . . .	506
8.7.6. Bevel or concurrent gears . . . . .	507
8.7.7. Worm gears . . . . .	510

8.7.8. Racks . . . . .	511
8.7.9. Control of gears with a vernier calipers . . . . .	513
8.7.10. Chordal thickness measurement . . . . .	515
8.7.11. Over wire measurement . . . . .	516
8.7.12. Measuring thickness of rack teeth . . . . .	517
8.8. Introduction to spline control . . . . .	518
8.8.1. Dimensional control of splines . . . . .	520
8.8.2. Control of the geometric correction of splines . . . . .	520
8.8.3. Woodruff key – standardized ANSI B17. 2-1967 (R1998) . . . . .	521
8.8.4. Control of key-seats . . . . .	522
8.8.5. Calculating the depth of the housing (groove) and the distance from the top of the key . . . . .	522
8.9. Summary . . . . .	529
8.10. Bibliography . . . . .	530
<b>Chapter 9. Control of Materials Hardness Testing . . . . .</b>	<b>531</b>
9.1. Introduction to non-destructive testing . . . . .	531
9.1.1. Measurements of hardness by indentation . . . . .	533
9.1.2. Presentation of the main hardness tests . . . . .	534
9.2. Principle and description of the Rockwell hardness . . . . .	537
9.2.1. Comparison of indentation methods (Table 9.4) . . . . .	539
9.2.2. Typical applications of Rockwell scales . . . . .	540
9.2.3. Rockwell superficial hardness test . . . . .	541
9.2.4. Rockwell hardness tests of plastics . . . . .	542
9.2.5. Comparison between Shore and Rockwell hardness ball testing . . . . .	542
9.2.6. Overall description of the Rockwell hardness testing machine . . . . .	544
9.3. Brinell hardness test . . . . .	545
9.3.1. Applied load and diameter of the ball . . . . .	547
9.3.2. Thickness of the tested metal . . . . .	548
9.3.3. Meyer hardness test (named after Rajakovic and Meyer) . . . . .	548
9.3.4. Operating procedure for Brinell hardness test . . . . .	549
9.4. Principle of the Vickers hardness test . . . . .	550
9.5. Knoop hardness (HK) . . . . .	553
9.6. Barcol hardness . . . . .	555
9.7. Rebound hardness test by Shore test (scleroscope) . . . . .	556
9.7.1. Comparison of the indenters for the Rockwell and Shore tests . . . . .	558
9.8. Mohs hardness for minerals . . . . .	558
9.8.1. Mohs scale of hardness minerals . . . . .	560
9.8.2. How should the hardness of a mineral be measured? . . . . .	560
9.9. IRHD rubber hardness tester . . . . .	560
9.9.1. Control of rubber and other elastomers by IRHD and Shore test . . . . .	561

9.10. Comparison of the three main hardness tests and a practical approach for hardness testing: Brinell HB, Rockwell HR, and Vickers HV . . . . .	562
9.11. Main mechanical properties of solid materials . . . . .	564
9.11.1. Flow testing . . . . .	564
9.11.2. Tensile testing of solid materials . . . . .	564
9.11.3. Impact test for steels . . . . .	567
9.12. Mechanical tests on plastic materials . . . . .	575
9.12.1. Tensile strength, strain, and modulus ASTM D638 (ISO 527) . . . . .	575
9.12.2. Flexural strength and modulus ASTM D 790 (ISO 178) . . . . .	576
9.12.3. Impact test . . . . .	576
9.12.4. Interpretation of resistance to impacts – ASTM compared to ISO . . . . .	577
9.12.5. Izod impact strength ASTM D 256 (ISO 180) . . . . .	577
9.13. Fatigue failure and dimensional metrology for the control of the dimensioning of materials assembled by welding . . . . .	578
9.13.1. Fatigue testing . . . . .	578
9.13.2. Tenacity . . . . .	578
9.13.3. General tolerances for welded structures according to ISO 13920 . . . . .	582
9.14. Summary . . . . .	583
9.14.1. There is seriously no universal solution to conduct hardness tests . . . . .	584
9.14.2. Some criteria for choosing hardness testing apparatus . . . . .	585
9.14.3. Indentation reading mode . . . . .	586
9.14.4. The expected result . . . . .	586
9.15. Bibliography . . . . .	587
<b>Chapter 10. Overall Summary . . . . .</b>	<b>589</b>
<b>Glossary . . . . .</b>	<b>595</b>
Lexicon of terms frequently used in metrology . . . . .	595
Warning . . . . .	596
Bibliography . . . . .	613
<b>Appendix 1 . . . . .</b>	<b>615</b>
<b>Appendix 2 . . . . .</b>	<b>631</b>
<b>Appendix 3 . . . . .</b>	<b>637</b>
<b>Appendix 4 . . . . .</b>	<b>641</b>
<b>Appendix 5 . . . . .</b>	<b>645</b>
<b>Appendix 6 . . . . .</b>	<b>665</b>
<b>Index . . . . .</b>	<b>673</b>