


Volker Schulze

 WILEY-VCH

Modern Mechanical Surface Treatment

States, Stability, Effects



Contents

1	Introduction	1
2	Procedures of Mechanical Surface Treatments	9
2.1	Shot Peening	9
2.1.1	Definition and Delimitation of Procedure	9
2.1.2	Application Examples	9
2.1.3	Devices, Tools and Important Parameters	11
2.2	Stress Peening	14
2.2.1	Definition and Delimitation of Procedure	14
2.2.2	Application Examples	14
2.2.3	Devices, Tools and Important Parameters	15
2.3	Warm Peening	15
2.3.1	Definition and Delimitation of Procedure	15
2.3.2	Application Examples	15
2.3.3	Devices, Tools and Important Parameters	16
2.4	Stress Peening at Elevated Temperature	16
2.5	Deep Rolling	16
2.5.1	Definition and Delimitation of Procedure	16
2.5.2	Application Examples	17
2.5.3	Devices, Tools and Important Parameters	18
2.6	Laser Peening	19
2.6.1	Definition and Delimitation of Procedure	19
2.6.2	Application Examples	20
2.6.3	Devices, Tools and Important Parameters	20
3	Surface Layer States after Mechanical Surface Treatments	25
3.1	Shot Peening	25
3.1.1	Process Models	25
3.1.2	Changes in the Surface State	44
3.2	Stress Peening	72
3.2.1	Process Models	72
3.2.2	Changes in the Surface State	74
3.3	Warm Peening	81

3.3.1	Process Models	81
3.3.2	Changes in the Surface State	84
3.4	Stress Peening at elevated Temperature	87
3.5	Deep Rolling	89
3.5.1	Process Models	89
3.5.2	Changes in the Surface State	92
3.6	Laser Peening	101
3.6.1	Process Models	101
3.6.2	Changes in the Surface State	108
4	Changes of Surface States due to Thermal Loading	135
4.1	Process Models	135
4.1.1	Elementary Processes	135
4.1.2	Quantitative Description of Processes	137
4.2	Experimental Results and their Descriptions	140
4.2.1	Influences on Shape and Topography	140
4.2.2	Influences on Residual Stress State	142
4.2.3	Influences on Workhardening State	157
4.2.4	Influences on Microstructure	170
5	Changes of Surface Layer States due to Quasi-static Loading	179
5.1	Process Models	179
5.1.1	Elementary Processes	179
5.1.2	Quantitative Description of Processes	180
5.2	Experimental Results and their Descriptions	184
5.2.1	Influences on Shape and Deformation Behavior	184
5.2.2	Influences on Residual Stress State	186
5.2.3	Influences on Workhardening State	227
5.2.4	Influences on Microstructure	243
6	Changes of Surface States during Cyclic Loading	247
6.1	Process Models	247
6.1.1	Elementary Processes	247
6.1.2	Quantitative Description of Processes	250
6.2	Experimental Results and their Descriptions	260
6.2.1	Influences on Residual Stress State	260
6.2.2	Influences on Workhardening State	291
6.2.3	Influences on Microstructure	298
6.3	Effects of Surface Layer Stability on Behavior during Cyclic Loading	303
6.3.1	Basic Results	303
6.3.2	Effects on Cyclic Deformation Behavior	304
6.3.3	Effects on Crack Initiation Behavior	310
6.3.4	Effects on Crack Propagation Behavior	313
6.3.5	Effects on Fatigue Behavior	319

7	Summary	355
	Acknowledgments	365
Index	367	