

Seventh Edition

Introduction to
**STATISTICAL
QUALITY
CONTROL**

DOUGLAS C. MONTGOMERY



Contents

PART 1

INTRODUCTION 1

1 QUALITY IMPROVEMENT IN THE MODERN BUSINESS ENVIRONMENT 3

Chapter Overview and Learning Objectives	3
1.1 The Meaning of Quality and Quality Improvement	4
1.1.1 Dimensions of Quality	4
1.1.2 Quality Engineering Terminology	8
1.2 A Brief History of Quality Control and Improvement	9
1.3 Statistical Methods for Quality Control and Improvement	13
1.4 Management Aspects of Quality Improvement	16
1.4.1 Quality Philosophy and Management Strategies	17
1.4.2 <i>The Link Between Quality and Productivity</i>	35
1.4.3 Supply Chain Quality Management	36
1.4.4 Quality Costs	38
1.4.5 Legal Aspects of Quality	44
1.4.6 Implementing Quality Improvement	45

2 THE DMAIC PROCESS 48

Chapter Overview and Learning Objectives	48
2.1 Overview of DMAIC	49
2.2 The Define Step	52
2.3 The Measure Step	54
2.4 The Analyze Step	55

2.5 The Improve Step	56
2.6 The Control Step	57
2.7 Examples of DMAIC	57
2.7.1 Litigation Documents	57
2.7.2 Improving On-Time Delivery	59
2.7.3 Improving Service Quality in a Bank	62

PART 2 STATISTICAL METHODS USEFUL IN QUALITY CONTROL AND IMPROVEMENT 65

3 MODELING PROCESS QUALITY 67

Chapter Overview and Learning Objectives	68
3.1 Describing Variation	68
3.1.1 The Stem-and-Leaf Plot	68
3.1.2 The Histogram	70
3.1.3 Numerical Summary of Data	73
3.1.4 The Box Plot	75
3.1.5 Probability Distributions	76
3.2 Important Discrete Distributions	80
3.2.1 The Hypergeometric Distribution	80
3.2.2 The Binomial Distribution	81
3.2.3 The Poisson Distribution	83
3.2.4 The Negative Binomial and Geometric Distributions	86
3.3 Important Continuous Distributions	88
3.3.1 The Normal Distribution	88
3.3.2 The Lognormal Distribution	90
3.3.3 The Exponential Distribution	92
3.3.4 The Gamma Distribution	93
3.3.5 The Weibull Distribution	95
3.4 Probability Plots	97
3.4.1 Normal Probability Plots	97
3.4.2 Other Probability Plots	99

X Contents

3.5 Some Useful Approximations 100
3.5.1 The Binomial Approximation to the Hypergeometric 100
3.5.2 The Poisson Approximation to the Binomial 100
3.5.3 The Normal Approximation to the Binomial 101
3.5.4 Comments on Approximations 102

4

INFERENCES ABOUT PROCESS QUALITY 108

Chapter Overview and Learning Objectives 109
4.1 Statistics and Sampling Distributions 110
4.1.1 Sampling from a Normal Distribution 111
4.1.2 Sampling from a Bernoulli Distribution 113
4.1.3 Sampling from a Poisson Distribution 114
4.2 Point Estimation of Process Parameters 115
4.3 Statistical Inference for a Single Sample 117
4.3.1 Inference on the Mean of a Population, Variance Known 118
4.3.2 The Use of *P*-Values for Hypothesis Testing 121
4.3.3 Inference on the Mean of a Normal Distribution, Variance Unknown 122
4.3.4 Inference on the Variance of a Normal Distribution 126
4.3.5 Inference on a Population Proportion 128
4.3.6 The Probability of Type II Error and Sample Size Decisions 130
4.4 Statistical Inference for Two Samples 133
4.4.1 Inference for a Difference in Means, Variances Known 134
4.4.2 Inference for a Difference in Means of Two Normal Distributions, Variances Unknown 136
4.4.3 Inference on the Variances of Two Normal Distributions 143
4.4.4 Inference on Two Population Proportions 145
4.5 What If There Are More Than Two Populations? The Analysis of Variance 146
4.5.1 An Example 146
4.5.2 The Analysis of Variance 148

4.5.3 Checking Assumptions: Residual Analysis 154
4.6 Linear Regression Models 156
4.6.1 Estimation of the Parameters in Linear Regression Models 157
4.6.2 Hypothesis Testing in Multiple Regression 163
4.6.3 Confidence Intervals in Multiple Regression 169
4.6.4 Prediction of New Observations 170
4.6.5 Regression Model Diagnostics 171

PART 3

BASIC METHODS OF STATISTICAL PROCESS CONTROL AND CAPABILITY ANALYSIS 185

5

METHODS AND PHILOSOPHY OF STATISTICAL PROCESS CONTROL 187

Chapter Overview and Learning Objectives 187
5.1 Introduction 188
5.2 Chance and Assignable Causes of Quality Variation 189
5.3 Statistical Basis of the Control Chart 190
5.3.1 Basic Principles 190
5.3.2 Choice of Control Limits 197
5.3.3 Sample Size and Sampling Frequency 199
5.3.4 Rational Subgroups 201
5.3.5 Analysis of Patterns on Control Charts 203
5.3.6 Discussion of Sensitizing Rules for Control Charts 205
5.3.7 Phase I and Phase II of Control Chart Application 206
5.4 The Rest of the Magnificent Seven 207
5.5 Implementing SPC in a Quality Improvement Program 213
5.6 An Application of SPC 214
5.7 Applications of Statistical Process Control and Quality Improvement Tools in Transactional and Service Businesses 221

6
CONTROL CHARTS
FOR VARIABLES **234**

Chapter Overview and Learning Objectives	235
6.1 Introduction	235
6.2 Control Charts for \bar{x} and R	236
6.2.1 Statistical Basis of the Charts	236
6.2.2 Development and Use of \bar{x} and R Charts	239
6.2.3 Charts Based on Standard Values	250
6.2.4 Interpretation of \bar{x} and R Charts	251
6.2.5 The Effect of Nonnormality on \bar{x} and R Charts	254
6.2.6 The Operating-Characteristic Function	254
6.2.7 The Average Run Length for the \bar{x} Chart	257
6.3 Control Charts for \bar{x} and s	259
6.3.1 Construction and Operation of \bar{x} and s Charts	259
6.3.2 The \bar{x} and s Control Charts with Variable Sample Size	263
6.3.3 The s^2 Control Chart	267
6.4 The Shewhart Control Chart for Individual Measurements	267
6.5 Summary of Procedures for \bar{x} , R , and s Charts	276
6.6 Applications of Variables Control Charts	276

7
CONTROL CHARTS
FOR ATTRIBUTES **297**

Chapter Overview and Learning Objectives	297
7.1 Introduction	298
7.2 The Control Chart for Fraction Nonconforming	299
7.2.1 Development and Operation of the Control Chart	299
7.2.2 Variable Sample Size	310
7.2.3 Applications in Transactional and Service Businesses	315
7.2.4 The Operating-Characteristic Function and Average Run Length Calculations	315
7.3 Control Charts for Nonconformities (Defects)	317
7.3.1 Procedures with Constant Sample Size	318

7.3.2 Procedures with Variable Sample Size	328
7.3.3 Demerit Systems	330
7.3.4 The Operating-Characteristic Function	331
7.3.5 Dealing with Low Defect Levels	332
7.3.6 Nonmanufacturing Applications	335
7.4 Choice Between Attributes and Variables Control Charts	335
7.5 Guidelines for Implementing Control Charts	339

8
PROCESS AND MEASUREMENT
SYSTEM CAPABILITY ANALYSIS **355**

Chapter Overview and Learning Objectives	356
8.1 Introduction	356
8.2 Process Capability Analysis Using a Histogram or a Probability Plot	358
8.2.1 Using the Histogram	358
8.2.2 Probability Plotting	360
8.3 Process Capability Ratios	362
8.3.1 Use and Interpretation of C_p	362
8.3.2 Process Capability Ratio for an Off-Center Process	365
8.3.3 Normality and the Process Capability Ratio	367
8.3.4 More about Process Centering	368
8.3.5 Confidence Intervals and Tests on Process Capability Ratios	370
8.4 Process Capability Analysis Using a Control Chart	375
8.5 Process Capability Analysis Using Designed Experiments	377
8.6 Process Capability Analysis with Attribute Data	378
8.7 Gauge and Measurement System Capability Studies	379
8.7.1 Basic Concepts of Gauge Capability	379
8.7.2 The Analysis of Variance Method	384
8.7.3 Confidence Intervals in Gauge R & R Studies	387
8.7.4 False Defectives and Passed Defectives	388
8.7.5 Attribute Gauge Capability	392
8.7.6 Comparing Customer and Supplier Measurement Systems	394

8.8	Setting Specification Limits on Discrete Components	396
8.8.1	Linear Combinations	397
8.8.2	Nonlinear Combinations	400
8.9	Estimating the Natural Tolerance Limits of a Process	401
8.9.1	Tolerance Limits Based on the Normal Distribution	402
8.9.2	Nonparametric Tolerance Limits	403

9.2.1	The Exponentially Weighted Moving Average Control Chart for Monitoring the Process Mean	433
9.2.2	Design of an EWMA Control Chart	436
9.2.3	Robustness of the EWMA to Non-normality	438
9.2.4	Rational Subgroups	439
9.2.5	Extensions of the EWMA	439
9.3	The Moving Average Control Chart	442

PART 4
OTHER STATISTICAL PROCESS-MONITORING AND CONTROL TECHNIQUES **411**

9
CUMULATIVE SUM AND EXPONENTIALLY WEIGHTED MOVING AVERAGE CONTROL CHARTS **413**

Chapter Overview and Learning Objectives	414
9.1 The Cumulative Sum Control Chart	414
9.1.1 Basic Principles: The CUSUM Control Chart for Monitoring the Process Mean	414
9.1.2 The Tabular or Algorithmic CUSUM for Monitoring the Process Mean	417
9.1.3 Recommendations for CUSUM Design	422
9.1.4 The Standardized CUSUM	424
9.1.5 Improving CUSUM Responsiveness for Large Shifts	424
9.1.6 The Fast Initial Response or Headstart Feature	424
9.1.7 One-Sided CUSUMs	427
9.1.8 A CUSUM for Monitoring Process Variability	427
9.1.9 Rational Subgroups	428
9.1.10 CUSUMs for Other Sample Statistics	428
9.1.11 The V-Mask Procedure	429
9.1.12 The Self-Starting CUSUM	431
9.2 The Exponentially Weighted Moving Average Control Chart	433

10
OTHER UNIVARIATE STATISTICAL PROCESS-MONITORING AND CONTROL TECHNIQUES **448**

Chapter Overview and Learning Objectives	449
10.1 Statistical Process Control for Short Production Runs	450
10.1.1 \bar{x} and R Charts for Short Production Runs	450
10.1.2 Attributes Control Charts for Short Production Runs	452
10.1.3 Other Methods	452
10.2 Modified and Acceptance Control Charts	454
10.2.1 Modified Control Limits for the \bar{x} Chart	454
10.2.2 Acceptance Control Charts	457
10.3 Control Charts for Multiple-Stream Processes	458
10.3.1 Multiple-Stream Processes	458
10.3.2 Group Control Charts	458
10.3.3 Other Approaches	460
10.4 SPC With Autocorrelated Process Data	461
10.4.1 Sources and Effects of Autocorrelation in Process Data	461
10.4.2 Model-Based Approaches	465
10.4.3 A Model-Free Approach	473
10.5 Adaptive Sampling Procedures	477
10.6 Economic Design of Control Charts	478
10.6.1 Designing a Control Chart	478
10.6.2 Process Characteristics	479
10.6.3 Cost Parameters	479
10.6.4 Early Work and Semieconomic Designs	481
10.6.5 An Economic Model of the \bar{x} Control Chart	482
10.6.6 Other Work	487
10.7 Cuscore Charts	488

10.8 The Changepoint Model for Process Monitoring 490

10.9 Profile Monitoring 491

10.10 Control Charts in Health Care Monitoring and Public Health Surveillance 496

10.11 Overview of Other Procedures 497

 10.11.1 Tool Wear 497

 10.11.2 Control Charts Based on Other Sample Statistics 498

 10.11.3 Fill Control Problems 498

 10.11.4 Precontrol 499

 10.11.5 Tolerance Interval Control Charts 500

 10.11.6 Monitoring Processes with Censored Data 501

 10.11.7 Monitoring Bernoulli Processes 501

 10.11.8 Nonparametric Control Charts 502

11
MULTIVARIATE PROCESS MONITORING AND CONTROL 509

Chapter Overview and Learning Objectives 509

11.1 The Multivariate Quality-Control Problem 510

11.2 Description of Multivariate Data 512

 11.2.1 The Multivariate Normal Distribution 512

 11.2.2 The Sample Mean Vector and Covariance Matrix 513

11.3 The Hotelling T^2 Control Chart 514

 11.3.1 Subgrouped Data 514

 11.3.2 Individual Observations 521

11.4 The Multivariate EWMA Control Chart 524

11.5 Regression Adjustment 528

11.6 Control Charts for Monitoring Variability 531

11.7 Latent Structure Methods 533

 11.7.1 Principal Components 533

 11.7.2 Partial Least Squares 538

12
ENGINEERING PROCESS CONTROL AND SPC 542

Chapter Overview and Learning Objectives 542

12.1 Process Monitoring and Process Regulation 543

12.2 Process Control by Feedback Adjustment 544

 12.2.1 A Simple Adjustment Scheme: Integral Control 544

 12.2.2 The Adjustment Chart 549

12.2.3 Variations of the Adjustment Chart 551

12.2.4 Other Types of Feedback Controllers 554

12.3 Combining SPC and EPC 555

PART 5
PROCESS DESIGN AND IMPROVEMENT WITH DESIGNED EXPERIMENTS 561

13
FACTORIAL AND FRACTIONAL FACTORIAL EXPERIMENTS FOR PROCESS DESIGN AND IMPROVEMENT 563

Chapter Overview and Learning Objectives 564

13.1 What is Experimental Design? 564

13.2 Examples of Designed Experiments In Process and Product Improvement 566

13.3 Guidelines for Designing Experiments 568

13.4 Factorial Experiments 570

 13.4.1 An Example 572

 13.4.2 Statistical Analysis 572

 13.4.3 Residual Analysis 577

13.5 The 2^k Factorial Design 578

 13.5.1 The 2^2 Design 578

 13.5.2 The 2^k Design for $k \geq 3$ Factors 583

 13.5.3 A Single Replicate of the 2^k Design 593

 13.5.4 Addition of Center Points to the 2^k Design 596

 13.5.5 Blocking and Confounding in the 2^k Design 599

13.6 Fractional Replication of the 2^k Design 601

 13.6.1 The One-Half Fraction of the 2^k Design 601

 13.6.2 Smaller Fractions: The 2^{k-p} Fractional Factorial Design 606

14
PROCESS OPTIMIZATION WITH DESIGNED EXPERIMENTS 617

Chapter Overview and Learning Objectives 617

14.1 Response Surface Methods and Designs 618

 14.1.1 The Method of Steepest Ascent 620

14.1.2	Analysis of a Second-Order Response Surface	622
14.2	Process Robustness Studies	626
14.2.1	Background	626
14.2.2	The Response Surface Approach to Process Robustness Studies	628
14.3	Evolutionary Operation	634

PART 6
ACCEPTANCE SAMPLING **647**

15
LOT-BY-LOT ACCEPTANCE SAMPLING FOR ATTRIBUTES **649**

Chapter Overview and Learning Objectives	649
15.1 The Acceptance-Sampling Problem	650
15.1.1 Advantages and Disadvantages of Sampling	651
15.1.2 Types of Sampling Plans	652
15.1.3 Lot Formation	653
15.1.4 Random Sampling	653
15.1.5 Guidelines for Using Acceptance Sampling	654
15.2 Single-Sampling Plans for Attributes	655
15.2.1 Definition of a Single-Sampling Plan	655
15.2.2 The OC Curve	655
15.2.3 Designing a Single-Sampling Plan with a Specified OC Curve	660
15.2.4 Rectifying Inspection	661
15.3 Double, Multiple, and Sequential Sampling	664
15.3.1 Double-Sampling Plans	665
15.3.2 Multiple-Sampling Plans	669
15.3.3 Sequential-Sampling Plans	670
15.4 Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859)	673
15.4.1 Description of the Standard	673
15.4.2 Procedure	675
15.4.3 Discussion	679
15.5 The Dodge-Romig Sampling Plans	681
15.5.1 AOQL Plans	682
15.5.2 LTPD Plans	685
15.5.3 Estimation of Process Average	685

16
OTHER ACCEPTANCE-SAMPLING TECHNIQUES **688**

Chapter Overview and Learning Objectives	688
16.1 Acceptance Sampling by Variables	689
16.1.1 Advantages and Disadvantages of Variables Sampling	689
16.1.2 Types of Sampling Plans Available	690
16.1.3 Caution in the Use of Variables Sampling	691
16.2 Designing a Variables Sampling Plan with a Specified OC Curve	691
16.3 MIL STD 414 (ANSI/ASQC Z1.9)	694
16.3.1 General Description of the Standard	694
16.3.2 Use of the Tables	695
16.3.3 Discussion of MIL STD 414 and ANSI/ASQC Z1.9	697
16.4 Other Variables Sampling Procedures	698
16.4.1 Sampling by Variables to Give Assurance Regarding the Lot or Process Mean	698
16.4.2 Sequential Sampling by Variables	699
16.5 Chain Sampling	699
16.6 Continuous Sampling	701
16.6.1 CSP-1	701
16.6.2 Other Continuous-Sampling Plans	704
16.7 Skip-Lot Sampling Plans	704

APPENDIX **709**

I. Summary of Common Probability Distributions Often Used in Statistical Quality Control	710
II. Cumulative Standard Normal Distribution	711
III. Percentage Points of the χ^2 Distribution	713
IV. Percentage Points of the t Distribution	714
V. Percentage Points of the F Distribution	715
VI. Factors for Constructing Variables Control Charts	720
VII. Factors for Two-Sided Normal Tolerance Limits	721
VIII. Factors for One-Sided Normal Tolerance Limits	722

BIBLIOGRAPHY **723**

ANSWERS TO SELECTED EXERCISES **739**

INDEX **749**