

Contents

Preface	xvii
List of Contributors	xix
Part 1: Troubleshooting Basics	1
1 The Economics of Troubleshooting Polymer Processing Systems	3
<i>Mark D. Wetzel</i>	
1.1 Introduction	3
1.2 Economic Incentives and Necessities	4
1.3 Troubleshooting Resources and Their Cost	6
1.4 Managing Resources and Costs	11
1.5 Troubleshooting Techniques and Their Relative Costs	12
1.6 Case Histories	14
1.6.1 Single Screw Extrusion Instability	14
1.6.2 Compounding Extruder Catastrophic Failure	14
1.6.3 Polymer Degradation During Melt Processing	16
1.7 Conclusions	20
References	20
2 Troubleshooting Philosophy	21
<i>John R. Wagner, Jr.</i>	
2.1 Introduction	21
2.2 Troubleshooting Methodology	23
Bibliography	25
3 Statistical Tools for Trouble Shooting a Process	27
<i>Vincent Vezza</i>	
3.1 Introduction	27
3.2 Basic Statistical Concepts	28
3.2.1 Histogram	28
3.2.2 Scatter Diagram	28
3.3 Sample Mean and Standard Deviation	29
3.4 Design of Experiments (DOE)	31
3.4.1 Factorial Design	31
3.4.2 Fractional Factorial Design	34
3.5 Process Capability	37
3.6 Control Charts	38
3.7.1 Central Limit Theorem	39
3.7.2 Variable Data Control Charts	41
3.7.3 Control Charts for Attribute Data	43

References	45
Bibliography	45
Statistics	45
Design of Experiments	45
Statistical Process Control	45
Part 2: Extrusion Processes	47
4 Single Screw Extrusion	49
<i>John R. Wagner, Jr.</i>	
4.1 Introduction	49
4.2 Process Description	51
References	54
5 Troubleshooting the Co-rotating Fully Intermeshing Twin-screw Compounding System	57
<i>Paul Andersen, Rich Kanarski and John R. Wagner, Jr.</i>	
5.1 Introduction	57
5.2 Equipment Description	58
5.3 Troubleshooting	59
5.3.1 What is Troubleshooting?	60
5.4 Tools of the Successful Troubleshooter	60
5.4.1 Experience	60
5.4.2 Vent Flow Problem	61
5.5 Product, Process and Equipment Knowledge	62
5.5.1 High Discharge Pressure Problem	64
5.5.2 Barrel Temperatures Higher than Set Points Problem	65
5.5.3 Climbing Discharge Temperature Problem	65
5.5.4 Gels and Un-melts in the Extrudate Problem	65
5.5.5 Holes or Bubbles in the Extrudate Problem	65
5.5.6 Process Surging Problem	66
5.6 Conclusion	66
References	67
6 Troubleshooting for Injection Molding	69
<i>James J. Wenskus</i>	
6.1 Introduction	69
6.1.1 The Basic Approach	70
6.2 Understanding Temperature Control	70
6.3 Product Shift to a Different Machine	72
6.3.1 Calculate the New Pressure Settings	72
6.3.2 Procedure	73
6.4 Part Weight as an Analytical Tool	74
6.4.1 Example – Part Weight for Process Variability Analysis	75
6.4.2 Long Term Variability Analysis	76
6.4.3 Short Term Variability Analysis	76
6.4.4 Variability Evaluation	76
6.4.5 Process Benchmarking for Quality	77
6.4.6 Benchmark Evaluation	78
6.4.7 Summary	79

6.5	Part Weight as Dimensional Aimpoint Control	79
6.5.1	Unconstrained Process	80
6.5.2	Partially Constrained Process	81
6.5.3	Constrained Process	82
6.5.4	Warpage	82
6.5.5	Relationship of Shot Weight and Hydraulic Pressure	84
6.6	Determining the Gate Freeze-Off Time	85
6.6.1	Procedure to Determine the Freeze-Off Point	86
6.6.2	Time Analysis	86
6.6.3	Pressure Procedure	86
	References	88
7	Blown Film	89
	<i>Karen Xiao and Steve Gammell</i>	
7.1	Introduction	89
7.2	Process Description	92
7.2.1	Extruders	94
7.2.2	Dies	94
7.2.3	Process Cooling	97
7.2.4	The Bubble Collapsing Process and Systems	98
7.2.5	Haul-Off/Primary Nip	99
7.2.6	Film Winding	101
	7.2.6.1 Center-drive Winder	102
	7.2.6.2 Surface Winders	102
7.3	Special Tools for Troubleshooting	105
	7.3.1 Winding Systems	108
7.4	Case Studies	109
	7.4.1 Case Study 1: Carbon Buildup	109
	7.4.2 Case Study 2: Poor Gauge Uniformity	110
	References	111
8	Cast Film Troubleshooting	113
	<i>Andrew W. Christie and Beth M. Foederer</i>	
8.1	Coextrusion Film Systems	113
8.2	Troubleshooting Method	114
	8.2.1 The Problem Statement	115
	8.2.2 The Hypothesis	115
	8.2.3 Testing the Hypothesis	116
	8.2.4 Evaluating the Results	117
8.3	Common Problems, Hypotheses and Tests	117
	8.3.1 Gels in Film	117
	8.3.2 Film Clarity	120
	8.3.3 Wrinkling	120
	8.3.4 Inability to Reach Output	121
	8.3.5 Poor Melt Mixing	122
	8.3.6 Melt Temperature Too Low	123
	8.3.7 Melt Temperature Too High	123
	8.3.8 Extruder Power Insufficient	124

8.3.9	Film Streaks or Lines	124
8.3.10	Melt Appearance Defects	125
8.3.11	Thickness Variation – Cross Direction	125
8.3.12	Thickness Variation – Machine Direction	126
8.3.13	Poor Wound Roll Appearance	126
8.3.14	Edge Tear (Unstable Edges)	127
8.3.15	Pin Holes	127
8.3.16	Extruder Surging	128
8.3.17	Draw Resonance	128
8.3.18	Film Discoloration	129
8.3.19	Poor Heat Seal Strength	129
8.3.20	Odor – Flavor Scalping	129
8.3.21	Poor Strength	129
8.3.22	Film Blocking	130
8.3.23	Poor Printability	130
8.3.24	Camber or Curl	131
8.3.25	Scratches	131
	References	131
9	Oriented Films-Troubleshooting and Characterization	133
	<i>Eldridge M. Mount, III</i>	
9.1	Introduction	133
9.2	Process Overview: Biaxial Orientation	134
9.3	Oriented Film Markets	141
9.3.1	Oriented Polypropylene OPP or BOPP	141
9.3.2	Oriented Polyester OPET	143
9.3.3	Oriented Polystyrene OPS	144
9.3.4	Oriented Polyamide (Nylon) OPA	145
9.4	Troubleshooting the Film Orientation Process as Applied to OPP Films	146
9.4.1	Control Variables	146
9.4.1.1	Resin Drying	146
9.4.1.2	Extrusion	147
9.4.1.3	Casting and Pinning	149
9.4.1.4	Machine Direction Orientation	153
9.4.1.5	Transverse Direction Orientation	153
9.4.1.6	Web Handling and Surface Treatment	156
9.4.1.7	Winding	156
9.4.2	Noise Variables	157
9.4.3	Dependent Variables	157
9.5	Special Tools for Troubleshooting	158
9.6	Case Studies	159
9.6.1	Casting Capacity Limitation in PET Film Production	159
9.6.2	Floating Gauge – Extrusion Instability and MDO Heat Transfer Limitations	160
9.6.3	Output Limitation from Coextrusion Instability	162
	References	164
	Bibliography	164

10	Troubleshooting the Thermoforming Process	167
	<i>James L. Throne</i>	
10.1	General Concepts in Thermoforming	167
10.2	Categorization of the Process	169
10.2.1	Thick-Gauge Process	169
10.2.2	Thin-Gauge Process	170
10.3	Specific Aspects of the Thermoforming Process	172
10.3.1	Critical Material Issues	172
10.3.2	Molds and Mold Design	173
10.3.3	Incoming Sheet Quality Issues	174
10.3.4	Materials Handling – Ingress	174
10.3.5	Heating	175
10.3.6	Pre-stretching (Plug Assist)	176
10.3.7	Pre-stretching (Vacuum/ Air Pressure Formation)	176
10.3.8	Contacting the Mold	176
10.3.9	Cooling and Rigidifying the Formed Part	177
10.3.10	Removing the Formed Part from the Mold	178
10.3.11	Materials Handling – Egress	178
10.3.12	Trimming	178
10.3.13	Post-trimming Issues	179
10.3.14	Regrind	180
10.4	Problem Solving Methodology	180
10.4.1	Trimming	182
10.5	General Preventative Maintenance Concepts	183
10.5.1	Crisis Maintenance	184
10.5.2	Routine Maintenance	184
10.6	General Predictive Maintenance Concepts	187
10.7	Safety during Troubleshooting	188
10.7.1	Make-up of a Troubleshooting Team	192
	Appendix 1: Thermoforming References with Troubleshooting Sections	193
	Appendix 2: Plastic Materials References	193
	Appendix 3: Troubleshooting Guidelines for Thick-Gauge Thermoforming	194
	Appendix 4: Troubleshooting Guidelines for Thin-Gauge Thermoforming	199
	Appendix 5: Time-dependent Ranking of Typical Courses of Action	209
	Appendix 6: Troubleshooting Guidelines for Trimming Parts	210
	Thin-Gauge	210
	Thick-Gauge	213
11	Proper Equipment Processing for Industrial/Technical Blow Molding	217
	<i>Robert A. Slawska</i>	
11.1	Introduction of Blow Molding	218
11.1.1	How Parts are Blow Molded	218
11.1.2	Positive Benefits of the Process	219
11.1.3	Negative Factors of Accumulator Head Blow Molding	219
11.2	Select the Proper Equipment	220
11.3	Extruder	222
11.4	Accumulator Head	225
11.5	Importance of Cleaning	226

x CONTENTS

11.6	Press	229
11.7	Hydraulics	230
11.8	Microprocessor	232
11.9	Pneumatic Systems	233
11.10	Part Take Out System	233
11.11	Selection of Equipment	234
12	PET Stretch Blow Molding	237
	<i>Dan Weissmann</i>	
12.1	Introduction	237
12.2	The PET Universe	238
12.3	Technology History	239
12.4	PET Chemistry	239
12.5	PET Morphology	241
12.6	Bottle Universe	243
12.7	Bottle Manufacturing	245
12.8	Commercial Manufacturing Processes	247
12.9	Process Elements	251
12.9.1	Injection Molding	251
12.9.1.1	IV Drop	251
12.9.1.2	Acetaldehyde	254
12.9.1.3	Molding Stresses	256
12.9.2	Hot Runner System	258
12.9.2.1	Gate Crystallinity and Separation	259
12.9.2.2	Gate Pin Holes	260
12.9.3	Mold Cooling	260
12.9.3.1	Preform Problem Analysis	261
12.9.4	Blow Molding	261
12.9.4.1	General Principles – Reheating and Preform Temperature	261
12.9.5	Preform Temperature Profiling	263
12.9.6	Blowing	264
12.9.6.1	Quality Attributes and Performance Issues	266
12.9.6.2	Blow Molding Process Monitoring	269
12.9.6.3	On Line Inspection	271
12.9.6.4	Testing and Test Procedures	271
12.9.6.5	Special Processes	272
12.10	Case Sample: Thermal Stability Failure of CSD Bottles	277
	References	278
13	Blow Molding – Problems and Solutions	281
	<i>Norman C. Lee</i>	
13.1	Introduction	281
13.2	Troubleshooting	282
13.3	Variables Affecting the Blow Molding Process	283
13.3.1	PART 1: Defects in Article	284
13.3.1.1	PART I – Defect in Finished Article	284
13.3.2	PART II: Parison Defects	289
13.3.2.1	PART II – Defects of the Parison	289

13.3.3	Noise	293
13.3.4	Ambient Conditions	293
13.4	Preventative Maintenance	293
13.4.1	Maintenance Recommendations	293
13.4.2	Machine Check Out	294
13.5	Injection and Stretch Blow Molding	294
13.6	Computer Integrated Manufacturing (CIM) in Extrusion Blow Molding	295
	Acknowledgement	297
	Bibliography	298
14	Extrusion Coating Troubleshooting	299
	<i>Beth M. Foederer and Andrew W. Christie</i>	
14.1	Coextrusion Extrusion Coating/Laminating Systems	299
14.2	Troubleshooting Method	300
14.3	Common Problems, Hypotheses and Tests	301
14.3.1	Gels in Film	301
14.3.2	Poor Adhesion	304
14.3.3	Wrinkling	305
14.3.4	Low Output	306
14.3.5	Poor Melt Mixing	307
14.3.6	Melt Temperature Too Low	308
14.3.7	Melt Temperature Too High	308
14.3.8	Extruder Power Insufficient	309
14.3.9	Die Lines	309
14.3.10	Melt Appearance Defects	309
14.3.11	Thickness Variation – Cross Direction	310
14.3.12	Thickness Variation – Machine Direction	310
14.3.13	Poor Wound Roll Appearance	311
14.3.14	Edge Tear (Unstable Edges)	311
14.3.15	Pin Holes	312
14.3.16	Extruder Surging	312
14.3.17	Draw Resonance	312
14.3.18	Poor Heatseal	313
14.3.19	Odor – Flavor Scalping	313
14.3.20	Poor Printability	313
14.3.21	Camber or Curl	314
14.3.22	Scratches	314
	References	314
Part 3:	Non-extrusion Processes	315
15	Adhesive and Thermal Lamination	317
	<i>Tom Dunn</i>	
15.1	Introduction	317
15.1.1	Process Overview	317
15.1.2	Markets Served	318
15.1.3	Historical and Future Growth Projections – Technology Challenges and Threats	318

15.2	Process Description	319
15.2.1	Major Process Components	319
15.2.2	Equipment Production Ranges	319
15.2.3	Manufacturers	319
15.3	Control Variables	320
15.4	Random Cause Variables	324
15.5	Dependent Variables	325
15.6	Special Tools for Troubleshooting	326
15.6.1	Product	327
15.7	Case Studies	328
15.7.1	Easy-peel or Rip-off	328
15.7.2	Spotty Results	330
	Bibliography	330
16	Troubleshooting for Rotomolding	331
	<i>Paul Nugent</i>	
16.1	The Basic Process	331
16.2	Key Quality Control Steps in Rotomolding	336
16.2.1	Materials In-bound and Powder Preparation	337
16.2.2	Colorants and Additives	339
16.2.3	Material Mixing	339
16.2.4	Molds and Fixtures	339
16.2.5	Machinery	340
16.2.6	Calibration	340
16.2.7	Production Process and Records	340
16.3	Typical Rotomolding Problems	343
16.4	Typical Solutions	347
16.4.1	Adhesion – Difficulty in Painting or Applying Labels	347
16.4.2	Blowholes – Around Inserts	347
16.4.3	Blowholes – Other Areas	348
16.4.4	Blowholes – Parting Line	348
16.4.5	Bubbles on Part Surface or in the Cross-section	349
16.4.6	Coining (Pockmarks)	350
16.4.7	Color – Part Burned / Discolored	350
16.4.8	Color – Static Swirl	351
16.4.9	Color – Unevenness	352
16.4.10	Flash at the Parting Line	352
16.4.11	Foaming – Coarse or Uneven Foam	353
16.4.12	Foaming – Gaps in Wall Cross-section	353
16.4.13	Foaming – Part Deformation	354
16.4.14	Incomplete Material Fusion	354
16.4.15	Incomplete Mold Fill (Bridging)	355
16.4.16	Low Impact Strength	355
16.4.17	Low Part Stiffness	356
16.4.18	Long Oven Cycle	357
16.4.19	Long-term Part Failure	357
16.4.20	Mold Distortion, Explosion	358

16.4.21	Plate Out	358
16.4.22	Sticking in Mold	359
16.4.23	Wall Thickness – Uneven	360
16.4.24	Warpage	360
16.4.25	Whitish Part Appearance	361
17	Plastics Calendering	363
	<i>Chellappa Chandrasekaran</i>	
17.1	Introduction	363
17.2	Blending and Fluxing	364
17.3	Mills and Strainers	365
17.4	Calender	365
17.5	General Description of a Calendering Machine	367
17.5.1	Rolls	367
17.5.2	Sheet Finishes	368
17.5.3	Roll Contours	369
17.5.4	Frame	370
17.5.5	Roll Adjustment	370
17.5.6	Bed Plate	370
17.5.7	Lubrication	371
17.5.8	Temperature Control	371
17.5.9	Safety and Safety Regulations	372
17.6	The Calendering Process	372
17.6.1	Heating and Delivery to the Calender	373
17.6.2	Roll Banks	373
17.6.3	Sheet Takeoff and Post-processing	374
17.6.4	Embossing and Laminating	374
17.7	Input Materials and Products	375
17.7.1	The Formulas	375
17.8	Why Calendering is Preferred to Extrusion	377
17.9	Calendering Process Variables	377
17.9.1	Barring and Noise Due to Roll Vibration	377
17.9.2	Machine Dependent Variable	378
17.9.3	Product Variation	379
17.9.4	Overcoming and Correcting Process Variation	381
17.10	Conclusion	381
	References	382
	Bibliography	382
18	Compression Molding	383
	<i>Muralisrinivasan Natamai Subramanian</i>	
18.1	Introduction	383
18.2	Materials	384
18.2.1	Thermoplastics and Compression Molding	384
18.2.2	Thermosets and Compression Molding	385
18.2.3	Premix or Prepreg Preparation	386
18.2.4	Fiber Alignment	386

18.2.5	Pre-form	386
18.2.6	Prepreg	386
18.3	Sheet Molding Compound – Production	386
18.3.1	Mold	388
18.4	Technology – Compression Molding	388
18.4.1	Important Variables during Processing	389
18.5	Troubleshooting	390
18.6	Problems and Solution(s)	392
18.7	Summary	393
18.7.1	Fundamentals	393
18.7.2	Advantages	393
18.7.3	Disadvantages	394
18.7.4	Future Trends	394
	References	395
19	Transfer Molding	397
	<i>Muralisrinivasan Natamai Subramanian</i>	
19.1	Introduction	397
19.2	Curing	398
19.3	Processing	399
19.4	Mold	400
19.5	Process Optimization	400
19.6	Method	401
19.7	Pot Type Transfer Molding	401
19.7.1	Plunger/Transfer Molding	402
19.7.2	Screw Type Transfer Molding	402
19.7.3	Screw Injection Type	402
19.8	Troubleshooting	403
19.9	Summary	404
19.9.1	Advantages	404
19.9.2	Disadvantages	404
19.9.3	Future Trends	405
19.9.4	Fundamentals	405
	References	405
20	Pultrusion Process Troubleshooting	407
	<i>Joseph E. Sumerak</i>	
20.1	Introduction	407
20.1.1	Pultruded Products are Governed by a Performance Specification	409
20.2	Materials Review	410
20.2.1	Resin	410
20.2.2	Resin Reactivity	411
20.2.3	Resin Reactivity Measurement	412
20.2.4	Resin Viscosity	414
20.2.5	Reinforcements	415
20.3	Process Parameters	416
20.3.1	Composition and Process Specification	417

20.4	Manufacturing Defects	417
20.4.1	Defects	417
20.5	Material Related Defects	419
20.5.1	Resin	419
20.5.2	Reinforcements	420
20.6	Process Parameter Related Defects	422
20.7	Methods Related Defects	426
20.8	The Troubleshooting Process	429
20.8.1	Subjective versus Objective	429
20.8.2	Visual Tools	430
20.8.3	On-Line Quantitative Analysis Tools	434
20.8.4	Off-Line Quality Assessment Tools	435
20.9	Troubleshooting Examples	438
20.10	Summary	438
	Acknowledgement	439
	References	439
21	Troubleshooting Static Problems in Plastics Processes	441
	<i>Kelly Robinson</i>	
21.1	Introduction	441
21.1.1	Nature and Character of Static	441
21.1.2	Cost of Static Problems	442
21.2	Root Causes of Static	443
21.2.1	Tribocharging/Contact Charging	443
21.2.1.1	Triboelectric Series	444
21.2.2	Application of the Triboelectric Series	445
21.2.3	Charge Induction	446
21.2.4	Ionizer Imbalance (Active Charging)	446
21.3	Static Measurement Tools	447
21.3.1	Electrostatic Fieldmeters (FMs) and Non-Contacting Electrostatic Voltmeters (ESVMs)	447
21.3.1.1	Electrostatic Fieldmeters – Fieldmeters Respond to Net Charge	447
21.3.1.2	Non-contacting Electrostatic Voltmeter – Voltmeters Respond to Surface Charge	448
21.3.1.3	Spatial Resolution and Response Time	450
21.3.1.4	Typical Applications – Monitor Static Performance with Fieldmeters and Voltmeters	451
21.3.2	Charge Meter – Coulomb Meters are a Direct Measure of Charge	455
21.3.2.1	Principles of Operation	455
21.3.2.2	Typical Applications	456
21.3.3	Resistivity Meters	457
21.3.3.1	Volumetric Resistivity Meters	457
21.3.3.2	Surface Resistivity Meters	460
21.3.4	Charge Dissipation Time Measurements	463
21.3.4.1	Importance of Charge Dissipation Time	463
21.3.4.2	Principles of Operation – Static Dissipation Time	463
21.3.4.3	Typical Application – Static Dissipation Time	464

xvi CONTENTS

21.4	Static Problem Diagnosis	464
21.4.1	Understand the Problem	464
21.4.2	Baseline Data and Control Charts	465
21.4.3	Hot Rolls	467
21.4.4	Static Specifications	469
21.5	Solving Static Problems	470
21.5.1	Locate the Source of Charge Separation	471
21.5.1.1	Unwinding Roll	471
21.5.1.2	Drive Roller	472
21.5.1.3	Coater Backing Roller	472
21.5.1.4	Dryer Conveyance Rollers	474
21.5.1.5	Dryer Exit Nip Roller	474
21.5.1.6	Winder Lay-on Roller	474
21.5.2	Static Control System Maintenance	475
21.5.2.1	Clean Static Bars	476
21.5.2.2	Replace Ionizing String	476
21.5.2.3	Verify Gaps	476
21.5.2.4	Verify Performance	476
21.5.2.5	Clean Rollers, Belts and Guides	476
21.5.2.6	Restore Surfaces of Tacky (Cleaning) Rollers	476
21.5.2.7	Check the Electrical Resistivity of Static Dissipative Rollers	476
21.5.2.8	Test the Bearing Drag on Low Wrap Rollers	477
21.5.2.9	Align Roller	477
21.5.2.10	Nip Pressure	477
21.5.2.11	Lay-on Rollers	477
21.5.2.12	Web Tension	477
21.5.2.13	Winding Tension Profile	477
21.5.2.14	Humidifier Maintenance	477
21.5.3	Conductive Layers in Products	477
	References	478
	Recommended Reading for Further Study	479