

Contents

Preface	xv
1. Failure Analysis	1
I. Introduction / 1	
II. Examples of Case Studies Involving Structural Failures / 6	
III. Summary / 25	
References / 25	
Problems / 26	
2. Elements of Elastic Deformation	27
I. Introduction / 27	
II. Stress / 27	
III. Strain / 32	
IV. Elastic Constitutive Relationships / 35	
V. State of Stress Ahead of a Notch / 44	
VI. Summary / 46	
References / 46	
Appendix 2-1: Mohr Circle Equations for a Plane Problem / 46	
Appendix 2-2: Three-Dimensional Stress Analysis / 49	
Appendix 2-3: Stress Formulas Under Simple Loading Conditions / 54	
Problems / 57	

3. Elements of Plastic Deformation

59

- I. Introduction / 59
- II. Theoretical Shear Strength / 59
- III. Dislocations / 61
- IV. Yield Criteria for Multiaxial Stress / 68
- V. State of Stress in the Plastic Zone Ahead of a Notch in Plane-Strain Deformation / 70
- VI. Summary / 74
- For Further Reading / 75
- Appendix 3-1: The von Mises Yield Criterion / 75
- Problems / 76

4. Elements of Fracture Mechanics

80

- I. Introduction / 80
- II. Griffith's Analysis of the Critical Stress for Brittle Fracture / 80
- III. Alternative Derivation of the Griffith Equation / 83
- IV. Orowan-Irwin Modification of the Griffith Equation / 84
- V. Stress Intensity Factors / 85
- VI. The Three Loading Modes / 88
- VII. Determination of the Plastic Zone Size / 88
- VIII. Effect of Thickness on Fracture Toughness / 89
- IX. The *R*-Curve / 91
- X. Short Crack Limitation / 92
- XI. Case Studies / 92
- XII. The Plane-Strain Crack Arrest Fracture Toughness, K_{Ia} , of Ferritic Steels / 95
- XIII. Elastic-plastic Fracture Mechanics / 96
- XIV. Failure Assessment Diagrams / 98
- XV. Summary / 101
- References / 101
- Problems / 102

5. Alloys and Coatings

105

- I. Introduction / 105
- II. Alloying Elements / 106
- III. Periodic Table / 107

IV. Phase Diagrams / 108

V. Coatings / 126

VI. Summary / 130

References / 130

Problems / 130

6. Examination and Reporting Procedures

132

I. Introduction / 132

II. Tools for Examinations in the Field / 132

III. Preparation of Fracture Surfaces for Examination / 133

IV. Visual Examination / 133

V. Case Study: Failure of a Steering Column Component / 134

VI. Optical Examination / 135

VII. Case Study: Failure of a Helicopter Tail Rotor / 136

VIII. The Transmission Electron Microscope (TEM) / 136

IX. The Scanning Electron Microscope (SEM) / 138

X. Replicas / 142

XI. Spectrographic and Other Types of Chemical Analysis / 143

XII. Case Study: Failure of a Zinc Die Casting / 144

XIII. Specialized Analytical Techniques / 145

XIV. Stress Measurement by X-Rays / 146

XV. Case Study: Residual Stress in a Train Wheel / 149

XVI. The Technical Report / 150

XVII. Record Keeping and Testimony / 151

XVIII. Summary / 154

References / 155

Problem / 155

7. Brittle and Ductile Fractures

156

I. Introduction / 156

II. Brittle Fracture / 156

III. Some Examples of Brittle Fracture in Steel / 159

IV. Ductile-Brittle Behavior of Steel / 161

V. Case Study: The Nuclear Pressure Vessel Design Code / 168

VI. Case Study: Examination of Samples from the Royal Mail Ship (RMS)
Titanic / 172

- VII. Ductile Fracture / 177
- VIII. Ductile Tensile Failure, Necking / 177
- IX. Fractographic Features Associated with Ductile Rupture / 183
- X. Failure in Torsion / 185
- XI. Case Study: Failure of a Helicopter Bolt / 185
- XII. Summary / 188
 - References / 191
 - Problems / 191

8. Thermal and Residual Stresses **196**

- I. Introduction / 196
- II. Thermal Stresses, Thermal Strain, and Thermal Shock / 196
- III. Residual Stresses Caused by Nonuniform Plastic Deformation / 200
- IV. Residual Stresses Due to Quenching / 204
- V. Residual Stress Toughening / 207
- VI. Residual Stresses Resulting from Carburizing, Nitriding, and Induction Hardening / 207
- VII. Residual Stresses Developed in Welding / 209
- VIII. Measurement of Residual Stresses / 211
- IX. Summary / 211
 - References / 211
 - Appendix 8-1: Case Study of a Fracture Due to Thermal Stress / 212
 - Problems / 213

9. Creep **216**

- I. Introduction / 216
- II. Background / 216
- III. Characteristics of Creep / 217
- IV. Creep Parameters / 220
- V. Creep Fracture Mechanisms / 222
- VI. Fracture Mechanism Maps / 224
- VII. Case Studies / 225
- VIII. Residual Life Assessment / 230
- IX. Stress Relaxation / 232
- X. Elastic Follow-up / 233

- XI. Summary / 234
- References / 234
- Problems / 234

10. Fatigue**237**

- I. Introduction / 237
- II. Background / 237
- III. Design Considerations / 240
- IV. Mechanisms of Fatigue / 246
- V. Factors Affecting Fatigue Crack Initiation / 254
- VI. Factors Affecting Fatigue Crack Growth / 257
- VII. Analysis of the Rate of Fatigue Crack Propagation / 261
- VIII. Fatigue Failure Analysis / 273
- IX. Case Studies / 276
- X. Thermal-Mechanical Fatigue / 285
- XI. Cavitation / 285
- XII. Composite Materials / 286
- XIII. Summary / 287
- References / 287
- For Further Reading / 290
- Problems / 290

11. Statistical Distributions**293**

- I. Introduction / 293
- II. Distribution Functions / 293
- III. The Normal Distribution / 294
- IV. Statistics of Fatigue; Statistical Distributions / 296
- V. The Weibull Distribution / 298
- VI. The Gumbel Distribution / 302
- VII. The Staircase Method / 307
- VIII. Summary / 310
- References / 310
- Appendix 11-1: Method of Linear Least Squares (C. F. Gauss, 1794) / 311
- Problems / 314

12. Defects	316
I. Introduction / 316	
II. Weld Defects / 316	
III. Case Study: Welding Defect / 321	
IV. Casting Defects / 328	
V. Case Study: Corner Cracking during Continuous Casting / 329	
VI. Forming Defects / 329	
VII. Case Studies: Forging Defects / 330	
VIII. Case Study: Counterfeit Part / 332	
IX. The Use of the Wrong Alloys; Errors in Heat Treatment, etc. / 333	
X. Summary / 334	
References / 334	
Problems / 334	
13. Environmental Effects	336
I. Introduction / 336	
II. Definitions / 336	
III. Fundamentals of Corrosion Processes / 337	
IV. Environmentally Assisted Cracking Processes / 342	
V. Case Studies / 348	
VI. Cracking in Oil and Gas Pipelines / 350	
VII. Crack Arrestors and Pipeline Reinforcement / 352	
VIII. Plating Problems / 353	
IX. Case Studies / 353	
X. Pitting Corrosion of Household Copper Tubing / 356	
XI. Problems with Hydrogen at Elevated Temperatures / 356	
XII. Hot Corrosion (Sulfidation) / 358	
XIII. Summary / 358	
References / 358	
Problems / 359	
14. Flaw Detection	360
I. Introduction / 360	
II. Inspectability / 360	
III. Visual Examination (VE) / 364	

IV. Penetrant Testing (PT) / 364	
V. Case Study: Sioux City DC-10 Aircraft / 367	
VI. Case Study: MD-88 Engine Failure / 374	
VII. Magnetic Particle Testing (MT) / 375	
VIII. Case Study: Failure of an Aircraft Crankshaft / 378	
IX. Eddy Current Testing (ET) / 382	
X. Case Study: Aloha Airlines / 384	
XI. Ultrasonic Testing (UT) / 384	
XII. Case Study: B747 / 389	
XIII. Radiographic Testing (RT) / 389	
XIV. Acoustic Emission Testing (AET) / 391	
XV. Cost of Inspections / 393	
XVI. Summary / 393	
References / 394	
Problems / 394	
15. Wear	396
I. Wear / 396	
II. The Coefficient of Friction / 397	
III. The Archard Equation / 398	
IV. An Example of Adhesive Wear / 399	
V. Fretting Fatigue / 399	
VI. Case Study: Friction and Wear; Bushing Failure / 403	
VII. Roller Bearings / 404	
VIII. Case Study: Failure of a Railroad Car Axle / 410	
IX. Gear Failures / 410	
X. Summary / 414	
References / 414	
Problems / 415	
Concluding Remarks	417
Solutions to Problems	419
Name Index	469
Subject Index	473