
Contents

Introduction	ix
1 What Would You Expect with a Parent Like GM?.....	1
Interview Process	2
Packard Electric Is Born	3
How Could GM (Packard's Parents) Make So Many Dumb Decisions?	7
So, How Are Things Working Out for GM Today?	12
How Does GM Compete with Toyota and the Vaunted Toyota Production System?	15
2 We Have to Do Something, Even if It's Wrong.....	19
Packard Does a Really Smart Thing Next.....	21
Where Did the Packard Training Program Originate?	23
Good News and Bad News about Packard's Management	27
A Move to the Warm South	29
What We Need Are Suppliers	30
Mexico, Here We Come	33
Black Friday.....	33
Something Had to Change for GM.....	36
Packard Goes International in a Big Way	37
We Are Not Ready for This	38
We Are in Real Trouble Here	40
Industrial Engineering (IE) Training Program.....	43
The Industrial Engineering Training Program	44
3 How Does a Company with So Many Smart People Do So Many Dumb Things?	49
Automation Can Save Us	51
That Worked So Well, Let's Try Something a Little Tougher.....	53
That Lead Prep Startup Surely Didn't Work Out Like We Had Planned....	56

Integrated Production System (IPS) to the Rescue (or Not).....	59
If IPS Didn't Get It Done, IPS II Surely Would	67
Remote Lead Prep: Yeah, That's the Answer!	70
How about Just Getting Rid of Our Productivity Control System.....	74
So Just How Are IDCs Going to Help Us with the 3% Give Back?	77
How about Let's Just Get into a New Business	79
Let's Sum Things Up.....	80

4 Let's Get Lean ... Not83

Just What Is the TPS?	85
Toyota Production System Rules	98
Packard Develops the PPS.....	100
What We Need Is Vista	100
Benchmarking: To Do or Not to Do	102
Kitting Looks Like a Cool Thing to Do.....	105
Let's Do the Team Concept Like Toyota.....	109
How about a Nice Quality Circle?.....	110
Did QS9000 Implementation Really Help?	112
Say Zero Defects and Mean It.....	114
The Good News Is That We Saved \$25 Million in Inventory, but	115
Just-in-Time Manufacturing?.....	118
U-Cells Gain Great Prominence	120
Somebody Finally Got One-Piece Flow Right ... Really?	122
Wrap-Up	128

5 Proper Manufacturing Organization Is Critical (or You Will Get the Performance You Motivate)..... 131

Plant Priority Meetings.....	132
Let's Just Change Reporting Lines to Get Better Support.....	133
Warren Got Some Things Right	139
Understanding Human Nature.....	139
So We Transferred Our Manufacturing Successes to Mexico, Right?	143
What's the Fix?	147
Manufacturing Supervision Is Tough.....	150
Providing Proper Manufacturing Support.....	150
Why Worry about Improved Productivity, Mexican Labor Is Cheap (and Philippine).....	151
Wiring Harness Departmental Organization Basics	152
Level 1 Operators	153
Level 2 Operators	153

Level 3 Operators	154
Level 4 Operators	155
Foreman's Responsibilities and Support Required	156
Job Responsibilities.....	156
Time Breakdown	157
Assistant Foremen/Group Leaders	158
Additional Advice	158
6 When You Measure Performance, Performance Improves	161
From Routings to Direct Labor Bibles (DLBs).....	162
Production Efficiency	164
Process and Operator Efficiencies.....	166
Wouldn't One Efficiency Number Be Sufficient?	168
The Warren Bottom Line	169
So, What Did We Do in Mexico?.....	170
I Finally Got a Chance to Do It Right in South Korea	171
How Much Could the Mexican Operations Have Saved?.....	177
When You Measure Performance.....	182
Packard Productivity Nose Dives	184
Are We Really Controlling Productivity in Our Plants?.....	184
Direct Labor Bibles (DLBs)	185
Efficiencies from a Budget Routing	186
Plant Productivity Information Available Based on Labor Estimates (Budget DLBs) Only.....	186
Plant Productivity Information Available with an Automated Productivity System Based on Production DLBs.....	188
Terms and Definitions Used with the Computerized Productivity System	190
Simple DLB Example	192
Metal Cutting.....	193
Component Subassembly	195
Final Assembly of a Widget	195
7 Preplanning: The Perfect Tool to Accomplish Toyota's Rule #1.....	199
What Is the Common Industry Practice?.....	200
But, Is It Worth It?.....	202
Packard Evolves, but Not for the Better	205
The Critical Four M Relationship	207
Wiring Harness Preplanning	208

8	The Computer Is a Moron.....	219
	A Rare Opportunity	222
	Controlling Absenteeism, Turnover, and Overtime Is a Must	226
	Material Availability Is Critical	231
	Summary	235
9	How to Drive Down Total Process Cycle Time (TPCT) without Wasting a Lot of Time (and Money).....	237
	Critical Value Streams	239
	Packard “Attacks” the TPCT for Engineering Change Implementation	240
	Key Activity Control Is Born.....	242
	Others Benefit from the System	248
	This System/Concept Will Work Anywhere.....	255
	The Bottom Line	258
10	What Size Should the Cycle Quantity (Lot Size) Be?.....	259
	Portugal Will Show the Way.....	263
	Cost Bucket One	264
	Cost Bucket Two	266
	Some People Don’t Want to Be Confused with Facts	267
	Free Rein in South Korea.....	270
	Determining Optimum Cut Quantity (or Optimum Process Quantity).....	272
	Summary	279
	Optimum Cut Quantity Subsystem.....	280
	Optimum Cutter Loading and Sequencing Subsystem (OCLASS)	286
11	Wrap-Up: How about “Intelligent Manufacturing” for Real Change in Which We Can Believe.....	291
	Index	301
	About the Author.....	309