

# Contents

<b>1</b>	<b>Introduction to the Technology of Cutting and Abrasive Processes</b> . . . . .	1
1.1	Economic Relevance . . . . .	1
1.2	Taxonomy . . . . .	3
1.3	Motions, Angles at the Cutting Edge and Engagement Parameters . . . . .	4
1.4	Cutting and Abrasive Processes as Black Box Systems . . . . .	8
1.5	Process Types and Engagement Parameters in Drilling . . . . .	9
1.6	Process Types and Engagement Parameters in Milling . . . . .	15
1.7	Questions . . . . .	18
	References . . . . .	19
<b>2</b>	<b>Chip Formation</b> . . . . .	21
2.1	Mechanisms of Chip Formation . . . . .	21
2.2	Chip Root Analysis . . . . .	25
2.3	Shear Plane Model . . . . .	29
2.4	Questions . . . . .	35
	References . . . . .	36
<b>3</b>	<b>Chip Control</b> . . . . .	37
3.1	Chip Volume Ratio and Chip Form Classification . . . . .	37
3.2	Chip Guidance . . . . .	38
3.3	Influence of the Workpiece Material . . . . .	42
3.4	Influence of the Cutting Conditions . . . . .	45
3.5	Questions . . . . .	46
	References . . . . .	48
<b>4</b>	<b>Forces and Powers in Cutting and Abrasive Processes</b> . . . . .	49
4.1	Empirical Models . . . . .	50
4.2	Modeling of the Feed Force and the Passive Force . . . . .	59
4.3	Surface Forces at the Cutting Edge . . . . .	60

4.4	Analytical Approaches in Plastomechanics . . . . .	63
4.4.1	Theory by Ernst and Merchant. . . . .	63
4.4.2	Hucks's Theory . . . . .	64
4.5	Flow Curves and Constitutive Equations . . . . .	66
4.6	Numerical Theory. . . . .	68
4.7	Powers, Torques and Forces in Drilling. . . . .	70
4.8	Power and Forces in Milling Processes . . . . .	76
4.9	Questions. . . . .	80
	References . . . . .	81
<b>5</b>	<b>Energy Conversion and Temperature . . . . .</b>	<b>83</b>
5.1	Conversion Effects . . . . .	83
5.2	Heat Flow . . . . .	86
5.3	Temperatures of Cutting Wedge and Workpiece. . . . .	89
5.3.1	Temperature Measurement. . . . .	89
5.3.2	Temperature Fields . . . . .	96
5.4	Optimization of the Cutting Wedge . . . . .	101
5.5	Questions. . . . .	102
	References . . . . .	103
<b>6</b>	<b>Modeling and Simulation . . . . .</b>	<b>105</b>
6.1	Kinematic Simulation . . . . .	106
6.1.1	Representation of the Workpiece . . . . .	108
6.1.2	Tool Model . . . . .	114
6.1.3	Determination of Process Values . . . . .	115
6.2	Numerical Simulation by FEM. . . . .	119
6.3	Molecular Dynamic Modeling . . . . .	123
6.4	Questions. . . . .	126
	References . . . . .	126
<b>7</b>	<b>Wear . . . . .</b>	<b>129</b>
7.1	Wear Forms. . . . .	129
7.2	Loading. . . . .	132
7.3	Wear Mechanisms . . . . .	138
7.4	Tool Life. . . . .	140
7.5	Tool Life Scatter and Process Reliability. . . . .	146
7.6	Influence of Work Material on Wear . . . . .	148
7.6.1	Work Material Composition. . . . .	149
7.6.2	Melting Procedure . . . . .	150
7.6.3	Heat Treatment . . . . .	152
7.7	Rounding of the Cutting Edge . . . . .	153
7.8	Questions. . . . .	156
	References . . . . .	157

<b>8</b>	<b>Cutting Materials</b> . . . . .	159
8.1	Requirements on Cutting Materials. . . . .	159
8.2	Tool Steels . . . . .	163
8.3	High Speed Steels . . . . .	163
8.4	Stellites . . . . .	165
8.5	Cemented Carbides. . . . .	166
8.6	Cermets . . . . .	174
8.7	Ceramics . . . . .	176
8.8	Diamond . . . . .	181
	8.8.1 Mono-Crystalline Diamond . . . . .	181
	8.8.2 Polycrystalline Diamond . . . . .	181
8.9	Boron Nitride. . . . .	183
8.10	Questions. . . . .	186
	References . . . . .	187
<b>9</b>	<b>High Speed Cutting</b> . . . . .	189
9.1	Definition . . . . .	189
9.2	Chip Formation . . . . .	192
9.3	Application . . . . .	193
9.4	High Power Cutting . . . . .	196
9.5	High Power Drilling . . . . .	196
9.6	Questions. . . . .	198
	References . . . . .	199
<b>10</b>	<b>Hard Machining, Process Design</b> . . . . .	201
10.1	Hard Turning . . . . .	201
10.2	Hard Drilling . . . . .	207
10.3	Hard Milling . . . . .	209
10.4	Materials . . . . .	211
10.5	Chip Formation, Forces and Temperature . . . . .	212
10.6	Cutting Materials and Tool Wear . . . . .	217
10.7	Questions. . . . .	218
	References . . . . .	219
<b>11</b>	<b>Hard Machining, Component Quality</b> . . . . .	221
11.1	Macro Geometrical Deviations. . . . .	221
11.2	Micro Geometrical Properties. . . . .	224
11.3	Physical Influence . . . . .	226
11.4	Rolling Fatigue Strength . . . . .	227
11.5	Fatigue Strength . . . . .	228
11.6	Sealability . . . . .	230
11.7	Post-treatment Processes . . . . .	231
	11.7.1 Hard Roller Burnishing . . . . .	231
	11.7.2 Water Peening . . . . .	233

11.8	Questions . . . . .	234
	References . . . . .	235
<b>12</b>	<b>Broaching . . . . .</b>	<b>237</b>
12.1	Broaching Process . . . . .	237
12.2	Machine Development . . . . .	242
12.3	Questions . . . . .	246
	References . . . . .	246
<b>13</b>	<b>Grinding . . . . .</b>	<b>247</b>
13.1	Cutting with Geometrically Undefined Cutting Edges . . . . .	247
13.2	Grinding Materials . . . . .	250
13.2.1	Corundum . . . . .	251
13.2.2	Silicon Carbide . . . . .	253
13.2.3	Cubic Crystalline Boron Nitride and Diamond . . . . .	254
13.2.4	Grain Sizes of Grinding Materials . . . . .	255
13.3	Bonding . . . . .	257
13.4	Grinding Wheels . . . . .	258
13.5	Burst Safety of Grinding Wheels . . . . .	261
13.6	Grinding Processes . . . . .	265
13.6.1	Input Variables . . . . .	266
13.6.2	Process Variables . . . . .	276
13.6.3	Output Variables . . . . .	279
13.7	Conditioning of Grinding Tools . . . . .	286
13.7.1	Basics . . . . .	286
13.7.2	Conditioning of Conventional Grinding Wheels . . . . .	290
13.7.3	Conditioning of Super Hard Grinding Wheels . . . . .	292
13.8	Grinding Costs . . . . .	295
13.9	Questions . . . . .	296
	References . . . . .	297
<b>14</b>	<b>Gear Grinding . . . . .</b>	<b>303</b>
14.1	Introduction . . . . .	303
14.2	Discontinuous Profile Grinding . . . . .	308
14.3	Continuous Generating Grinding with Grinding Worms . . . . .	312
14.4	Continuous Crossed Helical Grinding . . . . .	316
14.5	Questions . . . . .	320
	References . . . . .	321
<b>15</b>	<b>Process Layout and Integration into the Process Chain . . . . .</b>	<b>325</b>
15.1	Basics of Process Chain Layout . . . . .	325
15.1.1	Technological Interfaces . . . . .	326
15.1.2	Process Chain Layout . . . . .	327
15.2	Process Model Generation . . . . .	328

15.3	Process Layout Using the Example of “Hard Finishing” . . . . .	331
15.4	Process Chain Layout Using the Example “Gear Production” . . . . .	335
15.5	Process Supervision . . . . .	341
15.6	Questions. . . . .	345
	References . . . . .	346
<b>16</b>	<b>Surface and Subsurface Properties . . . . .</b>	<b>349</b>
16.1	Surface Properties. . . . .	350
	16.1.1 Determination of Surface Properties . . . . .	351
16.2	Subsurface Properties . . . . .	355
	16.2.1 Determination of Subsurface Properties. . . . .	356
	16.2.2 Effects of Cutting Processes. . . . .	362
16.3	Questions. . . . .	368
	References . . . . .	369
<b>17</b>	<b>Cooling Lubrication . . . . .</b>	<b>371</b>
17.1	Requirements . . . . .	371
17.2	Cooling Lubricating Fluids . . . . .	373
	17.2.1 Not Water-Mixable Cooling Lubricating Fluids . . . . .	373
	17.2.2 Water-Mixable Cooling Lubricating Fluids . . . . .	375
	17.2.3 Additivation of Cooling Lubricating Fluids . . . . .	378
17.3	Use of Cooling Lubricating Fluids in Geometrically Determined Cutting. . . . .	380
17.4	Use of Cooling Lubricating Fluid in Grinding . . . . .	383
	17.4.1 Methods to Determine the Cooling Lubricating Fluid Effect in Grinding . . . . .	385
	17.4.2 Applications and Effects . . . . .	387
17.5	Questions. . . . .	392
	References . . . . .	393
<b>18</b>	<b>Appendix . . . . .</b>	<b>397</b>
18.1	Solution to the Exercise for Chap. 3, Question 9 . . . . .	397
18.2	Solution to the Exercise for Chap. 4, Question 26 . . . . .	397
18.3	Solution to the Exercise for Chap. 5, Question 17 . . . . .	398
18.4	Solution to the Exercise for Chap. 6, Question 25 . . . . .	399