

Contents

Preface to the Second Edition of the Handbook of Induction Heating	xvii
Authors	xxi
1. Introduction	1
2. Industrial Applications of Induction Heating	9
2.1 Heat Treatment by Induction	12
2.1.1 Hardening	12
2.1.1.1 Surface Hardening	14
2.1.1.2 Through Hardening	20
2.1.1.3 Selective Hardening	21
2.1.2 Tempering and Stress Relieving	22
2.1.3 Normalizing	24
2.1.4 Annealing	25
2.1.4.1 Full Annealing and Homogenization	25
2.1.4.2 Intercritical Annealing	26
2.1.4.3 Subcritical Annealing	27
2.1.4.4 Spheroidized Anneal or Spheroidizing	30
2.1.5 Induction Heat Treating of Nonferrous Metallic Materials	30
2.2 Induction Mass Heating	32
2.2.1 Bar, Rod, and Billet Reheating	33
2.2.2 Thixoforming Applications	37
2.2.3 Tube, Pipe, and Vessel Heating	37
2.2.4 Wire, Rope, and Cable Heating	38
2.2.5 Slab, Plate, Rectangular Bar, and Bloom Heating	39
2.2.6 IH of Strips, Thin Slabs, Plates, Films, and Sheets	40
2.2.7 Coating	41
2.2.7.1 Curing of Paints and Varnishes	41
2.2.7.2 Preheating before Thermal Spraying	42
2.2.7.3 Galvannealing, Galvanizing, and Galvaluming	42
2.3 Special Applications of IH	43
2.3.1 Joining, Friction Welding, Brazing, Bonding, Soldering, and Sealing ...	43
2.3.2 Shrink Fitting and Disassembling	44
2.3.3 Motor Rotor Heating	45
2.3.4 Seam Annealing	46
2.3.5 Induction-Assisted Laser Materials Processing	46
2.3.6 Food Industry	47
2.3.7 Papermaking	47
2.3.8 Wool and Wood Processing	47
2.3.9 Chemical Industry	47
2.3.10 Cap Sealing	47
2.3.11 Miscellaneous	48
2.4 Induction Melting	48
2.4.1 Induction Channel-Type Melting Furnace	48

2.4.2	Induction Crucible-Type (Coreless) Furnace	48
2.4.3	Induction Vacuum Melting	49
2.5	Induction Welding	49
2.6	Conclusion.....	50
3.	Theoretical Background.....	51
3.1	Basic Electromagnetic Phenomena in IH	51
3.1.1	Electromagnetic Properties of Metallic Materials.....	53
3.1.1.1	Electrical Resistivity (Electrical Conductivity)	53
3.1.1.2	Magnetic Permeability and Relative Permittivity (Dielectric Constant)	55
3.1.2	Skin Effect.....	60
3.1.3	Electromagnetic Proximity Effect	66
3.1.4	Electromagnetic Slot Effect.....	69
3.1.5	Electromagnetic Ring Effect.....	71
3.1.6	Electromagnetic Force.....	72
3.1.7	Introduction to Electromagnetic End and Edge Effects.....	78
3.1.7.1	Electromagnetic Longitudinal End Effect	79
3.1.7.2	Helix Effect.....	85
3.1.7.3	Electromagnetic Transverse Edge Effect	85
3.1.7.4	Electromagnetic Effect of Joined Materials with Different Electromagnetic Properties (EEJ Effect).....	88
3.2	Thermal Phenomena in IH.....	90
3.2.1	Thermal Properties of the Materials	90
3.2.1.1	Thermal Conductivity	90
3.2.1.2	Heat Capacity and Specific Heat.....	91
3.2.2	Three Modes of Heat Transfer	92
3.2.2.1	Thermal Conduction.....	92
3.2.2.2	Convection Mode of the Heat Transfer	93
3.2.2.3	Radiation Mode of the Heat Transfer	94
3.3	Estimation of the Required Power and Dynamics of IH	95
3.3.1	Estimation of the Required Power for IH.....	95
3.3.2	Intricacies of the Dynamics of IH.....	99
3.4	Advanced Induction Principles and Mathematical Modeling	102
3.4.1	Mathematical Modeling of the Electromagnetic Field	103
3.4.2	Mathematical Modeling of the Thermal Processes	109
3.4.3	Numerical Computation of the Process.....	111
3.4.3.1	Traditional Methods of Calculation.....	111
3.4.3.2	Finite Difference Method	112
3.4.3.3	Finite Element Method	119
3.4.3.4	Mutual Impedance Method	126
3.4.3.5	Boundary Element Method	129
3.4.3.6	Coupling of the Electromagnetic and Thermal Problems.....	130
3.4.3.7	Comparison of Different Numerical Techniques and Final Remarks Regarding Computer Modeling	132
3.4.4	Limitations of Generalized All-Purpose Commercial Programs.....	133
3.4.5	Crucial Tips Executives Must Know Regarding Computer Modeling of IH.....	136

4. Heat Treatment by Induction	139
4.1 The Basics of Metallurgy and Principles of Heat Treatment of Steels and Cast Irons.....	139
4.1.1 Crystalline Structures and Critical Temperatures.....	140
4.1.2 Fe–Fe ₃ C Phase Transformation Diagram and Steel Classifications.....	145
4.1.2.1 Classifications of Steels.....	146
4.1.2.2 Steel Identification Systems	149
4.1.2.3 Phases of the Equilibrium Fe–Fe ₃ C Diagram.....	150
4.1.3 Time–Temperature Transformation Diagram and Continuous-Cooling Transformation Diagram.....	153
4.1.4 Steel's Trace (Residual) Elements and Alloying Elements	163
4.1.5 Hardenability	169
4.1.5.1 Through Hardening.....	169
4.1.5.2 Induction Surface (Case) Hardening	176
4.1.5.3 Summary of the Limitations of Standard Forms of Hardenability Tests	178
4.1.6 Effect of Heat Intensity (Heating Rate) and Prior Structure on Induction Heat Treatment Results in Steels	180
4.1.7 Super-Hardness Phenomenon	188
4.1.8 Inclusions	190
4.1.9 Grain Boundary Liquation (Incipient Melting).....	192
4.1.10 Specifics of Induction Hardening Stainless Steels and Bearing Steels.....	194
4.1.10.1 Physical Properties.....	196
4.1.10.2 Hardening Specifics.....	196
4.1.11 Induction Heat Treatment of Cast Irons.....	198
4.1.11.1 Gray Cast Irons.....	203
4.1.11.2 Ductile Cast Irons.....	205
4.1.11.3 Specifics of Electromagnetic and Thermal Properties.....	208
4.1.11.4 Good Practices in Induction Hardening of Cast Irons and Closing Remarks.....	210
4.1.12 Specifics of Induction Hardening of Powder Metallurgy Materials	218
4.2 Induction Hardening: Subtleties of Machine Design and Process Recipe Selection.....	222
4.2.1 Hardness Case Depth Definitions.....	225
4.2.2 Induction Hardening Methods.....	227
4.2.2.1 Scan Hardening.....	227
4.2.2.2 Continuous and Progressive Hardening	248
4.2.2.3 Single-Shot Hardening	254
4.2.2.4 Static Hardening.....	263
4.2.2.5 Pulse Heating Mode	267
4.2.3 Specialty Inductors	267
4.2.3.1 Pancake, Split-Return, Butterfly, and Hairpin Inductors.....	268
4.2.3.2 Specifics of Designing Inductors for Heating Interior Surfaces.....	272
4.2.3.3 Proximity Induction Heating of Flat and Plane Surfaces.....	275
4.2.3.4 Inductors with Inserts	275
4.2.3.5 Clamshell or Split Inductors	276
4.2.3.6 Profiled Inductors.....	278

4.2.4	Fabrication and Cooling of Hardening Inductors.....	280
4.2.4.1	Material Selection.....	280
4.2.4.2	Fabrication Techniques.....	282
4.2.4.3	Surface Conditions.....	286
4.2.4.4	Water Cooling of Hardening Inductors.....	289
4.2.5	Frequency Choice and Power Selection.....	293
4.2.5.1	Through Hardening.....	293
4.2.5.2	Surface Hardening.....	294
4.2.5.3	Heat Duration.....	296
4.2.6	Inductor Mounting Styles.....	297
4.2.7	Quenching and Spray Quench Designs.....	299
4.2.7.1	Introduction.....	299
4.2.7.2	Quench Media.....	301
4.2.7.3	Quench Methods.....	304
4.2.7.4	Part Cleaning before Heating and after Quenching.....	306
4.2.7.5	Quench Systems Design and Controls.....	307
4.2.8	Striping (Striation) Phenomena, Barber-Pole Effect, and Snakeskin (Soft-Spotting) and Fish-Tail Phenomena.....	310
4.2.8.1	Striping Phenomena and Barber-Pole Effect.....	310
4.2.8.2	Snake-Skin Effect and Soft-Spotting Phenomena.....	314
4.2.8.3	Fish-Tail Effect (Field-Fringing Phenomenon).....	315
4.3	Holes, Keyways, Grooves, Undercuts, and Other Geometrical Irregularities....	316
4.3.1	Longitudinal (Axial) Holes and Longitudinally Oriented Hollow Areas.....	317
4.3.2	Transverse (Radial) Holes.....	318
4.3.3	Angled Holes.....	320
4.3.4	Other Factors.....	321
4.4	Control of Distortion and Prevention of Cracking.....	324
4.5	Accessory Equipment and Work Handling for Heat Treating.....	335
4.5.1	Robots, Gantries, and Pick-and-Place Units.....	335
4.5.2	Hoppers and Magazines.....	336
4.5.3	Conveyors.....	336
4.5.4	Rotary Tables.....	337
4.5.5	Unscramblers and Bar Feeders.....	337
4.5.6	Cylindrical Part Feed Mechanisms.....	337
4.5.7	Pipe and Tube Handling Equipment.....	337
4.5.8	Basket-to-Basket Systems for Long Products.....	338
4.5.9	Strip Heating Mechanisms.....	338
4.5.10	Accessory Systems for Processing Large Steel Plates.....	338
4.5.11	Work Holding Centers.....	339
4.6	Tempering of Induction-Hardened Components.....	339
4.6.1	General Comments Regarding Tempering.....	339
4.6.2	Self-Tempering ("Slack Quenching").....	344
4.6.3	Induction Tempering and Its Features.....	347
4.6.3.1	Coil Design and Process Parameters.....	349
4.6.3.2	Flux Manager Technology for Stress Relief of Oil Country Tubular Goods.....	356
4.6.3.3	C-Core Inductors.....	370
4.6.4	Final Remarks.....	374

4.7	Magnetic Flux Control Techniques: Concentrators, Intensifiers, Shunts, and Shields.....	376
4.7.1	Electromagnetic Shields.....	377
4.7.2	Magnetic Shunts.....	379
4.7.3	Magnetic Flux Concentrators.....	379
4.7.3.1	Physics of the Magnetic Flux Concentration.....	380
4.7.3.2	Design and Application Features.....	381
4.7.3.3	Selection of the Flux Concentrator Materials.....	383
4.7.3.4	Advantages and Drawbacks of Using Magnetic Flux Concentrators.....	386
4.8	Heat Treating Equipment Maintenance.....	389
4.8.1	Power Supply.....	390
4.8.1.1	Visual Inspection.....	390
4.8.1.2	Mechanical Test.....	390
4.8.1.3	Ohm-Meter Tests.....	390
4.8.1.4	Power Measurements (Meter or Oscilloscope).....	391
4.8.1.5	Meters and Limit Lamps.....	391
4.8.1.6	Audible and Visual Observation.....	391
4.8.2	Heat Station, Bus Connections, and Inductor Foot.....	392
4.8.2.1	Visual.....	392
4.8.2.2	Mechanical Test.....	393
4.8.2.3	Ohm-Meter/Capacitor/Meter/Load Frequency Analyzer.....	393
4.8.2.4	Audible and Visual Observation.....	393
4.8.3	Water Recirculating System.....	394
4.8.3.1	Visual.....	394
4.8.3.2	Meter Measurement.....	394
4.8.3.3	Pressure Flow and Temperature Measurement.....	394
4.8.3.4	Audible and Visual Observation.....	395
4.8.4	Quench Recirculating System.....	395
4.8.4.1	Visual.....	395
4.8.4.2	Meter Measurement.....	396
4.8.4.3	Pressure Flow and Temperature Measurement.....	396
4.8.4.4	Audible and Visual Observation.....	396
4.8.5	Heat Treating Inductor Maintenance and Storage.....	396
4.8.5.1	Consistent Workpiece Holding.....	396
4.8.5.2	Keeping the Inductor Clean.....	396
4.8.5.3	Visual Inspection.....	397
4.8.5.4	Maintain Electrical Contacts.....	397
4.8.5.5	Maintaining Spares.....	398
4.8.6	Flux Concentrators.....	398
4.8.7	Heat-Treating Machinery Maintenance.....	400
4.8.7.1	Visual.....	400
4.8.7.2	Audible and Visual Observation.....	400
4.8.7.3	Safety Circuits.....	401
4.9	Review of Selected IHT Applications.....	401
4.9.1	Gear, Pinion and Sprocket Hardening.....	401
4.9.1.1	Material Selection and Required Gear Conditions before Heat Treatment.....	403

4.9.1.2	Overview of Hardness Patterns	404
4.9.1.3	Coil Design and Heating Mode.....	406
4.9.2	Hardening of Steering Racks	421
4.9.3	Induction Hardening Raceways for the Wind Energy Industry	422
4.9.4	Induction Hardening of Crankshafts	425
4.9.4.1	Introduction	425
4.9.4.2	Technologies for Crankshaft Heat Treating	426
4.9.4.3	Summary Regarding SHarP-C Technology	435
4.9.5	Induction Hardening of Camshafts	436
4.9.5.1	Scan Hardening	437
4.9.5.2	Single-Shot Hardening	438
4.9.5.3	Static (Nonrotational) Hardening	440
4.10	Solutions for Solving Typical IHT Problems: Questions and Answers	442
4.10.1	Case Study #1. The Power-Scan Rate-Hardness Relationship.....	442
4.10.2	Case Study #2. Cryogenic Coil Cooling.....	443
4.10.3	Case Study #3. Chain Hardening	443
4.10.4	Case Study #4. Hardness at Diameter Change in Scan Hardening of Stepped Shafts	444
4.10.5	Case Study #5. Quenchant pH and Corrosion.....	445
4.10.6	Case Study #6. Copper Coil Wall Thickness vs. Coil Life.....	445
4.10.7	Case Study #7. Residual Magnetism	446
4.10.8	Case Study #8. Heating with Variable Axial Gaps between Long Rods	448
4.10.9	Case Study #9. Hollow Shafts with Holes and Splines	448
4.10.10	Case Study #10. Graphs of Hardened Case Depth vs. Power.....	450
4.10.11	Case Study #11. Induction Tempering and Residual Stress Distribution.....	451
4.10.12	Case Study #12. Soft Spots after Grinding	453
4.10.13	Case Study #13. Safety Warning for People with Pacemakers, Metallic Implants, etc.	453
4.10.14	Case Study #14. Re-Hardening of Already Hardened Parts.....	455
4.10.15	Case Study #15. Etched vs. Unetched Samples in Crack Detection.....	456
4.10.16	Case Study #16. Induction Heating of Ultra-Thin Conductive Coatings.....	457
4.10.17	Case Study #17. Distortion of Shafts in Induction Hardening	457
4.10.18	Case Study #18. Uniform Heating of Steel Plates.....	459
4.10.19	Case Study #19. Circumferential Hardness Variation Using Single-Shot Inductors	460
4.10.20	Case Study #20. Non-Martensitic Structures in Induction Hardened Parts	461
5.	Joining Applications	463
5.1	Brazing and Soldering by Induction	463
5.1.1	Overview.....	465
5.1.2	Types of Joints	466
5.1.3	Size and Shape Factors.....	467
5.1.4	Frequency Selection.....	468
5.1.5	Types of Inductors and Coil Design Features.....	469
5.1.6	Overview of Filler Materials and Flux Selection.....	473

5.1.7	Fixturing and Handling	475
5.1.8	Summary.....	477
5.2	Bonding	478
5.3	Cap Sealing	481
5.4	Shrink Fitting.....	482
5.5	Motor Rotor Heating.....	484
6.	Induction Mass Heating.....	487
6.1	Applications, Design Approaches, and Fundamental Principles of Induction Mass Heating before Metal Hot and Warm Working	487
6.1.1	Hot and Warm Working Steels	488
6.1.2	Stainless Steels and Superalloys	490
6.1.2.1	Stainless Steels	490
6.1.2.2	Superalloys	492
6.1.3	Steel Surface Oxidation and Scaling	495
6.1.4	Target Temperatures. Factors Associated with Steel Overheating	502
6.1.5	Design Concepts	507
6.2	In-Line IH of Long Cylinder Bars and Rods	516
6.2.1	Electrothermal Nature of In-Line IH	516
6.2.2	Longitudinal and Transverse Cracks.....	522
6.2.3	Transient Processes and Nose-to-Tail Temperature Profiles	522
6.2.4	Energy Efficiency of In-Line Cylinder Bar and Rod Heaters	525
6.3	Billet Heating	527
6.3.1	IH of Steel Billets.....	527
6.3.1.1	Progressive Heating of Billets	527
6.3.1.2	Maximizing Flexibility of Induction Billet Heaters	536
6.3.1.3	Static Heating of Billets	539
6.3.2	IH of Nonferrous Billets.....	547
6.3.3	Hybrid Designs: Induction + Gas Furnace versus Gas Furnace + Induction	551
6.3.3.1	Induction Is Followed by Gas Furnace.....	551
6.3.3.2	Gas Furnace Is Followed by an Induction Heater	551
6.4	Bar/Billet/Rod End Heating	552
6.5	Billet/Slug Heating for Semisolid Processing.....	556
6.5.1	Nature of Semisolid Processing and Basic Phenomena	557
6.5.2	Shortcomings of Mathematical Modeling of IH for Semisolid Casting.....	559
6.5.3	Technological Aspects of Commercial IH Systems for SSM Forming....	561
6.6	Intricacies of Induction Wire/Cable/Rope Heating.....	562
6.6.1	Specifics of Design Criteria and Coil Arrangements.....	562
6.6.2	Energy Efficiency	565
6.6.2.1	Frequency Selection	565
6.6.2.2	Ferrous and Nonferrous Wires	565
6.6.2.3	System Geometry Factor	566
6.6.3	Commercial Aspects of Induction Wire, Cable, and Rope Heaters.....	567
6.7	Tube and Pipe Heating	568
6.7.1	Specifics of IH of Tubular Products.....	568
6.7.2	In-Line IH of Tubes and Pipes and Their Applications.....	571

6.7.3	Selective Heating of Tubular Products: Case Studies of Typical Applications.....	574
6.8	Slab, Plate, Bloom, and Rectangular Bar Heating	578
6.8.1	General Remarks.....	578
6.8.2	Longitudinal Electromagnetic End Effects of Rectangular Workpiece	581
6.8.2.1	Nonmagnetic Slab	581
6.8.2.2	Magnetic Slab.....	582
6.8.3	Electromagnetic Transverse Edge Effect.....	583
6.8.3.1	Transverse Edge Effect of Nonmagnetic Slab	583
6.8.3.2	Specifics of the Transverse Edge Effect of a Magnetic Slab...	585
6.8.3.3	Dynamics of Transverse Edge Effect during the Heating Cycle	586
6.8.4	Design Concepts of Heating Rectangular Workpieces: Case Studies of Commercial Installations	586
6.8.4.1	Static Heating.....	586
6.8.4.2	In-Line Continuous Heating.....	588
6.8.4.3	Oscillating Heating.....	589
6.9	In-Line IH of Strip, Sheet, Plate, Thin Slab, and Transfer Bar.....	591
6.9.1	Strip-Coating Processes	591
6.9.1.1	Metallic Coating of Strips (Galvanizing, Galvaluming, Galvannealing, and Tinning)	591
6.9.1.2	Nonmetallic Coatings.....	598
6.9.2	Coil Design Concepts for Heating Strips, Plates, Sheets, and Thin Slabs	598
6.9.2.1	Longitudinal Flux Inductor (Solenoid Coil)	599
6.9.2.2	Transverse Flux Induction Heater	603
6.9.2.3	Traveling Wave Induction Heater	606
6.9.2.4	Channel-Type Edge Heaters	607
6.9.2.5	C-Core Edge Heaters.....	608
6.9.2.6	Doorless Technology for Strip Processing Lines	609
7.	Power Supplies for Modern Induction Heating	611
7.1	Power–Frequency Combinations.....	611
7.2	Elements of Power Electronics	611
7.2.1	Inductors	613
7.2.2	Capacitors.....	614
7.2.3	Litz Wire and Cable	614
7.2.4	Vacuum Tubes and Power Semiconductors	614
7.2.4.1	SCR or Thyristor.....	614
7.2.4.2	Diode or Rectifier	615
7.2.4.3	Transistors	615
7.2.4.4	Vacuum Tube Oscillators	618
7.2.4.5	Power–Frequency Application of Semiconductors	618
7.3	Types of IH Power Supplies.....	618
7.3.1	Rectifier or Converter Section	620
7.3.1.1	Full-Bridge Uncontrolled Rectifier.....	620
7.3.1.2	Phase-Controlled Rectifier.....	621
7.3.1.3	Uncontrolled Rectifier followed by Regulator	621
7.3.1.4	Active Three-Phase Rectifiers.....	623

7.3.2	Importance of Good Input Line Power Factor	624
7.3.3	Input Line Harmonics and Their Reduction	624
7.3.3.1	Recommended Distortion Limits.....	625
7.3.3.2	Solutions to Power Factor and Harmonic Problems	626
7.3.4	Inverter Section	627
7.3.4.1	Full-Bridge Inverter.....	627
7.3.4.2	Half-Bridge Inverter.....	628
7.3.4.3	Voltage-Fed Inverters with Simple Series Load	628
7.3.4.4	Voltage-Fed Inverter with Series Connection to a Parallel Load (LC-LC).....	631
7.3.4.5	Voltage-Fed Inverter with Series Inductor Connected to a Parallel Load (L-LC).....	632
7.3.4.6	Full-Bridge Current-Fed Inverters	632
7.3.4.7	"E" Bridge Current-Fed Inverter	635
7.3.4.8	Single-Switch Inverter	636
7.3.5	Advances in Power Supply Control	636
7.3.5.1	Circuit Boards	637
7.3.5.2	Fault Detection.....	637
7.3.5.3	Communication	638
7.3.6	Operational Considerations	638
7.3.6.1	Initial Cost.....	638
7.3.6.2	Operating Cost.....	638
7.3.6.3	Reliability and Maintainability	639
7.3.6.4	Flexibility.....	639
7.4	Load Matching	639
7.4.1	Prelude to the Discussion of Load Matching.....	639
7.4.2	Understanding Load Matching for IH.....	640
7.4.2.1	Basic Concept.....	640
7.4.2.2	A Simple Example	642
7.4.2.3	Parallel and Series Connected Load Circuits.....	642
7.4.2.4	Load-Matching Procedures	643
7.4.2.5	Load-Matching Component Connections	651
7.4.3	Summary.....	653
7.5	Medium- and High-Frequency Transformers for Heat Treating and Mass Heating	653
7.5.1	AC/DC Reactors.....	654
7.5.2	Instrumentation Transformers.....	654
7.5.3	Heat Station Transformers.....	654
7.5.4	Ferrite-Core Transformers	655
7.5.5	Toroidal Transformers.....	656
7.5.6	Integrated Magnetic Transformers.....	657
7.5.7	Rectangular (C-Core) Transformers	657
7.5.8	Narrow-Profile Transformers.....	658
7.5.9	Air-Core Radio Frequency Transformers.....	658
7.5.10	Maintenance, Sizing, and Specification of Transformers.....	659
7.6	Special Considerations for Power Supplies	659
7.6.1	Duty Cycle	660
7.6.2	Rapid Cycling of Heat On and Off.....	660

7.6.3	Precise Control of Power and Time.....	660
7.6.4	Minimum Utilization of Floor Space	661
7.7	Special Considerations for Induction Brazing, Soldering, and Bonding	661
7.8	Special Considerations for IH Power Supplies in Mass Heating Applications ...	662
7.9	Special Considerations for IH Power Supplies in Strip Processing Applications	665
7.10	Simultaneous Dual-Frequency Power Supplies	666
7.10.1	Dual Inverter	666
7.10.2	Single Inverter	667
7.10.3	Duty Ratio Inverter.....	667
7.10.4	Dual Coupled Solenoid/C-Core.....	668
7.11	Inverters with Independent Frequency and Power Control.....	668
7.12	Power Supply Cooling.....	668
7.12.1	Water Quality	669
7.12.2	Cooling Water Flow Rate	669
7.12.3	Cooling Water Recirculating Systems.....	669
7.12.3.1	Pumps	670
7.12.3.2	Heat Exchanger.....	670
7.12.4	Common Water-Cooling Problems	671
7.13	Process Control, Monitoring, and Quality Assurance	672
7.13.1	Prelude to Discussion of Process Control and Monitoring	672
7.13.1.1	Specifics of Control and Monitoring of Induction Heat Treating.....	673
7.13.1.2	Specifics of Control and Monitoring of Induction Mass Heating	674
7.13.2	Meters and Meter Circuits.....	675
7.13.3	Features of Control/Monitoring Strategies for Induction Heat Treating versus Induction Mass Heating	676
7.13.3.1	Induction Heat Treating	676
7.13.3.2	Induction Mass Heating.....	678
7.13.4	Basic Principles of Feedback and Control Algorithms.....	680
7.13.4.1	Open-Loop Systems (Feedforward Control Systems).....	680
7.13.4.2	Closed-Loop Systems (Feedback Control Systems).....	681
7.13.4.3	ON-OFF Control Algorithms.....	681
7.13.4.4	P, I, D, PI, and PID Control Algorithms.....	682
7.13.4.5	PLC Controller.....	683
7.13.4.6	Controller Tuning.....	683
7.13.5	Energy Monitoring	683
7.13.6	Profile/Signature Process Monitoring.....	684
7.13.7	Protective Devices and Safety Principles	686
7.13.8	Final Remarks.....	686
Epilogue		689
Appendix: Periodic Table of the Elements		691
References		693
Index		719