

Second Edition

Modern Methods for Quality Control and Improvement



**Harrison M. Wadsworth
Kenneth S. Stephens
A. Blanton Godfrey**



CONTENTS

PART I

INTRODUCTION AND QUALITY MANAGEMENT

► CHAPTER 1

HISTORY AND EVOLUTION OF QUALITY CONTROL 1

- 1-1 Earliest Developments 3
- 1-2 Developments in the World War II Era 5
- 1-3 Modern Developments 7
- 1-4 Developments in Japan 9
- 1-5 Recent Developments 10
- 1-6 Training for Quality 12
- 1-7 References 13

► CHAPTER 2

QUALITY AND QUALITY SYSTEMS 15

- 2-1 Quality Concepts and Related Aspects 16
- 2-2 Quality Control and Quality Assurance 27
- 2-3 Quality Management Systems 30
- 2-4 Elements of Quality Systems 34
- 2-5 References 52
- 2-6 Problems 54

► CHAPTER 3

THE ISO 9000 QUALITY SYSTEM 55

- 3-1 The ISO 9000 Family of Standards 55
- 3-2 Quality Systems Documentation and Auditing 64
- 3-3 ISO 9000: Related Aspects 73
- 3-4 Other Quality Systems 79
- 3-5 References 84
- 3-6 Problems 85

► CHAPTER 4

TOTAL QUALITY MANAGEMENT 86

- 4-1 Introduction to Total Quality Management 87
- 4-2 The Evolution of Total Quality 98
- 4-3 The Impact of National and International Quality Awards on Total Quality Management 102
- 4-4 The European Quality Award 110
- 4-5 The Deming Application Prize 113

- 4-6 Comparison of National/International Quality Awards and International Standards 115
- 4-7 Six Sigma and Other Extensions of Total Quality Management 115
- 4-8 References 123
- 4-9 Problems 124

PART 2

STATISTICAL PROCESS CONTROL

► CHAPTER 5

REVIEW OF FUNDAMENTAL STATISTICAL CONCEPTS 125

- 5-1 Probability 125
- 5-2 Frequency Distributions 129
- 5-3 Measurements of Central Tendency 131
- 5-4 Measures of Dispersion 133
- 5-5 Probability Distributions 136
- 5-6 Statistical Inference 151
- 5-7 Quality Control as an Area of Statistics 157
- 5-8 References 159
- 5-9 Problems 159

► CHAPTER 6

INTRODUCTION TO CONTROL CHARTS 163

- 6-1 Variation and the Control Chart 163
- 6-2 An Attribute Control Chart 168
- 6-3 Variables Control Charts 175
- 6-4 General Principles of Control Charts 190
- 6-5 Summary 192
- 6-6 References 193
- 6-7 Problems 193

► CHAPTER 7

CONTROL CHARTS FOR ATTRIBUTES 196

- 7-1 Detection of Changes with Attribute Charts 196
- 7-2 Charts for Number of Pieces Nonconforming 200
- 7-3 Charts for Percent Nonconforming 204
- 7-4 Charts for Number of Nonconformities 210
- 7-5 OC Curves for Attributes Control Charts 213
- 7-6 Summary 216

7-7 References **216**

7-8 Problems **217**

► CHAPTER 8

CONTROL CHARTS FOR VARIABLES 221

8-1 Detection of Changes with Variables Charts **221**

8-2 Rational Subgroups: Design of Data Collection **226**

8-3 Range (R) Chart **227**

8-4 Standard Deviation Chart **230**

8-5 Average (\bar{x}) Chart **233**

8-6 Median (\bar{x}) **239**

8-7 Midrange (M) Chart **242**

8-8 Individuals (x) Chart **243**

8-9 Other Variables Control Charts **247**

8-10 Evaluation of Average Control Charts **248**

8-11 Other Evaluations **251**

8-12 Economic Design and Evaluation of Control Charts **251**

8-13 Conclusions **252**

8-14 References **252**

8-15 Problems **253**

► CHAPTER 9

SPECIAL CONTROL CHARTS 258

9-1 Cumulative Sum Control Charts **258**

9-2 The Exponentially Weighted Moving Average Control Chart **283**

9-3 Modified or Reject Control Limits for \bar{x} Charts **286**

9-4 Acceptance Control Charts **295**

9-5 References **306**

9-6 Problems **308**

► CHAPTER 10

SPECIFICATIONS LIMITS AND TOLERANCES 311

10-1 Specification Limits and Tolerances **311**

10-2 Relationship to Processes and Control Charts **312**

10-3 CUSUM Charts and Specification Limits **326**

10-4 Some Miscellaneous Procedures **327**

10-5 Statistical Addition of Tolerances **329**

10-6 References **336**

10-7 Problems **337**

PART 3

METHODS FOR QUALITY IMPROVEMENT

► CHAPTER 11

PROCESS CONTROL AND IMPROVEMENT TECHNIQUES 339

11-1 Principles, Methodologies, and Techniques **339**

11-2 Quality (Process) Improvement **344**

11-3 Control of Quality **382**

11-4 Further Graphical Methods for Quality Improvement and Control **394**

11-5 Conclusions **410**

11-6 References **410**

11-7 Problems **411**

► CHAPTER 12

INDUSTRIAL EXPERIMENTATION 416

12-1 One-Time Experiments **417**

12-2 Evolutionary Operations **428**

12-3 Analysis of Means **437**

12-4 Summary **448**

12-5 References **448**

12-6 Problems **449**

► CHAPTER 13

ROBUST DESIGN 451

13-1 The Concept of Robust Design **451**

13-2 Measurement **453**

13-3 Loss Functions **455**

13-4 Control Variables **457**

13-5 Noise Variables **457**

13-6 Planned Experimentation **457**

13-7 Robust Designs with Dynamic Characteristics **460**

13-8 A Special Case Study **464**

13-9 Summary **473**

13-10 References **474**

13-11 Problems **475**

► CHAPTER 14

RELIABILITY 476

14-1 Basic Concepts of Reliability **476**

14-2 Distributions Useful in Reliability **479**

14-3 Reliability Predictions **483**

14-4 Reliability Estimation **489**

- 14-5 Accelerated Life Testing **502**
- 14-6 Reliability Monitoring and Design
Considerations **505**
- 14-7 The Body of Knowledge for Reliability
Engineering **509**
- 14-8 References **514**
- 14-9 Problems **515**

PART 4

ACCEPTANCE SAMPLING

► CHAPTER 15

ACCEPTANCE SAMPLING FOR ATTRIBUTES 517

- 15-1 Sampling Risks **517**
- 15-2 Types of Sampling Plans **519**
- 15-3 Single Sampling **519**
- 15-4 Double Sampling Plans **532**
- 15-5 Sequential Sampling Plans **539**
- 15-6 Group Sequential Plans **548**
- 15-7 Derivation of Matched Plans **548**
- 15-8 Summary **551**
- 15-9 References **551**
- 15-10 Problems **552**

► CHAPTER 16

ATTRIBUTE SAMPLING TABLES 554

- 16-1 ISO 2859-1: 1999 **556**
- 16-2 The Dodge-Romig System **569**
- 16-3 An LQL Indexed System **581**
- 16-4 Other Attribute Acceptance Sampling Plans **584**
- 16-5 References **584**
- 16-6 Problems **586**

► CHAPTER 17

ACCEPTANCE SAMPLING BY VARIABLES 587

- 17-1 Estimating Fraction Nonconforming with the
Normal Distribution **588**
- 17-2 Estimating Fraction Nonconforming When the
Standard Deviation Is Known **590**

- 17-3 Acceptance Sampling by Variables Using
ANSI/ASQ Z1.9-1993 (MIL-STD 414) **594**
- 17-4 The Graphical Method—ISO 3951 **611**
- 17-5 Testing Normality **615**
- 17-6 Summary **615**
- 17-7 References **616**
- 17-8 Problems **616**

► CHAPTER 18

SPECIAL ATTRIBUTE SAMPLING PROCEDURES 618

- 18-1 Continuous Sampling Plans—CSP **618**
- 18-2 Skip-Lot Sampling Plans—SkSP **631**
- 18-3 Chain Sampling Plans—ChSP **637**
- 18-4 References **643**
- 18-5 Problems **645**

► APPENDIX

TABLES 647

- A Areas Under the Normal Curve **648**
- B Percentage Points of the Chi Square (χ^2)
Distribution **650**
- C Percentage Points of the t Distribution **651**
- D Percentage Points of the F Distribution **652**
- E Cumulative Binomial Distribution **657**
- F Summation of Terms of the Poisson
Distribution **659**
- G Control Chart Factors for Central Tendency **664**
- H Control Chart Factors for Dispersion **665**
- I One-Sided Statistical Tolerance Interval,
 μ, σ Unknown **668**
- J Two-Sided Statistical Tolerance Interval,
 μ, σ Unknown **669**
- K Exact Critical Values for the Analysis of Means **670**
- L Factors for Acceptance Control Charts **672**

INDEX 673