TALL PROFESSION AND APPROVED TO A STATE OF THE PROFESSION AND A ST

MARK A. FRYMAN

Contents

	Preface	·
PART I:	Underpinnings of Quality and Process Improvement Part I Overview: Chapters 1–4	
	1 The Fundamentals of Quality	3
	1.3 Introduction	
	1.4 What Is Quality?	
	1.5 Basic Terms and Definitions of Quality	
	1.6 The Quality Gurus	
	1.7 Quality System Awards and Guidelines	
	1.8 Important Quality Related Issues	
	1.9 Quality Case I: Lands' End	
	2 Measurement of Data for Quality	49
	2.3 Introduction	
÷ *	2.4 What Is Measurement?	
	2.5 A Brief History of Measurement	

	2.7 Data Concepts	
	3 The Fundamentals of Statistics for Quality	71
	3.3 Introduction	
	3.4 Basic Concepts of Random Numbers and Sampling	
	3.5 A Word about Surveys	
	3.6 The Normal Distribution	
	3.7 Central Tendency	
	3.8 Variability	
	3.9 Areas Under the Normal Curve	
	3.10 Other Statistical Concepts	
	4 Processes	119
	4.3 Introduction	
	4.4 Processes: What Are They?	
	4.5 The Process Checklist	
	4.6 Other Process Considerations	
PART I	I: The Roadmap	
	Part II Overview: Chapters 5–12	
	5 Step 1: Customers and Customer Requirements	139
	5.3 Introduction	
	5.4 Concepts Associated with Customers	
	5.5 Roadmap Step 1: Customer Requirements	
	6 Step 2: Flowcharting the Process	167
	6.3 Introduction	
	6.4 What Is a Flowchart?	
	6.5 Roadmap Step 2: Flowcharting the Process	
	- 1 10000	

6.6 Important Notes About Flowcharts and Flowchart Analysis

2.6 Why Measure and What Types of Data to Measure

7 St	ep 3: Pareto Analysis and Fishbone Diagram	187
7.3 In	ntroduction	
7.4 S	tep 3: Pareto Analysis and Fishbone Diagram	
7.5 E	extending the Pareto and Fishbone Concepts	
8 Co	ontrol Charts	211
8.3 Is	ntroduction	
8.4 V	What Is a Control Chart?	
8.5 T	ypes of Variation	
8.6 R	un Charts	
8.7 P	utting Variation and Time Together	
9 St	ep 4A: Variables Control Charts	231
9.3 In	ntroduction	
9.4 V	ariables Control Charts Overview	
9.5 S	tep 4A: Variables Control Charts	
9.6	Control Chart Interpretation	
9.7 E	Occument and Rebaseline the Process	
10 9	Step 4B: Attributes Control Charts	261
10.3 I	ntroduction	
10.4 A	ttributes Control Chart Overview	
10.5 S	tep 4B: Attributes Control Charts	
10.6 C	Control Chart Interpretation	
	Step 5: Process Capability and Process Capability Indices	293
11.3 I	ntroduction	
	tep 5: Process Capability	
	Side-By-Side Look at Cp and Cpk	
	he Engineering Specification Pitfall	
	tep 5D: Document and Rebaseline the Process	

12 St	ep 6: Design of Experiments (DOE)	317
12.3 Int	croduction	
12.4 W	hat Is Design of Experiments?	
12.5 Ty	pes of Experiments	
12.6 Pre	erequisite Steps in Conducting an Experiment	
12.7 Ste	ps in Conducting an Experiment	
	sign of Experiments Example	
Appen	dix	345
Table 1	500 Uniformly Distributed Five-Digit Random Numbers	
Table 2	Areas Under the Normal Curve	
Table 3	Control Chart Factors	
Glossary		351
Index		367