

A N N A C . T H O R N T O N

# Variation Risk

## MANAGEMENT

Focusing Quality  
Improvements  
in Product Development  
and Production

---

---

# CONTENTS

---

<b>Preface</b>	<b>xiii</b>
<b>Figures</b>	<b>xv</b>
<b>Tables</b>	<b>xix</b>
<b>Text Boxes</b>	<b>xxi</b>
<b>Nomenclature</b>	<b>xxiii</b>
<b>Acronyms</b>	<b>xxv</b>
<b>1 Introduction</b>	<b>1</b>
1.1. The Competitive Advantage of VRM / 5	
1.2. Guide to Readers / 8	
<b>2 Basics of Variation Risk Management</b>	<b>12</b>
2.1. Basic Principles of VRM / 13	
2.1.1. VRM Must Be Holistic / 14	
2.1.2. VRM Must Be Process Oriented / 17	
2.1.3. VRM Must Be Data Driven / 24	
2.2. Variation and Its Impact on Quality / 25	
2.3. Summary / 31	
<b>3 Identification</b>	<b>33</b>
3.1. Definition of Key Characteristics and Variation Flowdown / 34	
3.1.1. Key Characteristics / 35	
3.1.2. Variation Flowdown / 38	
3.2. Defining the Scope of the VRM Application / 42	
3.3. Identifying Critical System Requirements / 42	
3.3.1. Identify the Voice of the Customer / 43	

3.3.2.	Identify Specifications and Requirements / 43	
3.3.3.	Identify Critical System Requirements / 43	
3.4.	Identifying System Key Characteristics / 45	
3.4.1.	What Is a System Key Characteristic? / 45	
3.4.2.	Examples of System Key Characteristics / 47	
3.5.	Creating the Variation Flowdown / 52	
3.5.1.	What Information to Gather / 56	
3.5.2.	How to Conduct the Top-Down Process / 58	
3.5.3.	How to Conduct the Bottom-Up Process / 60	
3.5.4.	How to Conduct and Document the Identification Procedure / 63	
3.6.	Summary / 64	
<b>4</b>	<b>Overview of Assessment</b>	<b>68</b>
4.1.	Assessment during Product Development / 70	
4.2.	Assessment during Production / 73	
<b>5</b>	<b>Assessment of Defect Rates</b>	<b>76</b>
5.1.	Predicting the Frequency of Defects / 76	
5.1.1.	Variation Models / 79	
5.1.2.	Prediction Tools / 83	
5.2.	Estimating the Contributions of Part and Process KCs / 93	
5.2.1.	Qualitative Analysis of Variation Contribution / 95	
5.2.2.	Quantitative Analysis of Variation Contribution / 96	
5.3.	Measuring the Frequency of Defects / 96	
5.4.	Measuring the Contributions of Part and Process KCs / 100	
5.5.	Summary / 101	
<b>6</b>	<b>Assessment of Cost and Risk</b>	<b>102</b>
6.1.	Cost and Risk Assessment during Product Development / 103	
6.1.1.	Qualitative Assessments / 105	
6.1.2.	Step Cost Functions / 106	
6.1.3.	Continuous Cost Functions / 106	
6.2.	Total Cost of Variation Assessment during Production / 109	
6.2.1.	Cost Sources / 109	
6.2.2.	Representation of the Total Cost of Variation / 117	
6.2.3.	Cost Analysis and Aggregation / 119	
6.3.	Summary / 123	

<b>7</b>	<b>Assessment of the Quality Control System</b>	<b>124</b>
7.1.	QC Plan Maturity / 126	
7.1.1.	Detection Capability and Effectiveness / 126	
7.1.2.	Diagnosis Capability / 127	
7.1.3.	Efficient Resource Utilization / 128	
7.2.	QC Location in the Manufacturing Process / 129	
7.3.	QC Effectiveness Matrix / 133	
7.4.	Summary / 135	
<b>8</b>	<b>Mitigation</b>	<b>137</b>
8.1.	Mitigation during Product Development and Production / 138	
8.1.1.	Mitigation during Product Development / 139	
8.1.2.	Mitigation during Production / 140	
8.2.	Identifying Mitigation Strategies / 141	
8.2.1.	Design Changes / 141	
8.2.2.	Manufacturing Process Changes / 145	
8.2.3.	Manufacturing Process Improvements / 151	
8.2.4.	Monitoring and Controlling Manufacturing Processes / 151	
8.2.5.	Testing and Inspection / 154	
8.3.	Selecting a Mitigation Strategy / 155	
8.4.	Selecting a Project Portfolio / 157	
8.5.	Executing Mitigation Strategies / 160	
8.6.	Summary / 162	
<b>9</b>	<b>Integration of Variation Risk Management with Product Development</b>	<b>165</b>
9.1.	Basics of Product Development / 165	
9.1.1.	Stage Gate Product Development Process / 165	
9.1.2.	VRM during Product Development / 167	
9.1.3.	Metrics / 168	
9.2.	Requirements Development / 170	
9.3.	Concept Development / 172	
9.4.	Product Architecture Design / 174	
9.5.	System Concept Design / 178	
9.6.	Detail Design / 179	
9.7.	Product Testing and Refinement / 180	
9.8.	Transition to Production / 183	

- 9.8.1. Handling Customer Complaints / 184
- 9.8.2. Wrap-Up / 186
- 9.8.3. Documenting the Key Characteristic Plan / 186
- 9.9. Production / 188
  - 9.9.1. Continually Monitor Total Cost of Variation / 188
  - 9.9.2. Track Customer Complaint Data / 189
  - 9.9.3. Review Quality Control Data / 191
  - 9.9.4. Track Impact of Changes / 192
- 9.10. Summary / 192

**10 Roles and Responsibilities in Variation Risk Management 193**

- 10.1. Product Development / 194
  - 10.1.1. The Integrated Product Team Approach / 194
  - 10.1.2. Expert Teams / 199
  - 10.1.3. Coaches / 200
- 10.2. Production / 200
  - 10.2.1. Production Teams / 201
  - 10.2.2. Expert Teams / 201
- 10.3. Suppliers' Roles and Responsibilities / 202
  - 10.3.1. Role of Suppliers during Product Development / 203
  - 10.3.2. Role of Suppliers during Production / 206
  - 10.3.3. What Does a KC Mean to a Supplier? / 207
- 10.4. Summary / 208

**11 Planning and Implementing a Variation Risk Management Program 209**

- 11.1. Planning a VRM Program / 209
  - 11.1.1. Gathering Management Support / 210
  - 11.1.2. Gathering Organizational Support / 211
  - 11.1.3. Baselining the Existing VRM Processes / 211
  - 11.1.4. Formalizing VRM / 215
  - 11.1.5. Developing KC Tracking Methods / 215
  - 11.1.6. Identifying Lead Users / 217
  - 11.1.7. Developing Training Materials / 219
- 11.2. Implementing the VRM Program / 220
  - 11.2.1. Identifying Initial Projects / 221
  - 11.2.2. Training the Team / 221

- 11.2.3. Applying VRM / 221
- 11.2.4. Gathering Feedback / 222
- 11.3. Summary / 222

## **12 Summary** **223**

## **Appendix A Maturity Models** **226**

## **Appendix B Process Capability Databases** **231**

- B.1. Background on Process Capability Data / 232
  - B.1.1. Importance of Using Process Capability Data / 232
  - B.1.2. Structure and Content of a Process Capability Database / 234
  - B.1.3. Difficulties in Implementing Process Capability Databases / 235
- B.2. The Right Structure / 235
  - B.2.1. Designing the Indexing Scheme / 237
  - B.2.2. Choosing the Database Implementation Approach / 241
  - B.2.3. Creating the User Interfaces and Data Analysis / 242
- B.3. The Right Data / 245
- B.4. The Right Management Support / 247
- B.5. The Right Usage / 248
- B.6. Implementation of a Process Capability Database / 249
  - B.6.1. Who Should Be Involved / 250
  - B.6.2. What Decisions Should Be Made / 251
  - B.6.3. Implementation Steps / 252
- B.7. Summary / 252

## **Appendix C Other Initiatives** **253**

- C.1. Six Sigma / 254
- C.2. Design for Six Sigma / 259
- C.3. Lean Manufacturing / 260
- C.4. Continual Improvement, TQM, and Kaizen / 262
- C.5. Dimensional Management / 263
- C.6. Design for Manufacturing / 264
- C.7. Quality Function Deployment (House of Quality) / 264

**xii**      CONTENTS

C.8.    *FMEA / 267*

C.9.    *Summary / 267*

<b>Appendix D</b>	<b>Summary of Process Diagrams</b>	<b>269</b>
<b>Glossary</b>		<b>273</b>
<b>Bibliography</b>		<b>277</b>
<b>Index</b>		<b>281</b>