

Introduction to
STATISTICAL
QUALITY
CONTROL

5e

WILEY
INTERNATIONAL
EDITION
RESTRICTED
Not for Sale
In the United States

Douglas C. Montgomery

Contents

CHAPTER 1

Quality Improvement in the Modern
Business Environment 1

Chapter Overview and Learning Objectives 1

- 1-1 The Meaning of Quality and Quality Improvement 2
 - 1-1.1 Dimensions of Quality 2
 - 1-1.2 Quality Engineering Terminology 6
- 1-2 A Brief History of Quality Control and Improvement 8
- 1-3 Statistical Methods for Quality Control and Improvement 11
- 1-4 Management Aspects of Quality Improvement 15
 - 1-4.1 Quality Philosophy and Management Strategies 16
 - 1-4.2 The Link Between Quality and Productivity 27
 - 1-4.3 Quality Costs 28
 - 1-4.4 Legal Aspects of Quality 33
 - 1-4.5 Implementing Quality Improvement 35

- 2-2 Important Discrete Distributions 55
 - 2-2.1 The Hypergeometric Distribution 55
 - 2-2.2 The Binomial Distribution 57
 - 2-2.3 The Poisson Distribution 58
 - 2-2.4 The Pascal and Related Distributions 59
- 2-3 Important Continuous Distributions 61
 - 2-3.1 The Normal Distribution 61
 - 2-3.2 The Lognormal Distribution 66
 - 2-3.3 The Exponential Distribution 69
 - 2-3.4 The Gamma Distribution 70
 - 2-3.5 The Weibull Distribution 72
- 2-4 Probability Plots 74
 - 2-4.1 Normal Probability Plots 74
 - 2-4.2 Other Probability Plots 76
- 2-5 Some Useful Approximations 77
 - 2-5.1 The Binomial Approximation to the Hypergeometric 77
 - 2-5.2 The Poisson Approximation to the Binomial 78
 - 2-5.3 The Normal Approximation to the Binomial 78
 - 2-5.4 Comments on Approximations 79

PART I

Statistical Methods Useful in Quality Control
and Improvement 39

CHAPTER 2

Modeling Process Quality 41

Chapter Overview and Learning Objectives 41

- 2-1 Describing Variation 42
 - 2-1.1 The Stem-and-Leaf Plot 42
 - 2-1.2 The Histogram 44
 - 2-1.3 Numerical Summary of Data 47
 - 2-1.4 The Box Plot 50
 - 2-1.5 Probability Distributions 51

CHAPTER 3

Inferences about Process Quality 86

Chapter Overview and Learning Objectives 86

- 3-1 Statistics and Sampling Distributions 87
 - 3-1.1 Sampling from a Normal Distribution 88
 - 3-1.2 Sampling from a Bernoulli Distribution 92
 - 3-1.3 Sampling from a Poisson Distribution 92
- 3-2 Point Estimation of Process Parameters 93
- 3-3 Statistical Inference for a Single Sample 96
 - 3-3.1 Inference on the Mean of a Population, Variance Known 97
 - 3-3.2 The Use of P -Values for Hypothesis Testing 100

3-3.3 Inference on the Mean of a Normal Distribution, Variance Unknown **101**

3-3.4 Inference on the Variance of a Normal Distribution **105**

3-3.5 Inference on a Population Proportion **107**

3-3.6 The Probability of Type II Error and Sample Size Decisions **109**

3-4 Statistical Inference for Two Samples **112**

3-4.1 Inference for a Difference in Means, Variances Known **113**

3-4.2 Inference for a Difference in Means of Two Normal Distributions, Variances Unknown **116**

3-4.3 Inference on the Variances of Two Normal Distributions **125**

3-4.4 Inference on Two Population Proportions **126**

3-5 What If There Are More Than Two Populations? The Analysis of Variance **128**

3-5.1 An Example **128**

3-5.2 The Analysis of Variance **130**

3-5.3 Checking Assumptions: Residual Analysis **137**

PART II

Basic Methods of Statistical Process Control and Capability Analysis **145**

CHAPTER 4

Methods and Philosophy of Statistical Process Control **147**

Chapter Overview and Learning Objectives **147**

4-1 Introduction **148**

4-2 Chance and Assignable Causes of Quality Variation **148**

4-3 Statistical Basis of the Control Chart **150**

4-3.1 Basic Principles **150**

4-3.2 Choice of Control Limits **158**

4-3.3 Sample Size and Sampling Frequency **160**

4-3.4 Rational Subgroups **162**

4-3.5 Analysis of Patterns on Control Charts **164**

4-3.6 Discussion of Sensitizing Rules for Control Charts **166**

4-3.7 Phase I and Phase II of Control Chart Application **168**

4-4 The Rest of the "Magnificent Seven" **169**

4-5 Implementing SPC **175**

4-6 An Application of SPC **176**

4-7 Nonmanufacturing Applications of Statistical Process Control **183**

CHAPTER 5

Control Charts for Variables **194**

Chapter Overview and Learning Objectives **194**

5-1 Introduction **195**

5-2 Control Charts for \bar{x} and R **196**

5-2.1 Statistical Basis of the Charts **196**

5-2.2 Development and Use of \bar{x} and R Charts **200**

5-2.3 Charts Based on Standard Values **212**

5-2.4 Interpretation of \bar{x} and R Charts **214**

5-2.5 The Effect of Nonnormality on \bar{x} and R Charts **216**

5-2.6 The Operating-Characteristic Function **217**

5-2.7 The Average Run Length for the \bar{x} Chart **220**

5-3 Control Charts for \bar{x} and s **222**

5-3.1 Construction and Operation of \bar{x} and s Charts **222**

5-3.2 The \bar{x} and s Control Charts with Variable Sample Size **227**

5-3.3 The s^2 Control Chart **231**

5-4 The Shewhart Control Chart for Individual Measurements **231**

5-5 Summary of Procedures for \bar{x} , R , and s Charts **242**

5-6 Applications of Variables Control Charts **243**

CHAPTER 6

Control Charts for Attributes **265**

Chapter Overview and Learning Objectives **265**

6-1 Introduction **266**

6-2 The Control Chart for Fraction Nonconforming **266**

6-2.1 Development and Operation of the Control Chart **268**

6-2.2 Variable Sample Size **280**

6-2.3 Nonmanufacturing Applications **284**

6-2.4 The Operating-Characteristic Function and Average Run Length Calculations **286**

6-3 Control Charts for Nonconformities (Defects) **288**

- 6-3.1 Procedures with Constant Sample Size **289**
- 6-3.2 Procedures with Variable Sample Size **298**
- 6-3.3 Demerit Systems **300**
- 6-3.4 The Operating-Characteristic Function **302**
- 6-3.5 Dealing with Low Defect Levels **304**
- 6-3.6 Nonmanufacturing Applications **306**
- 6-4 Choice Between Attributes and Variables Control Charts **306**
- 6-5 Guidelines for Implementing Control Charts **311**

CHAPTER 7

- Process and Measurement System Capability Analysis **326**
- Chapter Overview and Learning Objectives **326**
- 7-1 Introduction **327**
- 7-2 Process Capability Analysis Using a Histogram or a Probability Plot **329**
 - 7-2.1 Using the Histogram **329**
 - 7-2.2 Probability Plotting **331**
- 7-3 Process Capability Ratios **333**
 - 7-3.1 Use and Interpretation of C_p **333**
 - 7-3.2 Process Capability Ratio for an Off-Center Process **338**
 - 7-3.3 Normality and the Process Capability Ratio **339**
 - 7-3.4 More about Process Centering **341**
 - 7-3.5 Confidence Intervals and Tests on Process Capability Ratios **343**
- 7-4 Process Capability Analysis Using a Control Chart **349**
- 7-5 Process Capability Analysis Using Designed Experiments **351**
- 7-6 Gauge and Measurement System Capability Studies **352**
 - 7-6.1 Basic Concepts of Gauge Capability **352**
 - 7-6.2 The Analysis of Variance Method **358**
 - 7-6.3 Confidence Intervals in Gauge R & R Studies **362**
 - 7-6.4 False Defectives and Passed Defectives **364**
- 7-7 Setting Specification Limits on Discrete Components **367**
 - 7-7.1 Linear Combinations **367**
 - 7-7.2 Nonlinear Combinations **371**

- 7-8 Estimating the Natural Tolerance Limits of a Process **374**
 - 7-8.1 Tolerance Limits Based on the Normal Distribution **374**
 - 7-8.2 Nonparametric Tolerance Limits **375**

PART III

Other Statistical Process-Monitoring and Control Techniques **383**

CHAPTER 8

- Cumulative Sum and Exponentially Weighted Moving Average Control Charts **385**
- Chapter Overview and Learning Objectives **385**
- 8-1 The Cumulative Sum Control Chart **386**
 - 8-1.1 Basic Principles: The Cusum Control Chart for Monitoring the Process Mean **386**
 - 8-1.2 The Tabular or Algorithmic Cusum for Monitoring the Process Mean **390**
 - 8-1.3 Recommendations for Cusum Design **395**
 - 8-1.4 The Standardized Cusum **397**
 - 8-1.5 Improving Cusum Responsiveness for Large Shifts **398**
 - 8-1.6 The Fast Initial Response or Headstart Feature **398**
 - 8-1.7 One-Sided Cusums **400**
 - 8-1.8 A Cusum for Monitoring Process Variability **401**
 - 8-1.9 Rational Subgroups **402**
 - 8-1.10 Cusums for Other Sample Statistics **402**
 - 8-1.11 The V-Mask Procedure **403**
- 8-2 The Exponentially Weighted Moving Average Control Chart **405**
 - 8-2.1 The Exponentially Weighted Moving Average Control Chart for Monitoring the Process Mean **406**
 - 8-2.2 Design of an EWMA Control Chart **411**
 - 8-2.3 Robustness of the EWMA to Nonnormality **412**
 - 8-2.4 Rational Subgroups **413**
 - 8-2.5 Extensions of the EWMA **413**
- 8-3 The Moving Average Control Chart **417**

CHAPTER 9

Other Univariate Statistical Process Monitoring and Control Techniques **423**

Chapter Overview and Learning Objectives **423**

- 9-1 Statistical Process Control for Short Production Runs **424**
 - 9-1.1 \bar{x} and R Charts for Short Production Runs **425**
 - 9-1.2 Attributes Control Charts for Short Production Runs **427**
 - 9-1.3 Other Methods **428**
- 9-2 Modified and Acceptance Control Charts **429**
 - 9-2.1 Modified Control Limits for the \bar{x} Chart **429**
 - 9-2.2 Acceptance Control Charts **433**
- 9-3 Control Charts for Multiple-Stream Processes **434**
 - 9-3.1 Multiple-Stream Processes **434**
 - 9-3.2 Group Control Charts **434**
 - 9-3.3 Other Approaches **437**
- 9-4 SPC With Autocorrelated Process Data **438**
 - 9-4.1 Sources and Effects of Autocorrelation in Process Data **438**
 - 9-4.2 Model-Based Approaches **443**
 - 9-4.3 A Model-Free Approach **452**
- 9-5 Adaptive Sampling Procedures **455**
- 9-6 Economic Design of Control Charts **457**
 - 9-6.1 Designing a Control Chart **457**
 - 9-6.2 Process Characteristics **458**
 - 9-6.3 Cost Parameters **458**
 - 9-6.4 Early Work and Semieconomic Designs **460**
 - 9-6.5 An Economic Model of the \bar{x} Control Chart **461**
 - 9-6.6 Other Work **466**
- 9-7 Cuscore Charts **467**
- 9-8 The Change-point Model for Process Monitoring **470**
- 9-9 Overview of Other Procedures **472**
 - 9-9.1 Tool Wear **472**
 - 9-9.2 Control Charts Based on Other Sample Statistics **473**
 - 9-9.3 Fill Control Problems **474**
 - 9-9.4 Precontrol **474**
 - 9-9.5 Tolerance Interval Control Charts **476**
 - 9-9.6 Monitoring Processes with Censored Data **476**
 - 9-9.7 Nonparametric Control Charts **477**

CHAPTER 10

Multivariate Process Monitoring and Control **486**

Chapter Overview and Learning Objectives **486**

- 10-1 The Multivariate Quality-Control Problem **487**
- 10-2 Description of Multivariate Data **489**
 - 10-2.1 The Multivariate Normal Distribution **489**
 - 10-2.2 The Sample Mean Vector and Covariance Matrix **490**
- 10-3 The Hotelling T^2 Control Chart **491**
 - 10-3.1 Subgrouped Data **491**
 - 10-3.2 Individual Observations **500**
- 10-4 The Multivariate EWMA Control Chart **504**
- 10-5 Regression Adjustment **507**
- 10-6 Control Charts for Monitoring Variability **511**
- 10-7 Latent Structure Methods **513**
 - 10-7.1 Principal Components **514**
 - 10-7.2 Partial Least Squares **519**
- 10-8 Profile Monitoring **520**

CHAPTER 11

Engineering Process Control and SPC **526**

Chapter Overview and Learning Objectives **527**

- 11-1 Process Monitoring and Process Regulation **527**
- 11-2 Process Control by Feedback Adjustment **528**
 - 11-2.1 A Simple Adjustment Scheme: Integral Control **528**
 - 11-2.2 The Adjustment Chart **535**
 - 11-2.3 Variations of the Adjustment Chart **536**
 - 11-2.4 Other Types of Feedback Controllers **540**
- 11-3 Combining SPC and EPC **541**

PART IV

Process Design and Improvement with Designed Experiments **547**

CHAPTER 12

Factorial and Fractional Factorial Experiments for Process Design and Improvement **549**

Chapter Overview and Learning Objectives **549**

- 12-1 What is Experimental Design? **550**
- 12-2 Examples of Designed Experiments In Process Improvement **551**
- 12-3 Guidelines for Designing Experiments **555**
- 12-4 Factorial Experiments **557**

- 12-4.1 An Example **560**
- 12-4.2 Statistical Analysis **560**
- 12-4.3 Residual Analysis **566**
- 12-5 The 2^k Factorial Design **567**
 - 12-5.1 The 2^2 Design **567**
 - 12-5.2 The 2^k Design for $k \geq 3$ Factors **573**
 - 12-5.3 A Single Replicate of the 2^k Design **585**
 - 12-5.4 Addition of Center Points to the 2^k Design **589**
 - 12-5.5 Blocking and Confounding in the 2^k Design **593**
- 12-6 Fractional Replication of the 2^k Design **595**
 - 12-6.1 The One-Half Fraction of the 2^k Design **595**
 - 12-6.2 Smaller Fractions: The 2^{k-p} Fractional Factorial Design **602**
- 14-2.3 Designing a Single-Sampling Plan with a Specified OC Curve **657**
- 14-2.4 Rectifying Inspection **658**
- 14-3 Double, Multiple, and Sequential Sampling **662**
 - 14-3.1 Double-Sampling Plans **662**
 - 14-3.2 Multiple-Sampling Plans **668**
 - 14-3.3 Sequential-Sampling Plans **669**
- 14-4 Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859) **672**
 - 14-4.1 Description of the Standard **672**
 - 14-4.2 Procedure **674**
 - 14-4.3 Discussion **679**
- 14-5 The Dodge–Romig Sampling Plans **681**
 - 14-5.1 AOQL Plans **682**
 - 14-5.2 LTPD Plans **685**
 - 14-5.3 Estimation of Process Average **685**

CHAPTER 13

Process Optimization with Designed Experiments **611**

- 13-1 Response Surface Methods and Designs **612**
 - 13-1.1 The Method of Steepest Ascent **614**
 - 13-1.2 Analysis of a Second-Order Response Surface **616**
- 13-2 Process Robustness Studies **621**
 - 13-2.1 Background **621**
 - 13-2.2 The Response Surface Approach to Process Robustness Studies **624**
- 13-3 Evolutionary Operation **631**

PART V

Acceptance Sampling **643**

CHAPTER 14

Lot-by-Lot Acceptance Sampling for Attributes **645**

Chapter Overview and Learning Objectives **645**

- 14-1 The Acceptance-Sampling Problem **646**
 - 14-1.1 Advantages and Disadvantages of Sampling **647**
 - 14-1.2 Types of Sampling Plans **648**
 - 14-1.3 Lot Formation **649**
 - 14-1.4 Random Sampling **649**
 - 14-1.5 Guidelines for Using Acceptance Sampling **650**
- 14-2 Single-Sampling Plans for Attributes **652**
 - 14-2.1 Definition of a Single-Sampling Plan **652**
 - 14-2.2 The OC Curve **652**

CHAPTER 15

Other Acceptance-Sampling Techniques **688**

- 15-1 Acceptance Sampling by Variables **689**
 - 15-1.1 Advantages and Disadvantages of Variables Sampling **689**
 - 15-1.2 Types of Sampling Plans Available **690**
 - 15-1.3 Caution in the Use of Variables Sampling **691**
- 15-2 Designing a Variables Sampling Plan with a Specified OC Curve **692**
- 15-3 MIL STD 414 (ANSI/ASQC Z1.9) **694**
 - 15-3.1 General Description of the Standard **694**
 - 15-3.2 Use of the Tables **695**
 - 15-3.3 Discussion of MIL STD 414 and ANSI/ASQC Z1.9 **698**
- 15-4 Other Variables Sampling Procedures **699**
 - 15-4.1 Sampling by Variables to Give Assurance Regarding the Lot or Process Mean **699**
 - 15-4.2 Sequential Sampling by Variables **700**
- 15-5 Chain Sampling **700**
- 15-6 Continuous Sampling **702**
 - 15-6.1 CSP-1 **703**
 - 15-6.2 Other Continuous-Sampling Plans **705**
- 15-7 Skip-Lot Sampling Plans **706**

Appendix **713**

- I. Summary of Common Probability Distributions Often Used in Statistical Quality Control **715**
- II. Cumulative Standard Normal Distribution **716**
- III. Percentage Points of the χ^2 Distribution **718**
- IV. Percentage Points of the t Distribution **719**
- V. Percentage Points of the F Distribution **720**