
Engineering Robust Designs

WITH SIX SIGMA

John X. Wang



Contents

	Preface	xii
	About the Author	xvi
Chapter I	Achieving Robust Designs with Six Sigma Dependable, Reliable, and Affordable	
	1.1 Six Sigma and Robust Design	
	1.2 Identify Project and Organize Team	3
	1.3 Develop VOC Models	
	1.4 Formulate Critical-to-Quality Characteristics	(
	1.5 Control Energy Transformation for Each CTQ Characteristic	8
	1.6 Determine Control and Noise Factors	12
	1.7 Assign Control Factors to the Inner Array	1.5
	1.8 Summary and Road Map	20
	Bibliography	23
Chapter 2	The Kano Model	
	Listening to the Voice-of-Customers	25
	2.1 How to Make the Customer Happy	26
	2.1.1 Basic Quality	28
	2.1.2 Performance Quality	30
	2.1.3 Excitement Quality	3 1

	2.2 Customer Requirements Over Time	32
	2.3 Control Factor Levels: Ensure Three Types of Quality	34
	2.4 Noise-by-Control Analysis: Making Products More Robust	38
	2.5 Variability Reduction	40
	2.6 The Outer Array: An Orthogonal Array Specifying	
	Multiple Noises	4.
	2.7 Selecting Noise Levels	4!
	2.8 Summary	47
	Bibliography	48
hapter 3	Quality Function Deployment	
	Building a House of Quality	5
	3.1 Market Research and Determining Customers' Needs	57
	3.1.1 Plan the Collection of Customer Information	53
	3.1.2 Prepare for Collection of Customers' Needs Data	50
	3.1.3 Using Data-Collection Mechanisms	5.
	3.1.4 Organize and Summarize Information	5-
	3.2 Goal Tree: Spelling Out Unspoken Needs	5
	3.3 Building a House of Quality	51
	3.4 Deploy Quality Through Design of Experiments	63
	3.5 Experiments for Deploying Robust Quality Functions	61
	3.6 Summary	7:
	Bibliography	7-
hapter 4	Theory of Inventive Problem Solving	
·	Creating Robust Design Concepts	7.
	4.1 Contradiction: The Gateway to New Designs	79
	4.2 Thirty-Nine Engineering Parameters to Standardize CTQs	8
	4.2.1 Identifying Contradictions	8:
	4.2.2 Using Standard Engineering Parameters	8
	4.3 Forty Principles to Identify Design Solutions	8
	4.3.1 Principle 1. Segmentation	8
	4.3.2 Principle 14. Spheroidality—Curvature	81
	4.3.3 Principle 35. Parameter Changes	90
	4.4 Calculating the Average of Control Factor Effects	9:
	4.5 Calculating the Effects of Noise Factors	9
	4.6 Noise-by-Control Interaction Effects	9

	4.7 Summary Appendix Bibliography	10: 10: 11
Chapter 5	Failure Mode and Effect Analysis	
	Being Robust to Risk	113
	5.1 The Historical Context of FMEA	114
	5.2 Using FMEA to Prevent Failure Before Any Harm Is Done	113
	5.3 Identifying Functions and Failure Modes	118
	5.4 Identifying Effects and Severity	12
	5.4.1 Effects and Consequences	12
	5.4.2 Ranking Effects' Severity	12
	5.5 Understanding Causes	12
	5.6 Assessing Current Controls	12
	5.7 Using FMEA for Risk Management	13
	5.8 Summary	13-
	Bibliography	13
Chapter 6	The P-Diagram	
	Laying Out a Robust Design Strategy	13
	6.1 Experimental Design and the P-Diagram	13
	6.1.1 P-Diagram	14
	6.1.2 Control Factors	14
	6.1.3 Noise Factors	14
	6.1.4 Signal Factors	14:
	6.1.5 Response Variables	14
	6.1.6 Ideal Function	14
	6.2 Quality Loss Function	14
	6.2.1 Traditional Quality Loss Function	14
	6.2.2 Taguchi's Quality Loss Function	14
	6.3 Noise Factor Management Strategies	15
	6.3.1 Identifying Noise Factors	15
	6.3.2 Strategies to Manage Noise	15:
	6.3.3 Parameter Design as a Noise Management Strategy	15
	6.4 Three Phases: From Thought to Things	15
	6.5 Summary	15
	Bibliography	16

gn I Factor Levels	163
nd Team	166
Function	168
mic Paramete <u>r D</u> esign	171
actors to an Inner Array	174
tors and Signal to an Outer Array	178
periment and Collect Data	183
and Select an Optimal Design	186
	192
	193
n	
cle Cost	195
versus Tolerancing	197
riability	201
ance Selectively to Maximize Quality-	203
	203 204
	210
ridge System	210
	213
_	
n Long-Lasting Satisfaction	219
ix Sigma	220
y as a Metric	221
rs' Perception of Reliability	
ust Design	223
•	225
tress-Strength Interference	231
rength Distribution Overlap	233
stribution with Tail	234
	225
Distribution with Tail lation with Weak Units	235 236
	Factor Levels and Team Function mic Parameter_Design actors to an Inner Array tors and Signal to an Outer Array eriment and Collect Data and Select an Optimal Design the Cost a versus Tolerancing hiability ance Selectively to Maximize Quality- eoffs Quality Loss Function hidge System In Long-Lasting Satisfaction fix Sigma as a Metric being Perception of Reliability ast Design bone to Engineer Robust Products tress-Strength Interference

CONTENTS

255

	9.3 Stress–Strength Interference Sigma Calculations	241
	9.4 Summary	248
	Bibliography	248
Appendix	The Process Map	
	Engineering Robust Products with Six Sigma	251

Index