

preface vii

Basic Part Modeling Techniques 1	5.3 A Part Created with a 3-D Sketch as the Sweep Path 132 Problems 137
.1 Engineering Design and Solid Modeling 1	
Part Modeling Tutorial: Flange 2	
 3 Modifying the Flange 19 4 An Alternate Method of Modeling the Flange 20 Problems 32 	Building Assembly Models from Part Models 141
	6.1 Creating the Part Models 141
	6.2 Creating a Simple Assembly of Parts 144
Engineering Drawings 37	6.3 Creating a Complex Assembly of Subassemblies and Parts 150
.2 Creating a Drawing Sheet Format 54	Problems 155
.3 Greating an eDrawing 58 Problems 62	Advanced Assembly Operations 159 7.1 Adding Features at the Assembly Level 159
Additional Part Modeling Techniques 65	7.2 Adding Fasteners Using the Smart Fasteners Tool 163
.1 Customizing the SolidWorks Environment 65	7.3 Creating an Exploded View 165
.2 Part Modeling Tutorial: Bracket 71	7.4 Detecting Interferences and Collisions 170
Problems 82	Problems 171
Use of Parametric Modeling Fechniques 87	Creating Assembly Drawings 175 8.1 Creating an Assembly Drawing 175
.1 Modeling Tutorial: Molded Flange 88	8.2 Adding an Exploded View 178
.2 Creation of Parametric Equations 97	8.3 Creating a Bill of Materials 180
Modeling Tutorial: Cap Screw with Design Table 100	8.4 Investigating Associativity 183
.4 Incorporating a Design Table in a Drawing 108	Problems 188
Problems 114	Using SolidWorks for the Generation of

Advanced Concepts in Part Modeling 121

A Part Created with a Swept Geometry 130

A Lofted and Shelled Part 121

5.1

2-D Layouts 189

Problems 202

9.1 A Simple Floor Plan Layout 1899.2 Finding the Properties of 2-D Shapes 198

Application of SolidWorks to Vector Mechanics 205

- 10.1 Vector Addition 205
- 10.2 Vector Addition with SolidWorks 206
- 10.3 Modifying the Vector Addition Drawing 208
- 10.4 Further Solution of Vector Equations 211
- 10.5 Kinematic Sketch of a Simple Mechanism 213

Problems 217

Using SolidWorks in the Design and Analysis of Mechanisms 219

- 11.1 Approaching Mechanism Design with SolidWorks Assemblies 220
- 11.2 Development of Part Models of Links 221
- 11.3 Development of the Assembly Model of the Four-Bar Linkage 222

Problems 229

The Use of SolidWorks as a Tool for Manufacturing: Mold Design and Sheet Metal Parts 235

- 12.1 A Simple Two-Part Mold 235
- 12.2 A Core-and-Cavity Mold 239
- 12.3 A Sheet Metal Part 246
 Problems 251

The Use of SolidWorks to Accelerate the Product Development Cycle 255

- 13.1 Rapid Prototyping 255
- 13.2 Finite Element Analysis 259
- 13.3 Product Data Management 260
- 13.4 Some Final Thoughts 262

Index 263