


Extrusion

The Definitive Processing
Guide and Handbook



Harold F. Giles, Jr.
John R. Wagner, Jr.
Eldridge M. Mount, III

Table of Contents

Part 1: Single Screw Extrusion

1 Extrusion Process	1
1.1 Raw Material Supply	1
1.2 Raw Material Blending and Mixing	2
1.3 Drying	4
1.4 Feeding Polymer to the Extruder	4
1.5 Extrusion	5
1.5.1 Shaping and Drawing	5
1.5.2 Solidification and Cooling	6
1.5.3 Puller	7
1.6 Secondary Operations	7
1.7 Inspection, Packaging, and Shipping	7
Review Questions	8
2 Extruder Safety	9
2.1 Hazards Associated with an Extruder	9
2.1.1 Hazards Associated with Takeoff Equipment	10
2.1.2 Personal Protective Equipment	10
2.1.3 Lock-Out, Tag, and Clear Procedure	10
2.2 Proper Training	11
2.3 Inspection and Housekeeping	11
2.4 Material Safety	11
Review Questions	11
3 Single Screw Extruder: Equipment	13
Introduction	13
3.1 Equipment	13
3.2 Drive	14
3.3 Feed	16
3.4 Screw, Barrel, and Heaters	16
3.5 Die and Adapter	20
3.6 Controls	22
3.6.1 Temperature Zone Control	23
3.6.2 Melt Temperature	26
3.6.3 Pressure Measurement	27
3.6.4 On-Line Measurements	29
3.6.5 Control Summary	31
3.7 Extruder Devolatilization	31
3.8 Vertical Extruders	32
References	32
Review Questions	32

4 Plastic Behavior in the Extruder	35
4.1 Feed Zone	35
4.2 Polymer Melting or Plastication	39
4.3 Melt Conveying	41
4.4 Mixing	42
4.5 Extruder Throughput Calculations	45
4.6 Devolatilization	47
4.7 Die	47
References	51
Review Questions	51
5 Screw Design	53
5.1 Barrier Screw	55
5.2 Mixing Screw	57
5.3 Screw Wear	59
5.3.1 Worn Screws	61
5.4 Screw Compression Ratios	61
5.5 Screw Performance	61
5.6 Summary	62
References and Photo Credits	62
Review Questions	63
6 Processing Conditions	65
6.1 Extruder Temperature Profiles	65
6.2 Extruder or Production Run Setup	67
6.3 Start-up	68
6.4 Steady-state Operation	68
6.5 Shutdown and Product Changes	69
References	72
Review Questions	72
7 Scale Up	75
References	77
Review Questions	77
8 Shear Rates, Pressure Drops, and Other Extruder Calculations	79
8.1 Shear Rates	79
8.2 Extruder Screw Calculations	80
8.3 Calculations of Output in Different Sections of the Extruder	81
References	81
Review Questions	81

Part 2: Twin Screw Extrusion

9 Twin Screw Extrusion Process	83
9.1 Raw Material Supply	83
9.2 Raw Material Blending and Mixing	84
9.3 Drying	85
9.4 Feeding Polymer to the Extruder	86
9.5 Extrusion	86
9.5.1 Shaping and Drawing	87
9.5.2 Solidification and Cooling	87
9.5.3 Puller	88
9.6 Secondary Operations	88
9.7 Inspection, Packaging, and Shipping	89
Review Questions	89
10 Extruder Safety	91
10.1 Hazards Associated with an Extruder	91
10.1.1 Hazards Associated with Takeoff Equipment	92
10.2 Personal Protective Equipment	92
10.3 Lock-Out, Tag, and Clear Procedure	92
10.4 Proper Training	93
10.5 Inspection and Housekeeping	93
10.6 Material Safety	93
Review Questions	93
11 Twin Screw Extruder Equipment	95
11.1 Drive	102
11.2 Feed	103
11.3 Screw and Barrel Heating and Cooling	105
11.4 Die and Adapter	109
11.5 Controls	110
11.5.1 Temperature Zone Control	111
11.5.2 Pressure Measurement	112
11.5.3 In-Line Measurements	112
11.5.4 Control Summary	112
References and Photo Credits	112
Review Questions	113
12 Plastic Behavior in Twin Screw Extruders	115
12.1 Feed	115
12.2 Plasticating and Melting	117
12.3 Melt Conveying	119
12.4 Mixing	119
12.5 Downstream Feeding	121
12.6 Devolatilization	123
12.7 Pumping	124
12.8 Die	124

12.9	Melt Pressure Profile	129
12.10	Residence Time	129
	References and Photo Credits	130
	Review Questions	131
13	Screw Design	133
13.1	Conveying	133
13.2	Mixing Elements	134
13.3	Screw Design Applications	136
	Reference	139
	Review Questions	140
14	Processing Conditions	141
14.1	Extruder Temperature Profile	141
14.2	Screw Speed	142
14.3	Process Variables	143
14.4	Extruder or Production Run Setup	143
14.5	Start-Up	144
14.6	Steady-State Operation	145
14.7	Shutdown and Product Changes	145
14.7.1	Disassembling Screw Elements	146
14.7.2	Scenario #1	147
14.7.3	Scenario #2	147
14.7.4	Scenario #3	147
14.7.5	Scenario #4	148
14.7.6	Scenario #5	148
14.7.7	Scenario #6	148
14.7.8	Scenario #7	149
14.7.9	Scenario #8	149
	Review Questions	150
15	Applications	151
15.1	Compounding	151
15.2	Reactive Extrusion and Devolatilization	152
15.3	Profile and Other Twin Screw Extrusion Applications	153
	References and Photo Credits	155
	Review Questions	155
16	Scale-Up	157
	Review Questions	159
17	Shear Rate, Pressure Drop, and Other Extruder Calculations	161
17.1	Shear Rates	161
17.2	Extruder Calculations	162
17.3	Other Calculations	163
	References	163
	Review Questions	163

Part 3: Polymeric Materials

18 Polymer Overview and Definitions	165
18.1 Overview	165
18.2 Thermoplastic versus Thermoset	167
18.3 Polymer Formation	168
18.4 Molecular Weight	170
18.5 Copolymers	174
18.6 Polymer Structures	174
Review Questions	176
19 Polymer Structure	179
19.1 Amorphous Polymers	179
19.2 Semicrystalline Polymers	181
19.3 Comparison of Semicrystalline and Amorphous Polymers	182
19.4 Crystallinity Measurement	184
19.5 Polyethylene Crystallinity	184
19.6 Polypropylene Crystallinity	184
19.7 Polystyrene Crystallinity	184
Review Questions	185
20 Polymer Rheology	187
20.1 Definitions	188
20.2 Measurement	188
20.3 Viscosity in Extrusion	191
References	193
Review Questions	193
21 Testing Properties	195
21.1 Density and Specific Gravity	196
21.2 Melt Flow Index	197
21.3 Tensile	197
21.4 Flexural Test	199
21.5 Compressive Strength	199
21.6 Heat Deflection Temperature	199
21.7 Long-Term Heat Aging	200
21.8 Thermal Properties	200
21.9 Time-Temperature Relationship	201
21.10 Izod Impact	201
21.11 Charpy	202
21.12 Comparative Thermoplastic Properties	203
21.13 Polymer Additives	203
21.14 Drying	203
Review Questions	204

22 Processing Recommendations for Various Resin Systems	207
22.1 Acrylonitrile Butadiene Styrene	207
22.1.1 Extrusion Temperature Profile	208
22.2 Polyamide	208
22.2.1 Drying	209
22.2.2 Extrusion Conditions	210
22.2.3 Amorphous Polyamide	211
22.3 Polyethylene	211
22.3.1 Extrusion Conditions	211
22.4 Polymethyl Methacrylate (Acrylic)	212
22.4.1 Extrusion Conditions	213
22.5 Polypropylene	213
22.5.1 Extrusion Conditions	213
22.6 Polycarbonate	214
22.6.1 Extrusion Conditions	214
22.7 Polystyrene	215
22.7.1 Extrusion Conditions	215
22.8 Polyvinyl Chloride	216
22.8.1 Extrusion Conditions	216
22.9 Polyester	217
22.9.1 Extrusion Conditions	218
References	218
Review Questions	219

Part 4: Troubleshooting the Extrusion Process

23 Problem Solving	221
Review Questions	225
24 Five Step Problem Solving Process	227
24.1 Problem Definition	227
24.2 Fix the Problem	228
24.3 Identify the Root Cause	228
24.4 Take Corrective Action	230
24.5 Process Monitoring	230
Reference	230
Review Questions	230
25 Design of Experiments	231
25.1 DOE Process	231
25.1.1 Defining the Problem	231
25.1.2 Plan the Experiment	232
25.1.3 Data Collection	233
25.1.4 Data Analysis	234
25.1.5 Report Conclusions	234
25.2 Experimental Design	234

25.3	Experiments	238
25.3.1	Factorial Design	238
25.3.2	Response Surface	240
25.3.3	Mixture Experiments	242
	References and Software Providers	244
	Review Questions	244
26	Quality	247
26.1	Statistical Process Control	248
26.2	Process Capability	249
	References	250
	Review Questions	250
27	Troubleshooting Mechanical Extrusion Problems	251
27.1	Problem 1—Extruder Screw Doesn't Turn	251
27.2	Problem 2—DC Motor Will Not Start	252
27.3	Problem 3—Drive Train Problems	252
27.4	Problem 4—Rupture Disk Failure in Barrel	252
27.5	Problem 5—Barrel/Screw Wear	253
27.6	Problem 6—Screw Turns and No Material Exits the Die	255
27.7	Problem 7—Extruder Shuts Itself Off	255
27.8	Problem 8—Melt Flows Out the Barrel Vent	256
27.9	Problem 9—Leaking Polymer at Breaker Plate or Die	257
27.10	Problem 10—Extruder Throughput Rate Is Lower than Anticipated	258
27.11	Problem 11—Temperature Overrides Setpoint	259
27.12	Problem 12—Extruder Surging Caused by the Equipment	260
27.13	Problem 13—Poor or Insufficient Polymer Mixing	261
27.14	Problem 14—Throughput Variation Over Time	262
	References	262
	Review Questions	263
28	Troubleshooting Extrusion Product Problems	265
28.1	Problem 1—Product Surging	265
28.2	Problem 2—Variation in the Product Over Time	266
28.3	Problem 3—Random Product Variation	267
28.4	Problem 4—Streaks in the Product Caused by Poor Mixing	268
28.5	Problem 5—Variation in Product Strength	268
28.6	Problem 6—Product Degradation	270
28.7	Problem 7—Dull Streaks	270
28.8	Problem 8—Machine Direction Die Lines	272
28.9	Problem 9—Color Contamination	272
28.10	Problem 10—Holes in Extrudate	273
28.11	Problem 11—Gels	274
28.12	Problem 12—Gauge Variations	275
28.13	Problem 13—Weld Lines	276
28.14	Problem 14—Weak Film or Coating	276
28.15	Problem 15—Warping	277

28.16	Problem 16—Sink	278
	Review Questions	279
29	Troubleshooting Sheet Extrusion	281
29.1	Mechanical Problems and Solutions	281
29.1.1	Problem 1—Die Lip Damage Causing Defects in the Machine Direction	281
29.1.2	Problem 2—Chill Roll Adjustment or Condition	282
29.1.3	Problem 3—Product Variations Caused by the Puller Rolls or Winder	284
29.1.4	Problem 4—Static Charge Build-up on Sheet	284
29.1.5	Problem 5—Other Equipment Problems	284
29.2	Product Problems and Solutions	285
29.2.1	Problem 1—Sheet Product Contamination	285
29.2.2	Problem 2—Poor and/or Nonuniform Gloss	286
29.2.3	Problem 3—Inferior Transparency	287
29.2.4	Problem 4—Color Shift or Wrong Color	287
29.2.5	Problem 5—Sheet Is Brittle	288
29.2.6	Problem 6—Surface Voids, Indentations, and Imperfections	288
29.2.7	Problem 7—High or Inconsistent Molecular Orientation	289
29.2.8	Problem 8—Warped Sheet	291
29.2.9	Problem 9—Thickness Variations	292
29.2.10	Problem 10—Lines and Roughness on Sheet	292
	Review Questions	294
30	Troubleshooting Cast Film	295
30.1	Problem 1—Molten Web Tears Easily When Exiting the Die	295
30.2	Problem 2—Film Thickness Variation	296
30.3	Problem 3—Lines, Streaks, and Foreign Contamination	296
30.4	Problem 4—Extrudate Width Is Too Narrow	298
30.5	Problem 5—Wrinkles Are Formed in the Film	298
30.6	Problem 6—Roughness on Film Due to Melt Fracture	298
	Review Questions	300
31	Troubleshooting Blown Film	301
31.1	Problem 1—Bubble Instability	301
31.2	Problem 2—Gauge Variation Around the Circumference	302
31.3	Problem 3—Wrinkles	303
31.4	Problem 4—Lines, Streaks, or Film Contamination	304
31.5	Problem 5—Rough Film Due to Melt Fracture	304
	Photo Credits	305
	Review Questions	306
32	Troubleshooting Profile and Pipe	307
32.1	Problem 1—Excessive Wall Thickness or Thinness	307
32.2	Problem 2—Wavy Surface Inside Pipe or Tubing	308
32.3	Problem 3—Weld or Knit Line Weakness	309
32.4	Problem 4—Nonuniform Resin Velocity from a Profile Die	309
	Review Questions	310

Part 5: Auxiliary Equipment

33 Feed Systems	311
33.1 Feed System	311
33.2 Blending Systems for Single Screw Extrusion	314
33.3 Feeders	321
33.3.1 Volumetric Feeder	322
33.3.2 Gravimetric Feeders	325
33.3.3 Liquid Feeders	328
References and Photo Credits	329
Review Questions	329
34 Drying	331
34.1 Drying Definitions and Factors Affecting Drying	333
34.2 Types of Drying Equipment	334
34.2.1 Oven Drying System	335
34.2.2 Hopper Dryers and Central Drying Systems	336
34.3 Purchasing a Dryer	338
References	339
Review Questions	339
35 Screen Changers	341
35.1 Breaker Plate with Screens	342
35.2 Manual Screen Changer	343
35.3 Hydraulic Screen Changer	343
35.4 Double Bolt Screen Changer	344
35.5 Ribbon-Type Screens	346
35.6 Rotary Disk Screen Changer	346
References and Photo Credits	347
Review Questions	348
36 Gear Pumps	349
36.1 Gear Pump System	350
36.2 Drive and Control System	352
36.3 Potential Gear Pump Problems	354
36.4 Applications	354
References and Photo Credits	356
Review Questions	356
37 Granulators	357
Review Questions	360
38 Chillers and Heaters	361
38.1 Chillers	361
38.2 Heaters	363
Reference	364
Review Questions	364

39 Screw Cleaning and Purge Compounds	365
39.1 Purge	365
39.2 Mechanical Cleaning	369
References and Suppliers	371
Review Questions	372

Part 6: Coextrusion

40 Coextrusion Applications	373
40.1 Film	373
40.2 Sheet	385
40.3 Pipe, Tubing, and Profile	385
40.4 Wire Coating	388
40.5 Large-Part Blow Molding	388
References and Suppliers	388
Review Questions	389
41 Feedblocks and Dies	391
41.1 Feedblocks	391
41.2 Multimanifold Dies	393
41.3 Feedblock Combined with a Manifold Die	398
41.4 Computer-Aided Design	398
References and Suppliers	399
Review Questions	399
42 Polymer Selection for Coextrusion	401
42.1 Melt Viscosity Matching	401
42.2 Interfacial Instability	403
References	409
Review Questions	409
43 Troubleshooting Coextrusion	411
43.1 Problem 1—Nonuniform Cross or Transverse Direction (CD or TD) Layer Thickness	411
43.2 Problem 2—Nonuniform Machine Direction (MD) Layer Thickness	412
43.3 Problem 3—Interfacial Instability	412
43.4 Problem 4—Repetitive Layer Thickness Variations	414
43.5 Problem 5—Layer Rearrangement	415
43.6 Problem 6—Layers Aren't the Correct Thickness	416
43.7 Problem 7—Poor Adhesion Between Layers in Structure	416
43.8 Problem 8—Structural Integrity Problems from Recycle	418
43.9 Problem 9—Haze Level Is Higher than Anticipated	419
43.10 Problem 10—Product Discoloration	419
43.11 Problem 11—Gel or Lump Formation	420
43.12 Problem 12—Warpage	420
43.13 Problem 13—Regrind Utilization	422
Review Questions	423

Part 7: Extrusion Applications

44 Compounding **425**

 44.1 Pelletizing Process 425

 44.2 Operation 432

 References and Suppliers 433

 Review Questions 433

45 Sheet and Cast Film **435**

 45.1 Sheet 435

 45.1.1 Die 435

 45.1.2 Three-Roll Stack 440

 45.1.3 Puller Rolls 442

 45.1.4 Windup or Stacker 442

 45.1.5 Thickness Measurement 443

 45.1.6 Operation 445

 45.2 Cast Film 446

 45.2.1 Die 447

 45.2.2 Rolls 447

 45.2.3 Film Treatment 449

 45.2.4 Slitter 450

 45.2.5 Gauging 450

 45.2.6 Winders 450

 45.2.7 Operation 451

 References And Suppliers 451

 Review Questions 452

46 Blown Film **453**

 46.1 Die 454

 46.2 Cooling 456

 46.3 Blown Film Tower 457

 46.4 Winders 458

 46.5 Gauging 459

 46.7 Operation 459

 References and Photo Credits 462

 Review Questions 463

47 Extrusion Coating and Lamination **465**

 Review Questions 468

48 Wire and Cable Coating **469**

 48.1 Pretreatment 471

 48.2 Die 471

 48.3 Downstream Equipment 472

 48.4 Polymers 473

 References 474

 Review Questions 474

49 Profile Extrusion	475
49.1 Die	476
49.2 Calibration and Cooling Tank	479
49.3 Puller	482
49.4 Cutters	483
49.5 Thermoplastic Materials	484
References and Photo Credits	484
Review Questions	484
50 Pipe and Tubing Extrusion	487
50.1 Die	488
50.2 Cooling and Sizing	489
50.3 Puller	494
50.4 Packaging	495
50.5 Scale-Up	495
References and Photo Credits	495
Review Questions	495
51 Monofilament	497
51.1 Die	498
51.2 Quench Tank	499
51.3 Drawing Unit with Ovens	500
51.4 On-Line Gauging	501
51.5 Creel	501
51.6 Testing	501
Supplier	502
Review Questions	502
52 Extrusion Blow Molding	505
52.1 Parison Delivery System	506
52.2 Tooling	507
52.3 Materials	511
52.4 Equipment Selection	511
References	512
Review Questions	512
53 Foam Extrusion	513
53.1 Blowing Agents	514
53.2 Downstream Equipment	516
53.3 Microcellular Foam	516
References and Suppliers	516
Review Questions	517
54 Solid Stock Shapes	519
Review Questions	521
55 Reprocessing	523
Supplier	524
Review Questions	524
Glossary	525
Index	539