


# Methods of X-Ray and Neutron Scattering in Polymer Science



Ryong-Joon Roe

# Contents

Preface      xiii

<b>1</b>	<b>Basics of X-Ray and Neutron Scattering</b>	<b>1</b>
1.1	Properties of X-Rays and Neutrons	1
1.2	Scattering and Interference	4
1.2.1	Flux, Scattering Cross Section, and Intensity	4
1.2.2	Interference Calculation	6
1.3	Scattering of X-Rays	10
1.3.1	Classical Scattering from an Electron	10
1.3.2	Electron Unit	12
1.3.3	Atomic Scattering Factor	13
1.3.4	Compton-Modified Scattering	15
1.4	Scattering of Neutrons	17
1.4.1	Scattering Length of a Single Nucleus	17
1.4.2	Coherent and Incoherent Scattering Length	19
1.5	Autocorrelation Function and Reciprocal Space	22
1.5.1	A Note on Notations	22
1.5.2	Autocorrelation Function	24
1.5.3	Ewald Sphere and Reciprocal Space	26
1.5.4	Invariant	28
1.6	Scattering due to the Sample as a Whole	29
1.7	Diffraction by Crystals	31
1.7.1	Effect of Temperature	33
	Further Reading	34
	References	35
	Exercises	35

<b>2 Experimental Techniques</b>	<b>37</b>
2.1 Radiation Source	37
2.1.1 X-Ray	37
2.1.1.1 X-Ray Tubes	37
2.1.1.2 Spectrum of X-Rays Generated	39
2.1.1.3 Synchrotron Radiation Source	40
2.1.2 Neutron	45
2.1.2.1 Nuclear Reactor	45
2.1.2.2 Neutron Guide	46
2.1.2.3 Pulsed Neutron Source	47
2.2 Monochromatization	48
2.2.1 Crystal Monochromator	48
2.2.2 Neutron Velocity Selector	51
2.3 Absorption	53
2.3.1 Absorption Coefficient	53
2.3.2 Wavelength Dependence	55
2.3.3 Filters	55
2.4 Detectors	57
2.4.1 Proportional and Scintillation Counters	58
2.4.1.1 Proportional Counter	58
2.4.1.2 Scintillation Counter	59
2.4.2 Position-Sensitive Detectors	60
2.4.3 Counting Statistics	61
2.4.4 Integrating Detectors	63
2.5 Cameras and Diffractometers	65
2.5.1 Collimation	66
2.5.2 Focusing Geometry	69
2.5.3 Diffractometer	71
2.6 Multiple Scattering	74
2.7 Absolute Intensity Calibration	77
Further Reading	80
References	80
<b>3 Crystalline Polymers</b>	<b>82</b>
3.1 Introduction	82
3.2 Lattice Parameters	84
3.2.1 Indexing	84

---

3.1 Introduction	82
3.2 Lattice Parameters	84
3.2.1 Indexing	84

3.2.2	Precision Measurement of Lattice Parameters	87
3.2.3	Examples of Lattice Parameter Measurements with Polymers	88
3.3	Crystal Structure Analysis	90
3.3.1	Fourier Synthesis	90
3.3.1.1	Effect of Symmetry	92
3.3.1.2	Resolution of the Fourier Map	94
3.3.2	Performing the Structure Analysis	95
3.3.2.1	Patterson Function	95
3.3.2.2	Methods of Phase-Angle Determination	97
3.3.2.3	Structure Refinement	98
3.3.3	Examples of Crystal Structure of Polymers	99
3.4	Line Broadening and Crystal Imperfections	101
3.4.1	Instrumental Broadening	102
3.4.2	Small Crystal Size	102
3.4.3	Crystal Imperfections	104
3.4.4	Crystal Imperfection of the First Kind	108
3.4.5	Crystal Imperfection of the Second Kind	110
3.4.6	Summary	113
3.5	Degree of Crystallinity	114
3.5.1	Evaluation of the Degree of Crystallinity	115
3.5.2	Ruland's Method	116
3.5.3	A Method Based on Small-Angle Scattering	117
3.6	Orientation	118
3.6.1	Orientation Distribution of Plane-Normals (Poles)	118
3.6.1.1	Uniaxial and Biaxial Orientation	118
3.6.1.2	Methods of Measurement	120
3.6.1.3	Pole Figure	122
3.6.2	Orientation Parameters	123
3.6.2.1	Hermans Orientation Parameter	123
3.6.2.2	Biaxial Orientation Parameters	126
3.6.3	Crystallite Orientation Distribution Function	128
	Further Reading	132
	References	132

## 4 Amorphous Polymers 134

### 4.1 Short-Range Order 134

#### 4.1.1 Pair Distribution Function: Cases with a Single Atomic Species 134

4.1.2	Pair Distribution Function: Cases with More Than One Atomic Species	137
4.1.3	Isotropic Polymers	140
4.1.4	Uniaxially Oriented Polymers	145
4.2	Thermal Density Fluctuation	147
	Further Reading	154
	References	154

## 5 Small-Angle Scattering 155

---

5.1	Model Structures Studied by Small-Angle Scattering	155
5.2	Dilute Particulate System	157
5.2.1	Radius of Gyration	158
5.2.2	Independent Scattering from Particles of Simple Geometric Shape	160
5.2.2.1	Sphere	160
5.2.2.2	Thin Rod	161
5.2.2.3	Thin Circular Disk	162
5.2.2.4	Comparison of the Three Intensity Curves	162
5.2.3	Independent Scattering from a Polymer Chain	162
5.2.3.1	Gaussian Chain	162
5.2.3.2	Worm-like Chain	164
5.2.4	Guinier law	167
5.2.4.1	Derivation of Guinier Law	168
5.2.4.2	Samples Containing Nonidentical Particles	170
5.2.5	Effect of Dense Packing	170
5.3	Nonparticulate Two-Phase System	174
5.3.1	Correlation Function and Invariant	174
5.3.2	Ideal Two-Phase Model	176
5.3.2.1	Invariant	177
5.3.2.2	Porod Law	178
5.3.2.3	Specific Interface Area and Length of Inhomogeneity	181
5.3.3	Deviations from the Ideal Two-Phase Model	184
5.3.3.1	Density Fluctuation within the Phases	184
5.3.3.2	Diffuse Interface Boundary	185
5.4	Fractal Objects	188
5.4.1	Definitions	188
5.4.2	Scattering from Fractal Objects	190
5.4.2.1	Scattering from a Mass Fractal	190
5.4.2.2	Scattering from a Surface Fractal	191

5.5	Periodic System	193
5.5.1	Scattering from Lamellar Structure	194
5.5.1.1	Ideal Two-Phase Lamellar Structure	194
5.5.1.2	Structure with Variable Lamella Thickness	196
5.5.2	Correlation Function of Lamellar Structure	201
5.6	Slit Collimation and Desmearing	204
5.6.1	Slit Collimation	204
5.6.2	Slit Desmearing	205
5.6.3	Infinite Slit Approximation	206
	Further Reading	208
	References	208

## 6 Polymer Blends, Block Copolymers, and Deuterium Labeling 210

---

6.1	Polymer Blends	210
6.1.1	Zero-Angle Scattering	210
6.1.1.1	Dilute Polymer Solution	212
6.1.1.2	Polymer Blend	212
6.1.1.3	Flory-Huggins Free Energy of Mixing	215
6.1.2	Finite-Angle Scattering	217
6.1.2.1	Some General Relationships and Assumptions	218
6.1.2.2	Dilute Polymer Solution	222
6.1.2.3	Polymer Blend	223
6.2	Block Copolymers	224
6.3	Deuterium Labeling	228
6.3.1	High Concentration Labeling	228
6.3.2	Method of Contrast Variation	230
6.3.3	Deuterium Isotope Effect	233
	Further Reading	235
	References	235

## 7 Study of Surfaces and Interfaces 236

---

7.1	Introduction	236
7.2	Reflectivity	238
7.2.1	Refractive Index	238
7.2.2	Snell's Law and Fresnel's Law	240
7.2.3	Reflectivity from a System with Two Parallel Interfaces	243

7.2.4	Reflectivity from a Multilayer Film	245
7.3	The Approximate Method	248
7.3.1	Reflectivity under the Kinematic Approximation	249
7.3.2	Comparison with Exact Results	251
7.3.3	Diffuse and Rough Interfaces	253
7.3.3.1	Diffuse Interface	253
7.3.3.2	Coherence Length and Rough Interface	255
7.4	Examples of Experimental Studies	256
	Further Reading	259
	References	259
<b>8</b>	<b>Inelastic Neutron Scattering</b>	<b>261</b>
8.1	Theory of Inelastic Scattering	261
8.1.1	Inelastic Scattering Cross Section	263
8.1.2	van Hove Correlation Function	264
8.1.3	Coherent and Incoherent Scattering	266
8.2	Simple Models of Motions	269
8.2.1	Translational Diffusion	269
8.2.2	Rotation	270
8.2.3	Vibration	274
8.2.4	Combination of Different Kinds of Motions	277
8.3	Spectrometers	278
8.3.1	Triple-Axis Spectrometer	279
8.3.2	Time-of-Flight Spectrometer	279
8.3.3	Back-Scattering Spectrometer	280
8.3.4	Spin-Echo Spectrometer	281
8.4	Examples of Experimental Studies	284
	Further Reading	290
	References	290
<b>Appendix A.</b>	<b>Refresher on Complex Numbers</b>	<b>291</b>
<b>Appendix B.</b>	<b>Fourier Transform</b>	<b>293</b>
B.1	Definitions	293
B.1.1	Fourier Transform	293
B.1.2	Cosine and Sine Transforms	294
B.2	Properties of Fourier Transform	294
B.2.1	Addition	294

B.2.2	Shift	295
B.2.3	Scaling	296
B.2.4	Differentiation	296
<b>B.3</b>	<b>Convolution</b>	<b>297</b>
B.3.1	Definition	297
B.3.2	Convolution Theorem	299
B.3.3	Derivative	299
<b>B.4</b>	<b>Delta Function</b>	<b>300</b>
B.4.1	Definition	300
B.4.2	Multiplication by $\delta(x)$	300
B.4.3	Convolution with $\delta(x)$	301
B.4.4	Fourier Transform of $\delta(x)$	301
B.4.5	Lattice Function $z(x)$	301
<b>B.5</b>	<b>Three-Dimensional Fourier Transform</b>	<b>302</b>
	Further Reading	304
	Exercises	305
<b>Appendix C.</b>	<b>Reciprocal Lattice</b>	<b>307</b>
C.1	Definition	307
C.2	Fourier Transform Relationship	308
C.3	Properties of the Reciprocal Lattice	311
C.4	Rotating-Crystal Method and Fiber Diagram	312
	Reference	314
	Exercises	314
<b>Appendix D.</b>	<b>Constants and Conversion Factors</b>	<b>316</b>
	Glossary of Symbols	317
	Index	323