Scale-up in Chemical Engineering

Second, Completely Revised and Extended Edition



Contents

Preface to th	e 1st Edition XIII
Preface to th	e 2nd Edition XV
Symbols X	VII
1	Introduction 1
2	Dimensional Analysis 3
2.1	The Fundamental Principle 3
2.2	What is a Dimension? 3
2.3	What is a Physical Quantity? 3
2.4	Base and Derived Quantities, Dimensional Constants 4
2.5	Dimensional Systems 5
2.6	Dimensional Homogeneity of a Physical Content 7
Example 1:	What determines the period of oscillation of a pendulum? 7
Example 2:	What determines the duration of fall θ of a body in a homogeneous
	gravitational field (Law of Free Fall)? What determines the speed v
	of a liquid discharge out of a vessel with an opening? (Torricelli's
	formula) 9
Example 3:	Correlation between meat size and roasting time 12
2.7	The Pi Theorem 14
3	Generation of Pi-sets by Matrix Transformation 17
Example 4:	The pressure drop of a homogeneous fluid in a straight, smooth pipe
	(ignoring the inlet effects) 17
4	Scale Invariance of the Pi-space – the Foundation of the Scale-up 25
Example 5:	Heat transfer from a heated wire to an air stream 27

VIII I	Contents

5	Important Tips Concerning the Compilation of the Problem Relevance List 31
5.1	Treatment of Universal Physical Constants 31
5.2	Introduction of Intermediate Quantities 31
Example 6:	Homogenization of liquid mixtures with different densities and viscosities 33
Example 7:	Dissolved air flotation process 34
6	Important Aspects Concerning the Scale-up 39
6.1	Scale-up Procedure for Unavailability of Model Material Systems 39
Example 8:	Scale-up of mechanical foam breakers 39
6.2	Scale-up Under Conditions of Partial Similarity 42
	Drag resistance of a ship's hull 43
Example 10:	Rules of thumb for scaling up chemical reactors: Volume-related
	mixing power and the superficial velocity as design criteria for mixing vessels and bubble columns $$ 47 $$
7	Preliminary Summary of the Scale-up Essentials 51
7.1	The Advantages of Using Dimensional Analysis 51
7.2	Scope of Applicability of Dimensional Analysis 52
7.3	Experimental Techniques for Scale-up 53
7.4	Carrying out Experiments Under Changes of Scale 54
8	Treatment of Physical Properties by Dimensional Analysis 57
8 8.1	Why is this Consideration Important? 57
8.1 8.2	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59
8.1 8.2	Why is this Consideration Important? 57
8.1 8.2 Example 11:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscos-
8.1 8.2 Example 11: Example 12:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materi-
8.1 8.2 Example 11: Example 12: Example 13:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of
8.1 8.2 Example 11: Example 12: Example 13:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T, F)$ 66
8.1 8.2 Example 11: Example 12: Example 13: Example 14:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T, F)$ 66 Reference-invariant Representation of a Material Function 68
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T, F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T, F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 15:	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 16: 8.5	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in Non-Newtonian Fluids 72
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 16: 8.5	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in Non-Newtonian Fluids 72 Rheological Standardization Functions 73
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 16: 8.5 8.5.1	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in Non-Newtonian Fluids 72 Rheological Standardization Functions 73 Flow Behavior of Non-Newtonian Pseudoplastic Fluids 73
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 16: 8.5 8.5.1.1 8.5.1.1	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in Non-Newtonian Fluids 72 Rheological Standardization Functions 73 Flow Behavior of Non-Newtonian Pseudoplastic Fluids 73 Flow Behavior of Non-Newtonian Viscoelastic Fluids 76
8.1 8.2 Example 11: Example 12: Example 13: Example 14: 8.3 8.4 Example 15: Example 16: 8.5 8.5.1	Why is this Consideration Important? 57 Dimensionless Representation of a Material Function 59 Standard representation of the temperature dependence of the viscosity 59 Standard representation of the temperature dependence of density 63 Standard representation of the particle strength for different materials in dependence on the particle diameter 64 Drying a wet polymeric mass. Reference-invariant representation of the material function $D(T,F)$ 66 Reference-invariant Representation of a Material Function 68 Pi-space for Variable Physical Properties 69 Consideration of the dependence $\mu(T)$ using the $\mu_{\rm w}/\mu$ term 70 Consideration of the dependence $\rho(T)$ by the Grashof number Gr 72 Rheological Standardization Functions and Process Equations in Non-Newtonian Fluids 72 Rheological Standardization Functions 73 Flow Behavior of Non-Newtonian Pseudoplastic Fluids 73

Example 17:	Dimensional-analytical treatment of Weissenberg's phenomenon -
	Instructions for a PhD thesis 81
8.5.2	Process Equations for Non-Newtonian Fluids 85
8.5.2.1	Concept of the Effective Viscosity $\mu_{\rm eff}$ According to Metzner–Otto 86
8.5.2.2	Process Equations for Mechanical Processes with Non-Newtonian Fluids 87
Example 18:	Power characteristics of a stirrer 87
	Homogenization characteristics of a stirrer 90
8.5.2.3	Process Equations for Thermal Processes in Association with
	Non-Newtonian Fluids 91
8.4.2.4	Scale-up in Processes with Non-Newtonian Fluids 91
9	Reduction of the Pi-space 93
9.1	The Rayleigh – Riabouchinsky Controversy 93
	Dimensional-analytical treatment of Boussinesq's problem 95
Example 21:	Heat transfer characteristic of a stirring vessel 97
10	Typical Problems and Mistakes in the Use of Dimensional Analysis 101
10.1	Model Scale and Flow Conditions – Scale-up and Miniplants 101
10.1.1	The Size of the Laboratory Device and Fluid Dynamics 102
10.1.2	The Size of the Laboratory Device and the Pi-space 103
10.1.3	Micro and Macro Mixing 104
10.1.4	Micro Mixing and the Selectivity of Complex Chemical
10 1 5	Reactions 105
10.1.5	Mini and Micro Plants from the Viewpoint of Scale-up 105
10.2	Unsatisfactory Sensitivity of the Target Quantity 106
10.2.1	Mixing Time θ 106
10.2.2	Complete Suspension of Solids According to the 1-s Criterion 106
10.3	Model Scale and the Accuracy of Measurement 107
10.3.1	Determination of the Stirrer Power 108
10.3.2	Mass Transfer in Surface Aeration 108
10.4 10.5	Complete Recording of the Pi-set by Experiment 109
10.5 10.5.1	Correct Procedure in the Application of Dimensional Analysis 111
	Preparation of Model Experiments 111
10.5.2	Execution of Model Experiments 111
10.5.3	Evaluation of Test Experiments 111
11	Optimization of Process Conditions by
	Combining Process Characteristics 113
	Determination of stirring conditions in order to carry out a
	homogenization process with minimum mixing work 113
	Process characteristics of a self-aspirating hollow stirrer and the deter-
	mination of its optimum process conditions 118
	Optimization of stirrers for the maximum removal of reaction
	heat 121

Contents	
12	Selected Examples of the Dimensional-analytical Treatment of Processes
	in the Field of Mechanical Unit Operations 125
Introductory	Remark 125
Example 25:	Power consumption in a gassed liquid. Design data for stirrers and
	model experiments for scaling up 125
Example 26:	Scale-up of mixers for mixing of solids 131
Example 27:	Conveying characteristics of single-screw machines 135
Example 28:	Dimensional-analytical treatment of liquid atomization 140
Example 29:	The hanging film phenomenon 143
Example 30:	The production of liquid/liquid emulsions 146
Example 31:	Fine grinding of solids in stirred media mills 150
Example 32:	Scale-up of flotation cells for waste water purification 156
Example 33:	Description of the temporal course of spin drying in centrifugal
	filters 163
Example 34:	Description of particle separation by means of inertial forces 166
Example 35:	Gas hold-up in bubble columns 170
Example 36:	Dimensional analysis of the tableting process 174
13	Selected Examples of the Dimensional-analytical Treatment of Processes
	in the Field of Thermal Unit Operations 181
	Introductory Remarks 181
	Steady-state heat transfer in mixing vessels 182
_	Steady-state heat transfer in pipes 184
	Steady-state heat transfer in bubble columns 185
	Foundations of the Mass Transfer in a Gas/Liquid (G/L) System 189
	duction to Examples 40, 41 and 42 189
Example 40:	Mass transfer in surface aeration 191
Example 41:	Mass transfer in volume aeration in mixing vessels 193
	Mass transfer in the G/L system in bubble columns with injectors as
_	gas distributors. Otimization of the process conditions with respect to
	the efficiency of the oxygen uptake $E \equiv G/\Sigma P$ 196
	Coalescence in the Gas/Liquid System 203
	Scaling up of dryers 205
	Selected Examples for the Dimensional-analytical Treatment of Processes in the Field of Chemical Unit Operations 211

Introductory Remark 211

Example 44: Continuous chemical reaction process in a tubular reactor 212

Example 45: Description of the mass and heat transfer in solid-catalyzed gas reactions by dimensional analysis 218

Example 46: Scale-up of reactors for catalytic processes in the petrochemical industry 226

Example 47: Dimensioning of a tubular reactor, equipped with a mixing nozzle, designed for carrying out competitive-consecutive reactions 229

Example 48	: Mass transfer limitation of the reaction rate of fast chemical reactions in the heterogeneous material gas/liquid system 233
15	Selected Examples for the Dimensional-analytical Treatment of Processes whithin the Living World 237
Introductor	y Remark 237
Example 49	The consideration of rowing from the viewpoint of dimensional analysis 238
Example 50	: Why most animals swim beneath the water surface 240
Example 51	: Walking on the Moon 241
Example 52	: Walking and jumping on water 244
Example 53	: What makes sap ascend up a tree? 245
16 16.1	Brief Historic Survey on Dimensional Analysis and Scale-up 247 Historic Development of Dimensional Analysis 247
16.2	Historic Development of Scale-up 250
10.2	Thistoric Development of Beate up 250
17	Exercises on Scale-up and Solutions 253
17.1	Exercises 253
17.2	Solutions 256
18	List of important, named pi-numbers 259
19	References 261

Index 269