


Keshra Sangwal



ADDITIVES AND CRYSTALLIZATION PROCESSES

From Fundamentals
to Applications

 WILEY

Contents

<i>Preface</i>	xiii
1 Complexes in Solutions	1
1.1 Structure of Common Solvents	2
1.2 Structure of Pure Aqueous Electrolyte Solutions	4
1.2.1 Solvation of Electrolyte Ions in Solutions	4
1.2.2 Concentrated and Saturated Electrolyte Solutions	6
1.2.3 Formation of Aquo and Partially Aquo Complexes	8
1.3 Structure of Aqueous Electrolyte Solutions Containing Additives	10
1.4 Polyelectrolytes and Surfactants in Solutions	16
1.5 Polydentate Ligands and Molecular Additives	18
1.6 Crystal–Additive Interactions	19
References	19
2 Three-Dimensional Nucleation and Metastable Zone Width	21
2.1 Driving Force for Phase Transition	22
2.2 Three-Dimensional Nucleation of Crystals	25
2.2.1 Three-Dimensional Nucleation Rate	25
2.2.2 Three-Dimensional Heterogeneous Nucleation	30
2.3 Metastable Zone Width	35
2.4 Nucleation and Transformation of Metastable Phases	38
2.4.1 Crystallization of Metastable Phases	38
2.4.2 Overall Crystallization	41
2.5 Induction Period for Crystallization	47
2.6 Effects of Additives	52
2.6.1 Solubility	52
2.6.2 Three-Dimensional Nucleation Rate	56
2.6.3 Metastable Zone Width	56
References	62

3	Kinetics and Mechanism of Crystal Growth: An Overview	65
3.1	Crystal Growth as a Kinetic Process	66
3.2	Types of Crystal–Medium Interfaces	67
3.3	Roughening of Steps and Surfaces	69
3.3.1	Thermodynamic Roughening and the Surface Entropy Factor	70
3.3.2	Kinetic Roughening	72
3.4	Growth Kinetics of Rough Faces	73
3.5	Growth Kinetics of Perfect Smooth Faces	75
3.6	Growth Kinetics of Imperfect Smooth Faces	78
3.6.1	Surface Diffusion and Direct Integration Models	78
3.6.2	Bulk Diffusion Models	80
3.6.3	Growth by a Group of Cooperating Screw Dislocations	82
3.6.4	Preferential Growth at Edge Dislocations	84
3.7	Effect of Foreign Substances on Growth Kinetics	85
3.7.1	Some General Considerations	87
3.7.2	Growth Kinetics by Heterogeneous Two-Dimensional Nucleation	90
3.8	Real Crystal Growth Mechanisms	96
3.8.1	Structure of Interfacial Layer	96
3.8.2	Sources of Growth Steps	100
3.9	Techniques for Studying Growth Kinetics	104
	References	105
4	Effect of Impurities on Crystal Growth Kinetics	109
4.1	Mobile and Immobile Impurities	109
4.2	Surface Coverage and Adsorption Isotherms	112
4.2.1	Adsorption Isotherms	113
4.2.2	Changes in Surface Free Energy by Adsorption of Impurities	115
4.3	Kinetic Models of Impurity Adsorption	115
4.3.1	Earlier Models	115
4.3.2	Velocity of Curved Steps	116
4.3.3	Impurity Adsorption at Kinks in Steps: Kubota–Mullin Model	118
4.3.4	Impurity Adsorption at Surface Terrace: Cabrera–Vermilyea Model	119
4.3.5	Effectiveness Factor for Impurity Adsorption	121
4.3.6	Adsorption of Two Competing Impurities	124
4.4	Confrontation of Impurity Adsorption Mechanisms with Experimental Data	127
4.5	Time-Dependent Impurity Adsorption	132
4.6	Growth Kinetics in the Presence of Impurities	136
4.6.1	Basic Kinetic Equations	136
4.6.2	Time Dependence of Face Displacement	141
4.6.3	Dependence of Kinetic Coefficient for Step Motion on Impurity Concentration	142
4.7	Tapering of KDP-Type Crystals	143

4.8	Growth-Promoting Effects of Impurities	146
4.8.1	Decrease in Step Free Energy and Roughening of Steps	147
4.8.2	Formation of Surface Macroclusters	152
4.9	Impurity Adsorption on Rough Faces	157
4.10	Formation of Two-Dimensional Adsorption Layer	158
4.11	Interactions Between Additives and Crystal Interface	160
4.11.1	Nature of Impurity–Crystal Interactions	160
4.11.2	Chemical Aspects of Impurity–Crystal Interactions	166
4.12	Tailor-Made Additives	172
	References	174
5	Dead Supersaturation Zone and Threshold Supersaturations for Growth	177
5.1	Origin of Threshold Supersaturations for Growth	179
5.1.1	Basic Kinetic Equations	179
5.1.2	Three Different Distances Between Impurity Particles	182
5.2	Determination of Threshold Supersaturations from $v(\sigma)$ and $R(\sigma)$	184
	Data	184
5.2.1	Relationship Between the Model Involving Cooperating Spirals and the Power-Law Approach	185
5.2.2	Relationship Between the Power-Law Approach and an Empirical Expression with Corrected Supersaturation	185
5.2.3	Determination of σ^*	186
5.3	Dependence of Threshold Supersaturations on Impurity Concentration: Basic Theoretical Equations and Linear Approximations	187
5.4	Confrontation of Theoretical Equations with Experimental Data	190
5.4.1	Impurity Adsorption at Kinks and Surface Terrace	190
5.4.2	Threshold Supersaturations and Impurity Adsorption Isotherms	193
5.5	Impurity Adsorption and Solution Supersaturation	197
5.6	Dependence of Ratios σ_d/σ^* and σ^*/σ^{**} on c_i	198
	References	202
6	Mineralization in Natural and Artificial Systems	205
6.1	Biom mineralization as a Process	205
6.1.1	Structure and Composition of Biominerals	205
6.1.2	Humans and Animals	206
6.1.3	Plants	209
6.1.4	Mollusk Shells and Avian Eggshells	211
6.2	Pathological Mineralization	216
6.3	Effect of Biologically Active Additives on Crystallization Processes	222
6.3.1	Overall Precipitation Kinetics	222
6.3.2	Overall Growth Kinetics	230
6.3.3	Phases and Polymorphs of Crystallizing Calcium Salts	242
6.3.4	Transformation of Metastable Phases	247

6.4	Scale Formation and Salt Weathering	258
	References	262
7	Morphology and Size Distribution of Crystals	265
7.1	Growth Morphology of Crystals	266
7.1.1	General Concepts	266
7.1.2	Effect of Additives on Surface Morphology	273
7.1.3	Effect of Solvent on Crystal Morphology	275
7.1.4	Growth Morphodroms	276
7.2	Ostwald Ripening and Crystal Size Dispersion	282
7.3	Crystal Size Distribution	284
7.3.1	Population Balance Approach	285
7.3.2	Balanced Nucleation-Growth Approach	289
7.3.3	Approach Based on Law of Proportionate Effect	291
7.3.4	Effect of Additives on Crystal Size Distribution	295
7.4	Control of Shape and Size of Particles	298
7.4.1	Growth-Directed Synthesis	298
7.4.2	Template-Directed Synthesis	307
7.5	Biological Tissue Engineering	311
	References	314
8	Additives and Crystallization Processes in Industries	319
8.1	Pharmaceutical Industry	320
8.1.1	Nucleation, Growth and Morphology of Drug Crystals	321
8.1.2	Preparation and Size Distribution of Drug Particles	324
8.2	Petroleum Industry	330
8.2.1	Some Basic Concepts	331
8.2.2	Crystallization Behavior of Linear Long-Chain <i>n</i> -Alkanes	332
8.2.3	Biodiesels and their Crystallization Behavior	338
8.3	Food Industry	348
8.3.1	Some Basic Concepts	351
8.3.2	Crystallization of Food Fats in the Bulk	356
8.3.3	Crystallization of Polymorphs	361
8.3.4	Crystallization of Fats and Oils in Emulsion Droplets	366
8.3.5	Number of Nucleation Centers and Overall Crystallization in Emulsion Systems	372
	References	377
9	Incorporation of Impurities in Crystals	381
9.1	Types of Impurity Incorporation and the Segregation Coefficient	382
9.2	Equilibrium Segregation Coefficient	386
9.2.1	Binary Mixture Approach	386
9.2.2	Thermodynamic Approach	388
9.2.3	Theoretical Predictions and their Comparison with Experimental Data on Segregation Coefficient	389
9.3	Effective Segregation Coefficient	396

9.3.1	Volume Diffusion Model	396
9.3.2	Diffusional Relaxation Approach	397
9.3.3	Statistical Selection Approach	401
9.3.4	Surface Adsorption Approach	402
9.4	Relationship Between Effective Segregation Coefficient and Face Growth Rate	410
9.5	Threshold Supersaturation for Trapping of Impurities During Growth	413
9.6	Effective Segregation Coefficient and Internal Stresses Caused by Impurities	416
	References	418
	<i>List of Symbols</i>	421
	<i>Subject Index</i>	427
	<i>Author Index</i>	437