

ROGER C. REED

The
SUPERALLOYS
Fundamentals and Applications



CAMBRIDGE

Contents

<i>Foreword by Dr Mike Hicks</i>	<i>Page xi</i>
<i>Preface</i>	<i>xiii</i>
<i>Acknowledgements</i>	<i>xv</i>
1 Introduction	1
1.1 Background: materials for high-temperature applications	1
1.1.1 Characteristics of high-temperature materials	1
1.1.2 The superalloys as high-temperature materials	2
1.1.3 Instances of superalloy component failures	5
1.2 The requirement: the gas turbine engine	8
1.3 The selection of materials for high-temperature applications	14
1.3.1 Larson–Miller approach for the ranking of creep performance	14
1.3.2 Historical development of the superalloys	18
1.3.3 Nickel as a high-temperature material: justification	25
1.4 Summary	28
<i>Questions</i>	<i>29</i>
<i>References</i>	<i>31</i>
2 The physical metallurgy of nickel and its alloys	33
2.1 Composition–microstructure relationships in nickel alloys	34
2.1.1 The FCC phase	35
2.1.2 The gamma prime phase	40
2.1.3 Other phases in the superalloys	49
2.2 Defects in nickel and its alloys	55
2.2.1 Defects in the gamma (FCC) phase	55
2.2.2 Defects in the gamma prime phase	65
2.3 Strengthening effects in nickel alloys	73
2.3.1 Strengthening by particles of the gamma prime phase	74
2.3.2 Temperature dependence of strengthening in the superalloys	81
2.3.3 The anomalous yielding effect in gamma prime alloys	86
2.4 The creep behaviour of nickel alloys	90
2.4.1 The creep behaviour of nickel	91
2.4.2 Creep strengthening in nickel alloys by solid-solution strengthening	95
2.4.3 Creep strengthening in nickel alloys by precipitation hardening	99

2.5	Summary	101
	<i>Appendix. The anisotropic elasticity displayed by nickel</i>	103
	<i>Questions</i>	108
	<i>References</i>	114
3	Single-crystal superalloys for blade applications	121
3.1	Processing of turbine blading by solidification processing	122
3.1.1	The practice of investment casting: directional solidification	122
3.1.2	Analysis of heat transfer during directional solidification	130
3.1.3	Formation of defects during directional solidification	139
3.1.4	The influence of processing conditions on the scale of the dendritic structure	143
3.2	Optimisation of the chemistry of single-crystal superalloys	147
3.2.1	Guideline 1	152
3.2.2	Guideline 2	154
3.2.3	Guideline 3	157
3.2.4	Guideline 4	162
3.3	Mechanical behaviour of the single-crystal superalloys	170
3.3.1	Performance in creep	171
3.3.2	Performance in fatigue	187
3.4	Turbine blading: design of its size and shape	194
3.4.1	Estimation of the length of the turbine aerofoils	196
3.4.2	Choice of mean radius for turbine blading	198
3.4.3	Estimation of exit angle from blade cross-section	200
	<i>Appendix. Growth of an isolated dendrite, using hemispherical needle approximation</i>	202
	<i>Questions</i>	203
	<i>References</i>	211
4	Superalloys for turbine disc applications	217
4.1	Processing of the turbine disc alloys	217
4.1.1	Processing by the cast and wrought route	222
4.1.2	Processing by the powder route	231
4.2	Composition, microstructure and properties of turbine disc alloys	236
4.2.1	Guideline 1	238
4.2.2	Guideline 2	246
4.2.3	Guideline 3	252
4.3	Service life estimation for turbine disc applications	259
4.3.1	Stress analysis of a turbine disc of simplified geometry	259
4.3.2	Methods for lifing a turbine disc	260
4.3.3	Non-destructive evaluation of turbine discs	271
	<i>Questions</i>	274
	<i>References</i>	278

5	Environmental degradation: the role of coatings	283
5.1	Processes for the deposition of coatings on the superalloys	285
5.1.1	Electron beam physical vapour deposition	285
5.1.2	Plasma spraying	288
5.1.3	Pack cementation and chemical vapour deposition methods	293
5.2	Thermal barrier coatings	297
5.2.1	Quantification of the insulating effect	297
5.2.2	The choice of ceramic material for a TBC	298
5.2.3	Factors controlling the thermal conductivity of a ceramic coating	301
5.3	Overlay coatings	305
5.3.1	Oxidation behaviour of Ni-based overlay coatings	307
5.3.2	Mechanical properties of superalloys coated with overlay coatings	312
5.4	Diffusion coatings	317
5.5	Failure mechanisms in thermal barrier coating systems	324
5.5.1	Introduction	324
5.5.2	Observations of failure mechanisms in TBC systems	325
5.5.3	Lifetime estimation models	331
5.5.4	The role of imperfections near the TGO	333
5.6	Summary	335
	<i>Questions</i>	337
	<i>References</i>	340
6	Summary and future trends	351
6.1	Trends in superalloys for turbine blade applications	353
6.2	Trends in superalloys and processes for turbine disc applications	357
6.3	Concluding remarks	361
	<i>References</i>	362
	<i>Index</i>	363