Product Development

A Structured Approach to Consumer Product Development, Design, and Manufacture

Anil Mital
Anoop Desai
Anand Subramanian
Aashi Mital



Table of Contents

Preface

Biographical Sketches

xvii

| Chapter 1 | | | |
|--------------------------|--|-----------------|----|
| The Signi | ificance of Manufacturing | | |
| 1.1 1.2 1.3 1.4 | Globalization and the World Economy Importance of Manufacturing 4 What Is Manufacturing? 6 Some Basic Concepts 7 | | |
| | 1.4.1 Capital Circulation or the Production Turn 1.4.2 Manufacturing Capability 9 1.4.3 Mass Production 9 1.4.4 Interchangeability 10 1.4.5 Product Life Cycle 10 1.4.6 The S Curve of the Technology Growth Cycle | 8 11 | 11 |
| 1.5 Refere | 1.4.8 Design for 'X' 12 1.4.9 The Engineering Problem-Solving Process Summary 15 | 13 | |
| Chapter 2 | | | |
| Developi | ing Successful Products | | |
| 2.1 2.2 2.3 | Key Factors to Developing Successful New Products 2.3.1 Uniqueness 19 | 18 20 | 19 |
| | 2.3.2 Customer Pocus and Market Orientation 2 2.3.3 Doing the Homework 20 | 50 | |

| 3.1 3.2 3.3 3.4 3.5 | Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 Establishing Functions, Setting Requirements, and Deve Specifications 60 Developing Provisional Designs 63 Evaluation and Decision-Making 66 | 46 loping |
|---------------------------------|---|---|--------------|
| 3.2 3.3 3.4 3.5 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 3.5.3 3.5.4 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 Establishing Functions, Setting Requirements, and Deve Specifications 60 Developing Provisional Designs 63 Evaluation and Decision-Making 66 | |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 3.5.3 3.5.4 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 Establishing Functions, Setting Requirements, and Deve Specifications 60 Developing Provisional Designs 63 | |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 3.5.3 3.5.4 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 Establishing Functions, Setting Requirements, and Deve Specifications 60 | |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 3.5.3 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 Establishing Functions, Setting Requirements, and Devo | |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 3.5.3 | Changing Design Process 38 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 Defining the Problem and Setting Objectives 52 | |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 3.5.2 | Changing Design Process 38 The Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Lequirements for Design 49 Lequirements for Design 50 Problem Confronting the Designers 50 Steps of the Engineering Design Process 52 | 46 |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D 3.5.1 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 Problem Confronting the Designers 50 | 46 |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R The D | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 Resign Process 50 | 46 |
| 3.2 3.3 | The C Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 3.3.6 The R | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 Avoiding Tunnel Vision 49 Requirements for Design 49 | 46 |
| 3.2 | The C. Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 | 46 |
| 3.2 | The C. Design 3.3.1 3.3.2 3.3.3 3.3.4 3.3.5 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 Avoiding Starting Problem Analysis in the Middle Avoiding Confirming a False Hypothesis 46 | 46 |
| 3.2 | The C. Design 3.3.1 3.3.2 3.3.3 3.3.4 | Changing Design Process 38 In Paradigms 40 In Phe Need for a Model 41 In Phe Need for Redundancy 42 In Phe Scale Effect 42 Avoiding Starting Problem Analysis in the Middle | 46 |
| 3.2 | The C. Design 3.3.1 3.3.2 3.3.3 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 The Scale Effect 42 | |
| 3.2 | The C. Design 3.3.1 3.3.2 | Changing Design Process 38 In Paradigms 40 The Need for a Model 41 The Need for Redundancy 42 | |
| 3.2 | The C. Design 3.3.1 | Changing Design Process 38 1 Paradigms 40 The Need for a Model 41 | |
| 3.2 | The C Design | Changing Design Process 38 1 Paradigms 40 | |
| 3.2 | The C | Changing Design Process 38 | |
| | | | |
| | | 1 - 13 - 2 - m 7 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - | |
| 1110 011 | | 9 | |
| | | of the Product Design Process | |
| Chapter | 3 | | |
| | | | |
| | | | |
| | erences | 36 | |
| 2.4 | Summ | 1 5 | |
| | 2.4.8 | Developing New Product Plans 29 | |
| | 2.4.7 | Managing the Portfolio 28 | |
| | 2,4.6 | Creating the Product Portfolio 28 | |
| | 2.4.5 | Setting Criteria for Product Inclusion in the Portfolio | 28 |
| | 2.4.4 | Developing a List of New Product Options 28 | |
| | 2.4.3 | Determining Existing Opportunities 26 | |
| | 2,4.2 | Gathering Strategic Information 25 | |
| | | New Products 25 | |
| _,-, | 2.4.1 | Determining the Company's Growth Expectation from | |
| 2.4 | | gy for New Product Development 25 | |
| | 2,3,14 | Miscellaneous Factors 24 | |
| | 2.3.12 | Experience and Core Competencies 23 | |
| | 2.3.11 | Market Attractiveness 23 | 200,7 |
| | 2.3.10 | Availability of a Systematic New Product Process | 23 |
| | 2.3.10 | Speed without Compromising Quality 22 | |
| | 2.3.9 | Role of the Top Management 22 | |
| | 2.3.7 | Project Selection Decisions 21 Telling the World You Have a Good Product 22 | |
| | 2.3.6 2.3.7 | Organizational Structure and Climate 21 Project Selection Decisions 21 | |
| | | | |
| | | Execution of Activities 21 | |
| | 2.3.4 | Sharp and Early Product Definition 20 Execution of Activities 21 | |

| Chapter 4 | | | |
|-----------|---------|---|-------------|
| Design I | Review | : Designing to Ensure Quality | |
| 4.1 | Introdu | ection 71 | |
| | 4.1.1 | Why Quality Control? 72 | |
| | 4.1.2 | Reactive versus Proactive Quality Control | 73 |
| 4.2 | Proced | ures for Incorporating High Quality in De | sign Stages |
| | 4.2.1 | Six Sigma 74 | 0 0 |
| | 4.2.2 | Mistake Proofing (<i>Poka-Yoke</i>) 75 | |
| | 4.2.3 | Quality Function Deployment 76 | |

74

4.2.4 Design Review
4.3 Case Studies 84

4.3.1 A Design Review Case Study 84

4.3.2 A Six Sigma Case Study 84

References 90

Chapter 5

Consideration and Selection of Materials

111

| | portance of Material Selection in Product Manufacture onomics of Material Selection 96 | 93 |
|------|---|----|
| 3 Ma | aterial Selection Procedures 96 | |
| 5.3 | .1 Grouping Materials in Families 96 | |
| 5.3 | .2 Grouping Materials Based on Process Compatibility 9 | 7 |
| 5.3 | | |
| 5.3 | .4 Computer Aided Material Selection 99 | |
| 4 De | sign Recommendations 102 | |
| 5.4 | .1 Minimize Material Costs 102 | |
| 5.4 | .2 Ferrous Metals, Hot-Rolled Steel 103 | |
| 5.4 | .3 Ferrous Metals, Cold-Finished Steel 103 | |
| 5.4 | .4 Ferrous Metals, Stainless Steel 106 | |
| 5.4 | .5 Nonferrous Metals 106 | |
| 5.4 | .6 Nonmetals 107 | |

Chapter 6

References

Selection of Manufacturing Processes and Design Considerations

| 6.1 | Introdu | uction 113 | |
|-----|---------|---|---|
| | 6.1.1 | Primary Processes 113 | |
| | 6.1.2 | Secondary Processes 114 | |
| | 6.1.3 | Tertiary Processes 116 | |
| 6.2 | Design | Guidelines 116 | |
| | 6.2.1 | Design Guidelines for Casting 116 | |
| | 6.2.2 | Design Guidelines for Forging 121 | |
| | 6.2.3 | Design Guidelines for Extrusion 122 | |
| | 6.2.4 | Design Guidelines for Metal Stamping 123 | |
| | 6.2.5 | Design Guidelines for Powdered Metal Processing 12- | 4 |

| | 6.2.8 | Design Guidelines for Screw-Machine Parts 130 |
|--------------|--------|--|
| | 6.2.9 | Design Guidelines for Milling 131 |
| | 6.2.10 | Design Guidelines for Planing and Shaping 132 |
| | 6.2.11 | Design Guidelines for Screw Threads 132 |
| | 6.2.12 | A Typical Part Drawing and Routing Sheet 133 |
| Refer | ences | 134 |
| Chapter 7 | | |
| Designin | g for | Assembly and Disassembly |
| 7.1 | Introd | |
| | 7.1.1 | Definition and the Importance of the Assembly Process 135 |
| | 7.1.2 | Definition and the Importance of the Disassembly Process 135 |
| 7.2 | | for Assembly 136 |
| | 7.2.1 | Definition 136 |
| | 7.2.2 | Different Methods of Assembly 136 |
| 7.3 | Design | Guidelines for Different Modes of Assembly 137 |
| | 7.3.1 | Manual Assembly 137 |
| | 7.3.2 | Automatic Assembly 139 |
| | 7.3.3 | Robotic Assembly 140 |
| 7.4 | Metho | ds for Evaluating Design for Assembly 140 |
| | 7.4.1 | The Hitachi Assemblability Evaluation Method 141 |
| | 7.4.2 | Lucas DFA Evaluation Method 142 |
| | 7.4.3 | The Boothroyd-Dewhurst DFA Evaluation Method 144 |
| 7 . 5 | A Desi | gn for Assembly Method Based on MTM Standards 149 |
| 7.6 | A Desi | gn for Assembly Case Study 151 |
| 7.7 | Design | for Disassembly 153 |
| | 7.7.1 | Definition 153 |
| | 7.7.2 | Disassembly Process Planning 156 |
| 7.8 | | for Disassembly Guidelines 157 |
| 7.9 | Disass | embly Algorithms 159 |
| | 7.9.1 | Product Recovery Approach 159 |
| | 7.9.2 | Optimal Disassembly Sequence Planning for Product |
| | | Recovery 160 |
| | 7.9.3 | Disassembly Sequence Planning for a Product with Defective |
| | | Parts 162 |
| | 7.9.4 | Evaluation of Disassembly Planning Based on Economic |
| | | Criteria 162 |
| | 7.9.5 | Geometric Models and CAD Algorithms to Analyze Disassembly |
| | | Planning 164 |
| | 7.9.6 | Automation of Disassembly Technology and Predicting Future |
| | | Trends 164 |
| 7.10 | A Pro | active Design for Disassembly Method Based on MTM |
| | Standa | |
| 7.11 | | ign for Disassembly Case Study 166 |
| 7.12 | Conch | uding Remarks 176 |
| Refer | ences | 177 |

Design Guidelines for Fine-Blanked Parts

Design Guidelines for Screw-Machine Parts

Design Guidelines for Machined Parts

125

127

6.2.6

6.2.7

Chapter 8 Designing for Maintenance

| 8.1 | Introd | uction 179 |
|------|--------|--|
| | 8.1.1 | Importance of Designing for Maintenance 179 |
| | 8.1.2 | Factors Affecting Ease of Maintenance 180 |
| 8.2 | Mainte | enance Elements and Concepts 182 |
| | 8.2.1 | Maintenance Elements 182 |
| | 8.2.2 | Maintenance Concepts 182 |
| | 8.2.3 | Design Review for Maintainability: Planning for Maintenance and Its |
| | | Management 186 |
| 8.3 | Mathe | matical Models for Maintainability 190 |
| | 8.3.1 | Simple Models 191 |
| | 8.3.2 | An Integrated Approach to Maintenance 192 |
| | 8.3.3 | Capital Replacement Modeling 193 |
| | 8.3.4 | Inspection Maintenance 193 |
| | 8.3.5 | Condition-Based Maintenance 193 |
| | 8.3.6 | Maintenance Management Information Systems 194 |
| 8.4 | | tion Models for Maintenance 195 |
| | 8.4.1 | The RCA Method 195 |
| | 8.4.2 | The Federal Electric Method 198 |
| | 8.4.3 | The Martin Method: TEAM 199 |
| | 8.4.4 | The RCM Method: Maintenance Management 201 |
| | 8.4.5 | Design Attributes for Enhancing Maintainability 203 |
| | 8.4.6 | The SAE Maintainability Standard 204 |
| | 8.4.7 | The Bretby Maintainability Index 209 |
| 8.5 | A Con | nprehensive Design for a Maintenance Methodology Based on Methods |
| | | Measurement 214 |
| | 8.5.1 | A Numeric Index to Gauge the Ease of Maintenance 215 |
| | 8.5.2 | Role of Work Standards and Standard Times 218 |
| | 8.5.3 | Common Maintenance Procedures and the Parameters Affecting |
| | | Them 218 |
| | 8.5.4 | Provision for Additional Allowances for Posture, Motion, Energy, and |
| | | Personnel Requirements 218 |
| | 8.5.5 | Design Parameters Affecting Premaintenance Operations 220 |
| | 8.5.6 | Structure of the Index 222 |
| | 8.5.7 | Using the Index 227 |
| | 8.5.8 | Priority Criteria for Design Evaluation 227 |
| 8.6 | Devel | oping and Evaluating an Index 228 |
| | 8.6.1 | Numeric Index and Design Method for Disassembly and |
| | | Reassembly 228 |
| | 8.6.2 | Numeric Index and Design Method for Maintenance 229 |
| | 8.6.3 | Priority Criteria for Maintenance 229 |
| | 8.6.4 | A Holistic Method for Maintainability 231 |
| | 8.6.5 | Design Modifications and Measures to Enhance Ease of |
| | | Maintenance 232 |
| 8.7 | | n for Maintenance Case Study 232 |
| 8.8 | Concl | luding Remarks 236 |
| Refe | | 2.37 |

Chapter 9

Designing Products for Functionality

10.2.3 Aesthetics

10.2.4 Reliability

298 298

| Desigim | igito | ducts for ranctionality | |
|-----------|------------------|---|-----|
| 9.1 | Introd | uction 241 | |
| | 9.1.1 | Definition and Importance of Functionality 241 | |
| | 9.1.2 | Factors Affecting Functionality 241 | |
| 9.2 | Concu | rrent Engineering in Product Design 242 | |
| | 9.2.1 | Functionality in Design 244 | |
| | 9.2.2 | Function and Functional Representations: Definitions 244 | |
| 9.3 | A Gen | eric, Guideline-Based Method for Functionality 247 | |
| | 9.3.1 | Phase 1. Development of Generic Criteria for Functionality | 248 |
| | 9.3.2 | Phase 2. Validation and Testing of Developed Criteria and | |
| | | Processes 249 | |
| 9.4 | The P | rocedure for Guideline Development 251 | |
| 9.5 | Functi | onality Case Study: Can Opener 254 | |
| | 9.5.1 | Can Opener Architecture 254 | |
| | 9.5.2 | Can Opener Manufacturing Processes 254 | |
| | 9.5.3 | Guideline Development Process for the Can Opener 255 | |
| | 9.5.4 | Identification of Important Manufacturing Variables Affecting | |
| | | Functionality 255 | |
| | 9.5.5 | Functionality-Manufacturing Links 256 | |
| | 9.5.6 | Survey Development 258 | |
| | 9.5.7 | Statistical Analysis and Testing 261 | |
| | 9.5.8 | Hypothesis Test Results 268 | |
| | 9.5.9 | Discussion of the Results 269 | |
| 9.6 | | ionality Case Study: Automotive Braking System 270 | |
| | 9.6.1 | The Function of an Automotive Braking System 270 | |
| | 9.6.2 | The Components of an Automotive Braking System 271 | |
| | 9.6.3 | Wheel Cylinder Architecture 271 | |
| | 9.6.4 | Wheel Cylinder Manufacturing Processes 271 | |
| | 9.6.5 | Guideline Development Procedure for the Automotive Brake | |
| | 0.6.6 | System 272 | |
| | 9.6.6 | Functionality-Manufacturing Links 274 | |
| | 9.6.7 9.6.8 | Survey Development 280 Testing and Statistical Analysis 280 | |
| | 9.6.8 | Discussion of the Results 292 | |
| Dofo | 9.0.9 erences | | |
| Kere | rences | 293 | |
| Chapter 1 | เก | | |
| - | | 1.11. | |
| Design | tor Us | ability | |
| 10.1 | Introd | luction 295 | |
| 10.2 | Criter | ria for Designing and Manufacturing Usable Consumer | |
| | Produ | | |
| | 10.2.1 | Functionality 296 | |
| | 10 2 2 | Face of Operation 207 | |

| | 10.2.5 | Serviceability and Maintainability 299 |
|--------------|---------|--|
| | 10.2.6 | Environmental Friendliness 300 |
| | 10.2.7 | Recyclability and Disposability 301 |
| | 10.2.8 | Safety 301 |
| 40.2 | 10.2.9 | Customizability 302 |
| 10.3 | 10.3.1 | Support Tools and Methodologies 303 |
| | 10.3.1 | Design for Producibility 303 |
| | 10.3.3 | Design for Assembly 303 Robust Design 304 |
| | | Group Technology 304 |
| | | Quality Function Deployment 305 |
| 10.4 | | Methodology for Usability 305 |
| 200. | 10.4.1 | Development of Generic Usability Evaluation Checklists 305 |
| | 10.4.2 | Development of Generic Design and Manufacturing |
| | | Checklists 306 |
| | 10.4.3 | Reliability and Validity Testing 307 |
| | | Testing the Effectiveness of the Design/Manufacturing |
| | | Guidelines 307 |
| 10.5 | Generic | Checklist Design: Methods and Case Studies 307 |
| | | Product Development for the Usability of a Can Opener 308 |
| | 10.5.2 | Product Development for the Usability of a Toaster 318 |
| | 10.5.3 | Checklists for Evaluating the Usability of a |
| | | Consumer Product 327 |
| 10.6 | | ady for the Development of Customized Checklists 345 |
| | | Gauging User Requirements 345 |
| | | Technical Requirements 348 |
| | | Product and Process Characteristics 350 |
| | | Manufacturing Process Attributes 353 |
| • • • | | Development of Usability and Design Checklists 356 |
| 10.7 | | ling Remarks 365 |
| Refer | ences | 365 |
| Chapter 1 | 1 | |
| | | e Product Selling Price |
| | | |
| 11.1 | - | timate Costs? 369 |
| 11.2 | | d Price Structure 370 |
| 11.3 11.4 | | tion Needs and Sources 373 |
| 11.4 | | ing Direct and Indirect Costs 374 |
| | | Direct Labor Costs 374 Direct Material Costs 376 |
| | | Direct Material Costs 376 Indirect or Overhead Costs 380 |
| | | |
| 11.5 | | An Example 381 Pricing Methods 382 |
| A.L. | | Conference and Comparison Method 383 |
| | | Investment Method 383 |
| | | Full Cost Method 383 |
| | | Direct Costing or Contribution Method 383 |
| | | = most morning or constitution and |

| 11.5 Refer | Summa rences | ry 383 384 |
|----------------------|-----------------|---|
| | | 304 |
| Chapter | | |
| Assessi | ng the ${ m I}$ | Market Demand for the Product |
| 12.1 | Why A | ssess the Market Demand? 385 |
| 12.2 | • | Is for Assessing the Initial Demand 387 |
| | 12.2.1 | Expert Evaluation Technique 387 |
| | 12.2.2 | Jury of Executive Opinion 387 |
| | 12.2.3 | Delphi Method 388 |
| | 12.2.4 | Sales Force Composite 388 |
| | 12.2.5 | • • • |
| | | Market Research 388 |
| | | Decision Tree Diagram 390 |
| | | Market Potential–Sales Requirement Method 391 |
| 12.3 | | ls for Determining the Annual Growth 391 |
| | 12.3.1 | Graphical Displays of Data 391 |
| | 12.3.2 | |
| | | Linear Model 395 |
| | | Quadratic Model 395 |
| 12.4 | | Exponential Model 397 |
| 12.4 | - | ing for Seasonal Fluctuations 398 Naive Model 398 |
| | 12.4.1 | * 1 W 1 = -1 = -1 |
| | | Moving Average Model 398 Exponential Smoothing 400 |
| 12.5 | 12.4.3 Summa | · · · |
| 12.3 | Summa | uy 400 |
| Chapter | 13 | |
| Plannir | ng the F | roduct Manufacturing Facility Design |
| 13.1 13.2 13.3 | Detern | uction 403 nining the Location of the Manufacturing Facility 404 ping the Preliminary Design for the Manufacturing Facility 407 |

407

409

412

13.3.1 Determining Space Requirements

415

Systematic Layout Planning

13.3.2 Assembly Line Balancing

416

Postscript 417 Index 419

References

13.4

13.3.3

Summary