






Wiley Series on Processing of Engineering Materials • Randall M. German, Series Editor



CHEMISTRY AND PHYSICS OF MECHANICAL HARDNESS



JOHN J. GILMAN



 WILEY

TABLE OF CONTENTS

Preface	xi
1 Introduction	1
1.1 Why Hardness Matters (A Short History)	1
1.2 Purpose of This Book	5
1.3 The Nature of Hardness	7
References	10
2 Indentation	11
2.1 Introduction	11
2.2 The Chin-Gilman Parameter	14
2.3 What Does Indentation Hardness Measure?	14
2.4 Indentation Size Effect	20
2.5 Indentation Size (From Macro to Nano)	22
2.6 Indentation vs. Scratch Hardness	23
2.7 Blunt or Soft Indenters	24
2.8 Anisotropy	24
2.9 Indenter and Specimen Surfaces	25
References	25
3 Chemical Bonding	27
3.1 Forms of Bonding	27
3.2 Atoms	28
3.3 State Symmetries	29
3.4 Molecular Bonding (Hydrogen)	31
3.5 Covalent Bonds	36
3.6 Bonding in Solids	41
3.6.1 Ionic Bonding	41
3.6.2 Metallic Bonding	43
3.6.3 Covalent Crystals	44
3.7 Electrodynamic Bonding	45
3.8 Polarizability	47
References	48

4	Plastic Deformation	51
4.1	Introduction	51
4.2	Dislocation Movement	52
4.3	Importance of Symmetry	55
4.4	Local Inelastic Shearing of Atoms	56
4.5	Dislocation Multiplication	57
4.6	Individual Dislocation Velocities (Microscopic Distances)	59
4.7	Viscous Drag	60
4.7.1	Pure Metals	61
4.7.2	Covalent Crystals	62
4.8	Deformation-Softening and Elastic Relaxation	62
4.9	Macroscopic Plastic Deformation	63
	References	64
5	Covalent Semiconductors	67
5.1	Introduction	67
5.2	Octahedral Shear Stiffness	69
5.3	Chemical Bonds and Dislocation Mobility	71
5.4	Behavior of Kinks	75
5.5	Effect of Polarity	77
5.6	Photoplasticity	79
5.7	Surface Environments	80
5.8	Effect of Temperature	80
5.9	Doping Effects	80
	References	81
6	Simple Metals and Alloys	83
6.1	Intrinsic Behavior	83
6.2	Extrinsic Sources of Plastic Resistance	85
6.2.1	Deformation-Hardening	85
6.2.2	Impurity Atoms (Alloying)	87
6.2.3	Precipitates (Clusters, Needles, and Platelets)	89
6.2.4	Grain-Boundaries	90
6.2.5	Surface Films (Such as Oxides)	94
6.2.6	Magnetic Domain Walls	95
6.2.7	Ferroelectric Domain-Walls	96
6.2.8	Twin Boundaries	96
	References	96
7	Transition Metals	99
7.1	Introduction	99
7.2	Rare Earth Metals	101
	References	101

8	Intermetallic Compounds	103
8.1	Introduction	103
8.2	Crystal Structures	104
8.2.1	Sigma Phase	104
8.2.2	Laves Phases	105
8.2.3	Ni ₃ Al	107
8.3	Calculated Hardness of NiAl	112
8.4	Superconducting Intermetallic Compounds	113
8.5	Transition Metal Compounds	115
	References	116
9	Ionic Crystals	119
9.1	Alkali Halides	119
9.2	Glide in the NaCl Structure	120
9.3	Alkali Halide Alloys	123
9.4	Glide in CsCl Structure	124
9.5	Effect of Impurities	124
9.6	Alkaline Earth Fluorides	126
9.7	Alkaline Earth Sulfides	128
9.8	Photomechanical Effects	128
9.9	Effects of Applied Electric Fields	129
9.10	Magneto-Plasticity	129
	References	129
10	Metal-Metalloids (Hard Metals)	131
10.1	Introduction	131
10.2	Carbides	132
10.3	Tungsten Carbide	134
10.4	Borides	136
10.5	Titanium Diboride	137
10.6	Rare Metal Diborides	138
10.7	Hexaborides	138
10.8	Boron Carbide (Carbon Quasi-Hexaboride)	140
10.9	Nitrides	141
	References	141
11	Oxides	143
11.1	Introduction	143
11.2	Silicates	143
11.2.1	Quartz	144
11.2.2	Hydrolytic Catalysis	146
11.2.3	Talc	146
11.3	Cubic Oxides	147
11.3.1	Alkaline Earth Oxides	147

11.3.2	Perovskites	148	
11.3.3	Garnets	150	
11.3.3.1	($Y_3Al_5O_{12}$)—YAG	151	
11.4	Hexagonal (Rhombohedral) Oxides	152	
11.4.1	Aluminum Oxide (Sapphire)	152	
11.4.2	Hexaboron Oxide	153	
11.5	Comparison of Transition Metal Oxides with “Hard Metals”	155	
	References	156	
12	Molecular Crystals		157
12.1	Introduction	157	
12.2	Anthracene	158	
12.3	Sucrose	159	
12.4	Amino Acids	159	
12.5	Protein Crystals	160	
12.6	Energetic Crystals (Explosives)	161	
12.7	Commentary	161	
	References	161	
13	Polymers		163
13.1	Introduction	163	
13.2	Thermosetting Resins (Phenolic and Epoxide)	164	
13.3	Thermoplastic Polymers	165	
13.4	Mechanisms of Inelastic Plasticity	166	
13.5	“Natural” Polymers (Plants)	166	
13.6	“Natural” Polymers (Animals)	168	
	References	168	
14	Glasses		171
14.1	Introduction	171	
14.2	Inorganic Glasses	172	
14.3	Metallic Glasses	176	
14.3.1	Hardness—Shear Modulus Relationship	177	
14.3.2	Stable Compositions	180	
	References	180	
15	Hot Hardness		183
15.1	Introduction	183	
15.2	Nickel Aluminide versus Oxides	184	
15.3	Other Hard Compounds	184	
15.4	Metals	185	

15.5	Intermetallic Compounds	187
	References	187

16 Chemical Hardness 189

16.1	Introduction	189
16.2	Definition of Chemical Hardness	190
16.3	Physical (Mechanical) Hardness	192
16.4	Hardness and Electronic Stability	193
16.5	Chemical and Elastic Hardness (Stiffness)	194
16.6	Band Gap Density and Polarizability	194
16.7	Compression Induced Structure Changes	195
16.8	Summary	196
	References	196

17 “Superhard” Materials 197

17.1	Introduction	197
17.2	Principles for High Hardness	197
17.3	Friction at High Loads	198
17.4	Superhard Materials	199
	References	200

Index 203