



ADVANCED PROCESS CONTROL

Beyond Single Loop Control



CECIL L. SMITH

 **WILEY**

AIChE[®]

CONTENTS

Preface	ix
1 Introduction	1
1.1. Implementing Control Logic / 2	
1.2. Control Blocks for Process Control / 12	
1.3. PID Controller / 16	
1.4. Integrator or Totalizer / 23	
1.5. Lead-Lag Element / 26	
1.6. Dead Time / 29	
1.7. Selector Block / 34	
1.8. Cutoff Block / 35	
1.9. Hand Station / 36	
2 Cascade Control	38
2.1. Jacketed Reactor / 38	
2.2. Block Diagrams / 43	
2.3. Problem Element / 45	
2.4. Cooling Media Disturbances / 49	
2.5. Effect of Varying Heat Transfer Rate / 51	
2.6. Cascade Control Modes / 55	
2.7. Remote Set Point / 58	
2.8. Output Tracking / 60	
2.9. Control Modes / 62	
2.10. Interacting Stages / 64	
2.11. Tuning Cascades / 69	
2.12. Windup in Cascade Controls / 74	
2.13. Integral Tracking / 78	
2.14. External Reset / 81	
2.15. Inhibit Increase/Inhibit Decrease / 83	

3	Split-Range Control	86
3.1.	Storage Tank Pressure Control / 87	
3.2.	Split Range / 95	
3.3.	Temperature Control Using Liquid Bypass / 103	
3.4.	Recirculating Jacket with Heat and Cool Modes / 113	
4	Override Control	126
4.1.	Limit on the Cooling Water Return Temperature / 126	
4.2.	Example without Windup Protection / 131	
4.3.	Integral Tracking / 137	
4.4.	External Reset / 143	
4.5.	Inhibit Increase/Inhibit Decrease / 149	
4.6.	Limits on Heat Transfer / 156	
4.7.	Other Examples / 168	
5	Valve Position Control	179
5.1.	Polymer Pumping Example / 180	
5.2.	Terminal Reheat Systems / 185	
5.3.	Equilibrium Reaction / 188	
5.4.	Reactor with a Once-Through Jacket / 192	
6	Ratio and Feedforward Control	198
6.1.	Simple Ratios / 200	
6.2.	Ratio Control in Digital Systems / 206	
6.3.	Feedback Trim / 210	
6.4.	Dynamic Compensation / 220	
6.5.	Ratio Plus Bias / 234	
6.6.	Characterization Function / 238	
6.7.	Cross-Limiting / 247	
6.8.	Directional Lags / 260	
6.9.	Feedforward Control / 262	
6.10.	Feedforward Control Example / 267	
7	Loop Interaction	277
7.1.	Multivariable Processes / 278	
7.2.	Issues with the P&I Diagram / 283	
7.3.	Steady-State Sensitivities or Gains / 292	
7.4.	Quantitative Measures of Interaction / 308	
7.5.	Loop Pairing / 317	

- 7.6. Starch Pumping System / 319
- 7.7. Reducing the Degree of Interaction / 331

8 Multivariable Control 345

- 8.1. Decoupler / 347
- 8.2. Dead-Time Compensation / 378
- 8.3. Model Predictive Control / 394

Index 447