



Second Edition

Charles A. Bishop

Vacuum Deposition onto Webs, Films, and Foils

Contents

Preface	xiii
Part I Vacuum Basics	1
1 What Is a Vacuum?	3
1.1 What Is a Vacuum?	3
1.2 What Is a Gas?	3
1.3 Pressure	4
1.4 Partial Pressure	5
1.5 Vapor Pressure	6
1.6 Saturated Vapor Pressure	6
1.7 Why Do We Need a Vacuum?	8
1.8 Mean Free Path	8
2 Products Using Vacuum Deposited Coatings	13
2.1 Metallized Packaging Film	14
2.2 Capacitor Films	17
2.3 Optical Data Storage Tapes	20
2.4 Holographic Coatings	21
2.5 Flake Pigments	23
2.6 Barrier Coatings	25
2.7 Transparent Conducting Oxides	32
2.8 Energy Conservation Windows	35
2.9 Solar Cells	37
2.10 Solar Absorbers	40
2.11 Flexible Circuits	42
2.12 Optical Variable Devices	42
2.13 Magnetic Electronic Article Surveillance Tags	43
2.14 Pyrotechnics	44
2.15 Thin Film Batteries	45
3 Pressure Measurement	53
3.1 Bourdon Gauge	54
3.2 Pirani and Thermocouple Gauges	55

3.3	Capacitance Manometer	56
3.4	Penning or Cold Cathode Ionization Gauge	58
3.5	Ion or Hot Cathode Ionization Gauge	59
4	Pumping	63
4.1	Rotary or Roughing Pumps	63
4.2	Roots Pumps or Blowers	65
4.3	Diffusion Pumps	66
4.4	Turbomolecular Pumps	68
4.5	Getter or Sputter Ion Pump	69
4.6	Cryopumps	70
4.7	Cryopanel	70
4.8	Pumping Strategy	72
4.9	System Pumping	75
4.10	Filtering	78
4.11	Conclusions	78
5	Process Diagnostics and Coating Characteristics	81
5.1	Reflectance (R), Transmittance (T), and Absorptance (A) Measurements	82
5.2	Optical Density	83
5.3	Conductivity/Resistivity	85
5.4	Online Resistance Monitoring	86
5.5	Transparent Conducting Coatings	89
5.6	Residual Gas Analyzers	90
5.7	Plasma Emission Monitors	92
5.8	Thickness	95
5.9	Barrier	99
5.10	Pinholes	102
5.11	Artificial Intelligence and Neural Network Control Systems	104
5.12	Chemometrics	106
5.13	Surface Energy Measurements	108
5.14	Emissivity	109
5.15	Lambda Probe/Sensor/Gauge	110
5.16	X-ray Fluorescence Sensor	111
5.17	Atomic Absorption Spectroscopy	111
6	Leaks, Water Vapor, and Leak Testing	115
6.1	Real Leaks	115
6.2	Imaginary Leaks	115
6.3	Outgassing and Water Vapor	116
6.4	Leak Detection	120
7	Mass Spectrometers, Helium Leak Detectors, and Residual Gas Analyzers	125

Part II	Substrates, Surface Modification, and Nucleation	133
8	Substrates and Surface Quality	135
8.1	Substrates	135
8.2	Polymer Surface Quality	140
8.3	Polymer Substrate Cleaning	158
8.4	Polymer Surface Etching	161
8.5	Higher Specification Polymer Substrates	164
8.6	Metal Web and Surface Quality	166
8.7	Metal Surface Contamination and Cleaning	167
8.8	Paper	168
8.9	Foams, Nonwovens, and Textiles	169
8.10	Cores	170
8.11	Packaging	172
8.12	Cost Benefit	173
9	Adhesion and Adhesion Tests	177
9.1	The "Sellotape" Test	177
9.2	Adhesion Tests	178
9.3	Adhesion and Surface Analysis	183
10	Surface Treatment of Webs and Foils	187
10.1	Atmospheric Treatments	188
10.2	Cleaning and Sealing	190
10.3	Cleaning	192
10.4	System Design Considerations	193
11	Polymer Coating Basic Information	197
11.1	Polymer Coating Processes	199
11.2	Coating Options	200
11.3	Radiation Cured Polymers—Acrylates	202
11.4	Comments	212
12	Nucleation, Coalescence, and Film Growth	215
12.1	Thin Film—Thick Film	215
12.2	Nucleation	215
12.3	Coalescence	217
12.4	Network and Percolation Threshold	218
12.5	Holes	218
12.6	Film Growth	219
12.7	Energy	221
12.8	Electrical and Optical Performance	226
12.9	Nodule Formation	229

12.10	Crystal Structure	232
12.11	Deposition Rules of Thumb	235
13	Pattern Metallization	239
13.1	Atmospheric Patterning	239
13.2	In-Vacuum Patterning	240
Part III	Process	249
14	The DC Glow Discharge or Plasma	251
14.1	The Townsend Discharge	252
14.2	The Breakdown Voltage	253
14.3	The Transition Region	256
14.4	The Normal Glow Discharge	256
14.5	The Abnormal Glow Discharge	256
14.6	The Arc	257
14.7	Triodes and Magnetically Enhanced Plasmas	257
15	Electron Beam (E-beam) Evaporation	261
15.1	Filaments and Electron Emission	261
15.2	E-beam Control	264
15.3	Power Supply	267
15.4	Crucibles and Feed Systems	268
15.5	System Design	268
16	Thermal Evaporation	273
16.1	Boats	273
16.2	Wire Feeding	281
16.3	Wire	283
16.4	Spitting and Pinholes	286
16.5	Thin Film Measurement	287
16.6	Power Supplies and Control	291
16.7	Coating Uniformity	292
16.8	Coating Strategy	296
16.9	Reactive Thermal Evaporation of Aluminum Oxide	298
17	Radiant-Heated, Induction-Heated, and Other Sources	305
17.1	Radiant-Heated Sources	305
17.2	Radiation Shields	308
17.3	Induction-Heated Sources	310
17.4	Magnetic Levitation Aluminum Deposition Source	313
17.5	Jet Vapor Sources	313
17.6	Molecular Beam Epitaxy Sources	315

18	Chemical Vapor Deposition/Polymerization onto Webs	319
18.1	Substrate Temperature	319
18.2	Power	320
18.3	Pressure	320
18.4	Substrate Bias	320
18.5	Fluorinated Plasma Polymerization	322
18.6	Carbon—Fluorine Plasmas	323
18.7	CVD of Barrier Coatings	324
18.8	Atmospheric Plasma Deposition	326
19	Atomic Layer Deposition	331
20	Magnetron Sputtering Source Design and Operation	337
20.1	DC Planar Magnetron Sputtering Source	337
20.2	Balanced and Unbalanced Magnetron Sputtering	343
20.3	Anodes	345
20.4	Radio Frequency Sputtering	346
20.5	Arcing and Control of Arcs	347
20.6	Water Cooling	352
20.7	End Effects	355
20.8	Troubleshooting Magnetron Sputtering Sources	356
21	Magnetron Sputtering Source Design Options	363
21.1	Single or Dual Magnetron Sputtering Source	364
21.2	Anode Included or Not	364
21.3	Balanced or Unbalanced Magnetic Fields	365
21.4	Fixed or Variable Magnetic Performance	365
21.5	Internal or External Fitting	366
21.6	Direct or Indirect Cooling	366
21.7	Single or Multiple Materials	367
21.8	Linked or Isolated Cathodes	368
21.9	Cost Implications	368
21.10	Coating Uniformity	369
21.11	Magnets	370
21.12	Planar or Rotatable?	371
21.13	Power Supply Choices	372
22	Reactive Sputter Deposition: Setup and Control	375
22.1	Target Preconditioning	375
22.2	Control Options	376
22.3	Hysteresis Loop	376
22.4	Monitors	379
22.5	Time Constants	380
22.6	Pumping	380

22.7	Control of Arcs	382
22.8	RF Sputtering	383
22.9	Other Processes	384

Part IV System Issues **389**

23	Machine Specification and Build Issues—Risk Analysis—Process	391
23.1	Risk Analysis: Process	391
23.2	Mistake-Proofing or Fool-Proofing	394
23.3	Project Management	395
23.4	Safety	396
23.5	Costs	396
23.6	Machine Specification	397
23.7	Maintenance and Spares	397
24	Heat Load on the Webs/Foils	401
24.1	Introduction	401
24.2	Cooling Webs	403
24.3	Free Span Deposition	404
24.4	Heated Substrates	405
24.5	Potential Winding Problems	406
24.6	Characteristic Winding Problems Associated with Too Much Heat	407
24.7	Heating Webs	410
25	Process Variables	417
25.1	Drum Surface Roughness	417
25.2	Polymer Surface Roughness	417
25.3	Material Properties	418
25.4	Deposition Rate and Winding Speed	419
25.5	Water Content of Polymer	419
25.6	Drum Temperature	422
25.7	Single or Double Side Coating	423
25.8	Source Type	424
25.9	Heat Load Calculations	424
25.10	Heat Transfer Coefficient	427
26	Mechanical Design	431
26.1	Pumping	431
26.2	Nonuniform Pumping	432
26.3	Shields	436
27	Winding Webs in Vacuum	441
27.1	System Design	441
27.2	Tension Measurement: Load Cells	447

27.3	Alignment and Spacing	447
27.4	Materials	450
27.5	Other Related Items and Materials	451
27.6	Substrates: Thermally and Dimensionally Variable	453
27.7	Safety	457
27.8	Key Points on Winding	458
28	Machine Building Trends	463
28.1	Metallizers	463
28.2	Speciality Vacuum Coaters	466
29	System Design	469
29.1	System Choices	469
29.2	Batch Versus Air-to-Air Processing	471
29.3	Source Choices	473
29.4	Summary	476
30	Hazards	481
30.1	Risk Assessment	481
30.2	Mechanical	483
30.3	Electrical	484
30.4	Thermal	485
30.5	Chemical	485
30.6	Material Interactions	486
30.7	Deposition Material and By-products	487
30.8	Hazardous Gases	488
30.9	Cold Traps and Cryopumps	489
30.10	Cleaning Hazards	490
30.11	Ergonomic and Miscellaneous	491
31	Troubleshooting	493
31.1	Troubleshooting Vacuum	493
31.2	Troubleshooting Process	495
31.3	Troubleshooting Winding Problems	496
31.4	Troubleshooting Adhesion	500
31.5	Troubleshooting—Loss of Barrier	501
31.6	Troubleshooting—Common Problems and Diagnostic Tools	502
31.7	Thermal Evaporation by Resistance-Heated Boats	503
31.8	Electron Beam Deposition	505
31.9	Magnetron Sputtering	507
32	Final Thoughts	513
	Index	517