

## Contents

### Preface *XI*

<b>1</b>	<b>Introduction</b>	<b>1</b>
1.1	Introduction	1
1.2	History of the MAX Phases	3
	References	10
<b>2</b>	<b>Structure, Bonding, and Defects</b>	<b>13</b>
2.1	Introduction	13
2.2	Atom Coordinates, Stacking Sequences, and Polymorphic Transformations	14
2.3	Lattice Parameters, Bond Lengths, and Interlayer Thicknesses	21
2.4	Theoretical Considerations	26
2.5	To Be or Not to Be	46
2.6	Distortion of Octahedra and Trigonal Prisms	47
2.7	Solid Solutions	49
2.8	Defects	50
2.9	Summary and Conclusions	57
	Appendix A: Bond distances and distortions in the $M_3AX_2$ and $M_4AX_3$ phases	58
	References	60
<b>3</b>	<b>Elastic Properties, Raman and Infrared Spectroscopy</b>	<b>65</b>
3.1	Introduction	65
3.2	Elastic Constants	65
3.3	Young's Moduli and Shear Moduli	71
3.4	Poisson's Ratios	79
3.5	Bulk Moduli	79
3.6	Extrema in Elastic Properties	87
3.7	Effect of Temperature on Elastic Properties	88
3.8	Raman Spectroscopy	90
3.9	Infrared Spectroscopy	99

3.10	Summary and Conclusions	100
	References	100
<b>4</b>	<b>Thermal Properties</b>	<b>107</b>
4.1	Introduction	107
4.2	Thermal Conductivities	107
4.3	Atomic Displacement Parameters	115
4.4	Heat Capacities	126
4.5	Thermal Expansion	136
4.6	Thermal Stability	142
4.7	Summary and Conclusions	146
4.A	Appendix	147
	References	149
<b>5</b>	<b>Electronic, Optical, and Magnetic Properties</b>	<b>155</b>
5.1	Introduction	155
5.2	Electrical Resistivities, Hall Coefficients, and Magnetoresistances	155
5.3	Seebeck Coefficients, $\Theta$	172
5.4	Optical Properties	175
5.5	Magnetic Properties	180
5.6	Superconducting Properties	181
5.7	Summary and Conclusions	182
	References	182
<b>6</b>	<b>Oxidation and Reactivity with Other Gases</b>	<b>187</b>
6.1	Introduction	187
6.2	Ti <sub>3</sub> SiC <sub>2</sub>	188
6.3	Ti <sub>n+1</sub> AlX <sub>n</sub>	197
6.4	Solid Solutions between Ti <sub>3</sub> AlC <sub>2</sub> and Ti <sub>3</sub> SiC <sub>2</sub>	210
6.5	Cr <sub>2</sub> AlC	211
6.6	Nb <sub>2</sub> AlC and (Ti <sub>0.5</sub> Nb <sub>0.5</sub> ) <sub>2</sub> AlC	213
6.7	Ti <sub>2</sub> SC	216
6.8	V <sub>2</sub> AlC and (Ti <sub>0.5</sub> V <sub>0.5</sub> ) <sub>2</sub> AlC	217
6.9	Ti <sub>3</sub> GeC <sub>2</sub> and Ti <sub>3</sub> (Si,Ge)C <sub>2</sub>	219
6.10	Ta <sub>2</sub> AlC	220
6.11	Ti <sub>2</sub> SnC, Nb <sub>2</sub> SnC, and Hf <sub>2</sub> SnC	221
6.12	Ti <sub>2</sub> InC, Zr <sub>2</sub> InC, (Ti <sub>0.5</sub> Hf <sub>0.5</sub> ) <sub>2</sub> InC, and (Ti <sub>0.5</sub> Zr <sub>0.5</sub> ) <sub>2</sub> InC	222
6.13	Sulfur Dioxide, SO <sub>2</sub>	222
6.14	Anhydrous Hydrofluoric, HF, Gas	223
6.15	Chlorine Gas	224
6.16	Summary and Conclusions	225
	Appendix A: Oxidation of Ti <sub>n+1</sub> AlX <sub>n</sub> When Alumina Does Not Form a Protective Layer	226
	References	231

<b>7</b>	<b>Chemical Reactivity</b>	<b>237</b>
7.1	Introduction	237
7.2	Diffusivity of the M and A Atoms	238
7.3	Reactions with Si, C, Metals, and Intermetallics	241
7.4	Reactions with Molten Salts	251
7.5	Reactions with Common Acids and Bases	255
7.6	Summary and Conclusions	263
7.A	Appendix	263
	References	267
<b>8</b>	<b>Dislocations, Kinking Nonlinear Elasticity, and Damping</b>	<b>271</b>
8.1	Introduction	271
8.2	Dislocations and Their Arrangements	271
8.3	Kink Band Formation in Crystalline Solids	274
8.4	Incipient Kink Bands	280
8.5	Microscale Model for Kinking Nonlinear Elasticity	280
8.6	Experimental Verification of the IKB Model	283
8.7	Effect of Porosity	287
8.8	Experimental Evidence for IKBs	289
8.9	Why Microcracking Cannot Explain Kinking Nonlinear Elasticity	292
8.10	The Preisach–Mayergoyz Model	293
8.11	Damping	294
8.12	Nonlinear Dynamic Effects	296
8.13	Summary and Conclusions	301
	References	302
<b>9</b>	<b>Mechanical Properties: Ambient Temperature</b>	<b>307</b>
9.1	Introduction	307
9.2	Response of Quasi-Single Crystals to Compressive Loads	308
9.3	Response of Polycrystalline Samples to Compressive Stresses	311
9.4	Response of Polycrystalline Samples to Shear Stresses	321
9.5	Response of Polycrystalline Samples to Flexure Stresses	322
9.6	Response of Polycrystalline Samples to Tensile Stresses	323
9.7	Hardness	324
9.8	Fracture Toughness and R-Curve Behavior	334
9.9	Fatigue Resistance	339
9.10	Damage Tolerance	342
9.11	Micromechanisms Responsible for High $K_{Ic}$ , R-Curve Behavior, and Fatigue Response	344
9.12	Thermal Shock Resistance	352
9.13	Strain Rate Effects	353
9.14	Solid Solution Hardening and Softening	354
9.15	Machinability	355
9.16	Summary and Conclusions	355
	References	356

<b>10</b>	<b>Mechanical Properties: High Temperatures</b>	<b>363</b>
10.1	Introduction	363
10.2	Plastic Anisotropy, Internal Stresses, and Deformation Mechanisms	364
10.3	Creep	378
10.4	Response to Other Stress States	388
10.5	Summary and Conclusions	394
	References	396
<b>11</b>	<b>Epilogue</b>	<b>399</b>
11.1	Outstanding Scientific Questions	399
11.2	MAX Phase Potential Applications	403
11.3	Forming Processes and Sintering	410
11.4	Outstanding Technological Issues	411
11.5	Some Final Comments	412
	References	413
	<b>Index</b>	<b>417</b>