

SINKHOLES and SUBSIDENCE

Karst and Cavernous Rocks in
Engineering and Construction



Tony Waltham, Fred Bell
and Martin Culshaw



Springer

PRAXIS

Contents

Preface	xi
Contributors	xiii
List of figures	xv
List of tables	xxv
List of boxes	xxvii
Glossary	xxix
1 Rocks, dissolution and karst	1
1.1 Limestone lithologies	2
1.2 Limestone and dissolution	5
1.2.1 Cavernous ground	7
1.3 Karst landforms development by dissolution	9
1.4 Climatic influence on limestone karst	10
1.4.1 Types of limestone karst landscape	12
1.5 Dolomite and its sinkholes	15
1.6 Chalk and its sinkholes	16
1.7 Evaporite rocks and their sinkholes	18
1.7.1 Dissolution and sinkholes on gypsum and anhydrite	19
1.7.2 Dissolution and sinkholes on salt	21
1.8 Man's influence on dissolution and sinkholes	21

2 Sinkhole classification and nomenclature	25
2.1 Sinkholes and dolines	25
2.2 Classification of sinkholes	26
2.3 Solution sinkholes and solution dolines	29
2.3.1 Solution dolines and engineering	35
2.3.2 Solution dolines on salt	37
2.3.3 Solution dolines on gypsum	40
2.4 Collapse and caprock sinkholes	41
2.5 Subsidence, suffosion and dropout sinkholes	43
2.6 Buried sinkholes	44
2.7 Karst types and sinkhole distribution	44
2.7.1 Sinkholes in the engineering classification of karst	45
3 Rock failure in collapse and caprock sinkholes	49
3.1 Karstic collapse	49
3.2 Collapse of cave chambers	50
3.2.1 Cave roof breakdown by bed failure	52
3.2.2 Stable arch development in cave roofs	55
3.2.3 Breakdown processes	56
3.3 Collapse sinkholes	58
3.3.1 Collapse sinkholes in limestones	58
3.3.2 Tianskengs	64
3.3.3 Collapse sinkholes in chalk	66
3.3.4 Collapse sinkholes in gypsum	67
3.4 Caprock sinkholes	70
3.4.1 Caprock sinkholes over limestone	70
3.4.2 Caprock sinkholes over gypsum	75
3.4.3 Caprock sinkholes over salt	78
3.5 Breccia pipes	80
3.6 The collapse geohazard	83
4 Soil failure in subsidence sinkholes	85
4.1 Subsidence sinkhole morphology	85
4.2 Types of subsidence sinkholes	92
4.3 Dropout sinkholes	95
4.3.1 Growth and failure of soil cavities	98
4.3.2 Evolution of subsidence sinkholes	101
4.4 Spatial distribution of subsidence sinkholes	103
4.4.1 Subsidence sinkholes related to cover thickness	107
4.5 The subsidence sinkhole geohazard	108
5 Buried sinkholes and rockhead features	111
5.1 Buried sinkhole morphology	112
5.1.1 Compaction and suffosion in buried sinkholes	118

5.2	Buried sinkholes as engineering hazards	120
5.3	Buried sinkholes and soil pipes in chalk.	125
6	Sinkholes in insoluble rocks	129
6.1	Lava tubes	129
6.1.1	Lava tube stability	132
6.1.2	Engineering failures related to lava sinkholes	136
6.2	Sinkholes in other forms of pseudokarst	137
7	Rock failure under imposed load over caves	141
7.1	Recorded collapse sinkholes induced by loading	142
7.2	Bearing capacity of cave roofs	144
7.2.1	Integrity of loaded rock arches	145
7.2.2	Modelling the failure of cave roofs under load	146
7.2.3	Punching failure of cave roofs	149
7.3	Safe cover thickness over caves	151
7.4	Existing structures over caves.	154
8	Sinkholes induced by engineering works	157
8.1	Sinkholes induced by increased water input	159
8.1.1	Sinkholes caused by reservoir impoundment.	164
8.2	Sinkholes induced by water table decline	165
8.2.1	Sinkholes induced by groundwater abstraction	166
8.2.2	Sinkholes induced by de-watering.	170
8.3	Sinkholes induced by ground disturbance.	176
8.4	The avoidable geohazard of induced sinkholes	177
9	Ground investigation in sinkhole terrains	181
9.1	Preliminary stages	182
9.2	Ground investigation fieldwork	184
9.3	Ground-based geophysical surveys	185
9.3.1	Geophysical methods.	186
9.3.2	Surface seismic surveys.	189
9.3.3	Electrical resistivity surveys.	190
9.3.4	Electromagnetic conductivity surveys.	191
9.3.5	Ground penetrating radar.	192
9.3.6	Microgravity surveys	193
9.3.7	Magnetic surveys	194
9.3.8	Cross-hole tomography	195
9.4	Airborne and satellite remote sensing	198
9.5	Direct investigations.	199
9.5.1	Soil probing.	200
9.5.2	Rock probing and boring	203

10 Hazard and risk assessment of sinkholes	205
10.1 Hazard and risk	205
10.2 Risk management	206
10.3 Karst hazard analysis	209
10.3.1 Parameters in sinkhole hazard assessment	212
10.3.2 Sinkhole hazard assessment in South Africa	215
10.4 Hazard maps and land-use planning	218
10.5 Legislation in response to sinkhole hazards	221
10.6 Sinkholes and insurance	223
11 Prevention and remediation of sinkholes	227
11.1 Soil treatment as sinkhole prevention	227
11.1.1 Grouting in karst	228
11.1.2 Compaction grouting over cavernous karst	229
11.1.3 Soil stabilisation for sinkhole limitation	231
11.2 Sinkhole remediation	233
11.2.1 Repairs to large sinkhole failures	235
11.3 Landfills in sinkhole karst	239
11.3.1 Sinkholes as pollution sources	241
11.3.2 Landfill within sinkholes	241
12 Construction in sinkhole terrains	245
12.1 Construction on soil over karst	245
12.1.1 Control of drainage	246
12.1.2 Foundations within the soil over pinnacled bedrock	247
12.1.3 Extended foundations on rafts and mattresses	248
12.1.4 Sinkhole flooding	251
12.2 Roads and railways on karst	253
12.2.1 Geogrid as a sinkhole defence	255
12.3 Foundations on karst bedrock	257
12.3.1 Driven piles and pin piles	261
12.3.2 Bored piles and caissons	264
12.3.3 Proof testing for piles in karst	265
12.4 Tunnels through cavernous ground	266
12.5 Dam construction in sinkhole karst	268
13 Case studies	271
# 1 Remediation of a sinkhole over gypsum at Ripon, U.K.	272
# 2 Collapse sinkhole at Dishman Lane, Kentucky	277
# 3 Caves and sinkholes in motorway construction, Slovenia	283
# 4 Road built over Sung Gul lava tube, Korea	289
# 5 Karst collapse prevention along Shui-Nan Highway, China	293
# 6 Construction over a cave in Huntsville, Alabama	299
# 7 Sinkhole destruction of Corporate Plaza, Pennsylvania	304
# 8 Subsidence over a chalk pipe at Chalfont St. Peter, U.K.	309

#9 Geophysical investigations of sinkholes in chalk, U.K.	313
#10 Detection of caves by microgravity geophysics, Bahamas	317
#11 Sinkholes and subsidence over salt at Wink, Texas.	321
#12 Subsidence over buried karst at Centurion, South Africa.	326
#13 Agriculture on sinkhole karst on gypsum, Lithuania	331
#14 Sinkhole remediation over Weeks Island salt, Louisiana	336
#15 Hazard assessment on dolomite at Simunye, South Africa	341
#16 Ground investigation in covered karst at Tournai, Belgium	347
References	351
Location index	375
Subject index	379