Contents

Pref	Preface Acknowledgments x	
Ack		
1	Perspective, perspective	1
•	Introduction	1
	The media rarely focuses on the benefits of the chemical industry	1
	A glance at the history of chemical manufacturing before the industrial	_
	revolution	2
	The modern industrial chemical industry modifies our way of living	4
	Risks are not necessarily how they are perceived	5
	Natural pesticides	11
	Plant employee safety versus life-style choices	12
	The chemical industry's excellent safety record	13
	Who has the most dangerous jobs?	14
	What events resulted in fatal occupational injuries in 2012?	18
	Just how dangerous is it to work in a US chemical plant?	19
	How are the chemical and refinery industries doing today when it comes	
	to major losses? And what should we do in the future?	19
	Process safety culture	20
	References	20
2	Good intentions	23
	Modifications made with good intentions	23
	A tank truck catastrophically fails	23
	Siphoning destroys a tender tank	27
	Tank roof splits from overfilling	31
	A well-intended change yields a storage tank collapse	31
	A water drain line is altered and a reactor explodes	37
	An air system is improved and a vessel blows up	39
	A new air system improved economics, but jeopardized safety	43
	Another incident with nitrogen backup for a compressed air supply	43
	The hazards of nitrogen asphyxiation	44
	Concerns for safety on a refrigerated ethylene tank	46
	Beware of impurities, stabilizers, or substitute chemicals	48
	Good intentions on certain new protection systems lead to troubles	49
	A gas compressor is protected from dirt, but the plant catches fire	50
	A replacement check valve installed – one detail overlooked	50
	What was one of the immediate causes of the fire?	52

	What did investigators recommend?	52
	Another good intentions project: new tanks are destroyed and the	
	neighborhood is disrupted	53
	Another tragic incident involving hydrogen sulfide takes the lives of two	
	workers	58
	Closing thoughts on sewers	59
	Carbon absorption incidents show history repeats	59
	The lighter side	60
	A review of good intentions	60
	References	61
3	Focusing on water and steam: the ever-present and sometimes	
	evil twins	63
	Hydro-test goes awry	64
	A flooded column collapses as water is being drained	
	from the system	68
	Water reacting with strong chemicals	71
	Easy-to-use steam heat can push equipment	
	beyond safe design limits	73
	Heating water in a confined system	74
	Steam condenses and a mega-vessel is destroyed	
	during commissioning	75
	A tragedy develops when hot oil is pumped	
	upon a layer of water	79
	Discussion and recommendations	83
	References	85
4	Major US incidents in the twenty-first century	87
	Unfortunately – there is often a certain sameness in process incidents	87
	Delaware City, Delaware, incident	88
	Rouseville, Pennsylvania, incident	88
	Buffalo, New York, incident	89
	Learning opportunities from major incidents in the twenty-first century	89
	President Obama signs an Executive Order relating to process safety	00
	management	90
	An explosion in a plastics manufacturing facility in Illinois results in five	0.1
	deaths, plant closure and eventual tear down of the facility	91
	A glimpse of the PVC plastic facility, the loss of life and property	93
	PVC reactor layout and most likely incident scenario	94
	Not learning from incidents	96
	Key findings on the Illiopolis PVC plant incident	97
	The CSB recommendations submitted to Formosa Plastics USA	98
	The March 2005 Texas City, Texas, refinery incident – the most tragic	
	US refinery accident of the decade	99
	Besides poor safety culture – what happened prior to the release?	100

What happened immediately after the release?	104
Besides poor safety culture – what are some key technical findings of the	
Chemical Safety Board?	105
Besides poor safety culture – what are some key organizational	
findings of the Chemical Safety Board?	107
BP shares their investigation findings on key issues	108
BP Texas City violations and settlement agreements	109
An independent blue ribbon panel investigates BP's North American	
operations	110
A foreword on the findings published by the Baker Panel – broadens	
the impact	110
The summary of the Baker Panel findings	111
Corporate safety culture	111
Refinery tragedy in Anacortes, Washington	112
Introduction to the Anacortes refinery incident	112
Details on the Tesoro refinery incident	113
Why the catastrophic rupture? The technical focus	114
Other Chemical Safety Board findings	115
The CSB video "Tesoro Tragedy – Behind the Curve"	116
CSB sweeping game changing recommendations for the	
US environmental agency	117
CSB recommendations for the State of Washington	118
CSB recommendations for the American Petroleum Institute	118
The Washington Department of Labor and Industries issues citations	118
Ammonium nitrate catastrophe in West, Texas April 17, 2013 –	
fifteen perish	119
Major incidents in the twenty-first century	121
References	121
Two highly destructive twenty-first century vapor cloud	
explosions: one in the United Kingdom and the other in Venezuela	125
Buncefield UK fuel storage and transfer	
depot explosion and fires 2005	125
Introduction to the Buncefield incident	
and impact in the area	126
A look at some details prior to the explosion	
and massive fire	127
The economic costs of the Buncefield incident	131
Fuel concerns after the explosion and fires	133
Instrumentation and control systems	134
Buncefield report recommendations	134
Recommendations for design and operation of fuel storage sites	135
Summary comments on the Buncefield incident	136
A catastrophic explosion at Amuay refinery in Venezuela	137
Immediate events leading up to the explosion	137

	A closer look a details at the Amuay refinery incident	138
	Petroleos de Venezuela (or PDVSA) leak source study	139
	RMG presented their view promptly after the incident	140
	"The Economist" speaks to some underlying issues	140
	The Manufacturing Center in Energy orientation (COENER) report One strongly critical media report speaks about the Amuay refinery	141
	operations	141
	The Amuay refinery based upon an insurance report	143
	Blunt recommendations by the Manufacturing Center in Energy	144
	Conclusions and recommendations for the Amuay disaster	145
	Vapor cloud explosions – closing comments	145
	When it comes to vapor clouds what can you do?	145
	References	146
6	Preparation for maintenance	149
	Some problems when preparing for maintenance	149
	A tank vent is routed to a water-filled drum to "Avoid" problems	151
	Preparing to paint large tanks	152
	Preparing a brine sludge dissolving system for maintenance	153
	What happened in the brine system?	153
	A violent eruption from a tank being prepared for maintenance	155
	An explosion while preparing to replace a valve	
	in an ice cream plant	156
	A chemical cleaning operation kills sparrows,	
	but improves procedures	159
	Other cleaning, washing, steaming, and purging operations	160
	A tragedy when preparing for valve maintenance	161
	A review of changes made to prepare for maintenance	163
	References	164
7	Maintenance-induced accidents and process piping problems	165
	Planning and communication	167
	Repaired reboiler passes the hydro-test and later creates a fire	168
	A tank explodes during welding repairs after passing a flammable gas test	169
	A phenol tank's roof lifts as repairs are made	170
	Catastrophic failures of storage tanks as reported by the Environmental	
	Protection Agency	171
	Hot work on tank catwalk results in a contractor's death, injuries,	
	and a costly off-site environmental insult	172
	Sulfuric acid tank background basics	174
	Unsafe condition report and hot work permit shortcomings	175
	The management of change shortcomings in sulfuric acid tank incident	175
	Root causes as defined by the CSB	177
	Similar tragic incidents involving hot work to tanks provided within the	
	CSB full report Delaware City	177

	The Chemical Safety Board offers safety advice on Hot Work within	
	a 14 min video	178
	Another tank explosion during maintenance hot work	179
	Repair activity to a piping spool results in a massive leak from a sphere	179
	The Phillips 66 incident: tragedy in Pasadena, Texas	182
	A massive fire, BLEVEs, and \$5 million damages after a mechanic	
	improperly removes a valve actuator	185
	Misdirected precautions on a reactor system isolation plug valve result	
	in a vapor cloud explosion	189
	A hidden blind surprises the operators	191
	Poor judgment by mechanics allowed a bad steam leak to result in a	
	minor explosion	194
	The Flixborough disaster and the lessons we should never forget	196
	Do piping systems contribute to major accidents?	199
	Beware of other piping issues	201
	Specific piping system problems reported as major incidents	202
	Four case histories of catastrophic pipe failures	202
	An 8-in. pipeline ruptures and an explosion occurs – December 24, 1989	203
	Piping problems review	204
	Concluding thoughts on maintenance – induced accidents and process	
	piping problems	205
	References	206
0	One-minute modifications: small quiek changes in a plant can	
8	One-minute modifications: small, quick changes in a plant can	
0	create bad memories	209
0	create bad memories Explosion occurs after an analyzer is repaired	209
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred	209 209
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected	209 209 210
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered	209 209 210 210
o	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant	209 209 210 210 215
o	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error	209 209 210 210 215 218
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur	209 209 210 210 215 218 218
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems	209 209 210 210 215 218 218 219
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly	209 209 210 210 215 218 218 219 220
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire	209 209 210 210 215 218 218 219 220 222
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid	209 209 210 210 215 218 218 219 220 222 223
•	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles	209 210 210 215 218 218 219 220 222 223 225
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves	209 209 210 215 218 218 219 220 222 223 225 226
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error	209 210 210 215 218 218 219 220 222 223 225
0	Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error Lack of respect for an open vent as a vacuum-relief device results in	209 209 210 215 218 218 219 220 222 223 225 227
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error Lack of respect for an open vent as a vacuum-relief device results in a partial tank collapse	209 209 210 215 218 218 219 220 222 223 225 227 228
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error Lack of respect for an open vent as a vacuum-relief device results in a partial tank collapse Just a bucket of water destroys a tank	209 210 210 215 218 219 220 222 223 225 226 227 228 229
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error Lack of respect for an open vent as a vacuum-relief device results in a partial tank collapse Just a bucket of water destroys a tank Lack of respect for an open vent as a pressure-relief device costs two lives	209 209 210 210 215 218 219 220 222 223 225 226 227 228 229 231
0	create bad memories Explosion occurs after an analyzer is repaired When cooling methods were changed, a tragedy occurred Instrument air backup is disconnected A furnace temperature safeguard is altered It appeared to be icicles hanging in a small plant Another costly gasket error While compressed asbestos gaskets are phased out, other leaks will occur Other piping gasket substitution problems New stud bolts fail unexpectedly A "Repaired" hose fails triggering a major fire Hurricane procedures are improperly applied to a tank conservation vent lid Painters create troubles Pipefitters can create troubles when reinstalling relief valves Another pipefitter's error Lack of respect for an open vent as a vacuum-relief device results in a partial tank collapse Just a bucket of water destroys a tank	209 210 210 215 218 219 220 222 223 225 226 227 228 229

9	Accidents involving compressors, hoses, and pumps	235
	Reciprocating compressors	235
	A piece of compressor water jacket is launched	235
	The misuse of hoses can quickly create problems	240
	The Chemical Safety Board investigates a chlorine unloading hose failure	241
	The Chemical Safety Board investigated a phosgene hose failure with	
	a fatality	242
	Fatality from a ruptured hose in HF service	243
	Hose mishaps frequently lead to loss of containment – maybe more	
	than we think	244
	The water hose at the Flixborough disaster	245
	Hoses used to warm equipment	246
	Three-Mile Island Incident involved a hose	246
	The Bhopal Tragedy was initiated by use of a hose	247
	Improper purge hose set up for maintenance creates major problems	247
	High-pressure hydrogen inadvertently backs into the nitrogen system	
	and an explosion occurs	251
	A nitric acid delivery to the wrong tank makes front-page news	252
	How do you prevent such an incident?	252
	Other truck delivery incidents	253
	An operator averts a sulfuric acid unloading tragedy	253
	Hoses cannot take excessive abuse	254
	What is the advice from practitioners?	254
	Centrifugal pumps	256
	River water pump piping explodes	256
	Severe pump explosions surprise employees	262
	A large condensate pump explodes	264
	Closing thoughts on pump explosions.	
	Courtesy of the "Beacon"	264
	Afterthoughts	266
	References	266
10	Failure to use, consult, or understand specifications	269
	Lack of well-defined, rigid operating instructions cost \$100,000 in	
	property damages	269
	Other thoughts on fired heaters	272
	Low-pressure tank fabrication specifications were not followed	273
	Explosion relief for low-pressure tanks	274
	Tinkering with pressured vessel-closure bolts ends with a harmless bang	275
	Piping specifications were not utilized	278
	Pump repairs potentially endanger the plant, but are corrected in	
	time to prevent newspaper headlines	284
	Plastic pumps installed to pump flammable liquids	286
	Weak walls wanted – but alternate attachments contributed to the damage	286
	References	288

11	"Imagine If" modifications and practical problem solving	289
	"Imagine If" modifications – let us not exaggerate the dangers as	
	we perform safety studies	289
	New fire-fighting agent meets opposition – "Could Kill Men	
	as Well as Fires"	289
	A process safety management quiz	290
	New fiber production methods questioned	293
	Practical problem solving	294
	The physics student and his mischievous methods	295
	References	296
12	The role of mechanical integrity in chemical process safety	297
	Mechanical integrity in a chemical plant	297
	A regulatory view of mechanical integrity	298
	Mechanical integrity programs must be tailored to the specific site	299
	Mechanical integrity in design and installation	300
	Equipment covered by mechanical integrity	300
	Regulatory enforcement of mechanical integrity	302
	What is all this about RAGAGEP?	303
	Struggling with mechanical integrity	304
	Written procedures and training	304
	Classification of equipment by hazard potential	305
	Mechanical integrity programs for pumps/compressors	306
	Mechanical integrity programs for piping, pressure vessels, storage	
	tanks, and process piping	312
	Inspecting pressure vessels, storage tanks, and piping	316
	Inspection of pressure vessels and storage tanks	316
	Mechanical programs for safety-critical instruments and safety	
	relief valves	329
	The critical role of safety relief valves	329
	"In-house" testing safety relief valves	331
	Mechanical integrity program for process safety interlocks and alarms	339
	Protective process safety interlocks at a DuPont plant	340
	Another company – a different emphasis on safety critical instrument	
	systems	341
	Another approach – prooftesting at a Louisiana plant	342
	Additional information on mechanical integrity	350
	References	351
13	Effectively managing change within the chemical industry	353
	Introduction	353
	Preliminary thoughts on managing change	353
	Are management of change systems like snowflakes?	354
	A reality check provided by previous chapters	355
	Keeping MOC systems simple	357

	Losing tribal knowledge	357
	Some historical approaches to plant changes	358
	The US OSHA PSM Standard addresses "management of change"	358
	Principles of an effective management of change system that prevents	
	uncontrolled change and satisfies OSHA	360
	An overall process description to create or improve a management of	
	change system	361
	Clear definitions are imperative	362
	Key steps for an effective management of change system for a medium	
	or large organization	364
	Key steps for an effective management of change system for a small	
	company	370
	Multidisciplined committee can provide an in-depth look when	
	identifying hazards	372
	Operational variances for maintenance need	
	a close examination too	374
	Variances, exceptions, and special cases	
	of change	375
	Should the MOC system be paperless?	377
	Over two dozen plants share their MOC practices	378
	Management of change approvals, documentation, and auditing	381
	Closing thoughts on management of change policy	382
	The Center for Chemical Process Safety	385
	Recommendations and regulations after 1988	385
	References	388
14	Investigating and sharing near misses and unfortunate accidents	391
	Introduction	391
	What does the regulation say about incident investigations?	391
	Plant cultures can affect investigations	393
	More guidelines on the culture of incident reporting	395
	An OSHA program coordinator's view	395
	Layers of incident causes	396
	A furnace tube failure case history is revisited	396
	Process safety incident investigation techniques	398
	Applying root cause analysis	399
	Some chemical manufacturers' approaches to incident investigation	400
	What is a root cause?	401
	STAMP – a new accident causality model	404
	Some thoughts on process safety incident investigation techniques	406
	Complying with the OSHA element on incident investigation	406
	Report approval, report distribution, sharing the findings,	
	corrective action tracking, and report retention	410
	Conclusions	411
	References	412

15	Keep a sense of vulnerability for safety sake: seven recommendations for keeping a sense of vulnerability at your chemical processing	
	or refining site	415
	Opening thoughts on unease and who should it impact	415
	How do you create a sense of unease or vulnerability?	416
	A focused effort is essential	417
	Success can blind us of reality	418
	Seven recommendations to reduce your vulnerability	418
	Why not step back in time?	424
	References	425
16	A strong safety culture is essential: it is essential to develop a strong	
	safety culture	427
	Process safety culture has been recognized and accepted in recent years	427
	Foundation for development of safety culture	428
	About 65 companies shared to shape the earlier definition of	
	"Safety Culture" in 2003	429
	What is process safety culture? Perhaps – it is the root cause	
	of the decade!	429
	A dozen features essential to developing a durable safety	
	culture within PSM	432
	API RP 754 describes the "Purpose of Indicators" as [17]	441
	Is safety culture really important?	442
	References	443
17	Sources of helpful information for practicing chemical process safety	445
	Key cost free process safety resources at your finger tips	445
	Process safety resources via consultants, professional associations and	
	trade associations via the web	451
	Excellent books addressing chemical process safety – from a process	
	engineer's viewpoint	460
	Two of the best process safety videos which focus on learning from case	
	histories	463
	References	464
Ind	ndex	