



ELSEVIER
PERGAMON

Comprehensive Structural Integrity

Fracture of Materials
from Nano to Macro

◆ VOLUME 1:

Structural Integrity Assessment
Examples and Case Studies

Volume Editors

- ◆ I. Milne
- ◆ R.O. Ritchie
- ◆ B. Karihaloo

Contents

Preface	vii
Contributors to Volume 1	xiii
1.01 Structural Integrity Assurance	1
I. MILNE, <i>Structural Integrity Management, Matlock, UK</i> , B. KARIHALOO, <i>University of Wales, Cardiff, UK</i> , and R. O. RITCHIE, <i>University of California, Berkeley, USA</i>	
1.02 Historic Masonry Structures	25
L. BINDA, A. ANZANI, and A. SAISI, <i>DIS Politecnico di Milano, Italy</i> , and G. MIRABELLA ROBERTI, <i>IUAV, Venice, Italy</i>	
1.03 Railways: Structural Integrity, Past, Present, and Future	49
R. A. SMITH, <i>Imperial College London, UK</i>	
1.04 Milestone Case Histories in Aircraft Structural Integrity	61
R. J. H. WANHILL, <i>National Aerospace Laboratory NLR, Amsterdam, The Netherlands</i>	
1.05 Case Histories in the Application of Structural Integrity Analysis in the Oil Industry	73
J. HARRISON, <i>TWI Ltd., Cambridge, UK</i>	
1.06 The Structural Integrity of Oil and Gas Transmission Pipelines	87
P. HOPKINS, <i>Penspen Ltd., Newcastle upon Tyne, UK</i>	
1.07 Structural Integrity in the Petrochemical Industry	125
I. LE MAY, <i>Metallurgical Consulting Services, Saskatoon, SK, Canada</i>	
1.08 Structural Integrity Issues in the Electricity Generating Industry	151
A. SAXENA, <i>Georgia Institute of Technology, Atlanta, GA, USA</i>	
1.09 Structural Integrity Issues in the Nuclear Industry	173
B. TOMKINS, <i>AEA Technology plc, Risley, Warrington, UK</i>	
1.10 Corrosion in the Power Industry	193
G. J. BIGNOLD, <i>Innogy Plc, Swindon, UK</i>	
1.11 Structural Integrity Issues Associated with Soils and Rock in Civil Engineering Industries	217
J. C. SMALL, <i>University of Sydney, NSW, Australia</i> , and H. G. POULOS, <i>University of Sydney, Australia and Coffey Geosciences, Sydney, NSW, Australia</i>	
1.12 Failure of Concrete Structures	241
B. I. G. BARR, <i>University of Wales, Cardiff, UK</i>	
1.13 Earthquake Resistant Structures	271
R. PARK, <i>University of Canterbury, Christchurch, New Zealand</i>	
1.14 Structural Integrity Issues in the Mining Industry: Learning from Failures—Instructive Case Studies	305
P. ANSOURIAN, <i>University of Sydney, NSW, Australia</i>	
1.15 Structural Integrity Issues Associated with Bridges	319
M. OGLE, <i>TWI Ltd., Cambridge, UK</i>	

1.16	Lessons from a Quarry: Failure of the Rotor of an Impact Rock Crusher	337
	A. BANNISTER, <i>Corus Research, Development & Technology, Rotherham, UK</i> , and I. MILNE, <i>Structural Integrity Management, Matlock, UK</i>	
1.17	Thin Sheet Fracture	355
	A. G. ATKINS, <i>University of Reading, UK</i>	
1.18	Castings	377
	M. JOLLY, <i>University of Birmingham, UK</i>	
1.19	Risk Assessment and Management	467
	T. G. THEOFANOUS, <i>University of California, Santa Barbara, CA, USA</i>	
	Colour Plate Section	between pages 210 and 211
	Subject Index	491